

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6346 7488

AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0268/19

DATE : 18-MAY-2019

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : MR GOH JENN JIUN (WU ZHENJUN)
ADDRESS : 20 JALAN KUPANG

S(468617)
TELEPHONE NO : 98257606

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 2100492762-02
VEHICLE NO : SLJ2937P
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2310475A
CHASSIS NO : SJNFEAJ11U1724149
MILEAGE : 30088 KM
DATE IN : 18/05/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : ELMER
ACCIDENT DATE : 18/05/2019

- 9645 0084 elmer@fanchoy.com

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLJ2937P

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOR CHARGES TO REPAIR RR END PANEL, BOTH RR FENDR RENEW HATCHBACK DOOR AND REAR BUMPER	1750.00	625
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME	1000.00	600
3	ZZ/003	RENEW RR WINDSCREEN GLASS	180.00	✓
4	ZZ/004	RENEW RR WINDSCREEN SOLAR FILM	150.00	✓
5	ZZ/005	APPLY SEALANT TO RR WINDSCREEN GLASS	100.00	✓
6	ZZ/006	APPLY SELANAT TO HATCHBACK DOOR	100.00	✓
7	ZZ/007	REMOVE AND INSTALL REVERSE CAMERA	240.00	✓
8	ZZ/008	REMOVE AND TRANSFER HATCHBACK DOOR MECHANISM TO THE NEW HATCHBACK DOOR	80.00	✓
9	ZZ/009	RENEW REVERSE SENSOR 4 POINT	110.00	✓
10	ZZ/011	SUPPLY REAR LICENSE PLATE		
11	ZZ/10	REMOVE AND INSTALL HATCHBACK DOOR LAMP AND REAR COMBINATION LAMP	48.00	✓
TOTAL LABOUR CHARGES			3758.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLJ2937P

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
1	PLATE LUGGAGE REAR GARNISH ?	84992-4EA0A	63.50	?
2	ORNAMENT BACK DOOR- QASHQAI <i>nee</i>	90892-4EA0A	87.00	✓
3	EMBLEM-REAR NISSAN <i>nee</i>	90890-4EA0A	59.70	✓
4	HATCHBACK DOOR LOCK <i>nee</i>	90502-4EA0B	154.80	+
5	STRIKER-HATCHBACK DOOR <i>nee</i>	90570-4EA0A	31.10	+
6	HATCHBACK DOOR STAY @ SGD \$ 216.80 EACH <i>nee</i>	90450-4EA0A	433.60	+
7	HATCHBACK DOOR GARNISH <i>nee</i>	90810-4ES0H	336.00	+
8	WEATHER STRIP HATCHBACK DOOR <i>nee</i>	90830-4EA0A	158.70	+
9	GLASS-HATCHBACK DOOR <i>nee</i>	90300-4EA0D	930.00	✓
10	REAR W/SCREEN SEALANT <i>nee</i>	SEALANT - 4	80.00	✓
11	SUNDRIES <i>nee</i>	NPN	50.00	20
12	REAR LICENCE PLATE <i>nee</i>	RLP	60.00	+
13	HATCHBACK DOOR <i>Deformed</i>	K0100-4EAAC	2936.80	✓
14	LH STAY RR BUMPER ?	H5210-4EAMA	126.00	?
15	LH STAY RR BUMPER ?	H5211-4EAMA	126.00	?
16	REINFORCEMENT RR BUMPER ?	H5030-4EAMA	619.20	?
17	ENERGY ABSORBER RR BUMPER ?	85090-4EA0B	126.40	?
18	RH SIDE BRACKET RR BUMPER <i>nee</i>	85220-4EA0A	35.90	✓
19	LH SIDE BRACKET RR BUMPER <i>nee</i>	85221-4EA0A	35.90	✓
20	TOW HOOK COVER RR BUMPER <i>nee</i>	85071-4EA0A	16.80	+
21	CLIP RR BUMPER @ \$1.20 EACH <i>nee</i>	01553-05933	7.20	✓
22	REAR BUMPER <i>Deformed</i>	85022-4EA0H	717.00	✓
SUB TOTAL			7001.60	0.00 190.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			1400.32	0.00 0.00
GRAND TOTAL			5601.28	0.00 190.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLJ2937P

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
OVERALL TOTAL			5791.28	

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLJ2937P

TOTAL LABOUR CHARGES	3758.00
TOTAL SPARE PARTS CHARGES	5791.28
GRAND TOTAL	9549.28 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	Adrian Lim . 96893735
SURVEYED DATE	:	23/05/19. Not Authorized
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00 05 Days.
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.