

ASS. REC. BY:

REF: CS/PC19008953/kqd3n2

Special Instruction:

Assigner: Kenneth

ASSIGNMENT (Office)

(CWS)

From (Person): Karim of FCI Date/Time: 21.5.17 5.47p.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGJ 6106D Insured: SHC 3357R

at Workshop m/s Chew Guan Moto Tel: 64841626

of BIR 10 AMK Industrial Park 2A Ave 5 # 01-15, 16, 17

Policy No: Claim No: D19003301MFSH

Sum Insured: Excess:

Make of Veh: D.O.A 16.5.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

sup

H.O.D. Endorsement:

Date/Time: 22.5.19 9.24am Person Contacted: Kelly Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate	Remarks
	SGJ 6106D - MA/INC 1600423/k4	✓	D.O.A - 09/03/2016
	SHC 3357R - CS/PC13005231/mink3		D.O.A - 17/03/2013
23/5/19 @ 4.04pm	REVISED TO KAREN TAN BY EMAIL		

REF: FCI

ASSIGNMENT

From: _____ Date: 22.5.2019

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 563 6106D

at Workshop m/s: Chew Goon Motors

of: B1K 10 Amk Industrial Park 2A Ave 5 #01-15

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: 563 61060 Yr Regn: 06, 06

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Jazz A1 c.c. 1339

Colour: Yellow A/C: Insured / Std / NI / NA

Sp. Reading: 208498 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: J12MGD18506S226775

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$14k

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS "N/A"

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Tyre Size: F: 195/65R15 R: _____

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TCYO / YOKO or

Front	Rear
R/Bal. 6 mm	R/Bal. 6 mm
L/Bal. 6 mm	L/Bal. 6 mm
D.O.A. 16/3/19	D.O.I. 22/5/19

Survey held at: _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S 141

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	1) Rep @ 2250k (LRA @ 2654.56, 54%)
	MV: \$14k (est) : LIA: \$9858 : NV: 4142
	RECEIVED 04 OCT 2019

Date/Time, File Pass to? : Preli. Report

1) 04/10 2019 : Final Report

Date/Time, File Return to? _____

Days Of Repair: 4

Resurvey No. of Trip: _____

Report Format: TP

Lump Sum / I.P.A. (\$) 2250

Add Fee: Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Survey Fee:	135
Transportation:	50
S + RS, SI	
Photos	17
Others	
TOTAL	202



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19003301MFSH

Date: 23 May 2019

Our Ref: CS/FCI19008953/Kqd3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SGJ 6106D

Please be informed that we had conducted the inspection of the abovementioned vehicle on 22/05/2019 at the premises of M/s CHEW GOON MOTOR, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>4,904.56</u>
Revised Estimate Amount	: S\$ <u>2,810.96</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the n/s front portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	17-05-2019	Our Ref No. D19003301MFSH
Accident Date	16-05-2019	Claim Type. Third Party
Insured Vehicle	SHC3357R	Third Party Vehicle. SGJ6106D
Survey Location	BLK 10, ANG MO KIO INDUSTRIAL PARK 2A AVE 5 #01-15,16,17 & #03-05AMK AUTOPOINT	
Contact Person.	KELLY	
Contact No.	64841626/ 0	Fax No. 64840465
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHEW GOON MOTOR	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 23 May 2019 4:04 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Karen Tan'; SUR
Subject: RE: SURVEY ASSESSMENT - D19003301MFSH/1
Attachments: CSFCI19008953Kqd3.pdf

Dear Karen,

Enclosed herewith preliminary advice of SGJ 6106D.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 22 May 2019 1:51 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19003301MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 21 May 2019 5:47 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003301MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Hello, CHEW_GOON_800085

Change Language Change Password Log Out

My Desktop
Notice of Loss

Policy Query

Policy No.: Date of Accident:
 Vehicle No.(For Motor): Certificate Number:

Search

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5097466884-01		JOSHUA TAN JIA WEI	S9208419C	GPC	drive CLASSIC	SGJ6106D	SGJ6106D	17/01/2019	16/01/2020

Continue

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 8418C

Vehicle Details

Vehicle No.: SGJ6106D
Vehicle to be Exported: No
Intended Deregistration Date: 16 May 2019
Vehicle Make: HONDA
Vehicle Model: JAZZ 1.4A
Primary Colour: Yellow
Manufacturing Year: 2006
Engine No.: L13A53000850
Chassis No.: JHMGD18506S226775
Maximum Power Output: 60.0 kW (80 bhp)
Open Market Value: \$15,057.00
Original Registration Date: 17 Jul 2006
First Registration Date: 17 Jul 2006
Transfer Count: 2
Actual ARF Paid: \$16,563.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 30 Jun 2021
COE Category: A - Car (1600cc & below)
COE Period(Years): 5
PQP Paid: \$23,227.00
COE Rebate Amount: \$9,858.00
Total Rebate Amount: \$9,858.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 16 May 2019

OK

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S9208418C



Name
JOSHUA TAN JIA WEI

陳家偉

Race
CHINESE

Date of birth
05-03-1992

Sex
M

Country of birth
SINGAPORE

S9208418C

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number S9208418C

Name
JOSHUA TAN JIA WEI

Birth Date 05 Mar 1992

Issue Date: 17 Jan 2013



002142836J

4016901



NRIC No. S9208418C



Date of issue
16-03-2007

Address
APT BLK 551 SERANGOON NORTH AVENUE 3
#10-53
SINGAPORE 550551

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars= \leq 3000kg with \leq 7 passengers, exclusive of the driver; and other motor vehicles \leq 2500kg 17 Jan 2013

NP 428A

Licence No: S9208418C



趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
 Tel: 6484 1626 (24Hrs) Fax: 6484 0465
 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

*Not within
 11 Day @ 2250/-
 Premium After Pain
 4 days*

To: First Capital Insurance Limited

Accident Date : 16.05.2019

Policy No: _____
 Third Party
 Date: 21.05.2019

Specialised in Car Painting, Welding,
 Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
 代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Honda Jazz" Reg. No. SGJ6106D Claiming Against Your Insured Veh. No. SHC3357R			
1pc	Front Bumper		<i>Bulloma</i> 523.50 ✓
10pcs	Front Bumper Clips	3.80	<i>na</i> 38.00 ✓
1pc	Front Bumper Top Retainer LH		<i>DIY</i> 13.50 ✓
1pc	Front Bumper Center Air Grille		<i>CM</i> 145.00 ✓
1pc	Front Bumper Reinforcement		<i>R</i> 154.80 X
1pc	Front Bumper Reinforcement	13.50	<i>DIY</i> 27.00 ✓
2pcs	Front Bumper Corner Holders		<i>CM</i> 118.50 ✓
1pc	Front Bumper Lower Splash Guard		<i>na</i> 972.40 ✓
2pcs	Headlamps	<i>N/S CR</i> 486.20	<i>A</i> 375.60 ✓
1pc	Front Fender LH		<i>na</i> 140.20 ✓
2pcs	Front Fender Shields	<i>DIY</i> 70.10	<i>na</i> 76.00 ✓
20pcs	Front Fender Shield Clips	3.80	<i>CM</i> 195.20 ✓
1pc	Engine Lower Splash Guard		<i>na</i> 1,178.50 X
1pc	Radiator		<i>na</i> 285.00 X
1pc	Radiator Fan Motor		
			4,243.20
	Less 20%		848.64
			3,394.56
	To Conduct Front Electrical Check, Focus Headlamp		30.00 <i>20</i>
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		50.00 <i>30</i>
	To Conduct Computerize Wheel Alignment Test		<i>na</i> 80.00 X
	Labour Charge - Panel Beating, Repairing Of Front N/S Chassis Member, Fender Inner Panel, Headlamp Panel, Front N/S Door and Parts Replacement		600.00 <i>450</i>
	To Respray Affected Areas		<i>600</i>
			750.00
			<u>4,904.56</u>

LKK Auto Consultants hence notify **Total :**
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FC19008953/Kqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 04-10-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 3357R	Veh. Inspected	SGJ 6106D
Policy No.		Coverage (\$)	0.00
Claim No.	D19003301MFSH	Excess (\$)	0.00
Assign From	KARENT	Assign Date	21/05/2019
2. Vehicle Particulars & Condition			
Make & Model	HONDA JAZZ (A)	c.c	1339
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	JHMGD18506S226775	Colour	YELLOW
Odometer	208498	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	DUNLOP	6 mm
L/H Front Tyre	195/65 R15	DUNLOP	6 mm
R/H Rear Tyre	195/65 R15	DUNLOP	6 mm
L/H Rear Tyre	195/65 R15	DUNLOP	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	16/05/2019	Inspection Date	22/05/2019
Survey held at	CHEW GOON MOTOR BLK 10 ANG MO KIO IND PARK 2A #01-15/16/17, AVE 5, AMK AUTOPOINT SINGAPORE 568047		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGJ 6106D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	BUCKLED / CRACKED	523.50	523.50
10	FRONT BUMPER CLIPS @\$3.80	NECESSARY	38.00	38.00
1	FRONT BUMPER TOP RETAINER LH	DISTORTED	13.50	13.50
1	FRONT BUMPER CENTER AIR GRILLE	CRACKED	145.00	145.00
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	154.80	-
2	FRONT BUMPER CORNER HOLDERS @\$13.50	DISTORTED	27.00	27.00
1	FRONT BUMPER LOWER SPLASH GUARD	CRACKED	118.50	118.50
2	HEADLAMPS @\$486.20	N/S CUT	972.40	486.20
1	FRONT FENDER LH	BENT	375.60	375.60
2	FRONT FENDER SHIELDS @\$70.10	O/S MISSING / N/S CRACKED	140.20	140.20
20	FRONT FENDER SHIELD CLIPS @\$3.80	NECESSARY	76.00	76.00
1	ENGINE LOWER SPLASH GUARD	CRACKED	195.20	195.20
1	RADIATOR	SERVICEABLE	1,178.50	-
1	RADIATOR FAN MOTOR	SERVICEABLE	285.00	-
	LESS 20% DISCOUNT		-848.64	-427.74
			3,394.56	1,710.96
LABOUR				
	TO CONDUCT FRONT ELECTRICAL CHECK, FOCUS HEADLAMP.		30.00	20.00
	TO APPLY RUST PROOFING/RESEAL TUFF COATING TREATMENT TO RESPRAY/REPLACED/REPAIR PANEL.		50.00	30.00
	TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT TEST.	NOT NECESSARY	80.00	-
	LABOUR CHARGE-PANEL BEATING, REPAIRING OF FRONT N/S CHASSIS MEMBER, FENDER INNER PANEL, HEADLAMP PANEL, FRONT N/S DOOR AND PARTS REPLACEMENT. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT.		600.00	450.00
	TO RESPRAY AFFECTED AREAS.		750.00	600.00
			1,510.00	1,100.00
GRAND TOTAL			4,904.56	2,810.96

Report Ref No. CS/FCI19008953/Kqd3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,250.00
---	--	--	----------

Report Ref No. CS/FCI19008953/Kqd3n2

MARKET VALUE: \$14,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$9,858.00=NETT VALUE: \$4,142.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.