

ASS. REC. BY:

REF: CS/KMO/9008969/ R/qd 3n2

Special Instruction:

Surveyor: RASU

ASSIGNMENT (Office)

From (Person): Agnes Chan Shu Hui

of SMO

Date/Time: 22.5.19 10:37a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SME 6336 L

Insured:

GIBB 655B

at Workshop m/s Moton Carz Garage

Tel:

9769 9299

of 53 Ibs Ave 1 #01-19

Policy No: DIA/MP/VE000753

Claim No: CNTD1902363

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 15.5.2019

CA / REV / REP. / REV 24 HRS

"up"

H.O.D. Endorsement:

Date/Time: 22.5.19 11:31a.m

Person Contacted:

Koman

Vehicle IN / OUT

Date/Time	Action/Instruction
	SME 6336 L - X
	GIBB 655B - X
22/5/19 @ 3.40pm	Informed Agnes Chan, we are pending estimate from repairer.
20/6/19 @ 10.00am	Verified to Agnes Chan via Wechat.

REF: SMO

0625H

ASSIGNMENT

From:

Date: 22.5.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SME 6336L

at Workshop m/s: MOTARICAR 2 Garage

of 53 Wb Ave 1 # 01-19

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

"rep"

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SME 6336L

Yr Regn:

2018 / Aug

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MITSUBISHI OUTLANDER 2.0 CC 1998

Colour:

Black

A/R:

Insured / Std / NI / NA

Sp. Reading:

016874

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GF7W 0402114

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Morder / Jammed / Leaked / Burnt or

Brake: Morder / Jammed / Leaked / Burnt or

Mod: Nil / R/Rim / STD A/Rim or

Tyre Size:

F:

225/50R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

YOYO / YOKO or

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A:

15/05/19

D.O.I:

22/05/19

Survey held at:

MOTARICAR 2

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

19/06/19 w/shop call to confirm final amount at \$6,450 / 8 days L/S
amount confirmed by KAMAN
(Led & 7344.70, 530%)

RECEIVED 6 JUN 2019

20/6/2019

Date/Time, File Pass to?



: Preli. Report

1) 20/6/2019



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 8

Resurvey No. of Trip: 2

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Report Format:

MER-TP

Lump Sum / I.B.A. (\$

6450

Survey Fee:

Transportation:

: \$ + R5 \$

: Photos

: Others

TOTAL

350

11

361

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sampo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: CHAN SHU HUI AGNES

Date: 20 Jun 2019

Preliminary Advice

Insured Vehicle No	: GBB655B	Accident Date	: 15/05/2019
TP Vehicle No	: SME6336L	Assignment Date	: 22/05/2019
Make	: MITSUBISHI OUTLANDER	Est. Duration of Repair	: 8.00
Date of Inspection	: 22/05/2019		
Inspection At	: MOTORICARZ GARAGE (HQ) 53 UBI AVENUE 1, #01-19 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,794.70
Revised Amount	:S\$	8,063.68
Check Items (Estimated)	:S\$	0.00
Total	:S\$	8,063.68
Lump Sum Repair	:S\$	6,450.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 May 2019		22 May 2019 10:37 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	EVERSHINE FLORIST PTE LTD, Co. Reg. No.: 197701114E		
Main Claimant:	PACIFIC-KSH COMPANY PTE. LTD., Co. Reg. No.: 200200685H		
Vehicle Reg. No.:	SME6336L	Date of Loss:	15/05/2019 00:00 - :59
Claim Type:	TP / CMTD1902363	Policy/Cover Note No.:	D19MTPCVE000753 (Third Party Only)
Vehicle Reg. No. (Insured):	GBB655B	Policy No. (Claimant):	
		Excess:	
Repairer:	Motoricarz Garage (HQ) 53 UBI AVENUE 1, #01-19 PAYA UBI INDUSTRIAL PARK, 408934 Paya Lebar - Tel: 68415383		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 31/05/2019]		
Adj Asg. Remarks:	WS: Mr Kaman 9769 9299		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Thursday, 23 May 2019 3:40 PM
To: do-not-reply@merimen.com
Cc: SUR
Subject: TP VEHICLE SME 6336L (YOUR REF: CMTD1902363)

This mail is associated with :
***SME6336L (CMTD1902363)**
[GBB655B]
TP
PACIFIC-KSH COMPANY PTE. LTD.
May 15 2019 12:00AM
[EVERSHINE FLORIST PTE LTD]
Motoricarz Garage

Dear Agnes,

Please be informed that we have inspected the vehicle SME 6336L on 22/05/2019.

We are pending estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)



AVG

This email has been checked for viruses by AVG antivirus software.
www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0685H
Vehicle Details	
Vehicle No.:	SME6336L
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Jun 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	OUTLANDER 2.0 CVT
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	4J11YQ0393
Chassis No.:	GF7W0402114
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$19,655.00
Original Registration Date:	21 Aug 2018
First Registration Date:	21 Aug 2018
Transfer Count:	0
Actual ARF Paid:	\$19,655.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Aug 2028
PARF Rebate Amount:	\$14,741.00
Intended COE Rebate Details	
COE Expiry Date:	20 Aug 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$37,989.00
COE Rebate Amount:	\$34,823.00
Total Rebate Amount:	\$49,564.00

The information contained herein is correct as at 20 Jun 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 15/05/2019 17:49
 Date Of Accident 15/05/2019 13:30
 Exact Location Of Accident SLIP ROAD OF PAYA LEBAR ROAD
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SME6336L
Insured/Policyholder
 Name Of Registered Owner PACIFIC-KSH COMPANY PTE. LTD.
 Co Reg No 200200685H
 Email Address SHKOH@PACIFICKSH.COM.SG
 Mobile Phone No (LOCAL) +65-90087706
 Alternative Phone No OFFICE-67420985

Vehicle Particulars

Manufacturer MITSUBISHI
 Model OUTLANDER-2.0 (A)
 Exact Purpose for which vehicle was being used at time of accident NORMAL USAGE

Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number 1800099536
 Cover Note Number

Driver

Name of Driver KOH SONG HING
 NRIC No S2719600D
 Date Of Birth 09/06/1967
 Occupation INDOOR
 Date Of Driving Pass 29/06/1990
 Driving Experience 28 YEARS AND 10 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-90087706
 Fax Number
 Contact Number
 EMail Address SHKOH@PACIFICKSH.COM.SG

Address	BLK 246 KIM KEAT LINK #04-07 SINGAPORE
Postcode	310246
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS MY CAR WAS STATIONARY WAITING ONCOMING TRAFFIC CLEAR BEFORE JOIN INTO PAYA LEBAR ROAD, SUDDENLY I FELT AN IMPACT FROM BEHIND, REALISED THAT VEHICLE B GBB655B HAD KNOCKED INTO MY CAR BEHIND.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBB655B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	OH FOOK SAN (HU FUSHAN)
NRIC/Passport Number	S7430185A
Contact Number	96549799
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan




MOTOR ACCIDENT REPORT FORM

BASIC INFORMATION			
Date of Report:	15/05/2019		Time:
Date of Accident:	15/05/2019		Time: 1330
Exact Location of Accident:	Side road of Paya Lebar Road		
DETAILS OF OWN VEHICLE			
Vehicle Registration Number:	SME 6336L		
Name of Registered Owner:	Pacific-KSH Company Pte. Ltd		
NRIC/Passport No./FIN:	-		
Company Reg. No./for Company Veh:	200200685H		
VEHICLE PARTICULARS			
Manufacturer:	MIT	Model:	outlander
Exact Purpose for which vehicle was being used at time of Accident:	☒ Normal Usage ☐ Others		
Are You Claiming Under Your Own Insurance?	☐ YES ☐ NO Reporting Only ☒ NO 3rd Party		
Vehicle Category:	☒ Private car ☐ Commercial Vehicle		
INSURANCE DETAILS			
Name of Insurer:	HIG		
Type of Coverage:	☒ Comprehensive ☐ Third Party		
Policy Number:	1800099536		
Driver when the Accident Happen			
Name of Driver:	Koh Seng Hing		NRIC/Passport/Fin No: 52719600D
Date of Birth:	29/06/1967		Occupation: Director
Date of Driving Pass:	29/06/1990		Gender: ☒ Male ☐ Female
Mobile No:	9008 7706		Home No: 6742095 (office)
Address:	186, 246 Kim Kiat Link #04-07 Singapore Postal Code 318246		
Email Address:	shub@pacific-ksh.com.sg		
Was the Driver an Employee of the Insured's Company:	☒ Yes ☐ No State the relationship of the driver to insured		
Vehicle Registration Number of driver's Own Vehicle:	-		
Insurance Company:	-		
OTHER INFORMATION OF THE ACCIDENT			
Type of Accident:	3rd Party HIT Insured (Head to Rear)		
Weather Condition:	☒ Clear ☐ Raining ☐ Others, please specify		
Road Surface:	☒ Dry ☐ Wet ☐ Others, please specify		
Was Anybody Injured:	☒ No ☐ Yes		
Was Any other material or Property Damaged:	☒ Yes ☐ No		
Any Accident Photo in the Scene of Accident:	☒ Yes ☐ No		
Was the Accident reported to police:	☐ Yes ☒ No		
Which Police Station:	-		
Was notice of Intended Prosecution given:	-		
DETAILS OF OTHER VEHICLE (Please fill Annex A if more vehicles involved)			
Vehicle Registration Number:	QBB 655B		
Name of Registered Owner:	-		
NRIC/Passport No./FIN:	-		
Company Reg. No./for Company Veh:	-		
Name of Driver:	Oh Eock Sen (Hu Fushen)		NRIC/Passport/Fin No: 87430185A
Mobile No:	9656 9799		Home No: -
Address:	-		
Postal Code:	-		
Email Address:	-		
Insurance Company:	-		
Details of Passenger if any			
Passenger Name:	-		
Contact Number:	-		
Gender:	-		
Details of Injured Person			
Name:	-		
Age:	-		
Address:	-		
Injured Sustained:	Injured Person in which vehicle:		
Were Seatbelts worn:	☐ Yes ☐ No		
Were injured convey to hospital by Ambulance:	☐ Yes ☐ No		

08/04/2012

Sketch Plan #3

SKETCH PLAN



A - SME 6336L

B - GBB 655B

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As my car was stationary, waiting oncoming traffic clear before join into Poya Lebar Road, suddenly I felt an impact from behind, realised that vehicle B GBB 655B had knocked into my car behind.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

15/05/2019
(3pm)

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Police Personnel's Signature
Name:
NRIC/ID No.:



Sketch Plan #2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the G&A Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or obtained by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be based outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

15/05/2019 (3PM)

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Resorting Centre Personnel's Signature
Name:
NIC/FIN No.:

Motoricarz Garage

Kamon
97699199

53 Ubi Avenue 1#01-19 Paya Ubi Industrial Park Singapore 408934
Tel: 6844 4290 Fax: 6841 6043 Email: motoricarzgarage@gmail.com
Register No.: 53188526K

Estimate

Vehicle: SME6336L

Make & Model: MITSUBISHI OUTLANDER

No	Particular	Qty	Amount (\$)
	<u>List Price</u>		
1	REAR BOOT LID <i>bu</i> ✓ <i>*Rear boot opener</i>	1PC	1,048.00 ✓
2	REAR BOOT LID SENSOR <i>Xsuc</i> ✓ <i>suc X #128</i>	1PC	108.00 X
3	REAR BOOT LOGO <i>ne</i> ✓ <i>*Rear boot inner</i>	1PC	390.00 94
4	REAR BOOT EMBLEM 'OUTLANDER' <i>ne</i> ✓ <i>ganish #385 CRA</i>	1PC	86.00 ✓
5	REAR BOOT EMBLEM 'LOGO' <i>ne</i> ✓	1PC	30.00 ✓
6	REAR BOOT EMBLEM 'C&C' <i>ne</i> ✓ <i>*Rear boot Lid sensor</i>	1PC	32.00 ✓
7	REAR BOOT EMBLEM 'MIVEC' <i>ne</i> ✓ <i>#102 CRA</i>	1PC	37.00 ✓
8	REAR BOOT CLONE MOULDING <i>CRA</i> ✓	1PC	466.00 ✓
9	REAR BOOT INNER LOCK <i>bt</i> ✓	1PC	379.00 ✓
10	REAR BOOT LOCK STRIKER <i>bt</i> ✓	1PC	20.00 ✓
11	REAR BOOT WEATHERSTRIP <i>ne</i> ✓	1PC	192.00 ✓
12	REAR BOOT HINGE @\$40.00 <i>Xsuc</i>	2PCS	80.00 X
13	REAR TAIL LAMP @\$563.00 <i>CRA - LH/RH - Xsuc</i>	1PC 2PCS	1,126.00 X
14	REAR BOOT LAMP @\$397.00 <i>CRA - LH/RH - Xsuc</i>	1PC 2PCS	794.00 X
15	REAR BUMPER <i>de</i> ✓ <i>5930.20</i>	1PC	910.20 ✓
16	REAR BUMPER LIP <i>de</i> ✓ <i>10%</i>	1PC	310.00 ✓
17	REAR BUMPER BEAM LH <i>Xsuc</i>	1PC	72.00 X
18	REAR BUMPER LAMP <i>CRA</i> ✓ <i>5337.18</i>	1PC	203.00 ✓
19	REAR BUMPER SIDE RETAINER @\$20.00 <i>ne</i> ✓	2PCS	40.00 ✓
20	REAR END PANEL <i>bt</i> ✓	1PC	310.00 ✓
21	REAR END PANEL GARNISH <i>de</i> ✓	1PC	180.00 ✓
22	REAR FLOOR BOARD <i>Xsuc</i>	1PC	266.00 X
23	REAR FLOOR PANEL <i>repair</i>	1PC	714.00 RY
24	REAR WINDSCREEN LOWER MOULDING <i>ne</i> ✓	1PC	146.00 ✓
	Sub-Total cost for parts		7,939.20
	<u>Part Replacement - Special</u>		
	<u>Nett Item</u>		
1	REAR END PANEL GARNISH CLIP <i>ne</i> ✓	1SET	22.50
2	REAR TAIL LAMP CLIP @\$12.50 <i>ne - LH/RH - XAN</i>	1PC 2PCS	25.00 X
3	REAR TAIL LAMP CLIP HOLDER @\$11.50 <i>ne - LH/RH - XAN</i>	1PC 2PCS	23.00
4	REAR WINDSCREEN GLASS SEALANT <i>ne</i> ✓	1PC	60 80.00

5	REAR REVERSE SENSOR <i>at</i>	1PC	280.00 ²²⁰
6	REAR BUMPER LOWER SPOILER <i>he</i>	1PC	760.00 ⁴⁰⁰
Sub-Total cost for Part Replacement - Special Nett Item			1,190.50
Labour & MISC Charges			
1	TO CHECK UP ELECTRICAL WIRING E-CARE AUTO SERVICES PTE LTD TEST FOR ANY LEAKAGE		120.00 60
2	TO REMOVE AND REFIX REVERSE SENSOR		100.00 60
3	TO REMOVE AND REFIX REAR INTERIOR TRIM TO ASSIT REPAIR		150.00 60
4	TO REMOVE AND REFIX REAR SEAT AND CARPET		150.00 XAN
5	TO REMOVE AND REFIX REAR WINDSCREEN GLASS		150.00 120
6	TO RESPRAY PAINT AND etc		180.00 }
7	TO RESPRAY UNDERCOATING		1400.00 } 900
8	PANEL BEAT, REMOVE AND REPLACE FOR THE ABOVE PARTS		1,800.00 800
Sub-Total Labour			4,050.00
Grand Total			13,179.70 ²⁰⁰⁰

LETTER to Consultants hence notify
claimer of the following:

- Survey before/after **spray painting**
- **damaged part(s) during repair**
- Parts prices are subject to **confirmation**
- Third party survey is on a "Without Prejudice"
- No illegal modification(s) is allowed
- Supplementary item(s) must be resubmitted
- is subject to final approval from Insurer

Acknowledged by Repairer
 Signature: _____
 Date: _____

Rasul
 Hp 90010068
 8 days
 4/5
 22/05/19 @ 1210
 Resey after repair

5337.18
 726.50
 2000.00
 8063.68
 20%
 6450.98
 4/5- 6,450

13,794.70

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19008969/R1QD3N2

Date: 21/06/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTPCVE000753
Claimant Vehicle No :	SME6336L	Insured Vehicle No :	GBB655B
Date of Loss:	15/05/2019	Nature of Claim:	TP
		Claim No:	CMTD1902363

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME6336L	Engine No:	4J11YQ0393
Make & Model:	MITSUBISHI OUTLANDER, 2.0 (A)	Chassis No:	GF7W0402114
Reg. Date:	21/08/2018 (Man. Year: 2018)	Odometer:	16874 km
Colour:	Black		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R18	Rear Tyre Size:	225/50 R18
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	9,744.70	6,063.68	3,681.02	37.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,050.00	2,000.00	2,050.00	50.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,794.70	8,063.68	5,731.02	41.55
Approved Total (Overridden) (\$\$)		6,450.00		
Nett Amount (\$\$)	13,794.70	6,450.00	7,344.70	53.24

INSPECTION

Date of Assignment:	22/05/2019	
Date Inspected:	22/05/2019 Inspected At:	Motorcarz Garage (HQ) 53 UBI AVENUE 1, #01-19 PAYA UBI INDUSTRIAL PARK Singapore 408934
Estimated Period of Repair:	8.0 days	

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Jun 2019)
Parts:	M1-SUV	MITSUBISHI OUTLANDER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SME6336L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Buckled	1,048.00 F	*1,048.00 FL
2	1		*REAR BOOT LID SENSOR	Serviceable	108.00 F	*- FL
3	1		*REAR BOOT LOGO	Necessary	390.00 F	*94.00 FL
4	1		*REAR BOOT EMBLEM OUTLANDER	Necessary	86.00 F	*86.00 FL
5	1		*REAR BOOT EMBLEM LOGO	Necessary	30.00 F	*30.00 FL
6	1		*REAR BOOT EMBLEM C&C	Necessary	32.00 F	*32.00 FL
7	1		*REAR BOOT EMBLEM MIVEC	Necessary	37.00 F	*37.00 FL
8	1		*REAR BOOT CLONE MOULDING	Cracked	466.00 F	*466.00 FL
9	1		*REAR BOOT INNER LOCK	Bent	379.00 F	*379.00 FL
10	1		*REAR BOOT LOCK STRIKER	Bent	20.00 F	*20.00 FL
11	1		*REAR BOOT WEATHERSTRIP	Necessary	192.00 F	*192.00 FL
12	2		*REAR BOOT HINGE	Serviceable	80.00 F	*- FL
13	1		*REAR TAILLAMP	N/s Cracked / O/s Serviceable	1,126.00 F	*563.00 FL
14	1		*REAR BOOT LAMP	N/s Cracked / O/s Serviceable	794.00 F	*397.00 FL
15	1		*REAR BUMPER	Deformed	910.20 F	*910.20 FL
16	1		*REAR BUMPER LIP	Deformed	310.00 F	*310.00 FL
17	1		*REAR BUMPER BEAM LH	Serviceable	72.00 F	*- FL
18	1		*REAR BUMPER LAMP	Cracked	203.00 F	*203.00 FL
19	2		*REAR BUMPER SIDE RETAINER	Necessary	40.00 F	*40.00 FL
20	1		*REAR END PANEL	Bent	310.00 F	*310.00 FL
21	1		*REAR END PANEL GARNISH	Deformed	180.00 F	*180.00 FL
22	1		*REAR FLOOR BOARD	Serviceable	266.00 F	*- FL
23	1		*REAR FLOOR PANEL	Repair	714.00 F	*- FL
24	1		*REAR WINDSCREEN LOWER MOULDING	Necessary	146.00 F	*146.00 FL
25	1		*REAR BOOT OPENER	Serviceable	128.00 F	*- FL
26	1		*REAR BOOT INNER GARNISH	Cracked	385.00 F	*385.00 FL
27	1		*REAR BOOT LID SENSOR	Cracked	102.00 F	*102.00 FL
28	1		*SET REAR END PANEL GARNISH CLIP	Necessary	22.50 FS	*22.50 FS
29	1		*REAR TAIL LAMP CLIP	Ns Necessary/Os Not Necessary	25.00 FS	*12.50 FS
30	1		*REAR TAIL LAMP CLIP HOLDER	Ns Necessary/Os Not Necessary	23.00 FS	*11.50 FS
31	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*60.00 FS
32	1		*REAR REVERSE SENSOR	Cut	280.00 FS	*220.00 FS
33	1		*REAR BUMPER LOWER SPOILER	Deformed	760.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **9,744.70** **6,656.70**
 - List Item Discount on L Items 0.00/10.00% (\$\$) **0.00** **593.02**

Total Parts (\$\$) 9,744.70 6,063.68

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIX REVERSE SENSOR.	New	100.00	60.00
2	TO REMOVE AND REFIX REAR INTERIOR TRIM TO ASSIST REPAIR.	New	150.00	60.00
3	TO REMOVE AND REFIX REAR SEAT AND CARPET.	New	150.00	0.00
4	TO REMOVE AND REFIX REAR WINDSCREEN GLASS.	New	150.00	120.00
5	PANEL BEAT, REMOVE AND REPLACE FOR THE ABOVE PARTS.	New	1,800.00	800.00
6	TO CHECK UP ELECTRICAL WIRING E-CARE AUTO SERVICE PTE LTD TEST FOR ANY LEAKAGE.	New	120.00	60.00
7	TO RESPRAY PAINT AND ETC.)	New	180.00	900.00
8	TO RESPRAY UNDERCOATING.)	New	1,400.00	0.00
Gross Labour Cost (S\$)			4,050.00	2,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >