

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

GRACE AUTO LEASING
8 KAKI BUKIT AVENUE 4
05-25 PREMIER @ KAKI BIKIT
Singapore 415875

TP111
ceilia.

21st MAY 2019

Accident date: 16th MAY 2019

Estimated repair cost for vehicle no: SJJ8432M MIT LANCER 1.6 A '08

S/n	Qty	Items	U/price	Amount
				\$650.00 X
1	1	Front bonnet		\$98.00 X
2	2	Front bonnet hinges	\$49.00	\$69.00 X
3	1	Front bonnet inner rubber		\$67.00 X
4	1	Front bonnet outer rubber		\$98.00 X
5	1	Front bonnet lock	\$3.50	\$70.00 X
6	20	Front bonnet rubber clips	\$528.00	\$1,056.00 X
7	2	Front headlamp		\$561.40 X
8	1	Front wiper garnish		\$131.75 X
9	1	Front wiper garnish rubber		\$98.00 X
10	1	front wiper		\$77.40 X
11	6	Front wiper garnish clips	\$12.90	\$625.00 X
12	1	Front support panel		\$750.00 X
13	1	front cross member		\$650.00 X
	1	front chassis -RH		\$708.00 X
14	1	Front bumper		\$82.00 X
15	2	Front Bumper Side Bracket	\$41.00	\$42.00 X
16	12	Front Bumper Side Bracket devit	\$3.50	\$50.00 X
17	1	Front bumper number plate		\$32.00 X
18	1	Front bumper number plate garnish		\$145.00 X
19	1	Front bumper lower garnish	\$58.00	\$116.00 X
20	2	Front bumper fog lamp cover	\$8.00	\$48.00 X
21	6	Front bumper clips	\$12.90	\$25.80 X
22	2	Front bumper side clips		\$285.00 X
23	1	Front bumper reinforcement		\$135.00 X
24	1	Front grille		

25	1	Front grille emble logo			\$35.00	X
26	2	Front grille side cover		\$135.00	\$270.00	X
27	5	Front grille clips		\$8.00	\$40.00	X
31	1	Front R/H fender	Distorted		\$460.00	✓
32	1	Front fender cowling	torn		\$107.00	✓
33	8	Front fender cowling clips	new	\$5.00	\$40.00	✓
34	1	Front R/H fender signal lamp	cracked		\$29.00	✓
35	1	Front windscreen moulding	new		\$68.00	✓
36	10	Front windscreen side moulding clips	new	\$7.50	\$75.00	30
37	1	Rim-RH Front	lit		\$400.00	✓
38	1	Front tire-RH	new		\$350.00	X
39	1	Front safety belt -RH	new		\$450.00	X
40	1	Front R/H door	Distorted		854.00	\$554.00
41	1	Front R/H door glass	new		\$411.30	X
42	1	Front R/H door inner gear & motor	new		\$432.40	X
43	2	Front R/H door top & lower hinge	Best	\$66.00	\$132.00	✓
44	1	Front R/H door side mirror	cracked		\$341.00	✓
45	1	Front R/H door pillar	Distorted		\$628.00	✓
46	1	Front R/H door lower skirt Sill Panel	Distorted		\$759.00	✓
47	10	Front R/H door lower skirt clips	new	\$5.00	\$50.00	X
48	1	Front R/H door inner lock	new		\$260.00	✓
49	1	Front R/H door inner trim board	Distorted		\$750.00	✓
50	1	Front R/H door lower protector	new		\$125.00	✓
51	1	Front R/H shock absorber	Best		\$387.00	✓
52	1	Front R/H drive shaft	new		\$1,103.00	✓
53	1	Front R/H knuckle arm	Panel		\$301.00	✓
54	1	front R/H knuckle arm bearing	new		\$130.00	✓
55	1	front R/H lower arm	Best		\$282.00	✓
Subtotal :-					\$16,040.05	

7474.40

6726.96

6681.96

labour charges

To Remove & install front crossmember & chassis

~~\$450.00~~ 150.

To remove & re-fix cushion

~~\$150.00~~ 80

To remove & re-fix front windscreen

~~\$120.00~~ ✓

to remove & install front seat & seat belt

~~\$180.00~~ X

Gum

~~\$50.00~~ ✓

To remove & Refix front undercarriage

~~\$280.00~~ 220

To Check Wiring System

~~\$80.00~~ 30

To Remove & refix R/H front & door glass, motor

~~\$250.00~~ 80

To check wheel alignment computer

~~\$150.00~~ 80

Tuff Kote

~~\$120.00~~ 100

Towing charges

~~\$100.00~~ 60

Panel beating

~~\$1,200.00~~ 1000

Spray painting

~~\$1,200.00~~ 1000.

Subtotal :- \$4,330.00

Total:- \$20,370.05

total 9696.96
7721.57

4/5: 77k

10 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Page 456

Signature:

Date: