

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 7022E

DATE 21/5/2019 14:15

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid			\$ 2,174.90
	Boot Lid Lock Upper			\$ 102.60
	Boot Lid Lock Lower			\$ 31.70
	Boot Lid 'H' Emblem			\$ 28.70
	Boot Lid CRDI Plate			\$ 27.90
	Boot Lid Lamp (LH/RH)		\$ 565.60	\$ 1,131.20
	Licence Lamp (LH/RH)		\$ 33.95	\$ 67.90
	Boot Lid Trimboard			\$ 116.40
	Boot Lid Trimboard Clips (10pcs)			\$ 11.00
	Bootlid Moulding			\$ 85.00
	Bootlid i40 Emblem			\$ 27.90
	Bootlid Lower Garnish			\$ 227.90
	Rear Bumper			\$ 553.00
	Rear Bumper Clip 10 pcs			\$ 22.00
	Rear Bumper Bracket		\$ 35.60	\$ 71.20
	Rear Bumper Under Cover			\$ 228.00
	Rear Panel			\$ 526.70
	Rear Panel Garnish			\$ 57.70
	Rear Panel Lower Panel			\$ 89.40
	Rear Fender (LH)			\$ 2,171.40
	Rear Fender Inner Lining (LH)			\$ 169.30
	Rear Windscreen Moulding			\$ 28.30
	Rear Fender (RH)			
	SUB TOTAL			\$ 7,950.10
	LESS 20%			\$ 1,590.02
	DISCOUNTED TOTAL			\$ 6,360.08
	Boot Lid Comfort Logo & Tel No. Sticker			\$ 30.00 Nett
	Rear No. Plate			\$ 25.00 Nett
	Rear Bumper Rubber Mat			\$ 50.00 Nett
	Rear Bumper Advertisement Logo			\$ 50.00 Nett
	Rear Windscreen Sealant			\$ 46.00 Nett
	Labour Charge			\$ 201.00
	Panel Beating			\$ 850.00
	Spray Painting Charge			\$ 1,000.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00
	Remove/Refix Rear Windscreen Glass			\$ 120.00
	Remove/Refix Reverse Sensor			\$ 80.00
	TOTAL LABOUR			\$ 2,300.00
	ESTIMATE TOTAL			\$ 8,861.08

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.