



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

Repair Estimates

SLM 8450 X

(a) Cost / List Price Items

Finalized
\$ 1668.70 5,020.27

Plus/Less 25%

\$ 417.17 1,255.07

Total of Cost / List

\$ 1251.53 3,765.20

(b) Nett Price Items

Less

Total of Nett Item

(c) Special Nett Items

\$ 200.00

Parts Cost

\$ 1251.53 3,965.20

r

\$ 575.00 2,740.00

\$ 1826.53 6,705.20

Not Authorized

Running Beyond

ove total will be subjected to 7% G.S.T.

ie of Surveyor

Kenneth

pany

Ukk

ey conducted on

22/5/19

at

Remarks By Surveyor

The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

Recommended Days of Repair

03

day(s)

Resurvey

Required / Not Required

Excess

\$

Signature of surveyor

De

Date:

22/5/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. :
Make & Model :
Chassis No. :

SLM 8450 X

TOYOTA PRIUS
JTDKB3FUX03555163

Submit By :
Year Manufacture :
Engine No. :
Cost / List

SERENGE
2017

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	Sn 1	\$200.00	S.N	X
2	Rear bumper	Bulim 1	\$497.50		✓
3	Rear bumper clip	Sn 10	\$40.00		✓
4	Rear bumper side retainer LH	Sn 1	\$112.70		X
5	Rear bumper side retainer RH	Sn 1	\$112.70		X
6	Rear bumper reinforcement	Bul 1	\$398.90		2
7	Rear bumper lower garnish centre	Ref/CM 1	\$582.60		2
8	Rear bumper lower garnish LH	mg/CM 1	\$149.70		X
9	Rear bumper lower garnish RH	Sn 1	\$149.70		X
10	Rear bumper tow cover	Sn 1	\$31.70		X
11	Rear bumper under cover	Sn 1	\$355.20		X
12	Rear bumper under cover clip	Sn 4	\$14.00		X
13	Tail door lock	R 1	\$487.70		X
14	Tail door emblem	Sn 1	\$61.70		X
15	Wording "PRIUS"	Sn 1	\$51.90		X
16	Wording "HYBRID"	Sn 1	\$55.47		X
17	Tail door plate garnish	Sn 1	\$782.50		X
18	Tail end panel	R 1	\$596.60		X
19	Tail end panel garnish	Sn 1	\$151.60		X
20	Tail end panel garnish clip	Sn 10	\$35.00		X
21	Boot weatherstrip	Sn 1	\$353.10		X
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / GST No. 20-0005485-N

166770



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Bik 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : SLM 8450 X

Submit By : SERENGE

Make & Model : TOYOTA PRIUS

Year of Manufacture : 2017

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, END PANEL, LHR FENDER SPARE TYRE COMPARTMENT)	\$1,000.00	2501
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, END PANEL, LHR FENDER SPARE TYRE COMPARTMENT)	\$1,000.00	2601
3	To tuff coat. <i>nn</i>	\$150.00	X
4	TO Check wiring	\$50.00	151
5	To transfer boot mechanism to new boot <i>nn</i>	\$120.00	X
6	To conduct water leakage tests to ensure proper air and sealing <i>nn</i>	\$120.00	X
7	To remove & refit reverse sensor	\$150.00	501
8	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load. <i>nn</i>	\$150.00	71

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

575 ✓