



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

Repair Estimates

SLM 8450 X

Finalised

Not Authorized

Murray Bepain

81826-53

(a) Cost / List Price Items	\$ <i>1668.70</i>	5,020.27
Plus/Less 25%	\$ <i>417.17</i>	1,255.07
Total of Cost / List	\$ <i>1251.53</i>	3,765.20
(b) Nett Price Items		
Less		
Total of Nett Item		
(c) Special Nett Items	\$	200.00
Parts Cost	\$ <i>1251.53</i>	3,965.20
r	\$ <i>575.00</i>	2,740.00
	\$ <i>1826.53</i> ✓ <i>ok</i>	6,705.20

ove total will be subjected to 7% G.S.T.

Name of Surveyor : *Kenneth*
Company : *UKK*
Survey conducted on : *22/5/11* at _____

Remarks By Surveyor

The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

Recommended Days of Repair : *03* day(s)

Resurvey : Required / ~~Not Required~~

Excess : \$ _____

Signature of surveyor : *De* Date: *22/5/11*



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

Spare Parts

Vehicle No. : **SLM 8450 X**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FUX03555163**

Submit By : **SERENGE**
Year Manufacture : **2017**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	1	\$200.00	S.N	X
2	Rear bumper	1	\$497.50		✓
3	Rear bumper clip	10	\$40.00		✓
4	Rear bumper side retainer LH	1	\$112.70		X
5	Rear bumper side retainer RH	1	\$112.70		X
6	Rear bumper reinforcement	1	\$398.90		2
7	Rear bumper lower garnish centre	1	\$582.60		✓
8	Rear bumper lower garnish LH	1	\$149.70		2
9	Rear bumper lower garnish RH	1	\$149.70		X
10	Rear bumper tow cover	1	\$31.70		X
11	Rear bumper under cover	1	\$355.20		X
12	Rear bumper under cover clip	4	\$14.00		X
13	Tail door lock	1	\$487.70		X
14	Tail door emblem	1	\$61.70		X
15	Wording "PRIUS"	1	\$51.90		X
16	Wording "HYBRID"	1	\$55.47		X
17	Tail door plate garnish	1	\$782.50		X
18	Tail end panel	1	\$596.60		X
19	Tail end panel garnish	1	\$151.60		X
20	Tail end panel garnish clip	10	\$35.00		X
21	Boot weatherstrip	1	\$353.10		X
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : SLM 8450 X Submit By : SERENCE
Make & Model : TOYOTA PRIUS Year of Manufacture : 2017

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, END PANEL, LHR FENDER SPARE TYRE COMPARTMENT)	\$1,000.00	2501
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, END PANEL, LHR FENDER SPARE TYRE COMPARTMENT)	\$1,000.00	2601
3	To tuff coat. <i>nn</i>	\$150.00	X
4	TO Check wiring	\$50.00	151
5	To transfer boot mechanism to new boot <i>nn</i>	\$120.00	X
6	To conduct water leakage tests to ensure proper air and sealing <i>nn</i>	\$120.00	X
7	To remove & refit reverse sensor	\$150.00	501
8	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load. <i>nn</i>	\$150.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

575