



JOO HAK KEE AUTO PTE LTD
 裕合记汽车私人有限公司
SINCE 1986

ATTN: MOTOR CLAIMS DEPARTMENT
 OWNER: TUNG CHOK SENG
 TP INSURER: AIG Asia Pacific Insurance Pte Ltd
 POLICY NO: 5108600438
 REFERENCE: TP CLAIM
 DOA: 16/05/2019

REPAIR ESTIMATE

Est. No. : E19050006
Date : 22/05/2019
Vehicle Num. : SJK6372K
Make/Model : HONDA, CIVIC
Chassis/Eng# : JHMF46209S200030

No	Description	Qty	U/P	Amt
Section: LIST ITEMS				
1	Rear Bumper	1.00	765.60	765.60 DL ✓
2	Rear End Panel	1.00	306.60	306.60 3DD ✓
3	Rear Exhaust Muffler	1.00	689.50	689.50 ?X R
				Amt S\$ 1,815.70 1071.60
				Discount (20.00%) S\$ 363.14 214.32
				Subtotal S\$ 1,452.56 857.28
Section: LABOUR				
4	Panel Beat	1.00	600.00	600.00 300.00 ?
5	To Remove and Replace Rear Exhaust Muffler	1.00	120.00	120.00 80.00
6	To Spray Paint	1.00	560.00	560.00 ?400.00
				Amt S\$ 1,280.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 1,280.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

? Photo
 Lump sum repair
 Repair days 4
 TGLim Lin
 22/5/19
 1200hrs
 Parts 857.28
 S/N 00.00
 Labour 780.00
 1637.28
 @20% 327.46
 1309.82
 L/S 1300/2 TGLim Lin
 16/8/19



Joo Hak Kee Auto Pte. Ltd.

LIST ITEMS Subtotal S\$ 1,452.56
LABOUR Subtotal S\$ 1,280.00
Total S\$ 2,732.56

BLK 3007 UBI ROAD 1 #01-406, SINGAPORE 408701
 BLK 3014 UBI ROAD 1 #01-324, SINGAPORE 408702

TEL: 6743 1913 FAX: 6743 5234
 EMAIL: admin@jhk.com.sg

CO/GST REG NO: 201300082W
 WEBSITE: www.jhk.com.sg

bizSAFE