



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: AXA INSURANCE PTE LTD	Document No.	: SQT19002568	Page	1
	8 SHENTON WAY	Date	: 11. Jun 2019		
	#27-01 AXA TOWER	Customer No.	: WZA006		
	SINGAPORE 068811	Svc Advisor	: NG SIN HAI		
Registration No	: SLS493T	Engine No	: K24W72041119		
Chassis No	: JHMRC1880HC203475	Date Time	: 11. Jun 2019 12:42:00 PM		
Model	: ODYSSEY 2.4 EX-S 17YM (EURO 6)	Surveyor Name	:		
Owner's Name	: OH SWEE YANG	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 11/5/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
BO-NUM-COMP-S	NUMBER PLATE WITH CASING-S(N) ✓ CMT	1	45.00		45.00	3.15	48.15
33100-T6A-Q01	HEADLIGHT ASSYR. X	1	904.00	25	678.00	47.46	725.46
33150-T6A-Q01	HEADLIGHT ASSY,L. ?	1	904.00	25	678.00	47.46	725.46
60100-T6A-000ZZ	HOOD COMP X	1	671.40	25	503.55	35.25	538.80
74120-T6A-003	LOCK ASSYHOOD X	1	106.20	25	79.65	5.58	85.23
74141-T6A-010	INSULATORHOOD X	1	94.40	25	70.80	4.96	75.76
74142-T6A-003	SEAL RUBBERINTAKE +	1	43.90	25	32.92	2.30	35.22
74145-T6A-000	STAY,HOOD OPEN +	1	19.10	25	14.32	1.00	15.32
74147-T6A-003	SEAL RUBBER,HOOD +	1	13.20	25	9.90	0.69	10.59
74148-T6A-003	SEAL RUBBER L.HOOD +	1	13.20	25	9.90	0.69	10.59
80050-SP0-000	LABELAIR CONDITIONER CAUTION +	1	1.80	25	1.35	0.09	1.44
19043-PLA-E00	LABELCOOLANT INFORMATION +	1	5.00	25	3.75	0.26	4.01
77875-SDA-G80	LABEL SRS CAUTION	1	0.80	25	0.60	0.04	0.64
71121-T6A-003	BASEFR.GRILLE ? +	1	169.00	25	126.75	8.87	135.62
71122-T6A-003	MOLDINGFR.GRILLE ?	1	263.30	25	197.47	13.82	211.29
75700-TA0-A00	EMBLEMFR. ?	1	26.70	25	20.02	1.40	21.42
90301-ST0-003	NUTPUSH 3MM ?	2	2.10	25	3.15	0.22	3.37
91505-TM8-003	CLIP,BUMPER / 10pc	6	2.30	25	10.35	0.72	11.07
04711-T6A-000ZZ	FACE,FR.BUMPER / DR	1	691.10	25	518.32	36.28	554.60

Printed on 11/6/2019 1:08:50 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SLS493T

Chassis No : JHMRC1880HC203475

Model : ODYSSEY 2.4 EX-S 17YM (EURO 6)

Owner's Name : OH SWEE YANG

Ins Policy No. :

Date of Accident : 11/5/2019

Document No. : SQT19002568 Page 2

Date : 11. Jun 2019

Customer No. : WZA006

Svc Advisor : NG SIN HAI

Engine No : K24W72041119

Date | Time : 11. Jun 2019 12:42:00 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
71104-T6A-003	GARNISHR.FR.BUMPER X	1	41.70	25	31.27	2.19	33.46
71105-T6A-003	GRILLEFR.BUMPER LOWER ?	1	76.80	25	57.60	4.03	61.63
71108-T6A-P00	LOWER PLATEFR.BUMPER ?	1	147.10	25	110.32	7.72	118.04
71109-T6A-003	GARNISHL.FR.BUMPER / CAT	1	41.70	25	31.27	2.19	33.46
71130-T6A-310ZZ	BEAM COMP.FR.BUMPER ?	1	291.80	25	218.85	15.32	234.17
71140-T6A-003	BEAMR.FR.BUMPER UPPER ?	1	34.90	25	26.17	1.83	28.00
71151-T6A-003	BASEMID GRILLE ?	1	219.40	25	164.55	11.52	176.07
71152-T6A-003	UPPER MOLDINGMID GRILLE ?	1	87.70	25	65.77	4.60	70.37
71153-T6A-003	LOWER MOLDINGMID GRILLE ?	1	87.70	25	65.77	4.60	70.37
71190-T6A-003	BEAML.FR.BUMPER UPPER ?	1	34.90	25	26.17	1.83	28.00
71193-T6A-003	SPACERR.FR.BUMPER SIDE / DR	1	11.80	25	8.85	0.62	9.47
71198-T6A-003	SPACERL.FR.BUMPER SIDE / AR	1	11.80	25	8.85	0.62	9.47
91505-TM8-003	CLIP,BUMPER / MC	16	2.30	25	27.60	1.93	29.53
60210-T6A-300ZZ	FENDER COMPR.FR. X	1	548.60	25	411.45	28.80	440.25
60260-T6A-300ZZ	FENDER COMPL.FR. X	1	548.60	25	411.45	28.80	440.25
74100-T6A-000	FENDER ASSYR.FR.INNER X	1	120.70	25	90.52	6.34	96.86
74105-T6A-000	ENCLOSURER.FR.FENDER X	1	26.30	25	19.72	1.38	21.10
74150-T6A-000	FENDER ASSYL.FR.INNER X	1	120.70	25	90.52	6.34	96.86
74155-T6A-000	ENCLOSUREL.FR.FENDER X	1	26.30	25	19.72	1.38	21.10
74201-T6A-000	GARNISHR.FR.FENDER X	1	33.10	25	24.82	1.74	26.56
74206-T6A-000	GARNISHL.FR.FENDER X	1	33.10	25	24.82	1.74	26.56
90682-SEA-003	CLIP ABUMPER X	4	2.60	25	7.80	0.55	8.35
91505-TM8-003	CLIP,BUMPER X	14	2.30	25	24.15	1.69	25.84
60400-T6A-310ZZ	BULKHEAD COMPFR. X	1	460.80	25	345.60	24.19	369.79
Sum Item					5317.41	372.19	5,689.60
BOSUN	SUNDRIES	1	100.00 30		100.00	7.00	107.00
BKBH01M	REMOVE & RENEW BULKHEAD. STRAIGHTEN	1	3000.00 560		3000.00	210.00	3210.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	180.00 /		180.00	12.60	192.60

Printed on 11/6/2019 1:08:50 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: AXA INSURANCE PTE LTD	Document No.	: SQT19002568	Page	3
	8 SHENTON WAY	Date	: 11. Jun 2019		
	#27-01 AXA TOWER	Customer No.	: WZA006		
	SINGAPORE 068811	Svc Advisor	: NG SIN HAI		
Registration No	: SLS493T	Engine No	: K24W72041119		
Chassis No	: JHMRC1880HC203475	Date Time	: 11. Jun 2019 12:42:00 PM		
Model	: ODYSSEY 2.4 EX-S 17YM (EURO 6)	Surveyor Name	:		
Owner's Name	: OH SWEE YANG	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 11/5/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2000.00	450	2000.00	140.00	2140.00
Sum Labor					5280.00	369.60	5649.60

Survey By	Steve (LKK) 9853228811						
Date & Time	12/6/19, 12.10pm						
Excess							
Status							
Signature							

Total Amount	10,597.41	741.79	11,339.20
Total (Inclusive of GST)			<u>11,339.20</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 11/6/2019 1:08:50 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.