

INS. CASE OWNER:

CC 0 / 14 1900 8987 / P90

IDAC:

Signature:

KSC

Date:

ASSIGNMENT

21/5/19

Date / Time

21/5/19

Registered in Merimen:

22/5/19

Personnel / CCU / FTE



Insured Vehicle No. : SHB 424SD

Claim No. : _____

Name of Insured : C1M

Policy No. : _____

Insured Tel No. : _____ HP: _____

Make / Model : _____

Excess Sec II : SS

D.O.A : 16/5/2019

Place of Accident : _____

Is driver the owner? (YES / NO)

Nature of Accident : _____

If NO, Driver Name / Age :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. :

(V/L: YES / NO)

Insured Liability : % Final ? Yes / No

SLT 3640K

INSRS:
WSP: Hui Yang
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time

SLT 3640K - NA / CTS 19003672/13 - DOP 26/03/2019
 - C3/SF 19005072/KJ 242 - DOP 16/07/2019
 SHB 424SD - C3/NSG 13024545/410342 - DOP 24/12/2013
 - C4/TIF 16015796/K #6352 - DOP 22/03/2016

STAGE	DATE / PIC		
Non-Reporting ltr (1st):			
Non-Reporting ltr (2nd):			
Non-Reporting ltr (Final):			
Notification ltr (if non-pickup):			
Call OI:			
After call ltr to OI:			
Documentation Check List:	Handler	Typist	
Notification ltr (if non-pickup)	☒	☐	☐
After call ltr to OI:	☒	☐	☐
Authorisation To Act:	☒	☐	☐
Release Voucher:	☒	☐	☐
Final Repair Bill:	☒	☐	☐
Car Rental Invoice:	☒	☐	☐
Towing Invoice:	☒	☐	☐
LTA / GIA :	☒	☐	☐
Medical Bill:	☒	☐	☐
PIR:	☒	☐	☐
Mandate/Reject Instruction:	☒	☐	☐
LOD	☒	☐	☐
Payment Breakdown Form:	☒	☐	☐
Post-Repair Photos:	☒	☐	☐
Others:	☒	☐	☐

8/6/19 seek liability via merimen

10/6/19 liability clear via merimen

14/6 - Rel we sent TP - pending lod m.

3/7/19 - LOD m (File pass ET + TP mandate).

24/7/19 - seek mandate (pending approval)

19/8/19 - offer GRS \$5260.00 (pending acceptance)

- TP reject offer. Re-offer \$5300 GRS.

(pending acceptance)

20/8/19 - settle @ GRS \$5300. DV send (pending DV).

20/8/19 - DV m (File pass Admin to close).

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: Kenneth

Repair Cost: US \$5450.00 (7 days) Reduction: 0.06 %

FINAL SETTLEMENT Date/Time: 19/8/19 5:41 PM

Email ☐ Call ☐

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : 59

Email ☒ Call ☐

Repair Cost: (W/CST) \$5482.50

If NO or B 28, Ass. Lia :

Loss of Rental (LOR): \$5 - (days)

Loss of Use (LOU): \$540.00 (\$55 x 8 days)

Loss of Income (LOI): \$5 - (\$ x days)

LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search \$5 -

Medical: \$5 -

Disbursement: \$5 -

Legal Cost \$5 -

(e.g. Tow/Independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: \$500/-

Total: \$5308.50

Global Sum \$5: 5300.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☒ Call ☐

Payee 1: \$5300.00

Name 1: Hui Yang motor Pte Ltd

Payee 2: (if N/A)

Name 2:

Payee 3: (if N/A)

Name 3:

辉陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Bldg 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) - Fax: 64514658
Reg No. 201629438M

16/05/2019

Owner: ANC MOTORING PTE LTD

ESTIMATE TO REPAIR TOYOTA PRIUS ALPHA 1.8S A - SLT3640K

1pc rear RH door
2pcs rear RH door hinge @\$141.45
1pc rear RH door frame sticker
1pc rear RH door handle base
1pc rear RH door glass moulding
1pc rear RH door glass motor & gear
1pc rear RH door glass pillar
1pc rear RH door inner lock
1pc rear RH door inner rubber
1pc rear RH door inner panel
1pc rear RH door inner step garnish
1pc rear RH door outer step garnish
1pc rear RH door pillar
1pc RH side skirt
1pc RH side rocket panel
1pc rear RH fender
1pc rear RH fender air-duct
1pc rear RH fender inner shield
8pcs rear RH fender inner shield clip @\$5.00
1pc rear RH fender inner garnish
1pc rear RH wheel house

less 25%

remove & refit rear cushions
remove & refit rear RH fender glass & rear RH door glass
sealant
tuffkote
wiring
spray painting
labour charges
Total

R S 1,217.45 ✓
R S 282.90 X
R S 158.50 ✓
R S 281.50 X
R S 181.25 ✓
R S 374.45 ✓
R S 181.25 X
R S 581.90 X
R S 172.45 ✓
R S 621.25 X
R S 381.50 X
R S 191.80 ✓
R S 852.50 X
R S 681.90 ✓
R S 852.50 ✓
R S 971.50 ✓
R S 178.85 X
R S 182.25 X
R S 40.00 X
R S 691.45 X
R S 561.60 X

\$ 9,638.75
\$ 2,409.69
\$ 7,229.06

\$ 180.00 100
\$ 180.00 60
\$ 80.00 40
\$ 120.00 60
\$ 120.00 20
\$ 1,600.00 800
\$ 1,600.00 1000
\$ 11,109.06



Indica
21/05/19
Kerneth

Not Authorised
6/15/19 8 4550h JOK
Refining After Paint
7days

辉 阳 汽 车 有 限 公 司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

16/05/2019

Owner: ANC MOTORING PTE LTD

ESTIMATE TO REPAIR TOYOTA PRIUS ALPHA 1.8S A - SLT3640K


1pc	rear RH door	Ry \$ 1,217.45 ✓
2pcs	rear RH door hinge @\$141.45	R \$ 282.90 X
1pc	rear RH door frame sticker	Ru \$ 158.50 ✓
1pc	rear RH door handle base	Lu \$ 281.50 X
1pc	rear RH door glass moulding	BuS \$ 181.25 ✓
1pc	rear RH door glass motor & gear	Ry \$ 374.45 ✓
1pc	rear RH door glass pillar	\$ 181.25 ?
1pc	rear RH door inner lock	R \$ 581.90 X
1pc	rear RH door inner rubber	M/Lu \$ 172.45 ✓
1pc	rear RH door inner panel	\$ 621.25 ?
1pc	rear RH door inner step garnish	Ru \$ 381.50 ✓ ?
1pc	rear RH door outer step garnish	Ru \$ 191.80 ✓
1pc	rear RH door pillar	R \$ 852.50 X
1pc	RH side skirt	BuS \$ 681.90 ✓
1pc	RH side rocket panel	Ry \$ 852.50 ✓
1pc	rear RH fender	Ry \$ 971.50 ✓
1pc	rear RH fender air-duct	Lu \$ 178.85 X
1pc	rear RH fender inner shield	Su \$ 182.25 X
8pcs	rear RH fender inner shield clip @\$5.00	Ru \$ 40.00 X
1pc	rear RH fender inner garnish	Lu \$ 691.45 ✓
1pc	rear RH wheel house	R \$ 561.60 X

less 25%

\$ 9,638.75
\$ 2,409.69
\$ 7,229.06

remove & refit rear cushions
remove & refit rear RH fender glass & rear RH door glass
sealant
tuffkote
wiring
spray painting
labour charges
Total

\$ 180.00 100l
\$ 180.00 80l
\$ 80.00 40in
\$ 120.00 60l
\$ 120.00 20l
\$ 1,600.00 800l
\$ 1,600.00 1000l
\$ 11,109.06



Ind 19
21/05/19
Remeth

Not Authorized
6/5/19
Refining After Paint
7 days

View Received Message

This mail is associated with :

***SLT3640K (MCT19050454)
[SHB4245D]**

TP

ANC MOTORING PTE LTD

May 16 2019 12:00AM

Hui Yang Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From India International Insurance Pte Ltd (HQ) (III_SG), sent on **12/06/2019 14:25 PM**.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$0.00) - SLT3640K - Claim Handler: Priya

Approved:0.00.

DOCUMENTS SUMMARY

There are no documents.

Print Received Message

This mail is associated with :

***SLT3640K (MCT19050454)**
[SHB4245D]

TP

ANC MOTORING PTE LTD

May 16 2019 12:00AM

[-]

Hui Yang Motor Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 25/07/2019 11:43 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$5348.50) - SLT3640K - Claim Handler: Priya

Approved:5348.50:Please request TP WS to raise Tax Invoice for Cost of repairs in III's name

ANC MOTORING PTE LTD

25 MANDAI ESTATE #02-10 INNOVATION PLACE S(729930)

RENTAL AGREEMENT

Kindly fill up all of the details below

GAR MODEL/CARPLATE:

Toyota Prius Alpha SLT3640K

HIRER'S NAME:

Jeffrey Bin Amat

NRIC/PASSPORT NO.:

S7142022A

4/11/1971 DOB

DRIVING LICENSE NO.:

S7142022A

ADDRESS:

665 Hougang Ave 4 #07-345 S530665

CONTACT NO.:

92296979

RENTAL DEPOSIT:

\$470

DATE OF COMMENCE:

31/5/2018 - (End 31/05/2020)

EMAIL:

a-jep@live.com

RENTAL PER DAY.:

\$80/-

BANK/ ACCOUNT NO.:

*All Payments will be transferred to you every Thursday. You may expect to receive it on the same day itself (for UOB account holders) or 3 working days later (for non-UOB account holders). Uber will only transfer us your earnings every Thursday at 2pm. Hence, we will only be able to process your payout after we receive their payment. Thank you.

CONTRACT VAILITY:

24 mths

VEHICLE MILEAGE:

Left Side



Right Side



Back



Front



Top



REMARKS:



Signature

D=DENT S=SCRATCHES C=CHIPS R=RUST M=MISSING

輝陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

Date: 01/07/2019

India International Insurance Pte Ltd

Motor Claims Department

64 Cecil Street

#04-00 IOB Building

Singapore 049711

**RE: ACCIDENT INVOLVING SLT3640K & SHB4245D ON 16/05/2019
ALONG BERWICK DRIVE TOWARDS TAVISTOCK AVENUE**

SETTLEMENT OF OUR CLAIM FOR SLT3640K

Lump Sum repair cost as recommended by surveyor (TP0634)	\$ 4,868.50
08 Days Loss of Use @ \$80.00 per day (07 Repair Days + 1 Sunday)	\$ 640.00
Total	<u>\$ 5,508.50</u>

**The above claim applies only to vehicle damage and expressly exclude all personal injuries and other consequential loss.*

Please let us have your reply soonest possible, thank you.

Best Regards,

Marco Neo

HUI YANG MOTOR PTE LTD

DID: 64515752

Fax: 64514658

email: hui_yang_motor@hotmail.com

AUTHORIZATION LETTER

TO WHOM IT MAY CONCERN

I/We, ANC Motoring Pte Ltd hereby declare and agree to use the address of **Hui Yang Motor Pte Ltd**, that is at Blk 176 Sin Ming Drive, #04-02 Sin Ming Autocare Singapore 575721 in all my correspondences with any party in connection with my claim.

Arising from an accident involving my motor vehicle registration number SLT3640K and other vehicles registration number SHB4245D along Berwick Dr Towards Tavistock Ave on 16/05/2019.

I/We, further grant authority to Messrs **Hui Yang Motor Pte Ltd** or any of their representatives to open all my/our letters and to negotiate my/our claim on my/our behalf.

I/We wish to inform you that you could issue the cheque payment in favour of my/our repairer Messrs **Hui Yang Motor Pte Ltd**.



.....
Signature of registered owner and Company's stamp

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MCT19050454
Claimant Ref: SLT 3640K

We/I, HUI YANG MOTOR PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 5,300.00 (global sum) ~~(repair cost) S\$~~ ~~(loss of vehicle) S\$~~ ~~(loss of profit) S\$~~ vehicle no. SLT 3640K that was damaged pursuant to the accident which occurred on 16/05/2019 (date) at SERANGOON GARDEN WAY X BERWICK DRIVE (location) involving vehicle no. 5HB 4245D (insured vehicle). This is pursuant to the inspection conducted on 21/05/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner ANC MOTORING PTE LTD ("the third party claimant") of vehicle no. SLT 3640K to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SLT 3640K (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 5,300.00 to HUI YANG MOTOR PTE LTD

Dated this 27 day of 8 2019

CLAIMANT:

Signature:

Signed by "the workshop" (with chop)

Name:

Hui Yang Motor Pte Ltd

NRIC:

2016294381M

Address:

176 Sin Ming Drive
#04-02, S(575721)

Nationality:

Occupation:

WITNESS:

Signature:

Signed by appointed Surveyor

Name:

LKK AUTO CONSULTANTS PTE LTD

NRIC:

199607198R

Address:

51 UBI AVE 1, PAYA UBI INDUSTRIAL PARK
#02-25 SINGAPORE 408933

Nationality:

Occupation:

HUI YANG MOTOR PTE LTD

TAX INVOICE

Bill To:

India International Insurance Pte Ltd
Motor Claims Department
64 Cecil Street
#04-00 IOB Building
Singapore 049711

TP Claim Invoice No: TP0634
Bill Date: 01/07/2019

Description		Amount
Date of Accident : 16/05/2019 Owner : ANC MOTORING PTE LTD Vehicle No : <u>SLT3640K</u> Make & Model : <u>TOYOTA PRIUS ALPHA</u> <u>Lump Sum repair cost as recommended by surveyor</u>		\$ 4,550.00
Sub-Total :		\$ 4,550.00
Add 7% GST :		\$ 318.50
Total Amount SGD :		\$ 4,868.50

Reg No.:201629438M
GST No.:201629438M

HUI YANG MOTOR PTE LTD



Authorised Signature

Hui Yang Motor Pte Ltd

Sin Ming Autocare Blk 176 Sin Ming Drive
#04-02 Singapore 575721

Email: hui_yang_motor@hotmail.com

H/P: 98625891 Office: 64515752 Fax : 64514658

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 May 2019 Edit Reg		21 May 2019 00:00 Edit Adj Rpt	\$4,550.00 Edit Estimates	\$4,550.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: COMFORT TRANSPORTATION PTE LTD , ID: 199303821R									
Main Claimant: ANC MOTORING PTE LTD , Co. Reg. No.: 201527433C									
Vehicle Reg. No.:	SLT3640K	Date of Loss:	16/05/2019 00:00 - :59 [18 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19050454	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHB4245D	Policy No. (Claimant):	999994417						
		Excess:							
Repairer: Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare, 575721 Sin Ming - Tel: 64515752									
Handling Insurer: India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]									
Claimant's Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 31/05/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (25/07/2019): Alert - Adj Mandate Approved (\$5348.50) - SLT3640K - Claim Handler: Priya - III_SG (12/06/2019): Alert - Adj Mandate Approved (\$90.00) - SLT3640K - Claim Handler: Priya									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLT3640K (MCT19050454)
[SHB4245D]
TP
ANC MOTORING PTE LTD
May 16 2019 12:00AM
[COMFORT TRANSPORTATION PTE LTD]
Hui Yang Motor Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Video							1 per page		☒	
No	Finalized On	India International Insurance Pte Ltd (HQ)					Thumbnail		Print	
1	12/06/19 14:26	Video - Accident					Load MP4			
Photos/Images							3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail		Print	
1	30/05/19 14:02	General View					Load JPG		☒	
2	30/05/19 14:02	General View					Load JPG		☒	
3	30/05/19 14:02	General View					Load JPG		☒	
4	30/05/19 14:02	General View					Load JPG		☒	
5	30/05/19 14:02	General View					Load JPG		☒	
6	30/05/19 14:02	General View					Load JPG		☒	
7	30/05/19 14:02	General View					Load JPG		☒	
8	30/05/19 14:02	General View					Load JPG		☒	
9	30/05/19 14:02	General View					Load JPG		☒	
10	30/05/19 14:02	General View					Load JPG		☒	
11	30/05/19 14:02	General View					Load JPG		☒	
12	30/05/19 14:02	General View					Load JPG		☒	
13	30/05/19 14:02	General View					Load JPG		☒	
14	30/05/19 14:02	Odometer Reading					Load JPG		☒	
15	30/05/19 14:02	General View					Load JPG		☒	
16	30/05/19 14:02	Chassis Number					Load JPG		☒	
17	30/05/19 14:02	General View					Load JPG		☒	
Documentation							1 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail		Print	
1	22/05/19 15:24	TP ESTIMATE					Load PDF			
2	22/05/19 16:50	TP GIA REPORT					Load PDF			
3	22/07/19 09:55	WORKSHOP INVOICE					Load PDF			
4	22/07/19 09:55	LOD					Load PDF			
5	30/08/19 12:26	DISCHARGE VOUCHER					Load PDF			
6	30/08/19 12:26	AUTHORISATION TO ACT FORM					Load PDF			
No	Finalized On	India International Insurance Pte Ltd (HQ)					Thumbnail		Print	
1	23/05/19 08:50	Singapore Accident Statement					Load PDF			

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

	↕
--	---

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III19008987/KGA3Q2

Date: 30/08/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

MCOM0015

Claimant Vehicle No: SLT3640K

Insured Vehicle No: SHB4245D

Date of Loss: 16/05/2019

Nature of Claim: TP

Claim No: MCT19050454

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLT3640K

Make & Model: TOYOTA PRIUS ALPHA HYBRID, 1.8 S CVT (A)

Engine No: 2ZR1993917

Reg. Date: 26/10/2017 (Man. Year: 2017)

Chassis No: ZVW400026264

Colour: Metallic Grey

Odometer: 129553 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size:

205/60 R16

Front Left Side: Goodride 8 mm

Rear Left Side:

Goodride 8 mm

Front Right Side: Goodride 8 mm

Rear Right Side:

Goodride 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,309.06	3,641.35	3,667.71	50.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,800.00	2,040.00	1,760.00	46.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,109.06	5,681.35	5,427.71	48.86
Approved Total (Overridden) (S\$)		4,550.00		
(S\$)	11,109.06	4,550.00	6,559.06	59.04
+ GST 7.00/7.00% (S\$)	777.63	318.50	459.13	59.04
Nett Amount (S\$)	11,886.69	4,868.50	7,018.19	59.04
+ Loss of Use (8.0 x S\$55.00/day) (S\$)		440.00		
Nett Liability (S\$)		5,308.50		
Global Sum Settlement (S\$)		5,300.00		

INSPECTION

Date of Assignment: 21/05/2019

Date Inspected: 21/05/2019 Inspected At:

Hui Yang Motor Pte Ltd (HQ)

176 Sin Ming Drive #04-02, Sin Ming

AutoCare
Singapore 575721

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Jul 2019)
Parts:	144	TOYOTA PRIUS ALPHA HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT3640K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH DOOR	Bent	1,217.45 FL	*1,217.45 FL
2	2		*REAR RH DOOR HINGE	Repair	282.90 FL	*- FL
3	1		*REAR RH DOOR FRAME STICKER	Necessary	158.50 FL	*158.50 FL
4	1		*REAR RH DOOR HANDLE BASE	Serviceable	281.50 FL	*- FL
5	1		*REAR RH DOOR GLASS MOULDING	Buckled	181.25 FL	*181.25 FL
6	1		*REAR RH DOOR GLASS MOTOR & GEAR	Bent	374.45 FL	*374.45 FL
7	1		*REAR RH DOOR GLASS PILLER	Serviceable	181.25 FL	*- FL
8	1		*REAR RH DOOR INNER LOCK	Repair	581.90 FL	*- FL
9	1		*REAR RH DOOR INNER RUBBER	Dented / Cut	172.45 FL	*172.45 FL
10	1		*REAR RH DOOR INNER PANEL	Repair	621.25 FL	*- FL
11	1		*REAR RH DOOR INNER STEP GARNISH	Serviceable	381.50 FL	*- FL
12	1		*REAR RH DOOR OUTER STEP GARNISH	Necessary	191.80 FL	*191.80 FL
13	1		*REAR RH DOOR PILLAR	Repair	852.50 FL	*- FL
14	1		*RH SIDE SKIRT	Buckled	681.90 FL	*681.90 FL
15	1		*RH SIDE ROCKER PANEL	Bent	852.50 FL	*852.50 FL
16	1		*REAR RH FENDER	Bent	971.50 FL	*971.50 FL
17	1		*REAR RH FENDER AIR -DUCT	Serviceable	178.85 FL	*- FL
18	1		*REAR RH FENDER INNER SHIELD	Serviceable	182.25 FL	*- FL
19	8		*REAR RH FENDER INNER SHIELD CLIP	Not Necessary	40.00 FL	*- FL
20	1		*REAR RH FENDER INNER GARNISH	Serviceable	691.45 FL	*- FL
21	1		*REAR RH WHEEL HOUSE	Repair	561.60 FL	*- FL
22	1		*SEALANT	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,718.75	4,841.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,409.69	1,200.45
Total Parts (\$\$)	7,309.06	3,641.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIT REAR CUSHION	New	180.00	100.00
2	REMOVE & REFIX REAR RH FENDER GLASS & REAR RH DOOR GLASS	New	180.00	60.00
3	TUFF KOTE	New	120.00	60.00
4	WIRING	New	120.00	20.00
5	SPRAY PAINTING	New	1,600.00	800.00
6	LABOUR CHARGES	New	1,600.00	1,000.00
Gross Labour Cost (S\$)			3,800.00	2,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >