

Hsian Tony



# MBM WHEELPOWER PTE. LTD.

YOUR REF.: PA 7632 K  
OUR REF.: SLX 6533 X

TO: AXA  
CC: MOTOR CLAIMS DEPARTMENT

FAX:

DATE: 18/5/2019  
FROM: CASSANDRA  
FAX: 6452 5333  
CONTACT: 8686 5188  
MAKE & MODEL: HONDA SHUTTLE  
CHASSIS NO.: GK81200929  
ENGINE NO.: L15B5461093  
YEAR MADE: 2017  
ACCIDENT DATE: 17 May 2019

ESTIMATE FOR VEHICLE NO.: SLX 6533 X

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	REAR SPOILER ROOF		1	\$ 800.00 /
2	TAILGATE		1	\$ 1193 / 1,344.80
3	REAR WINDSCREEN		1	\$ 1250 / 1,768.80
4	REAR WINDSCREEN MOULDING		1	\$ 136.40 /
5	TAILGATE CENTRE OUTER MOULDING		1	\$ 198 / 266.00
6	REAR HONDA EMBLEM "H"		1	\$ 78.88 /
7	TAILGATE LAMP RH		1	\$ 410 / 555.20
8	REAR TAILGATE CHROME MOULDING		1	\$ 258 / 555.20
9	REAR "SHUTTLE" EMBLEM		1	\$ 90.48 /
10	REAR BUMPER		10	\$ 1150 / 1,236.80
11	REAR BUMPER CLIP		1	\$ 30 / 70.00
12	TAILLAMP RH		1	\$ 568.40 /
13	TAILLAMP LH		1	\$ 568.40 /
14	REAR REFLECTOR RH		1	\$ 122.08 /
15	REAR REFLECTOR PLATE RH		1	\$ 52.40 /
16	REAR TOWING COVER		1	\$ 48.08 /
17	REAR BOOTLID LOCK		1	\$ 158.80 /
18	SUPP. TAILGATE TRIM		1	\$ 329.30 /
19	SUPP. TAILGATE WEATHERSTRIP		1	\$ 227.80 /
20	SUPP. END PANEL		1	\$ 487.40 /
21	SUPP. END PANEL TOP GARNISH		1	\$ 171.40 /
22	SUPP. REAR FENDER INNERSHIELD TRIM RH		1	\$ 406.40 /
23	SUPP. REAR FENDER INNERSHIELD TRIM LH		1	\$ 406.40 /
24	SUPP. REAR REFLECTOR SPONGE RH		1	\$ 94.10 /
25	SUPP. END PANEL RH		1	\$ 271.16 /
TOTAL:				\$ 10,814.68
LESS 20%:				\$ (2,162.94)
PARTS TOTAL:				\$ 8,651.74

9596-88  
- 20%  
7605.50

SPECIAL NETT

REAR REVERSE SENSOR (1 SET)	1	\$	200.00 /
BODY SEALANT	1	\$	30.00 /
SOLAR FILM	1	\$	250.00 150 /

380

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS	\$	600.00 /
TO REMOVE & REPLACE REAR WINDSCREEN	\$	100.00 /
TO REMOVE & REFIT REAR END PANEL LINING & GARNISH TO FACILITATE REPAIR	\$	30.00 /
TO REMOVE & REPLACE REVERSE SENSORS	\$	20.00 /
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$	30.00 /
TO CONDUCT CHASSIS ALIGNMENT	\$	80.00 /
TO APPLY ANTI RUST COATING	\$	30.00 /
TO SPRAY PAINT ON THE AFFECTED AREAS	\$	600.00 /

TOTAL:	\$	10,621.74
7% GST:	\$	743.52
GRAND TOTAL:	\$	11,365.27

1490

**PART BY PART: \$ 11,365.27**

6 DAYS

P- 7605-50  
M- 380  
L - 1490  
9475-50

# MBM WHEELPOWER PTE. LTD.



YOUR REF.: PA 7632 K  
 OUR REF.: SLX 6533 X

TO: AXA  
 CC: MOTOR CLAIMS DEPARTMENT

FAX:

DATE: 18/5/2019  
 FROM: CASSANDRA  
 FAX: 6452 5333  
 CONTACT: 8686 5188  
 MAKE & MODEL: HONDA SHUTTLE  
 CHASSIS NO.: GK81200929  
 ENGINE NO.: L15B5461093  
 YEAR MADE: 2017  
 ACCIDENT DATE: 17 May 2019

SUPP. ESTIMATE FOR VEHICLE NO.: SLX 6533 X

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
18	1 TAILGATE TRIM <i>de</i>		1	\$ 329.30
19	2 TAILGATE WEATHERSTRIP <i>out</i>		1	\$ 227.80
20	3 END PANEL <i>bt</i>		1	\$ 487.40
21	4 END PANEL TOP GARNISH <i>de</i>		1	\$ 171.40
22	5 REAR FENDER INNERSHIELD TRIM RH <i>de</i>		1	\$ 406.40
23	6 REAR FENDER INNERSHIELD TRIM LH <i>de</i>		1	\$ 406.40
24	7 REAR REFLECTOR SPONGE RH <i>cur</i>		1	\$ 94.10
25	End Panel RH / 00			
			TOTAL:	\$ 2,122.80
			LESS 20%:	\$ (424.56)
			<b>PARTS TOTAL:</b>	<b>\$ 1,698.24</b>

\$271.18

SPECIAL NETT


*24/5/19 5pm*

LABOUR

TOTAL:	\$	1,698.24
7% GST:	\$	118.88
<b>GRAND TOTAL:</b>	<b>\$</b>	<b>1,817.12</b>

MBM WHEELPOWER PTE. LTD.  
 160 SIN MING DRIVE, #06-02  
 SIN MING AUTOCITY  
 t 6262 8888 f 6452 5333  
 COMPANY REG. NO.: 200204110W

# MBM WHEELPOWER PTE. LTD.



YOUR REF.: PA 7632 K  
 OUR REF.: SLX 6533 X

*Steve CLKK) wml PIP L 23/5/19, 9:20 pm*  
*83228813* *day ↑*  
*6* *PIP*  
*Ry bec spy*

TO: AXA  
 CC: MOTOR CLAIMS DEPARTMENT

DATE: 18/5/2019  
 FROM: CASSANDRA ✓  
 FAX: 6452 5333  
 CONTACT: 8686 5188  
 MAKE & MODEL: HONDA SHUTTLE  
 CHASSIS NO.: GK81200929  
 ENGINE NO.: L15B5461093  
 YEAR MADE: 2017  
 ACCIDENT DATE: 17 May 2019

FAX:

ESTIMATE FOR VEHICLE NO.: SLX 6533 X

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
① / 1	REAR SPOILER ROOF <i>cut</i>		1	\$ 800 / 1,308.00
2	REAR BRAKE LIGHT <i>x</i>		1	\$ 330.00 <i>X</i>
② 3	TAILGATE / <i>DD</i>		1	\$ 1,344.80 ✓
③ 4	REAR WINDSCREEN / <i>BR</i>		1	\$ 1,768.80 ✓
④ 5	REAR WINDSCREEN MOULDING / <i>NEC</i>		1	\$ 136.40 ✓
⑤ 6	TAILGATE CENTRE OUTER MOULDING / <i>BR</i>		1	\$ 266.00 ✓
⑥ 7	REAR HONDA EMBLEM "H" / <i>NEC</i>		1	\$ 78.88 ✓
⑦ 8	TAILGATE LAMP RH <i>2</i> / <i>BR</i>		1	\$ 555.20 ✓
<i>x</i> 9	TAILGATE LAMP LH <i>x</i>		1	\$ 555.20 <i>X</i>
⑧ 10	REAR TAILGATE CHROME MOULDING / <i>BR</i>		1	\$ 555.20 ✓
⑨ 11	REAR "SHUTTLE" EMBLEM / <i>NEC</i>		1	\$ 90.48 ✓
⑩ 12	REAR BUMPER / <i>BR</i>		1	\$ 1,236.80 ✓
⑪ 13	REAR BUMPER CLIP / <i>NEC</i>		10	\$ 70.00 ✓
⑫ / 14	TAILLAMP RH <i>cut</i>		1	\$ 568.40 ✓
⑬ / 15	TAILLAMP LH <i>cut</i>		1	\$ 568.40 ✓
⑭ / 16	REAR REFLECTOR RH <i>2</i>		1	\$ 122.08 ✓
17	REAR REFLECTOR LH <i>x</i>		1	\$ 122.08 <i>X</i>
⑮ 18	REAR REFLECTOR PLATE RH / <i>cut</i>		1	\$ 52.40 ✓
19	REAR REFLECTOR PLATE LH <i>x</i>		1	\$ 52.40 <i>X</i>
⑯ 20	REAR TOWING COVER / <i>MIS</i>		1	\$ 48.08 ✓
⑰ 21	REAR BOOTLID LOCK / <i>BT</i>		1	\$ 158.80 ✓
TOTAL:				\$ 9,988.40
LESS 20%:				\$ (1,997.68)
PARTS TOTAL:				\$ 7,990.72

SPECIAL NETT

REAR REVERSE SENSOR (1 SET) / RR	1	\$	200 /	300.00
BODY SEALANT / NLC	1	\$	30 /	100.00
SOLAR FILM / NLC	1	\$	100 /	250.00
REAR NUMBER PLATE WITH FRAME X	1	\$		80.00 X

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS	\$	600	800.00	↑
TO REMOVE & REPLACE REAR WINDSCREEN	\$	100	180.00	
TO REMOVE & REFIT REAR END PANEL LINING & GARNISH TO FACILITATE REPAIR	\$	30	70.00	
TO REMOVE & REPLACE REVERSE SENSORS	\$	20	50.00	
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$	30	100.00	
TO CONDUCT ALL WHEEL COMPUTERISED ALIGNMENT	\$	X	80.00	
TO CONDUCT CHASSIS ALIGNMENT	\$		80.00	/
TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)	\$	X	150.00	
TO APPLY ANTI RUST COATING	\$	30	200.00	
TO SPRAY PAINT ON THE AFFECTED AREAS	\$	500	700.00	↑
TOTAL:	\$		11,130.72	
7% GST:	\$		779.15	
<b>GRAND TOTAL:</b>	<b>\$</b>		<b>11,909.87</b>	

MBM WHEELPOWER PTE. LTD.  
160 SIN MING DRIVE, #06-02  
SIN MING AUTOCITY  
t 6262 8888 f 6452 5333  
COMPANY REG. NO.: 200204110W

## Steve Chen (LKK Auto)

---

**From:** cassandra.chua@mbmwheelpower.com.sg  
**Sent:** Monday, June 10, 2019 5:36 PM  
**To:** Steve Chen (LKK Auto)  
**Cc:** 'Danny Ong '  
**Subject:** RE: Finalisation for SLX 6533 X DOA 17/05/2019

Dear Steve,

**Confirmed finalised amount @ \$9,475.50 (P/P, before GST), 6 repair days.**

Thank you.

Best Regards,  
Cassandra Chua | Claims Advisor



T 6262 8888 | F 6250 9015 | M 8686 5188

Email: [cassandra.chua@mbmwheelpower.com.sg](mailto:cassandra.chua@mbmwheelpower.com.sg)

**MBM Wheelpower PTE. LTD.**

160 Sin Ming Drive • #06-02

Sin Ming Autocity • Singapore 575722

[www.mbmwheelpower.com.sg](http://www.mbmwheelpower.com.sg)

---

**From:** Steve Chen (LKK Auto) <[SteveChen@lkkauto.com](mailto:SteveChen@lkkauto.com)>  
**Sent:** Monday, 10 June 2019 5:12 PM  
**To:** [cassandra.chua@mbmwheelpower.com.sg](mailto:cassandra.chua@mbmwheelpower.com.sg)  
**Subject:** Finalisation for SLX 6533 X DOA 17/05/2019

Dear Cass,

Our finalize \$9,475.50 (P/P, before GST). 6 repair days.

Kindly confirm.

Thanks

Best Regards,  
Steve Chen | Assistant Automotive Assessor  
LKK Auto Consultants

Phone: 6256 3561 | Email: [SteveChen@lkkauto.com](mailto:SteveChen@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)