

72/02/2019

ASS. REC. BY:

REF: CS/GA19009001/kqd352

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Sharon Ng of GAI Date/Time: 22/5/19 @ 10:45am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: G8D 8436D Insured: _____at Workshop m/s K. Kim Hin Tel: 64527018of 160 Sin Ming Drive #02-20Policy No: _____ Claim No: CLMOMXC000003661Sum Insured: _____ Excess: \$4100.00 600Make of Veh: _____ D.O.A. 15/05/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 2:10pm @ 22/5/19 Person Contacted: Jandra Vehicle IN / OUT MV: 462

H.O.D. Endorsement:

Date/Time	Action/Instruction	Estimate	Check damage consistency
	G8D 8436D - (C4 / III) 19002016 / Eha.3		D.O.A - 30/01/2019
22/5/19 @	5.41pm revert to Sharon Ng by email. (Repairer willing to undertake the repair cost not more than \$13k on US basis).		
24/5/19 @	6.18pm Kelvin informed C/A not more than \$12k & EX: \$400.		
28/5/19 @	10am. Informed Simon C/A not more than 15 \$ 12k which he agreed the cost is EX: \$400 by email.		

Kenneth

ASSIGNMENT

TOTAL

450

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 27 May 2019 10:00 AM
To: service@kkimhin.com.sg; admin1@kkimhin.com.sg
Cc: 'Sandra (Gmail)'; simon@kkimhin.com.sg; SUR
Subject: RE: GBD 8436 D - OD claim DOA : 15/5/2019

Dear Simon,

As spoken with you.

As instructed by our client, please proceed to repair the insured vehicle **GBD 8436D at repair cost not more than \$12,000.00 on Lump Sum basis (Excess \$4,100/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: service@kkimhin.com.sg <service@kkimhin.com.sg>
Sent: Friday, 24 May 2019 5:17 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; admin1@kkimhin.com.sg; Admin A <admin-a@lkkauto.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Cc: 'Sandra (Gmail)' <sandrakhong@gmail.com>; simon@kkimhin.com.sg
Subject: GBD 8436 D - OD claim DOA : 15/5/2019

Dear Shiau Chan

Per your request, enclosed company chop on statement.

We would appreciate a call to us for urgent cases as we are not always looking at email when we are busy with clients.

Seek your understanding.

Thanks & Regards
Sandra
6452 7018
K. Kim Hin Auto Pte Ltd

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 27 May 2019 11:17 AM
To: service@kkimhin.com.sg
Cc: Sandra (Gmail); simon@kkimhin.com.sg; SUR; survey2@kkimhin.com.sg; survey@kkimhin.com.sg
Subject: RE: GBD 8436 D - OD claim DOA : 15/5/2019

Dear Simon,

We have checked with insurance officer, the excess will be \$600.00 instead of \$4,100.00.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: service <service@kkimhin.com.sg>
Sent: Monday, 27 May 2019 10:05 AM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Cc: Sandra (Gmail) <sandrakhong@gmail.com>; simon@kkimhin.com.sg; SUR <sur@lkkauto.com>; survey2@kkimhin.com.sg; survey@kkimhin.com.sg; service@kkimhin.com.sg
Subject: RE: GBD 8436 D - OD claim DOA : 15/5/2019

Dear Shiau Chan

Good day to you.

Enclosed the driving licence before conversion.

Please review the excess applicable. Thank you.

Best Regards

Sandra

6452 7018

K. Kim Hin Auto Pte Ltd

From: "Shiau Chan (LKKAUTO)" <siewsc@lkkauto.com>
Sent: Monday, May 27, 2019 10:00 AM
To: "service@kkimhin.com.sg" <service@kkimhin.com.sg>, "admin1@kkimhin.com.sg" <admin1@kkimhin.com.sg>
Cc: "Sandra (Gmail)" <sandrakhong@gmail.com>, "simon@kkimhin.com.sg" <simon@kkimhin.com.sg>, "SUR" <sur@lkkauto.com>
Subject: RE: GBD 8436 D - OD claim DOA : 15/5/2019

Dear Simon,

As spoken with you.

As instructed by our client, please proceed to repair the insured vehicle **GBD 8436D** at repair cost not more than **\$12,000.00 on Lump Sum basis (Excess \$4,100/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

Shiau Chan (LKKAUTO)

From: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Sent: Monday, 27 May 2019 11:07 AM
To: Shiau Chan (LKKAUTO)
Cc: SUR
Subject: RE: GBD8436D (Own Damage) - DOA: 15 May 2019 || Our ref: CLMOMVC000003661

Hi Shiau

In this instance, the excess applicable will be \$600.00

Thanks
Kelvyna

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Monday, May 27, 2019 10:09 AM
To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Cc: SUR <sur@lkkauto.com>
Subject: [External] RE: GBD8436D (Own Damage) - DOA: 15 May 2019 || Our ref: CLMOMVC000003661

Dear Kelvyna,

Please find the attached of driver's driving license copy and confirm the excess.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 27 May 2019 10:01 AM
To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: GBD8436D (Own Damage) - DOA: 15 May 2019 || Our ref: CLMOMVC000003661

Dear Kelvyna,

We have checked with repairer, they able to undertake the repair cost not more than \$12,000.00.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Sent: Friday, 24 May 2019 6:18 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Monday, 27 May 2019 10:01 AM
To: Ngian, Kelvyna
Cc: SUR
Subject: RE: GBD8436D (Own Damage) - DOA: 15 May 2019 || Our ref: CLMOMVC000003661

Dear Kelvyna,

We have checked with repairer, they able to undertake the repair cost not more than \$12,000.00.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Sent: Friday, 24 May 2019 6:18 PM
To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: GBD8436D (Own Damage) - DOA: 15 May 2019 || Our ref: CLMOMVC000003661

Hi Shiau

Please proceed. Able to check with repairer if possible to keep the repair cost not more than \$12,000.00. Excess: \$4,100.00 (\$600.00 + \$3,500.00 YID)

Thanks
Kelvyna

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Friday, May 24, 2019 6:06 PM
To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Cc: SUR <sur@lkkauto.com>
Subject: [External] RE: GBD8436D (Own Damage) - DOA: 15 May 2019 || Our ref: CLMOMVC000003661

Dear Kelvyna,

Please refer the attached and advise the authorisation.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Sent: Friday, 24 May 2019 4:22 PM

To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>

Subject: RE: GBD8436D (Own Damage) - DOA: 15 May 2019 || Our ref: CLMOMVC000003661

Hi Shiau

Missing company stamp - Please inform repairer to furnish accident report with company stamp

Thanks

Kelvyna

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>

Sent: Friday, May 24, 2019 3:51 PM

To: Ng, Sharon <Sharon.Ng@sg.gaig.com>; Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>

Cc: SUR <sur@lkkauto.com>

Subject: [External] RE: GBD8436D (Own Damage) - DOA: 15 May 2019 || Our ref: CLMOMVC000003661

Dear Kelvyna,

Kindly advise on authorisation as repairer keep chasing.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng, Sharon <Sharon.Ng@sg.gaig.com>

Sent: Wednesday, 22 May 2019 6:09 PM

To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>

Cc: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: FW: GBD8436D (Own Damage) - DOA: 15 May 2019 || Our ref: CLMOMVC000003661

Hi Kelvyna

About 4 year old vehicle. To check if liability is cleared and instruct on authorization.

Thanks and Regards

Sharon Ng

Great American

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>

Sent: Wednesday, May 22, 2019 5:41 PM

To: Ng, Sharon <Sharon.Ng@sg.gaig.com>; SUR <sur@lkkauto.com>

Subject: [External] RE: GBD8436D (Own Damage) - DOA: 15 May 2019 || Our ref: CLMOMVC000003661

Dear Sharon,

Enclosed herewith preliminary advice of GBD 8436D.

Repairer willing to undertake the repair cost not more than \$13,000.00 on Lump Sum basis.

We have not authorise repair.

Nivitha (LKK Auto)

From: Ng, Sharon <Sharon.Ng@sg.gaig.com>
Sent: Wednesday, 22 May 2019 10:45 AM
To: SUR
Cc: assignments
Subject: FW: GBD8436D (Own Damage) - DOA: 15 May 2019 || Our ref: CLMOMVC000003661
Attachments: COE Rebate.pdf; DRIVER IC & DL.pdf; Estimate GBD 8436 D.pdf; GIAreport 8436.PDF; SFA9928M (LIB) TP2.pdf; YN9152R (NTUC) TP1.pdf

Dear LKK

Please arrange OD survey and verify damages consistency.
Excess: \$4,100.00 (i.e. \$600.00 + \$3,500.00 YID)

Regards
Sharon
Great American

From: service <service@kkimhin.com.sg>
Sent: Tuesday, May 21, 2019 7:27 PM
To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>; Ng, Sharon <Sharon.Ng@sg.gaig.com>
Cc: service@kkimhin.com.sg; Sandra (Gmail) <sandrakhong@gmail.com>; simon@kkimhin.com.sg
Subject: [External] GBD 8436 D (Own Damage) - DOA: 15 May 2019

Dear Ms Kelvyna/ Ms Sharon

Good evening.

Enclosed the estimate and GIA report for GBD 8436 D (DOA: 15 May 2019) to do Own Damage Claim under G.A.

Vehicle is in the workshop.

Please kindly appoint surveyor.

Best Regards
Sandra
6452 7018
9622 2116
K. Kim Hin Auto Pte Ltd

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 22 May 2019 5:41 PM
To: 'Ng, Sharon'; SUR
Subject: RE: GBD8436D (Own Damage) - DOA: 15 May 2019 || Our ref: CLMOMVC000003661
Attachments: GBD8436 EST.pdf; CSGAI19009001Kqd3.pdf

Dear Sharon,

Enclosed herewith preliminary advice of GBD 8436D.

Repairer willing to undertake the repair cost not more than \$13,000.00 on Lump Sum basis.

We have not authorise repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 22 May 2019 2:10 PM
To: 'Ng, Sharon' <Sharon.Ng@sg.gaig.com>; SUR <sur@lkkauto.com>
Cc: assignments <assignments@lkkauto.com>
Subject: RE: GBD8436D (Own Damage) - DOA: 15 May 2019 || Our ref: CLMOMVC000003661

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng, Sharon [<mailto:Sharon.Ng@sg.gaig.com>]
Sent: Wednesday, 22 May 2019 10:45 AM
To: SUR <sur@lkkauto.com>
Cc: assignments <assignments@lkkauto.com>
Subject: FW: GBD8436D (Own Damage) - DOA: 15 May 2019 || Our ref: CLMOMVC000003661

Dear LKK



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CLMOMVC000003661

Date: 22nd May 2019

Our Ref: CS/GAI19009001/Kqd3

The Motor Claims Department
Great American Insurance Company

Attn: Sharon

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. GBD 8436D


We thank you for the instruction on 15/05/2019.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 22/05/2019 at the premises of M/s K KIM HIN and have the following to report:-

Workshop Estimate Amount	: S\$ 21,923.40
Revised Estimate Amount	: S\$ 11,215.50
"Check" Items Amount	: S\$ 4,322.90
Market Value	: S\$ 46,000.00
Salvage Value	: S\$ 31,569.00
Nett Value	: S\$ 14,431.00

Description of Damage:

The vehicle sustained damages at the n/s body & rear o/s portion.



Comments/ Present Status:

Damages consistent.

Repair cost economical.

Repairer willing to undertake the repair cost not more than \$13,000.00 on Lump Sum basis.

Recommend repair days: 14 days

We have NOT authorise repair.

Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/05/2019 17:40
Date Of Accident	15/05/2019 16:00
Exact Location Of Accident	5058 ANG MO KIO INDUSTRIAL PARK 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBD8436D
Insured/Policyholder	
Name Of Registered Owner	JUBILEE FOODSTUFF PTE LTD
Co Reg No	200405334Z
Email Address	FOODSTUFF0506@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91994451
Alternative Phone No	OFFICE-62679582

Vehicle Particulars

Manufacturer	NISSAN
Model	NV350-2.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	GREAT AMERICAN INSURANCE COMPANY
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MOMVC000007886-00-000
Cover Note Number	

Driver

Name of Driver	RETHINAM BALASUBRAMANIAN
Passport No/FIN	G6778253X
Date Of Birth	21/05/1979
Occupation	INDOOR
Date Of Driving Pass	09/02/2018
Driving Experience	1 YEAR AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84927395
Fax Number	
Contact Number	
Email Address	NOEMAIL

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SFA9928M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

PLEASE REFER TO SKETCH

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS DRIVING ALONG ANG TWO KID INDUSTRIAL
PARK 2 AND I CHECK NO TRAFFIC AND
I DROVE OUT. NEAR THE OTHER SIDE, VEHICLE
B DROVE VERY FAST HIT MY VAN AND CAUSED MY
VAN TO SPIN AND HIT STATIONARY PARKED VEHICLE
C.

DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature

Date & Time:

Company Chop (if applicable)

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature _____

Name:

NRIC/FIN No.



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5334Z
Vehicle Details	
Vehicle No.:	GBD8436D
Vehicle to be Exported:	No
Intended Deregistration Date:	16 May 2019
Vehicle Make:	NISSAN
Vehicle Model:	NV350 PANEL VAN 2.5 5MT 5DR EURO V
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	YD25355747A
Chassis No.:	JN1MC2E26Z0003145
Maximum Power Output:	-
Open Market Value:	\$23,914.00
Original Registration Date:	12 Jun 2015
First Registration Date:	12 Jun 2015
Transfer Count:	2
Actual ARF Paid:	\$1,196.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	11 Jun 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$52,001.00
COE Rebate Amount:	\$31,569.00
Total Rebate Amount:	\$31,569.00

The information contained herein is correct as at 16 May 2019

OK

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

(N) OD -
GREAT
AMERICAN

Your Reference : MOMVC000007886-00-000
Accident Date : 15-May-2019

No. : 30466

Date : 17-May-2019

Our Ref : 190258 / SANDRA

GREAT AMERICAN INSURANCE COMPANY
3 TEMASEK AVE #16-01
CENTENNIAL TOWER
Singapore 039190



n/s body & Acc d/s

Ex @ 4100h

PAGE : 1

Not with a

C/Sing @?

Assembly After Paint

ESTIMATED COST OF REPAIR FOR NISSAN NV350 PANEL VAN 2.5 (2015) GBD8436D

Fax 62564315

1 pc	n/s front door
1 pc	n/s front door hinge top
1 pc	n/s front door hinge bottom
1 pc	n/s front door checker
1 pc	n/s front door weatherstrip
1 pc	n/s front door lower seal
1 pc	n/s front door frame weather strip
1 pc	n/s front door window glass
1 pc	n/s front door window glass regulator
1 pc	n/s front door window glass motor
1 pc	n/s front door window glass run channel
1 pc	n/s front door window glass run channel sash
1 pc	n/s front door window glass outer moulding
1 pc	n/s front door window glass inner moulding
1 pc	n/s front door lock
1 pc	n/s front door lock catch
1 pc	n/s front door outer handle
1 pc	n/s front door inner handle
1 pc	n/s front door inner trim board

690.00	c	✓
65.00	c	X
65.00	c	X
50.00	c	X
85.00	c	7X
45.00	c	7X
115.00	c	X
380.00	c	✓
130.00	c	7X
300.00	c	7X
75.00	c	✓
65.00	c	X
90.00	c	✓
55.00	c	X
125.00	c	7X
50.00	c	X
115.00	c	✓
60.00	c	X
380.00	c	X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Con't Page 2 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Your Reference : MOMVC000007886-00-000
Our Ref : 190258

Page : 2
No. : 30466

1 pc	n/s front door switch
1 pc	n/s front door outer pillar
1 pc	n/s sliding door outer pillar
1 pc	n/s sliding door step floor panel
1 pc	n/s front mudflap
1 pc	n/s sliding door
1 pc	n/s sliding door upper roller
1 pc	n/s sliding door upper roller bracket
1 pc	n/s sliding door centre roller
1 pc	n/s sliding door lower roller
1 pc	n/s sliding door upper guide rail assy
1 pc	n/s sliding door centre guide rail assy
1 pc	n/s sliding door lower guide rail assy
1 pc	n/s sliding door checker
1 pc	n/s sliding door weatherstrip
1 pc	n/s sliding door doretail-male
1 pc	n/s sliding door doretail female
1 pc	n/s sliding door inner trim
18 pcs	n/s sliding door inner trim clips @ S\$ 3.00
1 pc	n/s sliding door outer handle
1 pc	n/s sliding door outer handle seal
1 pc	n/s sliding door inner handle
1 pc	n/s sliding door lock control
1 pc	n/s sliding door lock-front
1 pc	n/s sliding door lock-rear
1 pc	n/s sliding door lock catch - front
1 pc	n/s sliding door lock catch - rear

SL	45.00	c	X
R	800.00	c	X X
B	800.00	c	X X
B	600.00	c	✓
T	150.00	c	✓
B	1,000.00	c	✓
SVC	70.00	c	? X
SVC	100.00	c	? X
MS	100.00	c	? ✓
MS	115.00	c	X ✓
SVC	190.00	c	? X
SL	220.00	c	X
SL	480.00	c	X
CM	55.00	c	✓
SL	185.00	c	✓
SVC	125.00	c	X ? X
SVC	140.00	c	X ? X
B	390.00	c	✓
	54.00	c	X m
MS	100.00	c	X ✓
SL	10.00	c	X
SL	85.00	c	X
JM	220.00	c	? ✓
B	140.00	c	✓
DD	165.00	c	? ✓
DD	50.00	c	✓
SVC	50.00	c	? X

Con't Page 3 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Your Reference : MOMVC000007886-00-000
Our Ref : 190258

Page : 3
No. : 30466

✓ 1 pc	n/s sliding door connector assy-male	CM	145.00	c	✓
1 pc	n/s sliding door connector assy-female	D	155.00	c	✓
1 pc	n/s sliding door switch assy	SVC	45.00	c	? X
1 pc	n/s rear body panel	R	1,150.00	c	X
1 pc	tailgate	R	1,100.00	c	✓
1 pc	tailgate third brake light	sn	190.00	c	X
1 pc	tailgate logo	sn	55.00	c	✓
1 pc	tailgate "NV350" emblem	sn	85.00	c	✓
2 pcs	taillamp assy (LH/RH) <i>olsm</i>	@ S\$130.00	260.00	c	✓
1 pc	rear bumper	R	330.00	c	✓
3 pcs	o/s rear bumper side retainer	@ S\$ 15.00	45.00	c	✓
10 pcs	o/s rear bumper clips	@ S\$ 2.00	20.00	c	✓
1 pc	n/s front upper arm		205.00	c	? X
1 pc	n/s front knuckle arm		300.00	c	? X
1 pc	n/s front knuckle arm bearing		160.00	c	? X
1 pc	n/s front bearing hub		340.00	c	? X
1 pc	n/s front lower arm		180.00	c	? X
1 pc	n/s front lower arm ball joint		85.00	c	? X
1 pc	n/s front stablizer bar linkage	sn	90.00	c	X
1 pc	n/s front shock absorber		125.00	c	? X
			14,444.00		
Add 10% :			1,444.40		
			15,888.40		
1 pc	n/s front door company registration sticker	sn	25.00	sn	✓
1 pc	tailgate windscreen glass sealant	sn	40.00	sn	✓
1 pc	tailgate windscreen glass damppling seal	sn	20.00	sn	✓
1 pc	tailgate "70 km/h" sticker	sn	25.00	sn	15/2
1 pc	tailgate "8pax" sticker	sn	25.00	sn	15/2
1 pc	reverse sensor	sn	220.00	sn	X

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Your Reference : MOMVC000007886-00-000
Our Ref : 190258

Page : 4
No. : 30466

1 pc n/s front tyre
1 pc n/s front rim

SVC 220.00 sn 7X
SVC 280.00 sn 7X

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

1,900.00 1600

To focus taillamps. To check rear
wiring and lighting operation.

50.00 400

To remove and refit rear windscreen
glass and conduct water leak test

120.00 ✓

To remove and refit rear upholstery
trimming, roof lining, seats,
speaker board in order to
facilitate repairing works

120.00 1000

To remove and refit front seat assy
trim board and carpet to facilitate
repairing works

180.00 1000

To remove aircon condenser, pipes
and driers. Vaccum and recharge gas

nn 100.00 X

To remove front instrument panel
assy and rewiring to facilitate
repair works.

nn 280.00 X

To remove door's fittings

100.00 600

To remove and transfer electrical
sliding door. To re-wiring
and re-setting

300.00 800

To dismantle and check front under-
carriages. To replace affected
portions.

40 150.00 7X



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Your Reference : MOMVC000007886-00-000
Our Ref : 190258

Page : 5
No. : 30466

To conduct front wheel alignment test.	100.00	601
To transfer tailgate's fittings	100.00	601
To remove and refit reverse sensor assy.	80.00	501
To putty and respray on affected portions.	1,600.00	14001
Total :	----- S\$21,923.40 =====	

Singapore Dollars Twenty One Thousand Nine Hundred
and Twenty Three and Cents Forty Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.



AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg



OD -
GREAT
AMERICAN

No. : 30466

Date : 17-May-2019

PAGE : 1

Not Notched

1 Sup B?

Acrylic After Paint

Ex 84100h

Your Reference : MOMVC000007886-00-000
Accident Date : 15-May-2019

Our Ref : 190258 / SANDRA

GREAT AMERICAN INSURANCE COMPANY
3 TEMASEK AVE #16-01
CENTENNIAL TOWER
Singapore 039190

n/s body & Acc d/s

ESTIMATED COST OF REPAIR FOR NISSAN NV350 PANEL VAN 2.5 (2015) GBD8436D

Fax 62564315

- 1 pc n/s front door
- 1 pc n/s front door hinge top
- 1 pc n/s front door hinge bottom
- 1 pc n/s front door checker
- 1 pc n/s front door weatherstrip
- 1 pc n/s front door lower seal
- 1 pc n/s front door frame weather strip
- 1 pc n/s front door window glass
- 1 pc n/s front door window glass regulator
- 1 pc n/s front door window glass motor
- 1 pc n/s front door window glass run channel
- 1 pc n/s front door window glass run channel sash
- 1 pc n/s front door window glass outer moulding
- 1 pc n/s front door window glass inner moulding
- 1 pc n/s front door lock
- 1 pc n/s front door lock catch
- 1 pc n/s front door outer handle
- 1 pc n/s front door inner handle
- 1 pc n/s front door inner trim board

R 690.00 c ✓
R 65.00 c x
R 65.00 c x
R 50.00 c x
R 85.00 c x
R 45.00 c x
R 115.00 c x
L R 380.00 c x
R 130.00 c x
R 300.00 c x
L R 75.00 c x
R 65.00 c x
R 90.00 c ✓
R 55.00 c x
R 125.00 c x
R 50.00 c x
R 115.00 c ✓
R 60.00 c x
R 380.00 c x

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

Page : 2
No. : 30466

Your Reference : MOMVC000007886-00-000
Our Ref : 190258

QTY	DESCRIPTION	UNIT PRICE	TOTAL	REMARKS
1 pc	n/s front door switch			
1 pc	n/s front door outer pillar			
1 pc	n/s sliding door outer pillar			
1 pc	n/s sliding door step floor panel			
1 pc	n/s front mudflap			
1 pc	n/s sliding door			
1 pc	n/s sliding door upper roller			
1 pc	n/s sliding door upper roller bracket			
1 pc	n/s sliding door centre roller			
1 pc	n/s sliding door lower roller			
1 pc	n/s sliding door upper guide rail assy			
1 pc	n/s sliding door centre guide rail assy			
1 pc	n/s sliding door lower guide rail assy			
1 pc	n/s sliding door checker			
1 pc	n/s sliding door weatherstrip			
1 pc	n/s sliding door doretail-male			
1 pc	n/s sliding door doretail female			
1 pc	n/s sliding door inner trim			
18 pcs	n/s sliding door inner trim clips	@ S\$ 3.00		
1 pc	n/s sliding door outer handle			
1 pc	n/s sliding door outer handle seal			
1 pc	n/s sliding door inner handle			
1 pc	n/s sliding door lock control			
1 pc	n/s sliding door lock-front			
1 pc	n/s sliding door lock-rear			
1 pc	n/s sliding door lock catch - front			
1 pc	n/s sliding door lock catch - rear			



CO. REG. NO: 199402370D

GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Page : 3

No. : 30466

Your Reference : MOMVC000007886-00-000
Our Ref : 190258

1 pc	n/s sliding door connector assy-male		CM 145.00 c	✓
1 pc	n/s sliding door connector assy-female		D 155.00 c	✓
1 pc	n/s sliding door switch assy		Sn 45.00 c	?
1 pc	n/s rear body panel		R 1,150.00 c	X
1 pc	tailgate		R 1,100.00 c	✓
1 pc	tailgate third brake light		Sn 190.00 c	X
1 pc	tailgate logo		Sn 55.00 c	✓
1 pc	tailgate "NV350" emblem		Sn 85.00 c	✓
2 pcs	taillamp assy (LH/RH)	o/s M @ S\$130.00	260.00 c	130 ✓
1 pc	rear bumper		R 330.00 c	✓
3 pcs	o/s rear bumper side retainer	@ S\$ 15.00	clip 45.00 c	15.00 ✓
10 pcs	o/s rear bumper clips	@ S\$ 2.00	Sn 20.00 c	✓
1 pc	n/s front upper arm		205.00 c	?
1 pc	n/s front knuckle arm		300.00 c	?
1 pc	n/s front knuckle arm bearing		160.00 c	?
1 pc	n/s front bearing hub		340.00 c	?
1 pc	n/s front lower arm		180.00 c	?
1 pc	n/s front lower arm ball joint		85.00 c	?
1 pc	n/s front stablizer bar linkage		Sn 90.00 c	X
1 pc	n/s front shock absorber		425.00 c	?
			14,444.00	
		Add 10% :	1,444.40	
			15,888.40	
1 pc	n/s front door company registration sticker		Sn 25.00 sn	✓
1 pc	tailgate windscreen glass sealant		Sn 40.00 sn	✓
1 pc	tailgate windscreen glass damppling seal		Sn 20.00 sn	✓
1 pc	tailgate "70 km/h" sticker		Sn 25.00 sn	15/2
1 pc	tailgate "8pax" sticker		Sn 25.00 sn	15/2
1 pc	reverse sensor		Sn 220.00 sn	X

Con't Page 4 ...



CO. REG. NO: 199402370D

GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Your Reference : MOMVC000007886-00-000
Our Ref : 190258

Page : 4
No. : 30466

1 pc n/s front tyre
1 pc n/s front rim

~~Sn 220.00 sn 7~~
~~Sn 280.00 sn 7~~

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

~~1,900.00~~ 1600

To focus taillamps. To check rear
wiring and lighting operation.

~~50.00~~ 40

To remove and refit rear windscreen
glass and conduct water leak test

120.00 ✓

To remove and refit rear upholstery
trimming, roof lining, seats,
speaker board in order to
facilitate repairing works

~~120.00~~ 100

To remove and refit front seat assy
trim board and carpet to facilitate
repairing works

~~180.00~~ 100

To remove aircon condenser, pipes
and driers. Vacuum and recharge gas

~~100.00~~ X

To remove front instrument panel
assy and rewiring to facilitate
repair works.

~~280.00~~ X

To remove door's fittings

~~100.00~~ 60

To remove and transfer electrical
sliding door. To re-wiring
and re-setting

~~300.00~~ 80

To dismantle and check front under-
carriages. To replace affected
portions.

~~150.00~~ 70

Con't Page 5 ...



金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Your Reference : MOMVC000007886-00-000
Our Ref : 190258

Page : 5
No. : 30466

To conduct front wheel alignment
test.

~~100.00~~ 601

To transfer tailgate's fittings

~~100.00~~ 601

To remove and refit reverse sensor
assy.

~~80.00~~ 501

To putty and respray on affected
portions.

~~1,600.00~~ 14001

Total : S\$21,923.40

Singapore Dollars Twenty One Thousand Nine Hundred
and Twenty Three and Cents Forty Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

\$ 7,455.00 - Part
+ 10%

\$ 8,200.50

\$ 115.00 - 1st

\$ 3,670.00 - 1st

\$ 11,985.50

- 20%

\$ 9,588.40

45 = \$ 9,600.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI19009001/Kqd3s2

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date : 18-11-2019



Code : GAI

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	GBD 8436D
Policy No.	MOMVC000007886-00-000	Coverage (\$)	0.00
Claim No.	CLMOMVC000003661	Excess (\$)	600.00
Assign From	SHARON NG	Assign Date	22/05/2019

2. Vehicle Particulars & Condition

Make & Model	NISSAN NV350	c.c	2488
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JN1MC2E26Z0003145	Colour	WHITE
Odometer	206042	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15 X8	BRIDGESTONE	6 mm
L/H Front Tyre	195 R15 X8	BRIDGESTONE	6 mm
R/H Rear Tyre	195 R15 X8	BRIDGESTONE	5 mm
L/H Rear Tyre	195 R15 X8	BRIDGESTONE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND REAR O/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/05/2019	Inspection Date	22/05/2019
Survey held at	K.KIM HIN AUTOMOTIVE PTE LTD 160 SIN MING DRIVE, #02-20 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A)THE MARKET VALUE IS S\$46,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	14 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 8436D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	N/S FRONT DOOR (WCP)	BENT	690.00	690.00
1	N/S FRONT DOOR HINGE TOP (WCP)	TO REPAIR SEE LABOUR	65.00	-
1	N/S FRONT DOOR HINGE BOTTOM (WCP)	TO REPAIR SEE LABOUR	65.00	-
1	N/S FRONT DOOR CHECKER (WCP)	SERVICEABLE	50.00	-
1	N/S FRONT DOOR WEATHERSTRIP (WCP)	SERVICEABLE	85.00	-
1	N/S FRONT DOOR LOWER SEAL (WCP)	SERVICEABLE	45.00	-
1	N/S FRONT DOOR FRAME WEATHER STRIP (WCP)	SERVICEABLE	115.00	-
1	N/S FRONT DOOR WINDOW GLASS (WCP)	CUT	380.00	380.00
1	N/S FRONT DOOR WINDOW GLASS REGULATOR (WCP)	SERVICEABLE	130.00	-
1	N/S FRONT DOOR WINDOW GLASS MOTOR (WCP)	SERVICEABLE	300.00	-
1	N/S FRONT DOOR WINDOW GLASS RUN CHANNEL (WCP)	CUT	75.00	75.00
1	N/S FRONT DOOR WINDOW GLASS RUN CHANNEL SASH (WCP)	SERVICEABLE	65.00	-
1	N/S FRONT DOOR WINDOW GLASS OUTER MOULDING (WCP)	DENTED	90.00	90.00
1	N/S FRONT DOOR WINDOW GLASS INNER MOULDING (WCP)	SERVICEABLE	55.00	-
1	N/S FRONT DOOR LOCK (WCP)	SERVICEABLE	125.00	-
1	N/S FRONT DOOR LOCK CATCH (WCP)	TO REPAIR SEE LABOUR	50.00	-
1	N/S FRONT DOOR OUTER HANDLE (WCP)	DENTED / CUT	115.00	115.00
1	N/S FRONT DOOR INNER HANDLE (WCP)	SERVICEABLE	60.00	-
1	N/S FRONT DOOR INNER TRIM BOARD (WCP)	SERVICEABLE	380.00	-
1	N/S FRONT DOOR SWITCH (WCP)	SERVICEABLE	45.00	-
1	N/S FRONT DOOR OUTER PILLAR (WCP)	TO REPAIR SEE LABOUR	800.00	-
1	N/S SLIDING DOOR OUTER PILLAR (WCP)	BENT	800.00	800.00
1	N/S SLIDING DOOR STEP FLOOR PANEL (WCP)	BENT	600.00	600.00
1	N/S FRONT MUDFLAP (WCP)	TORN	150.00	150.00
1	N/S SLIDING DOOR (WCP)	BENT	1,000.00	1,000.00

Report Ref No. CS/GAI19009001/Kqd3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	N/S SLIDING DOOR UPPER ROLLER (WCP)	SERVICEABLE	70.00	-
1	N/S SLIDING DOOR UPPER ROLLER BRACKET (WCP)	SERVICEABLE	100.00	-
1	N/S SLIDING DOOR CENTRE ROLLER (WCP)	DISTORTED	100.00	100.00
1	N/S SLIDING DOOR LOWER ROLLER (WCP)	DISTORTED	115.00	115.00
1	N/S SLIDING DOOR UPPER GUIDE RAIL ASSY (WCP)	SERVICEABLE	190.00	-
1	N/S SLIDING DOOR CENTRE GUIDE RAIL ASSY (WCP)	SERVICEABLE	220.00	-
1	N/S SLIDING DOOR LOWER GUIDE RAIL ASSY (WCP)	SERVICEABLE	480.00	-
1	N/S SLIDING DOOR CHECKER (WCP)	CRACKED	55.00	55.00
1	N/S SLIDING DOOR WEATHERSTRIP (WCP)	CUT	185.00	185.00
1	N/S SLIDING DOOR DORETAIL-MAIL (WCP)	SERVICEABLE	125.00	-
1	N/S SLIDING DOOR DORETAIL-FEMALE (WCP)	SERVICEABLE	140.00	-
1	N/S SLIDING DOOR INNER TRIM (WCP)	BUCKLED	390.00	390.00
18	N/S SLIDING DOOR INNER TRIM CLIPS @ \$3.00 (WCP)	NOT NECESSARY	54.00	-
1	N/S SLIDING DOOR OUTER HANDLE (WCP)	DENTED	100.00	100.00
1	N/S SLIDING DOOR OUTER HANDLE SEAL (WCP)	SERVICEABLE	10.00	-
1	N/S SLIDING DOOR INNER HANDLE (WCP)	SERVICEABLE	85.00	-
1	N/S SLIDING DOOR LOCK CONTROL (WCP)	JAMMED	220.00	220.00
1	N/S SLIDING DOOR LOCK - FRONT (WCP)	DENTED	140.00	140.00
1	N/S SLIDING DOOR LOCK - REAR (WCP)	DENTED	165.00	165.00
1	N/S SLIDING DOOR LOCK CATCH - FRONT (WCP)	DISTORTED	50.00	50.00
1	N/S SLIDING DOOR LOCK CATCH - REAR (WCP)	SERVICEABLE	50.00	-
1	N/S SLIDING DOOR CONNECTOR ASSY - MALE (WCP)	CRACKED	145.00	145.00
1	N/S SLIDING DOOR CONNECTOR ASSY - FEMALE (WCP)	DISTORTED	155.00	155.00
1	N/S SLIDING DOOR SWITCH ASSY (WCP)	SERVICEABLE	45.00	-
1	N/S REAR BODY PANEL (WCP)	TO REPAIR SEE LABOUR	1,150.00	-
1	TAILGATE (WCP)	BENT	1,100.00	1,100.00
1	TAILGATE THIRD BRAKE LIGHT (WCP)	SERVICEABLE	190.00	-
1	TAILGATE LOGO (WCP)	NECESSARY	55.00	55.00
1	TAILGATE "NV350" EMBLEM (WCP)	NECESSARY	85.00	85.00
2	TAILLAMP ASSY (LH/RH) @ \$130.00 (WCP)	O/S CRACKED	260.00	130.00
1	REAR BUMPER (WCP)	BENT	330.00	330.00
3	O/S REAR BUMPER SIDE RETAINER @ \$15.00 (WCP)	O/S DISTORTED	45.00	15.00

Report Ref No. CS/GAI19009001/Kqd3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
10	O/S REAR BUMPER CLIPS @\$2.00 (WCP)	NECESSARY	20.00	20.00
1	N/S FRONT UPPER ARM (WCP)	SERVICEABLE	205.00	-
1	N/S FRONT KNUCKLE ARM (WCP)	SERVICEABLE	300.00	-
1	N/S FRONT KNUCKLE ARM BEARING (WCP)	SERVICEABLE	160.00	-
1	N/S FRONT BEARING HUB (WCP)	SERVICEABLE	340.00	-
1	N/S FRONT LOWER ARM (WCP)	SERVICEABLE	180.00	-
1	N/S FRONT LOWER ARM BALL JOINT (WCP)	SERVICEABLE	85.00	-
1	N/S FRONT STABILIZER BAR LINKAGE (WCP)	SERVICEABLE	90.00	-
1	N/S FRONT SHOCK ABSORBER (WCP)	SERVICEABLE	125.00	-
	COST PLUS 10%		1,444.40	745.50
			15,888.40	8,200.50
	SPECIAL NETT ITEMS			
1	N/S FRONT DOOR COMPANY REGISTRATION STICKER (SN)	NECESSARY	25.00	25.00
1	TAILGATE WINDSCREEN GLASS SEALANT (SN)	NECESSARY	40.00	40.00
1	TAILGATE WINDSCREEN GLASS DAMPLING SEAL (SN)	NECESSARY	20.00	20.00
1	TAILGATE "70KM/H" STICKER (SN)	NECESSARY	25.00	15.00
1	TAILGATE "8PAX" STICKER (SN)	NECESSARY	25.00	15.00
1	REVERSE SENSOR (SN)	SERVICEABLE	220.00	-
1	N/S FRONT TYRE (SN)	SERVICEABLE	220.00	-
1	N/S FRONT RIM (SN)	SERVICEABLE	280.00	-
			855.00	115.00
	LABOUR			
	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW AFFECTED PARTS. INCLUSIVE OF THE REPAIR OF N/S FRONT DOOR HINGE TOP, N/S FRONT DOOR HINGE BOTTOM, N/S FRONT DOOR LOCK CATCH, N/S FRONT DOOR OUTER PILLAR AND N/S REAR BODY PANEL.		1,900.00	1,600.00
	TO FOCUS TAILLAMPS. TO CHECK REAR WIRING AND LIGHTING OPERATION.		50.00	40.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.		120.00	120.00
	TO REMOVE AND REFIT REAR UPHOLSTERY TRIMMING, ROOF LINING, SEATS, SPEAKER BOARD IN ORDER TO FACILITATE WORKS.		120.00	100.00

Report Ref No. CS/GAI19009001/Kqd3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT FRONT SEAT ASSY TRIM BAORD AND CARPET TO FACILITATE REPAIRING WORKS.		180.00	100.00
	TO REMOVE AIRCON CONDENSER, PIPES AND DRIERS. VACUUM AND RECHARGE GAS.	NOT NECESSARY	100.00	-
	TO REMOVE FRONT INSTRUMENT PANEL ASSY AND REWIRING TO FACILITATE REPAIR WORKS.	NOT NECESSARY	280.00	-
	TO REMOVE DOOR'S FITTINGS.		100.00	60.00
	TO REMOVE AND TRANSFER ELECTRICAL SLIDING DOOR. TO RE-WIRING AND RE-SETTING.		300.00	80.00
	TO DISMANTLE AND CHECK FRONT UNDERCARRIGES. TO REPLACE AFFECTED PORTIONS.	NOT NECESSARY	150.00	-
	TO CONDUCT FRONT WHEEL ALIGNMENT TEST.		100.00	60.00
	TO TRANSFER TAILGATE'S FITTINGS.		100.00	60.00
	TO REMOVE AND REFIT REVERSE SENSOR ASSY.		80.00	50.00
	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.		1,600.00	1,400.00
			5,180.00	3,670.00
GRAND TOTAL			21,923.40	11,985.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				9,600.00
LESS EXCESS				-600.00
NETT LIABILITY				9,000.00

Report Ref No. CS/GAI19009001/Kqd3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.