

Your Reference : MOMVC000007886-00-000
Accident Date : 15-May-2019

No. : 30466

Date : 17-May-2019

Our Ref : 190258 / SANDRA

PAGE : 1

GREAT AMERICAN INSURANCE COMPANY
3 TEMASEK AVE #16-01
CENTENNIAL TOWER
Singapore 039190

ESTIMATED COST OF REPAIR FOR NISSAN NV350 PANEL VAN 2.5 (2015) GBD8436D
=====

1 pc	n/s front door	690.00 c
1 pc	n/s front door hinge top	65.00 c
1 pc	n/s front door hinge bottom	65.00 c
1 pc	n/s front door checker	50.00 c
1 pc	n/s front door weatherstrip	85.00 c
1 pc	n/s front door lower seal	45.00 c
1 pc	n/s front door frame weather strip	115.00 c
1 pc	n/s front door window glass	380.00 c
1 pc	n/s front door window glass regulator	130.00 c
1 pc	n/s front door window glass motor	300.00 c
1 pc	n/s front door window glass run channel	75.00 c
1 pc	n/s front door window glass run channel sash	65.00 c
1 pc	n/s front door window glass outer moulding	90.00 c
1 pc	n/s front door window glass inner moulding	55.00 c
1 pc	n/s front door lock	125.00 c
1 pc	n/s front door lock catch	50.00 c
1 pc	n/s front door outer handle	115.00 c
1 pc	n/s front door inner handle	60.00 c
1 pc	n/s front door inner trim board	380.00 c

Con't Page 2 ...

Your Reference : MOMVC000007886-00-000
Our Ref : 190258

Page : 2
No. : 30466

1 pc	n/s front door switch	45.00	c
1 pc	n/s front door outer pillar	800.00	c
1 pc	n/s sliding door outer pillar	800.00	c
1 pc	n/s sliding door step floor panel	600.00	c
1 pc	n/s front mudflap	150.00	c
1 pc	n/s sliding door	1,000.00	c
1 pc	n/s sliding door upper roller	70.00	c
1 pc	n/s sliding door upper roller bracket	100.00	c
1 pc	n/s sliding door centre roller	100.00	c
1 pc	n/s sliding door lower roller	115.00	c
1 pc	n/s sliding door upper guide rail assy	190.00	c
1 pc	n/s sliding door centre guide rail assy	220.00	c
1 pc	n/s sliding door lower guide rail assy	480.00	c
1 pc	n/s sliding door checker	55.00	c
1 pc	n/s sliding door weatherstrip	185.00	c
1 pc	n/s sliding door doretail-male	125.00	c
1 pc	n/s sliding door doretail female	140.00	c
1 pc	n/s sliding door inner trim	390.00	c
18 pcs	n/s sliding door inner trim clips @ S\$ 3.00	54.00	c
1 pc	n/s sliding door outer handle	100.00	c
1 pc	n/s sliding door outer handle seal	10.00	c
1 pc	n/s sliding door inner handle	85.00	c
1 pc	n/s sliding door lock control	220.00	c
1 pc	n/s sliding door lock-front	140.00	c
1 pc	n/s sliding door lock-rear	165.00	c
1 pc	n/s sliding door lock catch - front	50.00	c
1 pc	n/s sliding door lock catch - rear	50.00	c

Con't Page 3 ...

Your Reference : MOMVC000007886-00-000
Our Ref : 190258

Page : 3
No. : 30466

1 pc	n/s sliding door connector assy-male	145.00	c
1 pc	n/s sliding door connector assy-female	155.00	c
1 pc	n/s sliding door switch assy	45.00	c
1 pc	n/s rear body panel	1,150.00	c
1 pc	tailgate	1,100.00	c
1 pc	tailgate third brake light	190.00	c
1 pc	tailgate logo	55.00	c
1 pc	tailgate "NV350"emblem	85.00	c
2 pcs	taillamp assy (LH/RH) @ S\$130.00	260.00	c
1 pc	rear bumper	330.00	c
3 pcs	o/s rear bumper side retainer @ S\$ 15.00	45.00	c
10 pcs	o/s rear bumper clips @ S\$ 2.00	20.00	c
1 pc	n/s front upper arm	205.00	c
1 pc	n/s front knuckle arm	300.00	c
1 pc	n/s front knuckle arm bearing	160.00	c
1 pc	n/s front bearing hub	340.00	c
1 pc	n/s front lower arm	180.00	c
1 pc	n/s front lower arm ball joint	85.00	c
1 pc	n/s front stablizer bar linkage	90.00	c
1 pc	n/s front shock absorber	125.00	c

		14,444.00	
Add 10% :		1,444.40	

		15,888.40	
1 pc	n/s front door company registration sticker	25.00	sn
1 pc	tailgate windscreen glass sealant	40.00	sn
1 pc	tailgate windscreen glass damppling seal	20.00	sn
1 pc	tailgate "70 km/h" sticker	25.00	sn
1 pc	tailgate "8pax" sticker	25.00	sn
1 pc	reverse sensor	220.00	sn

Con't Page 4 ...

Your Reference : MOMVC000007886-00-000
Our Ref : 190258

Page : 4
No. : 30466

1 pc n/s front tyre	220.00 sn
1 pc n/s front rim	280.00 sn
To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.	1,900.00
To focus taillamps. To check rear wiring and lighting operation.	50.00
To remove and refit rear windscreen glass and conduct water leak test	120.00
To remove and refit rear upholstery trimming, roof lining, seats, speaker board in order to facilitate repairing works	120.00
To remove and refit front seat assy trim board and carpet to facilitate repairing works	180.00
To remove aircon condenser, pipes and driers. Vaccum and recharge gas	100.00
To remove front instrument panel assy and rewiring to facilitate repair works.	280.00
To remove door's fittings	100.00
To remove and transfer electrical sliding door. To re-wiring and re-setting	300.00
To dismantle and check front under- carriages. To replace affected portions.	150.00

Con't Page 5 ...

Your Reference : MOMVC000007886-00-000
Our Ref : 190258

Page : 5
No. : 30466

To conduct front wheel alignment test.	100.00
--	--------

To transfer tailgate's fittings	100.00
---------------------------------	--------

To remove and refit reverse sensor assy.	80.00
--	-------

To putty and respray on affected portions.	1,600.00
--	----------

Total :	----- S\$21,923.40 =====
---------	--------------------------------

Singapore Dollars Twenty One Thousand Nine Hundred
and Twenty Three and Cents Forty Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.