



Case Details

Case Reference Number : TAX/05/19/2066
Type of Repair : Accident Repair
Vehicle Registration Number : SHB5823D

Company Type : SMRT Taxis Pte Ltd
Estimation ID : EST-6882-ID
Assigned By : Taxi Claims Manager Team

Insurance Company Name : EQ Insurance Company Ltd
Accident Date and Time : 14/05/2019 12:30 PM
Vehicle Age(In Months) : 17

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	0	Repair ▾	
One Time Key In	Main			COVER, FR BUMPER LH	1	28.10	28.10	25.00	21.08	Replace	0	0	Not Give ▾	
One Time Key In	Main			COVER, FR BUMPER RH	1	28.10	28.10	25.00	21.08	Replace	0	0	Not Give ▾	
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace ▾	
One Time Key In	Main			GRILLE SUB-ASSY	1	335.60	335.60	25.00	251.70	Replace	0	0	Not Give ▾	
One Time Key In	Main			EMBLEM ASSY FRONT	1	87.10	87.10	25.00	65.32	Replace	0	0	Not Give ▾	
One Time Key In	Main			GRILLE, RADIATOR	1	165.00	165.00	25.00	123.75	Replace	0	0	Not Give ▾	
One Time Key In	Main			SUPPORT, FR BUMPER LH	1	82.30	82.30	25.00	61.72	Replace	0	0	Not Give ▾	

Total Spare Part Cost 5,471.58

Surveyor Total 3,133.44

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 5,471.58

Final Sur Total 3,133.44

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SUPPORT, FR BUMPER RH	1	76.90	76.90	25.00	57.68	Replace	0	0	Not Give	
One Time Key In	Main			ABSORBER, FR BUMPER	1	70.30	70.30	25.00	52.72	Replace	0	0	Not Give	
One Time Key In	Main			REINFORCEMENT FRONT UPPER	1	691.10	691.10	25.00	518.33	Replace	0	0	Not Give	
One Time Key In	Main			ABSORBER, FR BUMPER LOWER	1	117.00	117.00	25.00	87.75	Replace	0	0	Not Give	
One Time Key In	Main			REINFORCEMENT FRONT LOWER	1	238.50	238.50	25.00	178.88	Replace	0	0	Not Give	
One Time Key In	Main			EXTENSION SUBASSY, LH	1	116.30	116.30	25.00	87.22	Replace	0	0	Not Give	
One Time Key In	Main			EXTENSION SUBASSY, RH	1	116.30	116.30	25.00	87.22	Replace	0	0	Not Give	
One Time Key In	Main			LAMP ASSY, FOG, RH	1	910.20	910.20	10.00	819.18	Replace	1	819.18	Replace	
One Time Key In	Main			SUPPORT, RADIATOR UPPER RH	1	76.70	76.70	25.00	57.53	Replace	0	0	Not Give	
One Time Key In	Main			UNIT, HEADLAMP , RH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	1	2,303.01	Replace	
One Time Key In	Main			LINER, FR FENDER, RH	1	198.40	198.40	25.00	148.80	Replace	0	0	Not Give	
One Time Key In	Main			LINER, FR FENDER, LH	1	194.30	194.30	25.00	145.73	Replace	0	0	Not Give	
Total Spare Part Cost									5,471.58		Surveyor Total		3,133.44	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)		0	
Final Spare Part Cost									5,471.58		Final Sur Total		3,133.44	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			338.00	200.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT PORTION	338.00	200	
Total:			338.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT SUPPORT PANEL	180.00	0	
Total:			558.00	200.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
2	Main	TO REMOVE AND REFIT WIRE HARDESS	120.00	0	
3	Main	TO WASH AND VACUUM	60.00	0	
Total:			260.00	20.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	5,471.58	3,133.44
Total Labour Cost	338.00	200.00
Total Spray Painting	558.00	200.00
Other	260.00	20.00
Overall Total	6,627.58	3,553.44
Lump Sum Repair Option	☐	☐
Lump Sum Total	0.00	3,553.44
Surveyor Approved Amount		3,553.44
No of Repair Days*	5	3

Estimator Assesment(\$)

Surveyor Assesment(\$)

Remarks

p/p repair, photo before paint.

Surveyor Name

Hwee jie

Signature



Save

Clear

Survey Date

17/05/2019

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: