



Cecilia

Section A - Accident Details

Registration Number	SHB5823D
Case Reference Number	TAX/05/19/2066
Registration Date	12/12/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	YONG KOK WAH
Type of Accident	Side Swipe
Accident Date and Time	14/5/2019 8:30 PM
Accident Reported Date and Time	15/5/2019 9:48 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	24101514
Special Instruction to ARC, if any	TP
Prepared Date and Time	15/5/2019 2:53 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$338.00	\$200.00
Total Spray Cost	\$558.00	\$200.00
Total Spare Part Cost	\$5,471.58	\$3,133.44
Total Other Cost	\$260.00	\$20.00
TOTAL COST	\$6,627.58	\$3,553.44 (P/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie(LKK) / EQ
ARC / Surveyor Sign Off Date	15/05/2019 3:44 PM	17/05/2019 2:18 PM
Signature		
Remarks	p/p repair, photo before paint.	

P/P \$3553.44 / 3 days.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1905-0459	Invoice Number	
Quotation Date	25.05.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	\$338.00	\$200.00
Total Labour	\$338.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$558.00	\$200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO REMOVE AND REFIT WIRE HARDESS	\$120.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$260.00	\$20.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119479 62	COVER, FR BUMPER	1.00	\$495.50	100.00	\$0.00	Replace	Approved Repair
		52128479 06	COVER, FR BUMPER LH	0.00	\$28.10	0.00	\$0.00	Replace	Not Given
		52127479 07	COVER, FR BUMPER RH	0.00	\$28.10	0.00	\$0.00	Replace	Not Given
		52161160 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace
		53101470 80	GRILLE SUB-ASSY	0.00	\$335.60	0.00	\$0.00	Replace	Not Given
		75310470 60	EMBLEM ASSY FRONT	0.00	\$87.10	0.00	\$0.00	Replace	Not Given
		53112472 40	GRILLE, RADIATOR	0.00	\$165.00	0.00	\$0.00	Replace	Not Given
		52116470 50	SUPPORT, FR BUMPER LH	0.00	\$82.30	0.00	\$0.00	Replace	Not Given
		52115470 50	SUPPORT, FR BUMPER RH	0.00	\$76.90	0.00	\$0.00	Replace	Not Given
		52611471 40	ABSORBER, FR BUMPER	0.00	\$70.30	0.00	\$0.00	Replace	Not Given
		52021471 10	REINFORCEMENT FRONT UPPER	0.00	\$691.10	0.00	\$0.00	Replace	Not Given
		52618470 90	ABSORBER, FR BUMPER LOWER	0.00	\$117.00	0.00	\$0.00	Replace	Not Given
		52132470 10	REINFORCEMENT FRONT LOWER	0.00	\$238.50	0.00	\$0.00	Replace	Not Given
		52103470 10	EXTENSION SUBASSY, LH	0.00	\$116.30	0.00	\$0.00	Replace	Not Given
		52102470 20	EXTENSION SUBASSY, RH	0.00	\$116.30	0.00	\$0.00	Replace	Not Given
		81210470 20	LAMP ASSY, FOG, RH	1.00	\$910.20	10.00	\$819.18	Replace	Replace
		53213470 50	SUPPORT, RADIATOR UPPER RH	0.00	\$76.70	0.00	\$0.00	Replace	Not Given
		81145476 91	UNIT, HEADLAMP, RH	1.00	\$2,558.90	10.00	\$2,303.01	Replace	Replace
		53875470 70	LINER, FR FENDER, RH	0.00	\$198.40	0.00	\$0.00	Replace	Not Given
		53876471 10	LINER, FR FENDER, LH	0.00	\$194.30	0.00	\$0.00	Replace	Not Given
Total					\$6,588.10		\$3,133.44		

3133.44
 + 200.00
 + 220.00
 3553.44