

ASS. REC BY: Sebastian REF: CS/EG17024463/Nrd302
From (Person): Yee Pei Li of EGI ASSIGNMENT (Office):
Date/Time: 4:12pm @ 27/12/17

Estimated Cost:

Bill to:

GD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGH 6754T Insured: YM 7813K

at Workshop m/z Lai Huiat (Meng Kee) Tel: 6453 8110

of 160 Sin Ming drive #04-01

Policy No: _____ Claim No: DSMF P1703060

Sum Insured: _____ Excess: _____

Make of Veh: _____
(Client's Record)

D.O.A. 22/12/2017

CA / REV / REP. / REV 24 HRS

(wp)

H.O.D. Endorsement: _____

Vehicle IN/OUT

Date/Time: 10:21am @ 27/12/17 Person Contacted: Jenny

Date/Time Action/Instruction (✓) Estimate

SGH 6754T-X

YM 7813K-CC4/AIG09010276/Kn1vn D.O.A: 06/05/2009

24/1/18 Sent preli through email.

15/11/18 Confirm with Jenny L/S \$5850.00 @ 12 days (Ref: \$1755.40, 23%)

REF:

31604

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of:

Insured:

Policy No:

Claims No:

Sum insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Soon:

Consistent? : Yes or No

Est. Repairs:

12

days

Res.:

Yes or No

Lump Sum:

70

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time / Action / Instruction

Veh No:

34H 67547

Yr Regn:

12/6/2006

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Nios

cc 1497

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp Reading:

107675

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MA015144204/92972

(Dear JM, No
Chap's Number
Photo)

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

175 / 65 R14

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

8

mm

R/Bal:

8

mm

L/Bal:

8

mm

L/Bal:

8

mm

D.O.A:

22/11/2017

D.O.I:

27/11/2017

Survey held at

Lai Thut Meng Kee

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

RECEIVED 15 NOV 2010

L/S \$5850.00 with 12 repair days

Laid = \$1875.00 / 20/11/10

12 repair days + 2 Sundays = 14 days

CaseTime, File Pass to?



Preli. Report

1) Typist



Final Report

CaseTime, File Return to?

2)

Report Format:

Lump Sum / H&T: (\$

TP
5850

Days Of Repair:

12

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Insp (\$



Weekend (\$

Survey Fee:

Transportation

) \$ + RS. \$

) Photos

) Copies

TOTAL

250

250



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD			Ref : CS/EGI17024463/Srd3	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985			Date : 27-12-2017	
			Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YM 7813K	Veh. Inspected	SGH 6754T	
Policy No.		Coverage (\$)	0.00	
Claim No.	DSMFP1703060	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	27/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	22/12/2017	Inspection Date	27/12/2017	
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sini Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

SUPPLEMENTARY

EST. No EST0018136
Sebastian Stella

Page 1 of 1
Your ref. TP-YM 7813K ERGO
Job No 69102
Our ref 17.12.32
Payment
Date 10/1/2018

Attn

Vehicle No SGH 6754T
Vehicle Model Toyota Vios
Accident on 22/12/2017

Quantity	Unit	Description	Unit price	Disc. pct	Amount
Supply of Parts.					
SUPPLEMENTARY ITEM.					
2.00	Pcs	Front shock absorber	444.80 222.40	25.00	333.60
2.00	Pcs	Rear shock absorber	350.6 175.30	25.00	262.95
2.00	Pcs	Front shock absorber support	124.40 62.20	25.00	93.30
2.00	Pcs	Suspension arm	453.2 226.10	25.00	339.15
					1029
1.00		Labour to remove and renew suspension, etc	320.00		320.00

2664

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer _____
Signature: _____
Date: _____

Sub-Total 1,349.00
GST 7.00% 94.43
Total S\$ 1,443.43

本公司拥有最先进的 CAROLINER MARK IV 机械。可提供给多种款式的车身及给予快速与准确的测量方式和大快修理。此外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."



Reg No : 196700086Z
 Reg No : MR-8500000-9

TAX INVOICE

Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive item!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyota-singapore.com.sg

Toyota Bodycare Centre
 No. 2 Pandan Crescent
 Singapore 128462
 Tel no: 6631 1188

Account Detail	Account No	Customer Detail
Bodyshop Retail Cash Sales Pandan TCBC Toyota	c0110038 / PBPREG	Ms Sebastian Stella
Bodyshop Retail Cash Sales	Document No	90 Dawson Road
Pandan TCBC Toyota	38021209	#17-14
	Document Date	Singapore 142090
	23/12/2017	Mobile: 96227969

Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
EEPSKT FL	NCP42R	19/06/2006	SGH6754T	107486	28910	66/CASH/SGH6754T
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On
13HY4204192517	1NEX443330	00	Shashitharan	--/--/----	0.00	--/--/---- 0.00

Qty	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	BP-LAB TOWING FEES *				80.00
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.					

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 0.00	80.00
		Labour 80.00	GST 7.00% 5.60
		Materials 0.00	Less 0.00
		Lubrication/Fluid 0.00	
		Others 0.00	
		0.00	Amount Due 85.60

PLEASE TEAR ALONG PERFORATED LINE

3545077

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679. Tel: 6433 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0018136
Sebastian Stella

Page 1 of 3
Your ref. TP-YM 7813K ERGO
Job No 69102
Our ref 17.12.32
Payment
Date 26/12/2017

Attn

Vehicle No SGH 6754T
Vehicle Model : Toyota Vios
Accident on ... 22/12/2017

Quantity	Unit	Description	Unit price	Disc. pct	Amount
Supply of Parts:					
1.00	Pc	Front fender LH ✓ BT	170.60	25.00	127.95
1.00	Pc	Front fender inner shield LH ✓ Deface	23.50	25.00	17.63
10.00	Pcs	Front fender inner shield clips LH ✓ NEC	3.00	25.00	22.50
1.00	Pc	Front fender signal lamp LH ✓ CRK	25.50	25.00	19.13
1.00	Pc	Front fender top side cover LH ✓ CRK	25.90	25.00	19.43
1.00	Pc	Front door LH ✓ PWN	1,208.00	25.00	906.00
1.00	Pc	Front door protector LH ✓ BT	58.90	25.00	44.18
1.00	Pc	Front door outer moulding LH ✓ NEC	29.90	25.00	22.43
1.00	Pc	Front door outer lock handle LH ✓ MS	61.95	25.00	46.46
1.00	Pc	Front door outer key lock cover LH ✓ MS	24.35	25.00	18.26
1.00	Pc	Front door lock LH ✓ BMS	415.40	25.00	311.55
1.00	Pc	Front door window weatherstrip LH ✓ NEC	49.90	25.00	37.43
1.00	Pc	Front door key lock LH ✓ BMS	93.50	25.00	70.13
1.00	Pc	Front door outer handle holder LH ✓ MS	148.30	25.00	111.23
1.00	Pc	Front door window glass LH ✓ CRK	102.20	25.00	76.65
1.00	Pc	Front door window regulator LH ? PHOTO	110.00	25.00	83.18 ✓
1.00	Pc	Front door window channel LH ✓ BT	88.20	25.00	66.15
1.00	Pc	Front door top hinge LH ✓ BT	87.30	25.00	65.48

2065.77 ✓

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大快修理。
此外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0018136
Sebastian Stella

Page 2 of 3
Your ref. TP-YM 7813K ERGO
Job No 69102
Our ref 17.12.32
Payment
Date 26/12/2017

Attn

Vehicle No SGH 6754T
Vehicle Model : Toyota Vios
Accident on : 22/12/2017

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00	Pc	Front door lower hinge LH ✓ BT	83.10	25.00	62.33
1.00	Pc	Front door wing mirror LH assy ✓ MS	175.90	25.00	131.93
1.00	Pc	Front door weatherstrip LH ✓ MS	49.90	25.00	37.43
1.00	Pc	Rear door LH ✓ Defor	1,295.14	25.00	971.36
1.00	Pc	Rear door protector LH ✓ NEC	49.80	25.00	37.35
1.00	Pc	Rear door top hinge LH ✓ BT	87.20	25.00	65.40
1.00	Pc	Rear door lower hinge LH ✓ BT	83.10	25.00	62.33
Nett item:					
1.00	Pc	Front fender signal lamp chrome ring LH ✓ cut	25.00	10.00	22.50
1.00	Pc	Front sport rim LH (14") ✓ cut	200.00	10.00	180.00
					1570.63
Special nett item:					
1.00	Pc	Front tyre LH (Michelin-175 65 R14) 80% ✓ PUN	130.00	104 (SN) 130.00	
Labour & Misc.					
1.00		Towing charge ✓	80.00		80.00 ✓

本公司拥有最先进的 CAROLINER MARK IV 机械。可提供给多种款式的车身及给予快速与准确的测量方式和大概修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICC Deluxe oven heater for re-spraying all motor vehicles."

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0018136
Sebastian Stella

Page 3 of 3
Your ref. TP-YM 7813K ERGO
Job No. 69102
Our ref. 17.12.32
Payment
Date 26/12/2017

Attn

Vehicle No SGH 6754T
Vehicle Model : Toyota Vios
Accident on : 22/12/2017

Quantity	Unit	Description	Unit price	Disc. pct	Amount
1.00		To check wheel alignment	60.00	✓	60.00
1.00		To remove and refix front and rear passenger seat, carpet, etc	150.00	120	150.00 120
1.00		To knock dents front door pillar LH, front door inner pillar LH, centre pillar LH, centre inner pillar LH, rocker panel LH and renew of parts	1,100.00	1000	1,100.00 1000
1.00		To spray paint	1,100.00	1150	1,100.00

2360

12 days

Sebastian
27/12/2017
- Lump Sum Repair.
- Photos After Paint.
- Question Mark Items Photo.
90086121

sebastiansg@ktauto.com

Sub-Total 6,266.40
GST 7.00% 437.95
Total S\$ 6,694.35

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大概修理。
除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

788540

Vehicle Ident no.
SGH 6754 T

Date
30.12.17 13:50

Odometer reading: km/miles
109675

			Before	Target Data		Actual
Rear axle	Camber	left	-1°03'	-0°55'	+/-0°25'	-1°03'
		right	-0°48'			-0°48'
		cross	-0°15'	0°00'	+/-0°30'	-0°16'
	Toe	left	0°04'	0°10'	+/-0°08'	0°04'
		right	0°20'			0°20'
		total	0°24'	0°19'	+/-0°15'	0°24'
	Geometrical driving axis		-0°08'	0°00'		-0°08'
Front axle	Camber	left	-1°18'	-0°35'	+/-0°45'	-1°18'
		right	-0°51'			-0°51'
		cross	-0°27'	0°00'	+/-0°30'	-0°27'
	Caster	left	2°14'	1°38'	+/-0°45'	2°14'
		right	1°14'			1°14'
		cross	1°01'	0°00'	+/-0°30'	1°01'
	SAI	left	10°31'	10°05'	+/-0°45'	10°32'
		right	10°30'			10°31'
		cross	0°01'	0°00'	+/-0°30'	0°01'
	Track differential angle	left				
		right				
	Toe	left	0°15'	0°00'	+/-0°05'	0°03'
		right	-0°24'			-0°03'
		total	-0°40'	0°00'	+/-0°12'	0°06'
	Setback			0°00'		
	Max steering lock	left steer		-35°47'	+/-2°00'	
		right		31°33'	+/-2°00'	
		left		31°33'	+/-2°00'	
		right steer		-35°47'	+/-2°00'	

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

Est No EST0016136
Estimation Status

Page 1 of 3
Your ref TP-YM 7813K ERGO
Job No 69102
Our ref 17-12-32
Payment
Date 26/12/2017

Vehicle No SGH 6754T
Vehicle Model Toyota Vios
Insured on 22/12/2017

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts					
1.00	Pc	Front fender LH ✓ BT	170.60	25.00	127.95
1.00	Pc	Front fender inner shield LH ✓ Defom	23.50	25.00	17.63
10.00	Pcs	Front fender inner shield clips LH ✓ NEC	3.00	25.00	22.50
1.00	Pc	Front fender signal lamp LH ✓ CRK	25.50	25.00	19.13
1.00	Pc	Front fender top side cover LH ✓ cut	25.90	25.00	19.43
1.00	Pc	Front door LH ✓ PUN	1,208.00	25.00	906.00
1.00	Pc	Front door protector LH ✓ BT	58.90	25.00	44.18
1.00	Pc	Front door outer moulding LH ✓ NEC	29.90	25.00	22.43
1.00	Pc	Front door outer lock handle LH ✓ MS	61.95	25.00	46.46
1.00	Pc	Front door outer key lock cover LH ✓ MS	24.35	25.00	18.26
1.00	Pc	Front door lock LH ✓ DMG	415.40	25.00	311.55
1.00	Pc	Front door window weatherstrip LH ✓ NEC	49.90	25.00	37.43
1.00	Pc	Front door key lock LH ✓ DMG	93.50	25.00	70.13
1.00	Pc	Front door outer handle holder LH ✓ MS	148.30	25.00	111.23
1.00	Pc	Front door window glass LH ✓ CRK	102.20	25.00	76.65
1.00	Pc	Front door window regulator LH ✓ X NN	110.90	25.00	83.18
1.00	Pc	Front door window channel LH ✓ BT	88.20	25.00	66.15
1.00	Pc	Front door top hinge LH ✓ BT	87.30	25.00	65.48

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大快修理。
此外，还有先进的 SAICO Deluxe 喷漆烘炉。

Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles.

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST No: EST0018136
Customer: Stella

Page: 2 of 3
Your ref: TP-YM 7813K ERGO
Job No: 69102
Our ref: 17.12.32
Payment:
Date: 26/12/2017

Vehicle No: SGH 6754T
Vehicle Model: Toyota Vios
Estimate on: 22/12/2017

Quantity	Unit	Description	Unit price	Disc pct	Amount
1.00	Pc	Front door lower hinge LH ✓ BT	83.10	25.00	62.33
1.00	Pc	Front door wing mirror LH assy ✓ MS	175.90	25.00	131.93
1.00	Pc	Front door weatherstrip LH ✓ NEC	49.90	25.00	37.43
1.00	Pc	Rear door LH ✓ Deform	1,295.14	25.00	971.36
1.00	Pc	Rear door protector LH ✓ NEC	49.80	25.00	37.35
1.00	Pc	Rear door top hinge LH ✓ BT	67.20	25.00	50.40
1.00	Pc	Rear door lower hinge LH ✓ BT	83.10	25.00	62.33
Nett item					
1.00	Pc	Front fender signal lamp chrome ring LH ✓ Cut	25.00	10.00	22.50
1.00	Pc	Front sport rim LH (14") ✓ Cut	200.00	10.00	180.00
Special nett item:					
1.00	Pc	Front tyre LH (Michelin-175 65 R14) 80% ✓ PUN	130.00	10%	117.00
Labour & Misc: 5 x NN					
1.00		Towing charge ✓	80.00		80.00

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大快修理。
此外, 还有先进的 SAICO Deluxe 喷漆烘炉。

Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support fully system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST No EST0018136
Estimation Site

Page 3 of 3
Your ref TP-YM 7813K ERGO
Job No 69102
Our ref 17.12.32
Payment
Date 26/12/2017

Vehicle No SGH 6754T
Vehicle Model Toyota Vios
Accident on 22/12/2017

Quantity	Unit	Description	Unit price	Disc pvt	Amount
1.00		To check wheel alignment	60.00	✓	60.00
1.00		To remove and refix front and rear passenger seat, carpet, etc	150.00 120.		150.00
1.00		To knock dents front door pillar LH, front door inner pillar LH, centre pillar LH, centre inner pillar LH, rocker panel LH and renew of parts	1,100.00 1,000		1,100.00
1.00		To spray paint	1,100.00 1,100		1,100.00

12 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sebastian
27/12/2017.

- Lung Sun Repair.
- Photo After Paint.
- Question Mark Item Photo.

90036121

sebastianyang@lkkauto.com

4467.54
25%

3350.66

+ 202.5

+ 2464.0

6017.16

20%

4813.73

Sub-Total

GST 7.00%

Total

∴ L/s \$4800 @ 12 days

7605.41

6,258.40

437.95

6,696.35

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。
还有先进的 SAICO Deluxe 喷漆烘炉。

Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support jolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles.

2016-21

7106.21

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3160H
Vehicle Details	
Vehicle No.:	SGH6754T
Vehicle to be Exported:	No
Intended De-registration Date:	28 Dec 2017
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS 1.5E A
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	1NZX443330
Chassis No.:	MR053HY4204192517
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,707.00
Original Registration Date:	19 Jun 2006
First Registration Date:	19 Jun 2006
Transfer Count:	0
Actual ARF Paid:	\$13,978.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	

COE Expiry Date:	18 Jun 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$23,227.00
COE Rebate Amount:	\$16,141.00
Total Rebate Amount:	\$16,141.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 28 Dec 2017

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 3160H

Vehicle Details

Vehicle No.: SGH6754T
Vehicle to be Exported: Yes
Intended De-registration Date: 23 Dec 2017
Vehicle Make: TOYOTA
Vehicle Model: VIOS 1.5E A
Primary Colour: Silver
Manufacturing Year: 2006
Engine No.: 1NZX443330
Chassis No.: MR053HY4204192517
Maximum Power Output: 80.0 kW (107 bhp)
Open Market Value: \$12,707.00
Original Registration Date: 19 Jun 2006
First Registration Date: 19 Jun 2006
Transfer Count: 0
Actual ARF Paid: \$13,978.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 18 Jun 2021
COE Category: A - Car (1600cc & below)
COE Period(Years): 5
PQP Paid: \$23,227.00
COE Rebate Amount: \$16,203.00
Total Rebate Amount: \$16,203.00

Message

REPUBLIC OF SINGAPORE DRIVING LICENCE

11 JUN 1965

SEBASTIAN STELLA

11 JUN 1965

10 May 2003

000415550

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S1693160H

Name

SEBASTIAN STELLA

செபாஸ்தியன் ஸ்டெல்லா

Race

INDIAN

Date of Birth

11-06-1965

Sex

F

Country of Birth

SINGAPORE

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

VALID DATE

27 Apr 1994

Licence No: S1693160H

NP 428A

1285921

33664

Barcode

NRIC No: S1693160H

Printed Group

A-

Date of issue

16-05-1993

APT BLK 90 DAWSON ROAD #17-14

SINGAPORE 142060

NPIC No: S1693160H

Date: 04/04/2016

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Tuesday, 26 December, 2017 4:12 PM
To: 'admin-d@lkkauto.com'
Subject: OI : YM7813K / TP : SGH6754T/LKK / DOA : 22/12/2017 (DSMFP1703060)
Attachments: YM7813K - SAS.pdf; SGH6754T - SAS.pdf; SGH6754T - ESTIMATE.pdf; SGH6754T - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **LAI HUAT (MENG KEE) MOTOR PTE LTD**,

ADDRESS : BLK 160 SIN MING DRIVE
#04-01 SIN MING AUTOCITY
SINGAPORE 575722

PERSON TO CONTACT : JENNY @ 6453 8110

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured and third party SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you.

Best Regards

Yee Per Li
Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
DID: 65 6829 9194
Fax: 65 6829 9247
Website: www.ergo.com.sg



Have you tried our new travel insurance product yet?
TravelProtect comes with comprehensive benefits at some of the most
affordable prices available in the market.

ERGO
TravelProtect

your Global Safety Net

TravelProtect is underwritten by ERGO Insurance Plc Ltd



Buy now on [www.ergo.co.uk](#)

Janice Lee (LKKAUTO)

From: Jenny Lim <jenny.lim@laihuat.com.sg>
Sent: Wednesday, November 07, 2018 4:11 PM
To: SUR
Subject: FW: Finalisation - SGH 6754T / Toyota Vios
Attachments: SGH 6754T.pdf; IMG_3200.jpg; IMG_3201.jpg; IMG_3202.jpg; IMG_3203.jpg; IMG_3568.jpg; IMG_3569.jpg; IMG_3570.jpg; IMG_6110.jpg; IMG_6111.jpg; IMG_6112.jpg; PHOTO-2018-02-08-09-05-27.jpg; PHOTO-2018-02-08-09-05-28 (1).jpg; PHOTO-2018-02-08-09-05-28 (2).jpg; PHOTO-2018-02-08-09-05-28.jpg; PHOTO-2018-02-08-09-05-29 (3).jpg; PHOTO-2018-02-08-09-05-29.jpg

Importance: High

Dear Sir

For your confirmation, please.

Thank you.

Kind regards.

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596257

From: Jenny Lim [mailto:jenny.lim@laihuat.com.sg]
Sent: Wednesday, 29 August, 2018 3:10 PM
To: sebastianeang@lkkauto.com
Cc: sur@lkkauto.com
Subject: Finalisation - SGH 6754T / Toyota Vios

Dear Sir

- Parts: \$4,665.40 (include supplementary)
- SN: \$ 104.00
- L&P: \$2,680.00 (include supplementary)

Sub-total: \$7,449.40
LS -20%: (\$1,489.88) = \$5,959.52
Lump Sum: \$5950.00 / 15 days

Supporting document and photographs are enclosed for your reference.

Thank you.

Kind regards.

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
160 Sin Ming Drive

Janice Lee (LKKAuto)

From: Jenny Lim <jenny.lim@laihuat.com.sg>
Sent: Thursday, November 15, 2018 3:18 PM
To: Janice Lee (LKKAuto)
Subject: RE: Finalization - SGH 6754T / Toyota Vios

Dear Janice

Amount confirm with thanks.

Thank you.

Kind regards.

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596267

From: Janice Lee (LKKAuto) [mailto:JaniceLee@lkkauto.com]
Sent: Tuesday, 13 November, 2018 4:09 PM
To: Jenny Lim
Subject: RE: Finalization - SGH 6754T / Toyota Vios

Dear Jenny,

Kindly confirm \$5,850.00 @ 12 Days

Parts : \$4,467.55 = \$3,350.66(25%)
Nett item : \$225.00 = \$202.50(10%)
Labour : \$2,464.00
Supp Part : \$1,372.00 = \$1,029.00(25%)
Labour : \$260.00
Total : \$7,306.16 = \$5,850.00(L/S)

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jenny Lim [mailto:jenny.lim@laihuat.com.sg]
Sent: Wednesday, November 07, 2018 4:11 PM
To: SUR <sur@lkkauto.com>

Subject: FW: Finalisation - SGH 6754T / Toyota Vios
Importance: High

Dear Sir

For your confirmation, please.

Thank you.

Kind regards,

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
150 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596267

From: Jenny Lim [<mailto:jenny.lim@laihual.com.sg>]
Sent: Wednesday, 29 August, 2018 3:10 PM
To: sebastianyeang@lkkauto.com
Cc: sun@lkkauto.com
Subject: Finalisation - SGH 6754T / Toyota Vios

Dear Sir

- Parts: \$4,665.40 (include supplementary)
- SN: \$ 104.00
- L&P: \$2,680.00 (include supplementary)

Sub-total: \$7,449.40

LS -20%: (\$1,489.88) = \$5,959.52

Lump Sum: \$5950.00 / 15 days

Supporting document and photographs are enclosed for your reference.

Thank you.

Kind regards,

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
150 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596267

Cecilia Chong (LKK Auto)

From: Jenny Lim <jenny.lim@laihuat.com.sg>
Sent: Friday, 24 May 2019 4:39 PM
To: Cecilia Chong (LKK Auto)
Subject: RE: Your ref: SGH 6754T (Our ref: CS/EGI17024463/Nga3-1) *** ACCIDENT INVOLVING YM 7813K & SGH 6754T ON 22/12/2017 ***

Dear Cecilia

We refer to the above matter.

We are agreeable to accept your offer as provided therein.

Please let us have the payment soon enough.

Thank you.

Kind regards.

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596267

From: Cecilia Chong (LKK Auto) [mailto:CeciliaChong@lkkauto.com]
Sent: Friday, 24 May, 2019 3:56 PM
To: Jenny Lim
Subject: RE: Your ref: SGH 6754T (Our ref: CS/EGI17024463/Nga3-1) *** ACCIDENT INVOLVING YM 7813K & SGH 6754T ON 22/12/2017 ***

Without Prejudice

Dear Jenny,

We would withdraw previous offer to you.

We re-offer Global Sum of \$7,610.00(all-in)

Kindly confirm acceptance.

Thank you

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.


Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Cecilia Chong (LKK Auto)

Sent: Friday, 24 May 2019 11:53 AM

To: Jenny Lim <jenny.lim@laihuat.com.sg>

Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Your ref: SGH 6754T (Our ref: CS/EGI17024463/Nga3-1) *** ACCIDENT INVOLVING YM 7813K & SGH 6754T ON 22/12/2017 ***

Your Ref: **SGH 6754T**

Without Prejudice

Our Ref: CS/EGI17024463/Nga3-1

Dear Sirs/Mdm,

ACCIDENT INVOLVING YM 7813K & SGH 6754T ON 22/12/2017

We refer to the above matter.

We propose settlement at a global sum of **\$7,760.00(all-in)**.

Please confirm acceptance.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.


Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Jenny Lim [<mailto:jenny.lim@laihuat.com.sg>]

Sent: Thursday, 23 May 2019 5:49 PM

To: Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>

Subject: RE: Your ref: SGH 6754T (Our ref: CS/EGI17024463/Nga3-1) *** ACCIDENT INVOLVING YM 7813K & SGH 6754T ON 22/12/2017 ***

Dear Cecilia

Please find enclosed claim documents for your kind attention.

Please let us hear from you soon.

Thank you.

Kind regards,

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596267

From: Cecilia Chong (LKK Auto) [<mailto:CeciliaChong@lkkauto.com>]

Sent: Thursday, 23 May, 2019 3:47 PM

To: Jenny Lim

Cc: Hsiao Tong (LKKAuto); Admin A

Subject: Your ref: SGH 6754T (Our ref: CS/EGI17024463/Nga3-1) *** ACCIDENT INVOLVING YM 7813K & SGH 6754T ON 22/12/2017 ***

Without Prejudice

Dear Sirs/Mdm,

For cost of repair, recommended amount at L/S **\$5,850.00 (W/O GST) with 12 repair days.**

*** Kindly forward your LOD with all the relevant documents (ie: final repair bill, authorisation to act, rental receipt) to us (LKK) for our necessary action.

Thank you.

Please note that all finalisation subject insurer's approval.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

來發(明記)摩多有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity
160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722
Tel: 64538110 Fax: 64596267
UEN: 199407592C

5 April 2019

Your Ref: YM 7813K
Our Ref: SGH 6754T - 2017/JL

WITHOUT PREJUDICE

ERGO Insurance Pte Ltd
5 Temasek Boulevard
#04-01
Suntec Tower Five
Singapore 038985
Attention: Motor Claims

Dear Sirs

ACCIDENT INVOLVING VEHICLE NOS. SGH 6754T AND YM 7813K ON 22/12/2017 AT MARGARET DRIVE (NEAR LAMP POST 49 / QUEENSWAY SECONDARY SCHOOL MAIN GATE)

We refer to the above matter wherein your insured's vehicle no. YM 7813K was involved in an accident with our client's vehicle no. SGH 6754T.

As the accident was caused by your insured's negligence, our client is now claiming for the following losses:

- Repair cost: \$6,259.50 (include GST)
- Rental cost: \$1,348.20 (14 days x \$90 per day + GST)
- LTA search fee: \$ 5.35
- **Total: \$7,613.05**


Relevant documents in support of our client's claim are enclosed for your reference.

Please do not hesitate to contact Jenny Lim at telephone 64533757 or email jenny.lim@laihuat.com.sg should you need any additional information.

Meanwhile, we look forward to receiving your affirmative response soon enough.

Thank you.

Yours faithfully,



LAI HUAT (MENG KEE) MOTOR PTE LTD

encs

LETTER OF AUTHORITY

To: Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722

Dear Sirs

ACCIDENT INVOLVING VEHICLE NOS: SGH 6754T & YM 7813K ON 22/12/2017
AT MARGARET DRIVE (NEAR LAMP POST 49/QUEENSWAY SECONDARY SCHOOL MAIN GATE)

This is to confirm that on 23/12/2017, I / We gave you instructions to repair my / our vehicle no. SGH 6754T which was damaged in the above accident.

In consideration of your agreement to repair my vehicle no. SGH 6754T, pay for my other expenses and to defer demanding for payment of the costs of repair which was damaged as a result of the above accident, I / We hereby authorise you and/or your solicitors as my / our representative to write, negotiate and settle the accident claim on my / our behalf against any part involved in the abovementioned accident.

I / We hereby undertake to co-operate with you and render you all the assistance (including having my / our vehicle re-inspected and being a witness at trial) that may be necessary for you to recover the cost of repairs and the loss of use to my / our vehicle. I / We further undertake to keep you informed at all times of any communication received from any party involved in the abovementioned accident.

I / We hereby confirm that by signing this Letter of Authority, I / We are not entitled in law to receive any payment. If a cheque is sent to me, I / We shall return the same to the sender as I am precluded in law from accepting any payment.

In the event of my / our claim against any party involved in the abovementioned accident being unsuccessful for any reason whatsoever, I / We shall bear the repair / excess cost payable to Lai Huat (Meng Kee) Motor Pte Ltd either by cash / cheque or claim against my / our insurance policy.

I / We hereby authorise the payment of my / our claim (including any or all medical related invoices / receipts) to be made directly to my / our representative, Lai Huat (Meng Kee) Motor Pte Ltd accordingly.

In relation to the personal and vehicle information collected or otherwise provided during the course of the claim process (including by way of recordings), I agree and consent that Lai Huat (Meng Kee) Motor Pte Ltd may use, disclose and process my personal data for the purpose of responding and administering all activities related to my insurance claim.

Yours faithfully

Signature:



Name:

Sebastian Stella

NRIC No:

S1693160H

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

TAX INVOICE

EST No.: EST0018136
Sebastian Stella

GST Reg No: M2-0128609-3
Page: 1 of 1
Number: INV0021832
Your ref.: TP-YM 7813K ERGO
Job No.: 69102
Our ref: 17.12.32
Payment
Date: 5/4/2019

Attn

Vehicle No: SGH 6754T
Vehicle Model : Toyota Vios
Accident on ...: 22/12/2017

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		To supply and replace parts; labour charges for repairing, knocking, welding and to respray paint	5,850.00		5,850.00

Sub-Total		5,850.00
GST 7.00%		409.50
Total	S\$	6,259.50

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

APEX Car Rental Pte Ltd

37A BARTLEY ROAD SINGAPORE 539777

TEL: 6459 0206 FAX: 6553 4645

GST REGISTRATION NO: 20-0102894-H RCB NO: 200102894H

HIRING AGREEMENT CUM TAX INVOICE NUMBER:

1004196

(Please quote this number in all payments and correspondence)

Vehicle number : SJF 7431T
Make & model : Toyota Vios Auto

HIRER'S PARTICULARS

Hirer : SEBASTIAN STELLA
Address : BLK 90 DAWSON ROAD #17-14
SINGAPORE 142090

NRIC No: S1693160H

Contact Number Off :
H/p: 96227969

Res:

Nationality : SINGAPOREAN
Date Of Birth : 11.06.1965

Licence Number: AS NRIC NO
Licence Expiry : NEW PHOTO LIC.

Driver : AS ABOVE
Address :

NRIC No:

Contact Number Off :
H/p:

Res:

Nationality : SINGAPOREAN
Date Of Birth :

Licence Number: AS NRIC NO
Licence Expiry : NEW PHOTO LIC.

RENTAL PRICING

Daily Rental Rate : S\$ 90.00
Days On Rental : 14 /Day

Date Out : 23.12.2017
Time Out : 12.45 pm

Sub-Total : S\$ 1260.00
G.S.T.@7.0% : S\$ 88.20
Total : S\$ 1348.20

Date Return: 6.1.2018
Time Return: 1 pm

***RENTER'S Liability for Vehicle Damage EXCESS is S\$1,500.00 ON ALL CLAIMS.
***Applicable to driver below 23YRS old and above 70YRS old OR with less than 2YRS driving experience
EXCESS is S\$5,000.00

REMARK - Vehicle no: SGH 6754T
Job No: 69102

HIRER'S DECLARATION

I agree to the terms and conditions above and as set out
overleaf. If I opt to pay by credit/charge card, my signature
here is deemed to have been made on the application credit
card charge slip.



Authorised Signatory and Company Stamp

Date: 23 DEC 2017



APEX CAR RENTAL PTE LTD
Prepared by: 23 DEC 2017
Date:

Enquire Vehicle No.	Insurer Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
YM7813K	22 Dec 2017 / 16:00:00	Successful	N03	ERGO INSURANCE PTE. LTD.

Previous OK

Thank you



Lai Mei Ling Deborah has successfully logged out.
Your last login date and time was 23 Dec 2017, 11:53:32.

To return to ONE.MOTORING, please click [here](#)
For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

<u>S/No.</u>	<u>Asset Type</u>	<u>Asset ID</u>	<u>Asset Owner ID</u>	<u>Transaction Type</u>	<u>Transaction Amount(S\$)</u>	<u>Log Date/Time</u>
1	Vehicle	YM7813K	-	18.32 Insurance Enquiry (GIRO Payment)	7.49	23 Dec 2017 / 11:54:06



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s ERGO INSURANCE PTE LTD

Date: 27/06/2019

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	YM 7813K	(Insd Veh)	Your Ref. No. : DSMFP1703060
	SGH 6754T	(TP Veh)	Our Ref. No. : CS/EGI17024463/Nga3q2-1
Date of Accident	22/12/2017		

Liability	100%	
Final Repair Cost	: \$ 6,259.50	
Loss of Use	: \$	days
Rental (If any)	: \$ 1,348.20	14 days
Others:	: \$ 5.35	
	: \$	
	7,613.05	
Final Settlement Sum	: \$ 7,610.00	GLOBAL SUM
Remarks	:	

Payment Instruction: Payee's Breakdown

1)	LAI HUAT (MENG KEE) MOTOR PTE LTD	: \$ 7,610.00
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD			Ref : CS/EGI17024463/Nrd3e2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985			Date : 03-12-2018	
			Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YM 7813K	Veh. Inspected	SGH 6754T	
Policy No.		Coverage (\$)	0.00	
Claim No.	DSMFP1703060	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	27/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VIOS	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	MR053HY4204192517	Colour	SILVER	
Odometer	109675	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	175/65 R14	MICHELIN	8 mm	
L/H Front Tyre	175/65 R14	MICHELIN	8 mm	
R/H Rear Tyre	175/65 R14	MICHELIN	8 mm	
L/H Rear Tyre	175/65 R14	MICHELIN	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/12/2017	Inspection Date	27/12/2017	
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGH 6754T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT FENDER LH	DENTED	170.60	170.60
1	FRONT FENDER INNER SHIELD LH	DEFORMED	23.50	23.50
10	FRONT FENDER INNER SHIELD CLIPS LH @\$3.00	NECESSARY	30.00	30.00
1	FRONT FENDER SIGNAL LAMP LH	CRACKED	25.50	25.50
1	FRONT FENDER TOP SIDE COVER LH	CUT	25.90	25.90
1	FRONT DOOR LH	PUNCTURE	1,208.00	1,208.00
1	FRONT DOOR PROTECTOR LH	BENT	58.90	58.90
1	FRONT DOOR OUTER MOULDING LH	NECESSARY	29.90	29.90
1	FRONT DOOR OUTER LOCK HANDLE LH	MISSING	61.95	61.95
1	FRONT DOOR OUTER KEY LOCK COVER LH	MISSING	24.35	24.35
1	FRONT DOOR LOCK LH	DAMAGED	415.40	415.40
1	FRONT DOOR WINDOW WEATHERSTRIP LH	NECESSARY	49.90	49.90
1	FRONT DOOR KEY LOCK LH	DAMAGED	93.50	93.50
1	FRONT DOOR OUTER HANDLE HOLDER LH	MISSING	148.30	148.30
1	FRONT DOOR WINDOW GLASS LH	CRACKED	102.20	102.20
1	FRONT DOOR WINDOW REGULATOR LH	NOT NECESSARY	110.90	-
1	FRONT DOOR WINDOW CHANNEL LH	BENT	88.20	88.20
1	FRONT DOOR TOP HINGE LH	BENT	87.30	87.30
1	FRONT DOOR LOWER HINGE LH	BENT	83.10	83.10
1	FRONT DOOR WING MIRROR LH ASSY	MISSING	175.90	175.90
1	FRONT DOOR WEATHERSTRIP LH	NECESSARY	49.90	49.90
1	REAR DOOR LH	DEFORMED	1,295.14	1,295.14
1	REAR DOOR PROTECTOR LH	NECESSARY	49.80	49.80
1	REAR DOOR TOP HINGE LH	BENT	87.20	87.20
1	REAR DOOR LOWER HINGE LH	BENT	83.10	83.10
2	FRONT SHOCK ABSORBER @\$222.40 (ADDITIONAL)	BENT	444.80	444.80
2	REAR SHOCK ABSORBER @\$175.30 (ADDITIONAL)	BENT	350.60	350.60
2	FRONT SHOCK ABSORBER SUPPORT @\$62.20 (ADDITIONAL)	BENT	124.40	124.40
2	SUSPENSION ARM @\$226.10 (ADDITIONAL)	DISTORTED	452.20	452.20

Report Ref No. CS/EGI17024463/Nrd3e2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-1,487.61	-1,459.89
			4,462.83	4,379.65
	NETT ITEMS			
1	FRONT FENDER SIGNAL LAMP CHROME RING LH (N)	CUT	25.00	25.00
1	FRONT SPORT RIM LH (14") (N)	CUT	200.00	200.00
	LESS 10% DISCOUNT		-22.50	-22.50
			202.50	202.50
	SPECIAL NETT ITEMS			
1	FRONT TYRE LH (MICHELIN - 175 65 R14) (SN) (80%)	PUNCTURE	130.00	104.00
			130.00	104.00
	LABOUR			
	TOWING CHARGE.		80.00	80.00
	TO CHECK WHEEL ALIGNMENT.		60.00	60.00
	TO REMOVE AND REFIX FRONT AND REAR PASSENGER SEAT, CARPET, ETC.		150.00	120.00
	TO KNOCK DENTS FRONT DOOR PILLAR LH, FRONT DOOR INNER PILLAR LH, CENTRE PILLAR LH, CENTRE INNER PILLAR LH, ROCKER PANEL LH AND RENEW OF PARTS.		1,100.00	1,000.00
	TO SPRAY PAINT.		1,100.00	1,100.00
	LABOUR TO REMOVE AND RENEW SUSPENSION, ETC. (ADDITIONAL)		320.00	260.00
			2,810.00	2,620.00
GRAND TOTAL			7,605.33	7,306.15

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,850.00
---	--	--	-----------------

Report Ref No. CS/EG17024463/Nrd3e2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part does so at his or her own risk.