

22/03/2003

ASS. REC. BY:

REF:

CS/CTI/19009006/Uvd30

Special Instruction:

Surveyor: MARCUS

ASSIGNMENT (Office)

From (Person): Chong Boon Sen

of

CTI

Date/Time:

22/5/19 @ 10:23am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLN 6388B

Insured:

SKRSL

at Workshop m/s

Tan Jim Motor

Tel:

6858 5151

of

1 Defu Lane 6

Policy No:

Claim No:

SNM19D202241

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

18/5/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:47am @ 22/5/19

Person Contacted:

william

Vehicle IN (OUT)

Date/Time

Action/Instruction

Estimate (✓)

SLN 6388B-X

SKRSL-CS/AXA/6018093/Rlgbm2

DoA: 18/9/2016

(08/11/13) wef

REF:

ASS. REC. BY: *Merous*

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: *SLN 6388B*at Workshop m/s *Tanham*

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: *3* days Res.: Yes or NoLum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: *SLN 6388B* Yr Regn: *K 117*Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or *CA*Make: *Infiniti* Q50 c.c. *1991*Colour: *silver* A/C: Insured / Std / NI / NASp. Reading: *27532* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *JN1BCAV3720510179*Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *225/50 R18*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. *6* mm R/Bal. *6* mmL/Bal. *6* mm L/Bal. *6* mmD.O.A. *18/5/19* D.O.I. *23/5/19*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

25/3/19 4/5 & 1500 contact with willon. (Red 1118.50, 439)

RECEIVED 27 MAY 2019

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2) *7/5- typist*Days Of Repair: *3*Resurvey No. of Trip: *1*Survey Fee: *20*

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____) \$ + RS. \$ _____☐ : Interview (\$ _____) Photos☐ : Tech. Invs (\$ _____) Others☐ : Weekend (\$ _____)Report Format: *merimen*Lump Sum / I.B.I.: (\$ *1500*)

TOTAL

20

Celine Fong (LKKAuto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Wednesday, 22 May 2019 10:23 AM
To: Wei Shong
Cc: 'TLM - Sam'; 'Caymen'; assignments
Subject: RE: Arrange survey - Accident Involving SLN6388B (TLM) and SKR5L (China Taiping) on 18.05.2019 / our ref: snm19d202241

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson Road
#16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Wei Shong [mailto:wei.shong@tlmotor.com.sg]
Sent: Wednesday, 22 May, 2019 9:57 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: 'TLM - Sam' <sam@tlmotor.com.sg>; 'Caymen' <caymen@tlmotor.com.sg>
Subject: RE: Arrange survey - Accident Involving SLN6388B (TLM) and SKR5L (China Taiping) on 18.05.2019 / our ref: snm19d202241

Without prejudice

Dear Boon Sen,

We select LKK Auto – Marcus Chua to survey our client vehicle.

Veh Out

Thank you.

Regards,



Lam Wei Shong
William
wei.shong@tlmotor.com.sg

O. +65 6858 5151
F. +65 6858 0877

Tan Lim Motor Pte Lt
1 Defu Lane 6
Singapore 539365
<http://www.tlmotor.com.sg>

Confidentiality Notice: This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan Lim Pte Ltd. Any use of the information (including, but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place anti-virus programs, we do not accept responsibility for any damage caused by viruses passed on unwittingly.

From: Chong Boon Sen [<mailto:boonsen.chong@sg.cntaiping.com>]

Sent: Wednesday, May 22, 2019 9:34 AM

To: wei.shong@tlmotor.com.sg

Subject: RE: Arrange survey - Accident Involving SLN6388B (TLM) and SKR5L (China Taiping) on 18.05.2019 / our ref: snm19d202241

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
LOW SAR HUEI
HONG FOOK CHOY
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson Road
#16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Wednesday, 22 May, 2019 9:23 AM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; wei.shong@tlmotor.com.sg

Cc: Angie Foo <angie.foo@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow
<sochow.chee@sg.cntaiping.com>

Subject: FW: Arrange survey - Accident Involving SLN6388B (TLM) and SKR5L (China Taiping) on 18.05.2019

Dear Boon Sen,

Please conduct PRS on behalf of Elaine – TP: SLN6388B (SNM19D202241) soonest possible.
File with OIC – Boon Sen - 63896171

From: Wei Shong [<mailto:wei.shong@tlmotor.com.sg>]

Sent: Tuesday, 21 May 2019 6:18 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Cc: 'Caymen' <caymen@tlmotor.com.sg>; 'TLM - Sam' <sam@tlmotor.com.sg>

Subject: Arrange survey - Accident Involving SLN6388B (TLM) and SKR5L (China Taiping) on 18.05.2019

Your Ref: SKR5L

Our Ref: SLN6388B

DOA: 18.05.2019

Without Prejudice

Dear All,

We refer to the above matter.

We enclose the following documents for your attention:-

- a. Copy of our client's SAS report and damaged photos;
- b. Copy of the estimated cost of repair.

Please arrange for survey as soon as possible.

Pursuant to paragraph 2.3 of Pre-Action Protocol for NIMA Cases, please let us have a **list of 10 motor surveyors** for our selection and please let us know within **2 working days** whether you would like to conduct a pre-repair survey of our client's vehicle. If we do not hear from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

In the event that you request for post repair inspection pursuant to paragraph 4.1 under the NIMA Protocol, you must compensate our client for the loss of use of his/her vehicle for the day that the inspection is conducted.

In addition, please confirm in writing whether you are agreeable to direct settle with us at 100% liability for this case.

Thank you.

Regards,



Lam Wei Shong
William
wei.shong@tlmotor.com.sg

O. +65 6858 5151
F. +65 6858 0877

Tan Lim Motor Pte Lt
1 Defu Lane 6
Singapore 539365
<http://www.tlmotor.com.sg>

Confidentiality Notice: This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan Lim Pte Ltd. Any use of the information (including but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place anti-virus programs, we do not accept responsibility for any damage caused by viruses passed on unwittingly.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 5777J

Vehicle Details

Vehicle No.: SLN6388B
Vehicle to be Exported: No
Intended Deregistration Date: 21 May 2019
Vehicle Make: INFINITI
Vehicle Model: Q50 2.0T A/T (R18) EU6 NAV
Primary Colour: Silver
Manufacturing Year: 2016
Engine No.: 274AE057126A
Chassis No.: JN1BCAV37Z0510179
Maximum Power Output: 155.0 kW (207 bhp)
Open Market Value: \$33,612.00
Original Registration Date: 19 May 2017
First Registration Date: 19 May 2017
Transfer Count: 0
Actual ARF Paid: \$39,057.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 18 May 2027
PARF Rebate Amount: \$29,292.00

Intended COE Rebate Details

COE Expiry Date: 18 May 2027
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$55,414.00
COE Rebate Amount: \$44,276.00
Total Rebate Amount: \$73,568.00

The information contained herein is correct as at 21 May 2019

OK



INVOICE

Z3M PTE LTD
22 Sin Ming Lane #06-76
Midview City
Singapore, 573969
Singapore

Phone: +65 84847701
Mobile: +65 84847701

BILL TO
Charles

Invoice Number: Z3M-IN-2018-5337

P.O./S.O. Number: Z30

Invoice Date: August 24, 2018

Payment Due: August 24, 2018

Amount Due (SGD): \$188.00

Items	Quantity	Price	Amount
Maintenance SLN6388B	1	\$198.00	\$198.00
Discount	1	(\$10.00)	(\$10.00)
Total:			\$188.00
Amount Due (SGD):			\$188.00

Next appt Jan 2019.

Next touch up May-June 2019.



ANGELWAX INVOICE

Asia Angelwax Pte Ltd
31 Woodlands Close, #08-08
Singapore, 737855
Singapore

Phone: +65 97493881
Mobile: +65 84847701

BILL TO
Cash

Invoice Number: 15122017-002

Invoice Date: December 15, 2017

Payment Due: January 29, 2018

Amount Due (SGD): \$400.00

Services	Quantity	Price	Amount
Angelwax 1st Angelic Visit N6388B Polishing and Coating	1	\$400.00	\$400.00
Total:			\$400.00
Amount Due (SGD):			\$400.00

Notes

This is a computer generated invoice and requires no signature. Payable to: Asia Angelwax Pte Ltd UOB - Serangoon Garden
Branch SGD 344-307-491-9 Bank Code: 7375 Swift Code: UOVBSGSG

Next visit : 26/12 for complimentary
car wash and shine
analysis.

Dear Customer(s), should you find any discrepancies in your invoice, please email jwil@asiaangelwax.com



INVOICE

Tan Lim Motor Pte Ltd
Attention: Tan Lim Motor Pte Ltd
1 Defu Lane 6
SINGAPORE SINGAPORE 539365
SINGAPORE

Invoice Date
24 May 2019

Invoice Number
Z3M-IN-19-6722

Reference
Z3M-IN-19-6716

Z3M PTE LTD
22 Sin Ming Lane #06-76
Midview City
SINGAPORE 573969

Item	Description	Quantity	Unit Price	Amount SGD
9H Ceramic ating	SLN6388B REAR BUMPER ONLY	1.00	150.00	150.00
Subtotal				150.00
TOTAL SGD				150.00

Due Date: 7 Jun 2019

This is a computer generated invoice and requires no signature.

Payable to: Z3M Pte Ltd, DBS Bank, Bank Code : 7171, Swift Code: DBSSSGSG, Branch Code : 047, Account : 047-903006-9

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/05/2019 11:28
Date Of Accident	18/05/2019 23:00
Exact Location Of Accident	TAVISTOCK AVENUE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN6388B
Insured/Policyholder	
Name Of Registered Owner	TAY SOON ANN CHARLES
NRIC No	S1535777J
Email Address	CHARLES.TAY62@GMAIL.COM
Mobile Phone No	(LOCAL) +65-83288980
Alternative Phone No	OFFICE-83288980

Vehicle Particulars

Manufacturer	INFINITI
Model	Q50-2.0 T (R18) EU6 NAV (A)
Exact Purpose for which vehicle was being used at time of accident	PARKED
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	HL ASSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MP305540
Cover Note Number	

Driver

Name of Driver	TAY SOON ANN CHARLES
NRIC No	S1535777J
Date Of Birth	28/04/1962
Occupation	INDOOR
Date Of Driving Pass	30/05/1985
Driving Experience	33 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83288980
Fax Number	
Contact Number	OFFICE-83288980
EMail Address	CHARLES.TAY62@GMAIL.COM

Address	2 HOUGANG STREET 32 #08-05
Postcode	534041
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Refer to sketch plan.


Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKR5L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LING ZHI JIE RAYSON
NRIC/Passport Number	S9432757A
Contact Number	91764953
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 18/5/19 @ 2300 hrs, my car SLN 6388B was parked along the roadside of 38, Tavistock Avenue.

On 19/5/19 @ 1100 hrs, I went back to collect my car and found a damaged and a note on my front windscreen wiper. I had contacted third party and the driver couldn't agree to the repair cost.

Thus, we proceeded with insurance claims.

Third party vehicle number is SKR5L.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 21/6/19 @ 1100hrs

Driver's Signature

(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name: Sam Low

NRIC/FIN No.:



陳林澤嗎私人有限公司
TAN LIM MOTOR PTE LTD

CTP Insured's Veh No : SKR5L

Date of Accident : 18 May 2019

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Mr Tay Soon Ann Charles

Date : 21 May 2019

Estimate To Repair SLN6388B - Infiniti Q50 2.0T A/T (R18) EU6 NAV

Chassis No : JN1BCAV37Z0510179

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	rear bumper <i>DD</i>	\$ 1,080.00
02	8 ps	rear bumper clip @ \$5.00 <i>na</i>	\$ 40.00
03	1 pc	rear bumper reflector LH <i>11</i>	\$ 125.00
04	1 pc	rear bumper reverse sensor LH <i>should</i>	\$ 420.00
			\$ 1,665.00
		Less 10 %	\$ 166.50
			\$ 1,498.50
		<u>LABOUR & MISC. CHARGES</u>	
01		To reinstall of rear bumper parking sensor.	\$ 120.00
02		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 300.00
03		Putty and spray painting of the affected portion.	\$ 300.00
04		To redo polishing and base coating.	\$ 400.00
			\$ 1,120.00
		Total <i>not Adult</i>	\$ 2,618.50
		<i>h/s 1500/-</i>	
		<i>2 day</i>	
		<i>23/5/19</i>	
		<i>the ph Affix</i>	
		<i>7-1540</i>	

LICK Auto Consults will hence notify the Repairer of the following:

- To ensure transparent spray painting
- To ensure accurate control during resurvey
- To ensure accurate control to confirmation
- To ensure accurate control to "Without Prejudice" basis
- To ensure accurate control to repair allowed
- To ensure accurate control to survey and
- To ensure accurate control to insurance Company

Acknowledged by Repairer

Signature

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 May 2019		22 May 2019 16:16 Edit Adj Rpt	S\$1,500.00 Edit Estimates	S\$1,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	0, Co. Reg. No.: 0								
Main Claimant:	TAY SOON ANN CHARLES								
Vehicle Reg. No.:	SLN6388B	Date of Loss:	18/05/2019 00:00 - :59 [23 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D202241C02	Policy/Cover Note No.:	DMPCSN16727218022						
Vehicle Reg. No. (Insured):	SKR5L	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6, 539365 Defu Lane - Tel: 6858 5151								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 31/05/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLN6388B (SNM19D202241C02)
[SKR5L]
TP
TAY SOON ANN CHARLES
May 18 2019 12:00AM
[0]
Tan Lim Motor Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	23/05/19 17:31	Chassis Number		Load JPG	<input checked="" type="checkbox"/>					
2	23/05/19 17:31	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>					
3	23/05/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>					
4	23/05/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>					
5	23/05/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>					
6	23/05/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>					
7	23/05/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>					
8	23/05/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>					
9	23/05/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>					
10	23/05/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>					
11	23/05/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>					
12	23/05/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>					
13	23/05/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>					
14	23/05/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>					
15	23/05/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>					
16	23/05/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>					
17	23/05/19 17:31	General View		Load JPG	<input checked="" type="checkbox"/>					
18	27/05/19 09:57	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>					
19	27/05/19 09:57	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>					
20	27/05/19 09:57	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>					
21	27/05/19 09:57	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>					
22	27/05/19 09:57	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>					
Documentation							1 per page	<input checked="" type="checkbox"/>		
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print					
1	22/05/19 16:19	PRI CONTACT DETAILS		Load PDF						

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; min-height: 100px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			



LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119009006/UVD3E2

Date: 30/05/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN16727218022

Claimant Vehicle
No: SLN6388BInsured Vehicle
No: SKR5L

Date of Loss: 18/05/2019

Nature of Claim: TP

Claim
No: SNM19D202241C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLN6388B**

Make & Model: INFINITI Q50, 2.0 T (R18) EU6 NAV (A)

Engine No: 274AE057126A

Reg. Date: 19/05/2017 (Man. Year: 2016)

Chassis No: JN1BCAV37Z0510179

Colour: Silver

Odometer: 27562 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50R18	Rear Tyre Size:	225/50R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,498.50	1,386.00	112.50	7.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,120.00	520.00	600.00	53.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,618.50	1,906.00	712.50	27.21
Approved Total (Overridden) (S\$)		1,500.00		
(S\$)	2,618.50	1,500.00	1,118.50	42.72
+ GST 7.00/7.00% (S\$)	183.30	105.00	78.30	42.72
Nett Amount (S\$)	2,801.80	1,605.00	1,196.80	42.72

INSPECTION

Date of Assignment: 22/05/2019

Date Inspected: 23/05/2019 Inspected At:

Tan Lim Motor Pte Ltd (Defu)
1 Defu Lane 6
Singapore 539365

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 28 May 2019)
Parts: 143	INFINITI Q50 2.0 T (R18) EU6 NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN6388B)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	1,080.00 FL	*1,080.00 FL
2	8		*REAR BUMPER CLIP	Necessary	40.00 FL	*40.00 FL
3	1		*REAR BUMPER REFLECTOR LH	Not Necessary	125.00 FL	*- FL
4	1		*REAR BUMPER REVERSE SENSOR LH	Shorted	420.00 FL	*420.00 FL
					Sub Total (S\$)	1,665.00 1,540.00
					- List Item Discount on L Items 10.00/10.00% (S\$)	166.50 154.00
					Total Parts (S\$)	1,498.50 1,386.00

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	120.00	50.00
2	PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	300.00	120.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	300.00	200.00
4	TO REDO POLISHING AND COATING	New	400.00	150.00
Gross Labour Cost (S\$)			1,120.00	520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >