

1 SMB1538U - 1

DRIVER**SMB1538U**

Untitled - Notepad

File Edit Format View Help

BUS WAS STATIONARY**BUS DRIVER'S HANDS OFF THE STEERING WHEEL****MOTORBIKE CAME FROM BEHIND,
SQUEEZING BETWEEN TWO STATIONARY
VEHICLES, ONE OF WHICH IS OUR BUS SMB1538U**

-FPS -Kbps

10/05/2019 17:59:48

Vehicle Status

Channels

Speed

ACC

Channel 1

Channel 5

17:59:48 X1



1 SMB1538U - 1

DRIVER
SMB1538U

Untitled - Notepad

File Edit Format View Help

BUS WAS STATIONARY**BUS DRIVER'S HANDS OFF THE STEERING WHEEL****MOTORBIKE CAME FROM BEHIND,
SQUEEZING BETWEEN TWO STATIONARY
VEHICLES, ONE OF WHICH IS OUR BUS SMB1538U**

704°576 0 FPS 0 Kbps

Google

This page can't load G

[Do you own this website?](#)**10/05/2019 17:59:48**

Vehicle Status

Channels

Speed

ACC

Channel 1

Channel 5

17:59:48 X1



1 SMB1538U - 1

**DRIVER
SMB1538U**

Untitled - Notepad

File Edit Format View Help

BUS WAS STATIONARY**BUS DRIVER'S HANDS OFF THE STEERING WHEEL****MOTORBIKE CAME TOO CLOSE TO STATIONARY
BUS AND SCRAPED / LACERATED AGAINST BUS.**

704°576 0 FPS 7 Kbps

10/05/2019 17:59:48

Vehicle Status

Channels

Speed

ACC

Channel 1

Channel 5

17:59:48 X1



1 SMB1538U - 1

DRIVER
SMB1538U

Untitled - Notepad

File Edit Format View Help

BUS WAS STATIONARY**BUS DRIVER'S HANDS OFF THE STEERING WHEEL****MOTORBIKE CAME TOO CLOSE TO STATIONARY
BUS AND SCRAPED / LACERATED AGAINST BUS.**

704*576 0 FPS 0 Kbps

10/05/2019 17:59:48

Vehicle Status

Channels


Speed

ACC

Channel 1

Channel 5

17:59:48 X1



1 SMB1538U - 1

DRIVER
SMB1538U

Untitled - Notepad

File Edit Format View Help

BUS WAS STATIONARY**BUS DRIVER'S HANDS OFF THE STEERING WHEEL****MOTORBIKE CAME TOO CLOSE TO STATIONARY
BUS AND SCRAPED / LACERATED AGAINST BUS.**

704*576 0 FPS 4 Kbps

10/05/2019 17:59:48

Vehicle Status

Channels

Speed

ACC

Channel 1

Channel 5

17:59:48 X1



