

Surveyor:

DOI:

ASSIGNMENT

Date / Time:

Registered in Merimen:

re-assign / CCU / FTE



Insured Vehicle No.

Name of Insured

Insured Tel No.

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

Premium



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SLV9778Y - X ; SLA 3288U - X

20/2/2020 File Pass To HML To LMR

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No. : 27

If NO or B 28, Ass. Lia:

Repair Cost: (w/hit)

S\$ 5867.88

Loss of Rental (LOR):

S\$ -

(

days)

Loss of Use (LOU):

S\$ 300.00

(\$ 100 x 3 days)

Loss of Income (LOI):

S\$ -

(\$ x days)

LOR only ☐ LOU only ☒LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$ 2.00

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

Total:

S\$ 6169.88

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 6169.88

Name 1:

Premium Automobiles Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Payee 3: (Strike if N.A.)

S\$

1) Claim status: Notional/Reject/Private Settle

2) Report Format: IP

3) Survey fee: \$400

COPY SENT

ASS. REC. BY:

REF:


Adrian

ASSIGNMENT

Front: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC / Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Vehicle: IN / OUT
 Person Contacted: _____

Veh No: SLV9778Y Yr Regn: 2015, March
 Type: LCar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A6 cc 1984
 Colour Bronze A/C: Insured / Std / Nil / NA
 Sp. Reading 64316 T/Radio: Insured / Std / Nil / NA

Eng/No: _____
 C/No: WAUZZZ4G1EN200935

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/40R19
 R: 245/40R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front	Rear
R/Bal. <u>06</u> mm	R/Bal. <u>06</u> mm
L/Bal. <u>06</u> mm	L/Bal. <u>06</u> mm
D.O.A. _____	D.O.I. <u>21/05/19</u>

Survey held at: Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Ergo.

PIP - \$5484 (Red \$3820/412)

MV:

PV:

Nett:

Date/Time, File Pass to?

Date/Time, File Return to?

1)	2)
3)	4)
5)	6)
Prel. Report:	
Final Report:	

Part Prices Check:

IN OUT

Survey Fee:

Date:

Basic & Add.
 S + RS, SI
 Photos
 Others
 TOTAL

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/0641/2019/NK
Date	:	18-May-19

Vehicle not in workshop. Kindly arrange for survey.

Your insured vehicle : **SLA 3288 U**

ERGO INSURANCE PTE LTD

Motor Claims Dept
5 Temasek Boulevard
#04-01 Sunteck Tower Five
Singapore 038985

Attn: Motor Claims Dept
Tel: 6829 9199

Owner's Name	:	Mr. Liow Ket Fui
Address	:	67 Admiralty Drive #10-183 Singapore 750467
Telephone	:	HP +65 93363861
Type of Claim	:	Third Party Claims
Policy No.	:	VA1/GA335599
Vehicle No	:	SLV 9778 Y
Model Code	:	Audi A6 C7 2.0 TFSI MU
Model / Year	:	10-03-2015
Engine No	:	CDN 416939
Chassis No	:	WAUZZZ4G1EN200935
Mileage	:	-
Date In	:	-
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	16-May-19

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Acciden

S/n	Nature of Jobs	Surveyor's Recommendation
1	To remove and transfer rear parking aid and kick sensor. Check function and renew accc damage.	P/P →
2	To dismantle and renew rear bumper. To inspect panelling. Reorganise rear crash management components. Reinstall all parts removed.	\$ 1,200.00
3	To respray rear bumper	\$ 1,000.00
4	To carry out diagnostic check.	S/N \$ 192.00
TOTAL LABOUR CHARGES		: \$ 2,752.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLV 9778 Y

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>Replaced</i>	\$	2,343.00 ✓
2	REAR BUMPER STICKT PADS <i>new</i>	NEC \$	21.00 +
3	REAR BUMPER FIXING PARTS <i>new</i>	NEC \$	249.00 +
4	REAR BUMPER SPOILER <i>confirmed</i>	\$	316.00 ✓
5	REAR BUMPER SECURING STRIP <i>? New</i>	NEC \$	157.00 ? 156.50
6	REAR BUMPER REINFORCEMENT <i>? NV</i>	\$	887.00 X
7	REAR BUMPER SEAL LH / RH <i>new</i>	2 \$	26.00 +
8	REAR BUMPER GUIDE SECTION LH / RH <i>new</i>	2 \$	60.00 +
9	CONNECTING PLATE <i>new</i>	2 \$	22.00 +
10	REAR BUMPER GUIDE PROFILE UPPER LH / RH	2 \$	106.00 +
11	REAR BUMPER GUIDE SECTION CENTRE	\$	96.00 +
12	REAR BUMPER GUIDE SECTION LOWER LH / RH	2 \$	96.00 +
13	REAR BUMPER COVER RH <i>new</i>	\$	105.00 +
14	REAR SENSORS <i>new</i>	2 \$	462.00 +
15	SEAL RINGS INNER / OUTER <i>new</i>	4 \$	5.00 +
16	BOOTLID CONTROL UNIT <i>new</i>	\$	387.00 +
17	TAILGATE OPENING SENSOR LINE <i>new</i>	\$	190.00 +
18	BOOTLID CONTROL UNIT RETAINER <i>new</i>	\$	7.00 +
19	EXHAUST CHROME TRIM PIPE <i>tot. Dented</i>	\$	517.00 516.50
20	SUNDRIES <i>? NV</i>	\$	500.00 X
GRAND TOTAL SPARE PARTS		\$	6,552.00
TOTAL LABOUR CHARGES		\$	2,752.00
GRAND TOTAL		\$	9,304.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

L&K Auto Consultants hence notify the Insurer of the following:

- * To ensure full coverage spray painting
- * To ensure full coverage during resurvey
- * To ensure full coverage to confirmation
- * To ensure full coverage on "Without Prejudice" basis
- * To ensure full coverage is allowed
- * To ensure full coverage must be resurveyed and approved from Insurance Company

Acknowledged by Insurer
Signature:

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian King*
Surveyed Date : *21/05/19.*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, 03 days.*

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0641/2019/NK
Date : 18-May-19

Vehicle not in workshop. Kindly arrange for survey.

Your insured vehicle : **SLA 3288 U**

ERGO INSURANCE PTE LTD

Motor Claims Dept
5 Temasek Boulevard
#04-01 Sunteck Tower Five
Singapore 038985

Attn: Motor Claims Dept
Tel: 6829 9199

Hi Adrian

3 days - ok - jb - 27 Jun 19

Owner's Name : Mr. Liow Ket Fui
Address : 67 Admiralty Drive
#10-183
Singapore 750467
Telephone : HP +65 93363861
Type of Claim : Third Party Claims
Policy No. : VA1/GA335599
Vehicle No : **SLV 9778 Y**
Model Code : Audi A6 C7 2.0 TFSI MU
Model / Year : 10/3/2015
Engine No : CDN 416939
Chassis No : WAUZZZ4G1EN200935
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 16-May-19

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLV 9778 Y

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N	\$ 360.00	\$ 360.00
2	To dismantle and renew rear bumper. To inspect end panelling. Reorganise rear crash management components. Reinstall all parts removed. (\$800/- for A6)		\$ 1,200.00	\$ 800.00
3	To respray rear bumper (\$800/- for A6)		\$ 1,000.00	\$ 800.00
4	To carry out diagnostic check.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 2,752.00</u>	<u>\$ 2,152.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLV 9778 Y

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER	\$ 2,343.00	\$ 2,343.00
2	REAR BUMPER STICKT PADS	NEC \$ 21.00	
3	REAR BUMPER FIXING PARTS	NEC \$ 249.00	
4	REAR BUMPER SPOILER	\$ 316.00	\$ 316.00
5	REAR BUMPER SECURING STRIP	NEC \$ 157.00	\$ 156.50
6	REAR BUMPER REINFORCEMENT	\$ 887.00	
7	REAR BUMPER SEAL LH / RH	2 \$ 26.00	
8	REAR BUMPER GUIDE SECTION LH / RH	2 \$ 60.00	
9	CONNECTING PLATE	2 \$ 22.00	
10	REAR BUMPER GUIDE PROFILE UPPER LH / RH	2 \$ 106.00	
11	REAR BUMPER GUIDE SECTION CENTRE	\$ 96.00	
12	REAR BUMPER GUIDE SECTION LOWER LH / RH	2 \$ 96.00	
13	REAR BUMPER COVER RH	\$ 105.00	
14	REAR SENSORS	2 \$ 462.00	
15	SEAL RINGS INNER / OUTER	4 \$ 5.00	
16	BOOTLID CONTROL UNIT	\$ 387.00	
17	TAILGATE OPENING SENSOR LINE	\$ 190.00	
18	BOOTLID CONTROL UNIT RETAINER	\$ 7.00	
19	EXHAUST CHROME TRIM PIPE	\$ 517.00	\$ 516.50
20	SUNDRIES	\$ 500.00	
GRAND TOTAL SPARE PARTS		\$ 6,552.00	\$ 3,332.00
TOTAL LABOUR CHARGES		\$ 2,752.00	\$ 2,152.00
GRAND TOTAL		\$ 9,304.00	\$ 5,484.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC3/EGI19009015/Aea3

Date: 22/05/2019

The Motor Claims Department
M/s ERGO INSURANCE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLV 9778Y

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 21/05/2019 at the premises of M/s Premium Automobiles Pte Ltd - Ubi and have the following to report:-

Workshop Estimate Amount	: S\$	9,304.00
Revised Estimate Amount	: S\$	5,128.00
"Check" Items Amount	: S\$	1,544.00
Total (Including Check Items)	: S\$	6,672.00
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3 days

Yours faithfully,

ADRIAN LING
Licensed Appraiser



redefining / insurance

AXA Insurance Pte Ltd
 1800 880 4888 (Within Singapore)
 (65) 6880 4888 (International)
 (65) 6880 4740
 customer.care@axa.com.sg
 www.axa.com.sg

LIOW KET FUI
 BLK 467 ADMIRALTY DRIVE
 #10-183
 SINGAPORE 750467

Renewal

date
 03/04/2019

your servicing distributor
**ANIKA INS BROKERS & CONSULTANTS P
 L / 00914**

your servicing distributor contact
 6672 9988

Policy Schedule

Your SmartDrive Comprehensive Essential

Your policy snapshot

Policyholder name	LIOW KET FUI	Policy number	VA1 / GA335599
Cover	Comprehensive	FIN / NRIC	S77858531
Period of Insurance	from 20/03/2019 to 09/03/2020 (both dates inclusive)		

Premium breakdown

Gross Premium after 50% NCD	SGD 937.47
7% GST	SGD 65.62
Final Premium	SGD 1,003.09

Your benefits highlights

(refer to Policy Wording for full terms and conditions)

SmartDrive Comprehensive Essential Benefits

- 24/7 Towing & Transportation in Singapore or Overseas
- Windscreen Replacement with Excess OR Repair your windscreen at your preferred location and get \$50 cash reward with no excess
- Guaranteed Repairs for twelve (12) Months
- Loss or Damage
- Legal Liability

Claim Protector Pack Benefits

- Basic own damage excess waiver
- No Claim Discount Protector

Vehicle details

Make & Model of Vehicle	AUDI A6 2.0 TFSI MU	Year of manufacture	2014
Vehicle registration number	SLV9778Y	Type of Use	Private use
Body type	SALOON	Engine capacity (c.c.)	1984
Sitting capacity (excl driver)	4	Engine number	CDN416939
Off-Peak car	No	Chassis number	WAUZZZ4G1EN200935

Insured's Estimated Market Value	Market Value at the time of Loss (including accessories and spare parts)
Limitation to use	As per Certificate of Insurance
Finance Loan Company	TOKYO CENTURY LEASING (SINGAPORE) PTE LTD

Excess applicable (refer to Policy Wording for other applicable Excesses)

Windscreen Excess	Not Applicable
-------------------	----------------

Drivers details



AXA Insurance Pte Ltd (199903512M)
 8 Shenton Way, #24-01, AXA Tower,
 Singapore 068811
 Customer Centre, #B1-01

Mei Kwan (LKKAuto)

From: Steve Lim <steve.lim@ergo.com.sg>
Sent: Thursday, 23 May, 2019 10:28 AM
To: Mei Kwan (LKKAuto); ERGO Insurance Pte. Ltd. (Claims Department); Jeannie Cheng
Cc: Asher Sng (LKKAuto); CS A Team; Admin A
Subject: RE: Direct Settlement - Accident Involving SLA3288U (OI : EGI - CDMPG19000952) and SLV9778Y (TP : LKK REF - CC3/EGI19009015/Aea3) on 16/05/2019
Attachments: OI report.PDF
Categories: HMK

Hi Mei Kwan,

Attached

Steve Lim
Manager - Claims

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-05 Suntec Tower Five
Singapore 038985
Tel : +65 6829 9197
Fax : +65 6829 9247
steve.lim@ergo.com.sg

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates in Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message.
Any views expressed in this email communication are those of the individual sender. ERGO Insurance Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference.
ERGO Insurance Pte. Ltd. asserts copyright in respect to this email including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]
Sent: Wednesday, 22 May, 2019 7:25 PM
To: ERGO Insurance Pte. Ltd. (Claims Department); Jeannie Cheng
Cc: Steve Lim; Asher Sng (LKKAuto); CS A Team; Admin A
Subject: Direct Settlement - Accident Involving SLA3288U (OI : EGI - TBA) and SLV9778Y (TP : LKK REF - CC3/EGI19009015/Aea3) on 16/05/2019

WITHOUT PREJUDICE
SAVE AS TO COSTS

Premium Automobiles

Telefax

to **Ergo Insurance Pte Ltd**
5 Temasek Boulevard
#04-01 Suntec Tower 5
Singapore 038985
Attn: Motor Claims Dept
Your Ref: SLA 3288 U

Norah Khai
6768 9828
6841 1183

Body Repair

PA/TP/0641/2019/KK
13th June 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages


RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A6 C7 2.0 TFSI MU
Vehicle Chassis No. : WAUZZZ4G1EN200935
Vehicle Regn No. : SLV 9778 Y
Vehicle Mileage : 65809 KM
Vehicle Owner : Mr. Liow Ket Fui
Liability Clearance : Direct Settlement by Jeannie Cheng from ERGO
via email dated 22/05/2019 with LOU.
Accident Date : 16/5/2019
Place : Woodlands Ave 12
Repair Cost : \$ 5067.80
WIP No. : 53900
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time :
Date : 15/6



redefining / insurance

AXA Insurance Pte Ltd
 1800 880 4888 (Within Singapore)
 (65) 6880 4888 (International)
 (65) 6880 4740
 customer.care@axa.com.sg
 www.axa.com.sg

LIOW KET FUI
 BLK 467 ADMIRALTY DRIVE
 #10-183
 SINGAPORE 750467

Renewal

date
 03/04/2019

your servicing distributor
**ANIKA INS BROKERS & CONSULTANTS P
 L / 00914**

your servicing distributor contact
 6672 9988

Policy Schedule

Your SmartDrive Comprehensive Essential

Your policy snapshot

Policyholder name	LIOW KET FUI	Policy number	VA1 / GA335599
Cover	Comprehensive	FIN / NRIC	S77858531
Period of Insurance	from 20/03/2019 to 09/03/2020 (both dates inclusive)		

Premium breakdown

Gross Premium after 50% NCD	SGD 937.47
7% GST	SGD 65.62
Final Premium	SGD 1,003.09

Your benefits highlights

(refer to Policy Wording for full terms and conditions)

SmartDrive Comprehensive Essential Benefits

- 24/7 Towing & Transportation in Singapore or Overseas
- Windscreen Replacement with Excess OR Repair your windscreen at your preferred location and get \$50 cash reward with no excess
- Guaranteed Repairs for twelve (12) Months
- Loss or Damage
- Legal Liability

Claim Protector Pack Benefits

- Basic own damage excess waiver
- No Claim Discount Protector

Vehicle details


Make & Model of Vehicle	AUDI A6 2.0 TFSI MU	Year of manufacture	2014
Vehicle registration number	SLV977BY	Type of Use	Private use
Body type	SALOON	Engine capacity (c.c.)	1984
Seating capacity (excl driver)	4	Engine number	CDN416939
Off-Peak car	No	Chassis number	WAUZZZ4G1EN200935

Insured's Estimated Market Value	Market Value at the time of Loss (including accessories and spare parts)
Limitation to use	As per Certificate of Insurance
Finance Loan Company	TOKYO CENTURY LEASING (SINGAPORE) PTE LTD

Excess applicable (refer to Policy Wording for other applicable Excesses)

Windscreen Excess	Not Applicable
-------------------	----------------

Drivers details





Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s ERGO INSURANCE PTE LTD

Date: 20/02/2020

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	SLA 3288U (Insd Veh)	Your Ref. No. : CDMPG19000952
	SLV 9778Y (TP Veh)	Our Ref. No. : CC3/EG19009015/Ada3q2
Date of Accident	16/5/2019	

Liability	100%	
Final Repair Cost	: \$ 5,867.88	
Loss of Use	: \$ 300.00	3 days
Rental (If any)	: \$	days
Others:	: \$ 2.00	
	: \$	
	6,169.88	
Final Settlement Sum	: \$ 6,169.88	
Remarks	:	

Payment Instruction: Payee's Breakdown

1)	PREMIUM AOTOMOBILES PTE LTD	: \$ 6,169.88
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CC3/EG119009015/Ada3q2

5 TEMASEK BOULEVARD
#04-05 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 20-02-2020



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLA 3288U	Veh. Inspected	SLV 9778Y
Policy No.	DMPG19002554	Coverage (\$)	0.00
Claim No.	CDMPG19000952	Excess (\$)	0.00
Assign From		Assign Date	21/05/2019

2. Vehicle Particulars & Condition

Make & Model	AUDI A6	c.c	1984
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WAUZZZ4G1EN200935	Colour	BRONZE
Odometer	64316	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/40 R19	PIRELLI	6 mm
L/H Front Tyre	245/40 R19	PIRELLI	6 mm
R/H Rear Tyre	245/40 R19	PIRELLI	6 mm
L/H Rear Tyre	245/40 R19	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	16/05/2019	Inspection Date	21/05/2019
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1. SINGAPORE 408699		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 9778Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (SN)	DEFORMED	2,343.00	2,343.00
1	REAR BUMPER STICKT PADS (SN)	NOT NECESSARY	21.00	-
1	REAR BUMPER FIXING PARTS (SN)	NOT NECESSARY	249.00	-
1	REAR BUMPER SPOILER (SN)	CRACKED	316.00	316.00
1	REAR BUMPER SECURING STRIP (SN)	NECESSARY	157.00	156.50
1	REAR BUMPER REINFORCEMENT (SN)	NOT NECESSARY	887.00	-
2	REAR BUMPER SEAL LH /RH (SN)	NOT NECESSARY	26.00	-
2	REAR BUMPER GUIDE SECTION LH/RH (SN)	NOT NECESSARY	60.00	-
2	CONNECTING PLATE (SN)	NOT NECESSARY	22.00	-
2	REAR BUMPER GUIDE PROFILE UPPER LH/RH (SN)	NOT NECESSARY	106.00	-
1	REAR BUMPER GUIDE SECTION CENTRE (SN)	NOT NECESSARY	96.00	-
2	REAR BUMPER GUIDE SECTION LOWER LH/RH (SN)	NOT NECESSARY	96.00	-
1	REAR BUMPER COVER RH (SN)	NOT NECESSARY	105.00	-
1	REAR SENSORS (SN)	NOT NECESSARY	462.00	-
4	SEAL RINGS INNER /OUTER (SN)	NOT NECESSARY	5.00	-
1	BOOTLID CONTROL UNIT (SN)	NOT NECESSARY	387.00	-
1	TAILGATE OPENING SENSOR LINE (SN)	NOT NECESSARY	190.00	-
1	BOOTLID CONTROL UNIT RETAINER (SN)	NOT NECESSARY	7.00	-
1	EXHAUST CHROME TRIM PIPE (SN)	DENTED	517.00	516.50
1	SUNDRIES (SN)	NOT NECESSARY	500.00	-
			6,552.00	3,332.00
LABOUR				
TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SNESOR .CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.			360.00	360.00
TO DISMANTLE AND RENEW REAR BUMPER .TO INSPECT END PANELLING .REORGANISE REAR CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED.			1,200.00	800.00
TO RESPRAY REAR BUMPER .			1,000.00	800.00
TO CARRY OUT DIAGNOSTIC CHECK .			192.00	192.00
			2,752.00	2,152.00

Report Ref No. CC3/EGI19009015/Ada3q2



GRAND TOTAL		9,304.00	5,484.00
RECOMMENDED COST OF REPAIRS			5,484.00

Report Ref No. CC3/EGI19009015/Ada3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.