

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0641/2019/NK
Date : 18-May-19

Vehicle not in workshop. Kindly arrange for survey.

Your insured vehicle : **SLA 3288 U**

ERGO INSURANCE PTE LTD

Motor Claims Dept
5 Temasek Boulevard
#04-01 Suntect Tower Five
Singapore 038985

Attn: Motor Claims Dept
Tel: 6829 9199

Owner's Name : Mr. Liow Ket Fui
Address : 67 Admiralty Drive
#10-183
Singapore 750467
Telephone : HP +65 93363861
Type of Claim : Third Party Claims
Policy No. : VA1/GA335599
Vehicle No : **SLV 9778 Y**
Model Code : Audi A6 C7 2.0 TFSI MU
Model / Year : 10-03-2015
Engine No : CDN 416939
Chassis No : WAUZZZ4G1EN200935
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 16-May-19

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLV 9778 Y

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00	✓
2	To dismantle and renew rear bumper. To inspect end panelling. Reorganise rear crash management components. Reinstall all parts removed.	\$ 1,200.00	700
3	To respray rear bumper	\$ 1,000.00	700
4	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: <u>\$ 2,752.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLV 9778 Y

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
1	REAR BUMPER <i>Red</i>	\$	2,343.00	✓
2	REAR BUMPER STICKT PADS <i>new</i>	NEC \$	21.00	+
3	REAR BUMPER FIXING PARTS <i>new</i>	NEC \$	249.00	+
4	REAR BUMPER SPOILER <i>new</i>	\$	316.00	✓
5	REAR BUMPER SECURING STRIP ?	NEC \$	157.00	?
6	REAR BUMPER REINFORCEMENT ?	\$	887.00	?
7	REAR BUMPER SEAL LH / RH <i>new</i>	2 \$	26.00	+
8	REAR BUMPER GUIDE SECTION LH / RH <i>new</i>	2 \$	60.00	+
9	CONNECTING PLATE <i>new</i>	2 \$	22.00	+
10	REAR BUMPER GUIDE PROFILE UPPER LH / RH	2 \$	106.00	+
11	REAR BUMPER GUIDE SECTION CENTRE	\$	96.00	+
12	REAR BUMPER GUIDE SECTION LOWER LH / RH	2 \$	96.00	+
13	REAR BUMPER COVER RH <i>new</i>	\$	105.00	+
14	REAR SENSORS <i>new</i>	2 \$	462.00	+
15	SEAL RINGS INNER / OUTER <i>new</i>	4 \$	5.00	+
16	BOOTLID CONTROL UNIT <i>new</i>	\$	387.00	+
17	TAILGATE OPENING SENSOR LINE <i>new</i>	\$	190.00	+
18	BOOTLID CONTROL UNIT RETAINER <i>new</i>	\$	7.00	+
19	EXHAUST CHROME TRIM PIPE <i>tot Dented</i>	\$	517.00	?
20	SUNDRIES ?	\$	500.00	?
GRAND TOTAL SPARE PARTS		:	\$ 6,552.00	
TOTAL LABOUR CHARGES		:	\$ 2,752.00	
GRAND TOTAL		:	\$ 9,304.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 21/05/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 Days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant