

ASS. REC. BY:

REF: CS/ICS/1009032/Atd3

Special Instruction:

Senior: Adrian

ASSIGNMENT (Office)

~~Mon~~

From (Person): Janice Goh

of

JES

Date/Time:

22/5/19 @ 10:41am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBH 4360T

Insured:

at Workshop m/s

First Autoworks

Tel:

68441985

of

23 Kaki Bukit Ave 4 #04-01

Policy No:

Claim No:

DMCV/100024H

Sum Insured:

Excess:

\$ 375.00

Make of Veh:

(Client's Record)

D.O.A.

14/5/2019

CA / REV / REP. / REV 24 HRS

23/4/19

H.O.D. Endorsement:

Date/Time:

2:23pm 22/5/19

Person Contacted:

Kelvin

Vehicle

OUT

Date/Time	Action/Instruction
	Estimate ✓
	GBH 4360T-X
23/5/19 @ 3:01pm	Request to Janice Goh via Messenger.
27/5/19	Janice Goh request send for authorise WSP to check repair cost. (Sent 3m WSP: progressive-ubi; Chang Hoe-June; SNE MOTOR).
31/May 13:20	mandate approve by Janice Goh
3/6 @ 10:19	Inform workshop authorise repair lump sum \$11,650

REF: 108

ASSIGNMENT

From:

Date: 23/5/2019

Veh No:

GBH4360T

Regn:

2018, May

Estimated Cost:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

GBH 4360T

Make:

Opel Combo

cc 1598

at Workshop m/s

First Autoworks

Colour:

Silver

A/C:

Insured / Std / NI / NA

of 23 kaki Bukit Ave 4 # 04-01

Sp Reading

9455

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

WOL6WZS1BJ9624858

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

\$375.00

Steering: Disorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Disorder / Jammed / Leaked / Burnt or

Make of Veh:

Mod: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

56K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA (REV) REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Tyre Size:

F:

195/60R16

R:

195/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

23/05/19

Survey held at

First Autoworks

Des. of Damages (Fr) /

Rear /

O/S /

N/S /

UIC /

Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

OD ECICS.

Repair Sum \$116507 (Red: 8868.60, 430%)

mv: 56

rv: 28k

Nett: 28k

RECEIVED 11 JUL 2019

Date/Time, File Path to:



Prel. Report

1) 1117 Typist



Final Report

Date/Time, File Path to:

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + PS: 31

Fees:

Other:

Total:

Add Fee:



Site Insp: 15



Interview: 15



Tech. Insp: 15



Workload: 15

Report Format: OD

Lump Sum / Blk: 11,650/-

450

11

461

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
10 Eunus Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Janice Goh

Date: 23 May 2019

Preliminary Advice

Vehicle No	: GBH4360T	Accident Date	: 14/05/2019
Make	: OPEL ASTRA	Policy No.	: MCV18A00038900
Assignment Date	: 22/05/2019	Excess	: S\$375.00
Date of Inspection	: 23/05/2019	Est. Duration of Repair	: 7.00
Inspection At	: FIRST AUTOWORKS PTE LTD (HQ) 23 KAKI BUKIT AVE 4 #04-01 SOUTH WING SINGAPORE 415933		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages first portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,518.60
Revised Amount	:S\$	9,855.40
Check Items (Estimated)	:S\$	4,704.00
Total	:S\$	14,559.40

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	56,000.00
COE / PARF Rebate	:S\$	28,000.00
Salvage Value	:S\$	
Margin for Repair	:S\$	28,000.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

View Received Message

This mail is associated with :

*GBH4360T (DMCV1900024H/JG)

OD

May 14 2019 12:00AM

[~]

First Autoworks Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From ECICS Limited (HQ) (ECICS), sent on 31/05/2019 15:20 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$11650.00) - GBH4360T - Claim Handler: Janice Goh

Approved:11650.00:Please submit survey report.

DOCUMENTS SUMMARY

There are no documents,

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 3 June 2019 10:19 AM
To: Kelvin.chew@alpinemotors.sg
Cc: suhaimi@firstautoworks.com.sg; SUR
Subject: GBH 4360T / OD / ECICS DOA: 14/5/2019

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **GBH 4360 (Excess \$375/-). ALL IN LUMP SUM \$11,650/-**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Nivitha (LKK Auto)

From: Janice Goh Siew Geok (ECICS, Claims) <Janice_Goh@ecics.com.sg>
Sent: Wednesday, 22 May 2019 10:41 AM
To: vincent.sim@alpinemotors.sg; assignments
Cc: matthew.tan@sew-eurodrive.com; motorsurvey
Subject: RE: GBH4360T - OPEL COMBO - OWN DAMAGED CLAIM - DOA 14-5-2019
Attachments: GBH4360T - OWN DAMAGED.PDF; GBH4360T_0001.jpg; GBH4360T_0002.jpg; GBH4360T_0003.jpg

Hi Vincent

Thank you for your email.
We will appoint LKK for the OD survey.

Aside to LKK

Please assist to arrange for OD survey.
Excess: \$375.00.

Our claim no. DMCV1900024H/JG and I am the case handler for this case.

Thank you.

Best regards

Janice Goh

Senior Associate | Claims



DID (65) 6303 0182

Tel (65) 6337 4779

Email janice_goh@ecics.com.sg Web www.ecics.com.sg

Address 10 Eunos Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

From: Vincent Sim [mailto:vincent.sim@alpinemotors.sg]
Sent: Wednesday, 22 May 2019 10:32 AM
To: motorsurvey
Cc: Janice Goh Siew Geok (ECICS, Claims); Crystabelle Tan Gek Peng (ECICS, Claims); matthew.tan@sew-eurodrive.com
Subject: GBH4360T - OPEL COMBO - OWN DAMAGED CLAIM - DOA 14-5-2019

Dear Sir, Madam.
Hereby attached the above estimate, kindly sent surveyor to inspect the vehicle.

Vehicle location at :
Person in charge :-
Suhaimi, Kelvin – 82925595 H/P.
68441985 – office phone
E-mail :
suhaimi@alpinemotors.sg

Kelvin.chew@alpinemotors.sg

Add;
First Autoworks Pte Ltd
23, Kaki Bukit Ave 4
#04-01 (South Wing)
singapore 415933
(Vicom Building)
tel; 6844-1985

Regards,
Vincent Sim- Claims Dept

Alpine Motors Pte Ltd / Auto Germany Pte Ltd

vincent.sim@alpinemotors.sg

65113022 ext 343

H/P 9247-8842

The information contained in this message is intended only for the recipient, and may be a confidential attorney-client communication or may otherwise be privileged and confidential and protected from disclosure. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, please be aware that any dissemination or copying of this communication is strictly prohibited. If you have received this communication in error, please immediately notify us by replying to the message and deleting it from your computer.

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

Denise Tay (LKKAuto)

From: Kelvin Chew <Kelvin.chew@alpinemotors.sg>
Sent: Tuesday, 4 June 2019 12:17 PM
To: Denise Tay (LKKAuto)
Cc: suhaimi@firstautoworks.com.sg; SUR
Subject: re: GBH 4360T / OD / ECICS DOA: 14/5/2019

Hi Dennis,

(Excess \$375/-). **ALL IN LUMP SUM \$11,650/-**.
agree with thanks.

from,
kelvin chew
8292 5595

From: "Denise Tay (LKKAuto)" <denisetay@lkkauto.com>
Sent: 03 June 2019 10:21
To: "Kelvin.chew@alpinemotors.sg" <Kelvin.chew@alpinemotors.sg>
Cc: "suhaimi@firstautoworks.com.sg" <suhaimi@firstautoworks.com.sg>, "SUR" <sur@lkkauto.com>
Subject: GBH 4360T / OD / ECICS DOA: 14/5/2019

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **GBH 4360 (Excess \$375/-). ALL IN LUMP SUM \$11,650/-**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

The information contained in this message is intended only for the recipient, and may be a confidential attorney-client communication or may otherwise be privileged and confidential and protected from disclosure. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, please be aware that any dissemination or copying of this communication is strictly prohibited. If you have received this communication in error, please immediately notify us by replying to the message and deleting it from your computer.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Thursday, 11 July 2019 3:08 PM
To: Kelvin.chew@alpinemotors.sg; SUR
Cc: suhaimi@firstautoworks.com.sg
Subject: RE: GBH 4360 T OPEL COMBO ECICS OD DOA 14.05.2019 finalise

Dear Kelvin,

Agree amount \$11,650.00 before excess \$375.00 & 7 working days.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Kelvin Chew <Kelvin.chew@alpinemotors.sg>
Sent: Thursday, 11 July 2019 11:23 AM
To: SUR <sur@lkkauto.com>
Cc: suhaimi@firstautoworks.com.sg
Subject: GBH 4360 T OPEL COMBO ECICS OD DOA 14.05.2019 finalise

Hi Lkk,

attach is finalise report.
global sum as agree amount \$11,650.00 before excess \$375.00 & 7 working days.
kindly please check & confirm with me.
vehicle survey by Mr. Adrian on 23.05.2019.
thanks.

from,
kelvin chew
8292 5595


The information contained in this message is intended only for the recipient, and may be a confidential attorney-client communication or may otherwise be privileged and confidential and protected from disclosure. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, please be aware that any dissemination or copying of this communication is strictly prohibited. If you have received this communication in error, please immediately notify us by replying to the message and deleting it from your computer.

500+ dealers
competed to
buy my car!



Sell us Car for More Cash
Highest Price or Get \$100 Free
Get Paid Now, Handover Later

SELL YOUR CAR



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

2011 KIA Niro 1.6A



Model: 2011 KIA Niro 1.6A
Mileage: 110,000 km
Price: \$11,000
Contact: 09-12345678

Post an Ad

Advertiser Login

Ways of Selling

AutoInn
No Depreciation For Car Buyer!

click here to view
our **PRISTINE USED CARS**
at GREAT PRICES

Browse by Category

Sort by Date Posted 20 results/page

4 vehicles

Opel Combo

Refinement: Basic

	Make	Model	Price	Depreciation	Year Used	Eng Cap	Mileage	Veh Type	Status
Search Selection	Opel	Combo	Any	Any	2018	Any	Any	Any	Available
	Opel	Combo 1.6A	\$59,888	\$6,570 /yr	09-May-2018	1,598 cc	-	Van	Available
Fuel Type: Diesel One Of The Silver Fishes Is Out Of The Ocean And Roaming Now On Land. Do Call Me Or Drop Me An WhatsApp Sms To Make Appointment To View This Vehicle. Posted: 21-Apr-2019 Tags: 2018 Opel Combo, 2018 opel combo, Opel Combo, opel combo, Opel, Combo, combo, Used Opel									
	Opel	Combo 1.6A	\$59,888	\$6,570 /yr	28-Jun-2018	1,598 cc	-	Van	Available
Fuel Type: Diesel Semi Auto Transmission. Management Vehicle For Sales. To Avoid Disappointment As Vehicle Will Be Driven Out Most Of The Time, Do Call Me And Make An Appointment Before Coming Down To View. Posted: 06-Apr-2019 Tags: 2018 Opel Combo, 2018 opel combo, Opel Combo, opel combo, Opel, Combo, combo, Used Opel									
	Opel	Combo 1.6A	\$59,888	\$6,570 /yr	27-Jun-2018	1,598 cc	-	Van	Available
Fuel Type: Diesel Semi Auto Transmission. Management Vehicle For Sale. To Avoid Disappointment As Vehicle Will Be Driven Out Most Of The Time, Do Call Me And Make An Appointment Before Coming Down To View. Posted: 06-Apr-2019 Tags: 2018 Opel Combo, 2018 opel combo, Opel Combo, opel combo, Opel, Combo, combo, Used Opel									
	Opel	Combo 1.6A	\$59,888	\$6,710 /yr	20-Apr-2018	1,598 cc	-	Van	Available
Fuel Type: Diesel Call Or Drop An Whatsapp Message To Our Friendly Sales Staff For A Viewing Of This Stylo Milo Vehicle. Posted: 03-Apr-2019 Tags: 2018 Opel Combo, 2018 opel combo, Opel Combo, opel combo, Opel, Combo, combo, Used Opel									

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Year Used Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

Home New Cars Used Cars Sell My Car Directory Products Insurance Article Forum Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to CDE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Opel Combo, Opel Combo Singapore, used Opel Combo Singapore, used Opel Combo, used vehicles Singapore or even buy used Opel Combo Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & CDE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement

©2004-2019 sgCarMart. All rights reserved.

Copyright

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	5464C

Vehicle Details

Vehicle No.:	GBH4360T
Vehicle to be Exported:	Yes
Intended Deregistration Date:	17 May 2019
Vehicle Make:	OPEL
Vehicle Model:	COMBO-D 1.6 MT E6
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	263A90008105265
Chassis No.:	W0L6WZ51BJ9624858
Maximum Power Output:	-
Open Market Value:	\$23,538.00
Original Registration Date:	31 May 2018
First Registration Date:	31 May 2018
Transfer Count:	0
Actual ARF Paid:	\$1,177.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	30 May 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$35,001.00
COE Rebate Amount:	\$28,000.00
Total Rebate Amount:	\$28,000.00

The information contained herein is correct as at 17 May 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/05/2019 09:45
Date Of Accident	14/05/2019 17:15
Exact Location Of Accident	JUNCTION JURONG TOWN HALL RD/WEST COAST RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBH4360T
Insured/Policyholder	
Name Of Registered Owner	SEW- EURODRIVE PTE LTD
Co Reg No	198105464C
Email Address	MATTHEW.TAN@SEW-EURODRIVE.COM
Mobile Phone No	(LOCAL) +65-96210212
Alternative Phone No	OFFICE-68621701

Vehicle Particulars

Manufacturer	OPEL
Model	COMBO 1.6 DIESEL MTA
Exact Purpose for which vehicle was being used at time of accident	WORKING PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	ECICS LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	WOL6WZS1BJ9624858
Cover Note Number	

Driver

Name of Driver	TAN JOO LEM MATTHEW
NRIC No	S1384564F
Date Of Birth	29/11/1959
Occupation	OUTDOOR
Date Of Driving Pass	16/10/2007
Driving Experience	11 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96210212
Fax Number	
Contact Number	
Email Address	MATTHEW.TAN@SEW-EURODRIVE.COM

Address	25 WEST COAST DRIVE
Postcode	127468
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP4770D
Vehicle Make/Model/Colour	ISUZU
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Lorry in front of me suddenly stop. I also applied
Brake to stop - but not in time I hit his rear

(A) YIP 4770

(B) GAM 4360

DECLARATION

I/we declare the following particulars are true in every respect

X

Policyholder's Signature
& Time

15-May-2019
1500 hrs

Chau

Driver's Signature
(If driver is not the policyholder)
Date & Time

15-May-2019
1520 hrs

[Signature]

Reporting Centre Personnel's Signature
Name
NIC/PIN No

Sketch Plan #2

SKETCH PLAN

IMPORTANT NOTICE

1. ✓ State report correctly the details of the accident to uphold the claims process.
2. ✓ The Form must be completed by the Policyholder and/or the Authorized Driver.
3. ✓ Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insured companies to repudiate policy liability.
4. ✓ The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. ✓ Any false reporting may be referred to the Police for investigation.
6. ✓ The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copy of this report will for a fee be made available upon application by interested parties.
7. ✓ By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. ✓ Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time
 15-May-2019
 15.00 hrs


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time
 15-May-2019
 15.00 hrs


 Reporting Centre Personnel's Signature
 Name
 SKH/CPN No.

LETTER TO AUTHORISE



SEW-EURODRIVE PTE LTD

149, R Tirth Drive 2 • Jurong • Singapore 628811 • Tel: (65) 6862 1111 • Fax: (65) 6861 0811 5927 • E: sew@sew-eurodrive.com.sg
SEW-EURODRIVE

16-May-2019

Alpine Motors Pte Ltd / Auto Germany Pte Ltd

7 Ubi Close, Alpine Centre

Singapore 408604

Dear Sir/Madam,

Our employee, Tan Joo Lem Matthew IC No. S1384564F is authorised to do the reporting on behalf of the company in matters relating to the accident vehicle GBH4360T.

Thanking you in advance.

Yours sincerely,

A handwritten signature in black ink, appearing to read "Lim Ai Leng".

Lim Ai Leng

Head Admin Dept.



ORIGINAL COPY

MOTOR COVER NOTE

Motor Vehicles (Third-Party Risk Compensation) Act (Chapter 185)
 Motor Vehicles (Third-Party Risk and Compensation) Rules 1997
 Road Transport Act, 1987 (Malaysia)
 Motor Vehicles (Third-Party Risk) Rules, 1976 (Malaysia)
 And any subsequent amendments to the above Acts and Regulations

The insured mentioned in the Schedule having proposed for insurance in respect of the Motor Vehicle described in the Schedule, in hereby **WEL COMED** under the terms of the Company's usual terms of Motor Policy applicable thereto for the period mentioned in the Schedule and that the cover be terminated by the Company by notice in writing in which case the insurance will thereupon cease and a proportionate part of the annual premium otherwise payable for such insurance will be charged for the term the Company has been on risk.

COVER NOTE NO:	EC100012	Class 1 Job:	W000V2518/962454
Agency Name:	ASPIRE INSURANCE AGENCY PTE LTD	Engine No:	244A90038106265
Agency Code:	48000362	Year:	2017
File Purchase Company:	MSL		

1. Index Mark and Registration Number of Vehicle:	B6H 4560T	TO GO ADVISE
2. Name of the Holder:	SEM-SUBSIDIARY PTE LTD	SEM-DRIVE-4560T
3. Effective date of the Commencement of Insurance:	31 MAY 2018	
Date of Expiry of Insurance:	30 MAY 2019	
4. Details of Vehicle:		
Make and Description of Vehicle:	OPSL COMBO 1.6M	
Year of manufacture:	2017	
Vehicle Tonnage:	0.50	
5. Cover Type:	COMPREHENSIVE	
Excess:	S\$750.00	
6. Value (\$\$)	AS PER MARKET VALUE	
7. Authorized Workshop:	OPSL WORKS-HQ	

(We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risk and Compensation) Act (Chapter 185) and Part IV of the Road Transport Act, 1987 (Malaysia).)

Issued by: SUCO LMS112

OR

EDR500103804

Signed By:

Authorized Officer

NOTE:

This Cover Note is valid only for 14 days from the date of issue, unless reported by the Certificate of Insurance issued by ICQ United.

Premium is charged on the basis of the premium for the first year will be charged at a rate of S\$10.00 (exclusive of GST).

An administrative fee of S\$25.00 (exclusive of GST) will be charged for retaining old registration number for a new vehicle.



Date :17/05/2019

Reference: OPEL
Make: COMBO

To Whom It May Concern

Dear Sir,

RE: VEHICLE : GBH4360T
CHASSIS NO.: W0L6WZS1BJ9624858
ENGINE NO.: 263A90008105265

Name of insured : SEW-EURODRIVE PTE LTD
Date of accident.: 14/05/2019

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	FRT BONNET <i>Distorted</i>	\$ 662.00
2	1	FRT BONNET HINGE RH <i>3 Best</i>	\$ 122.00
3	1	FRT BONNET HINGE LH	\$ 184.00
4	1	FRT BONNET STOPPED SET <i>new</i>	\$ 112.00
5	1	FRT BONNET VEHICLE MODEL LABEL <i>3 piece</i>	\$ 30.00
6	1	FRT BONNET VEHICLE PAINT LABEL	\$ 42.00
7	1	FRT BONNET INSULATOR <i>cracked</i>	\$ 154.00
8	1	FRT BONNET INSULATOR ENGINE WARNING LABEL <i>new</i>	\$ 48.00
9	10	FRT BONNET INSULATOR CLIP <i>new</i>	\$ 65.00
10	1	FRT BONNET LOCK <i>Distorted</i>	\$ 142.00
11	1	FRT BONNET LOCK CABLE <i>new</i>	\$ 115.00
12	1	FRT BUMPER <i>Distorted</i>	\$ 1,194.00
13	1	FRT BUMPER FOG LAMP LH <i>3 piece</i>	\$ 196.00
14	1	FRT BUMPER FOG LAMP RH	\$ 196.00
15	10	FRT BUMPER CLIP <i>new</i>	\$ 65.00
16	1	FRT BUMPER SPONGE <i>cracked</i>	\$ 160.00
17	1	FRT BUMPER REINFORCEMENT <i>3rd</i>	\$ 362.00
18	1	FRT BUMPER NUMBER PLATE BASE <i>cracked</i>	\$ 58.00
19	1	FRT BUMPER SIDE RETAINER RH <i>3 piece</i>	\$ 18.00
20	1	FRT BUMPER SIDE RETAINER LH	\$ 18.00
21	1	FRT BUMPER TOP CENTRE RETAINER <i>Distorted</i>	\$ 112.00
22	1	FRT BUMPER LOW LIP <i>new</i>	\$ 174.00
23	1	FRT GRILLE ASSY <i>cracked</i>	\$ 364.00
24	1	FRT HEADLAMP RH <i>3 cracked</i>	\$ 678.00
25	1	FRT HEADLAMP LH	\$ 678.00
26	1	A/C CONDENSOR <i>Distorted</i>	\$ 1,178.00
27	1	A/C PIPE SUCTION(coil to condensor) <i>new</i>	\$ 578.00
28	1	A/C PIPE DISCHARGE(condensor to compressor) <i>new</i>	\$ 578.00
29	1	A/C CONDENSOR AIR GUIDE TOP <i>cracked</i>	\$ 110.00
30	1	A/C CONDENSOR AIR GUIDE LOW <i>cracked</i>	\$ 167.00

31	1	RADIATOR <i>Bent</i>		\$ 1,170.00	2
32	2	RADIATOR TOP MOUNTING <i>new</i>		\$ 12.00	3
33	2	RADIATOR LOW MOUNTING <i>new</i>		\$ 16.00	2
34	1	RADIATOR INLET HOSE <i>new</i>		\$ 116.00	2
35	1	RADIATOR OUTLET HOSE <i>new</i>		\$ 108.00	2
36	1	RADIATOR FAN COWLING <i>new</i>		\$ 336.00	2
37	1	RADIATOR FAN BLADE & MOTOR <i>new</i>		\$ 907.00	2
38	1	RADIATOR SPARE TANK <i>new</i>		\$ 294.00	2
39	1	RADIATOR SPARE TANK HOSE INLET <i>new</i>		\$ 86.00	2
40	1	RADIATOR SPARE TANK HOSE OUTLET <i>new</i>		\$ 98.00	2
41	1	RADIATOR SUPPORT PANEL TOP CENTRE <i>new</i>		\$ 510.00	2
42	1	FRT HEADLAMP LOW PANEL LH <i>new</i>		\$ 220.00	2
43	1	FRT HEADLAMP LOW PANEL RH <i>new</i>		\$ 220.00	2
44	1	P.S.F COOLER PIPE <i>new</i>		\$ 389.00	2
45	1	TURBO INTAKE COOLER <i>new</i>		\$ 1,146.00	2
46	1	TURBO INTAKE COOLER HOSE INLET <i>new</i>		\$ 292.00	2
47	1	TURBO INTAKE COOLER HOSE OUTLET <i>new</i>		\$ 216.00	2
48	1	FRT FENDER RH <i>new</i>		\$ 352.00	2
49	1	FRT FENDER INNER SHIELD RH <i>new</i>		\$ 220.00	2
50	10	FRT FENDER INNER SHIELD CLIP <i>new</i>		\$ 65.00	2
51	1	FRT FENDER LH <i>new</i>		\$ 352.00	2
52	1	FRT FENDER INNER SHIELD LH <i>new</i>		\$ 220.00	2
53	1	FRT WIPER GARNISH <i>new</i>		\$ 212.00	2

Parts Total: \$ 16,117.00
Less 20%: \$ 3,223.40
Total : \$ 12,893.60

Labour

Labour Description

No.		Price (SGD)	
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 3,300.00	2200
2	Carry out spray painting on affected area, FRT BUMPER, FRT BONNET, FRT SUPPORT PANEL, FRT FENDER LH, FRT FENDER RH, FRT DOOR RH, FRT DOOR LH	\$ 3,000.00	2100
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 180.00	120
4	To remove and refit aircon condensor, vacuum, refill and check air con gas system	\$ 600.00	300
5	To remove and refit radiator and conduct pressure test	\$ 120.00	80
6	To conduct reset of engine light on	\$ 350.00	✓

Labour Total : \$ 7,550.00

Others

Other Description

No.			Price (SGD)
1	FRT NUMBER PLATE	<i>combined</i>	\$ 35.00 ✓
2	POWER STEERING FLUID	<i>new</i>	\$ 20.00 ✓
3	RADIATOR COOLANT	<i>per</i>	\$ 20.00 ✓

Other Total: \$ 75.00

TOTAL: \$ 20,518.60

GST (7%): \$ 1,436.30

GRAND TOTAL : \$ 21,954.90

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully

Service Advisor

Adnan bin
P/P 23/05/19.

07 Days
Not Authorised
Excess \$375.



Date :17/05/2019

Reference: OPEL
Make: COMBO

To Whom It May Concern

Dear Sir,

RE: VEHICLE .: GBH4360T
CHASSIS NO.: W0L6WZS1BJ9624858
ENGINE NO.: 263A90008105265

Name of insured .: SEW-EURODRIVE PTE LTD
Date of accident.: 14/05/2019

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	FRT BONNET <i>Distorted</i>	\$ 662.00
2	1	FRT BONNET HINGE RH <i>3 Best</i>	\$ 122.00
3	1	FRT BONNET HINGE LH	\$ 184.00
4	1	FRT BONNET STOPPED SET <i>new</i>	\$ 112.00
5	1	FRT BONNET VEHICLE MODEL LABEL <i>green</i>	\$ 30.00
6	1	FRT BONNET VEHICLE PAINT LABEL	\$ 42.00
7	1	FRT BONNET INSULATOR <i>cracked</i>	\$ 154.00
8	1	FRT BONNET INSULATOR ENGINE WARNING LABEL <i>new</i>	\$ 48.00
9	10	FRT BONNET INSULATOR CLIP <i>new</i>	\$ 65.00
10	1	FRT BONNET LOCK <i>Distorted</i>	\$ 142.00
11	1	FRT BONNET LOCK CABLE <i>new</i>	\$ 115.00
12	1	FRT BUMPER <i>Distorted</i>	\$ 1,194.00
13	1	FRT BUMPER FOG LAMP LH <i>green</i>	\$ 196.00
14	1	FRT BUMPER FOG LAMP RH	\$ 196.00
15	10	FRT BUMPER CLIP <i>new</i>	\$ 65.00
16	1	FRT BUMPER SPONGE	\$ 160.00
17	1	FRT BUMPER REINFORCEMENT	\$ 362.00
18	1	FRT BUMPER NUMBER PLATE BASE <i>cracked</i>	\$ 58.00
19	1	FRT BUMPER SIDE RETAINER RH <i>green</i>	\$ 18.00
20	1	FRT BUMPER SIDE RETAINER LH	\$ 18.00
21	1	FRT BUMPER TOP CENTRE RETAINER <i>Distorted</i>	\$ 112.00
22	1	FRT BUMPER LOW LIP <i>new</i>	\$ 174.00
23	1	FRT GRILLE ASSY <i>cracked</i>	\$ 364.00
24	1	FRT HEADLAMP RH <i>cracked</i>	\$ 678.00
25	1	FRT HEADLAMP LH	\$ 678.00
26	1	A/C CONDENSOR	\$ 1,178.00
27	1	A/C PIPE SUCTION(coil to condensor) <i>new</i>	\$ 578.00
28	1	A/C PIPE DISCHARGE(condensor to compressor) <i>new</i>	\$ 578.00
29	1	A/C CONDENSOR AIR GUIDE TOP	\$ 110.00
30	1	A/C CONDENSOR AIR GUIDE LOW	\$ 167.00

31	1	RADIATOR		\$ 1,170.00	?
32	2	RADIATOR TOP MOUTING	?	\$ 12.00	?
33	2	RADIATOR LOW MOUTING	?	\$ 16.00	?
34	1	RADIATOR INLET HOSE	?	\$ 116.00	?
35	1	RADIATOR OUTLET HOSE	?	\$ 108.00	?
36	1	RADIATOR FAN COWLING	?	\$ 336.00	?
37	1	RADIATOR FAN BLADE & MOTOR	?	\$ 907.00	?
38	1	RADIATOR SPARE TANK	?	\$ 294.00	?
39	1	RADIATOR SPARE TANK HOSE INLET	?	\$ 86.00	+
40	1	RADIATOR SPARE TANK HOSE OUTLET	?	\$ 98.00	+
41	1	RADIATOR SUPORT PANEL TOP CENTRE	Best	\$ 510.00	✓
42	1	FRT HEADLAMP LOW PANEL LH	?	\$ 220.00	?
43	1	FRT HEADLAMP LOW PANEL RH	?	\$ 220.00	?
44	1	P.S.F COOLER PIPE	?	\$ 389.00	?
45	1	TURBO INTAKE COOLER	?	\$ 1,146.00	+
46	1	TURBO INTAKE COOLER HOSE INLET	?	\$ 292.00	+
47	1	TURBO INTAKE COOLER HOSE OUTLET	?	\$ 216.00	+
48	1	FRT FENDER RH	Buckled	\$ 352.00	✓
49	1	FRT FENDER INNER SHIELD RH	?	\$ 220.00	+
50	10	FRT FENDER INNER SHIELD CLIP	?	\$ 65.00	+
51	1	FRT FENDER LH	Buckled	\$ 352.00	✓
52	1	FRT FENDER INNER SHIELD LH	?	\$ 220.00	+
53	1	FRT WIPER GARNISH	new	\$ 212.00	+

Parts Total: \$ 16,117.00

Less 20%: \$ 3,223.40

Total : \$ 12,893.60

Labour

No.	Labour Description	Price (SGD)	
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 3,300.00	2200
2	Carry out spray painting on affected area, FRT BUMPER, FRT BONNET, FRT SUPORT PANEL, FRT FENDER LH, FRT FENDER RH, FRT DOOR RH, FRT DOOR LH	\$ 3,000.00	2100
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 180.00	120
4	To remove and refit aircon condensor, vacuum, refill and check air con gas system	\$ 600.00	300
5	To remove and refix radiator and conduct pressure test	\$ 120.00	80
6	To conduct reset of engine light on	\$ 350.00	✓

Labour Total : \$ 7,550.00

Others

Other Description

No.			Price (SGD)
1	FRT NUMBER PLATE	<i>cracked</i>	\$ 35.00
2	POWER STEERING FLUID	<i>new</i>	\$ 20.00
3	RADIATOR COOLANT	<i>per</i>	\$ 20.00

Other Total: \$ 75.00

TOTAL: \$ 20,518.60

GST (7%): \$ 1,436.30

GRAND TOTAL : \$ 21,954.90

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully

Service Advisor

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adnan bin
P/P 23/05/19.

07 Days

Not Authorised

Excess \$375

FINALIZE

Wir leben Autos.

ECICS LIMITED

GST Ref. No: 20-0000274-Z

Vehicle No: GBH4360T
Chassis No: W0L6WZS1BJ9624858
Engine No: 263A90008105265
Date of accident: 14/05/2019

Invoice No:

Invoice Date:

DESCRIPTION	AMOUNT	SGD
-------------	--------	-----

Parts

No.	Qty.	Description	Price (SGD)
1	1	FRT BONNET	\$ 662.00
2	1	FRT BONNET HINGE RH	\$ 122.00
3	1	FRT BONNET HINGE LH	\$ 184.00
4	1	FRT BONNET VEHICLE MODEL LABEL	\$ * 30.00
5	1	FRT BONNET VEHICLE PAINT LABEL	\$ 42.00
6	1	FRT BONNET INSULATOR	\$ 154.00
7	1	FRT BONNET INSULATOR ENGINE WARNING LABEL	\$ 48.00
8	5	FRT BONNET INSULATOR CLIP	\$ 30.00
9	1	FRT BONNET LOCK	\$ 142.00
10	1	FRT BUMPER	\$ 1,194.00
11	6	FRT BUMPER CLIP	\$ 40.00
12	1	FRT BUMPER SPONGE	\$ 160.00
13	1	FRT BUMPER REINFORCEMENT	\$ 362.00
14	1	FRT BUMPER NUMBER PLATE BASE	\$ 58.00
15	1	FRT BUMPER SIDE RETAINER RH	\$ 18.00
16	1	FRT BUMPER SIDE RETAINER LH	\$ 18.00
17	1	FRT BUMPER TOP CENTRE RETAINER	\$ 112.00
18	1	FRT GRILLE ASSY	\$ 364.00
19	1	FRT HEADLAMP RH	\$ 678.00
20	1	FRT HEADLAMP LH	\$ 678.00
21	1	A/C CONDENSOR	\$ 1,178.00
22	1	A/C CONDENSOR AIR GUIDE TOP	\$ 110.00
23	1	A/C CONDENSOR AIR GUIDE LOW	\$ 167.00
24	1	RADIATOR	\$ 1,170.00
25	1	RADIATOR FAN COWLING	\$ 336.00
26	1	RADIATOR FAN BLADE & MOTOR	\$ 907.00
27	1	RADIATOR SUPPORT PANEL TOP CENTRE	\$ 510.00
28	1	TURBO INTAKE COOLER	\$ 1,146.00
29	1	FRT FENDER RH	\$ 352.00
30	1	FRT FENDER LH	\$ 352.00

Supplementary

1	-		\$	-
---	---	--	----	---

Total: \$ 11,324.00
 Less 20%: \$ 2,264.80
 Parts Total: \$ 9,059.20

Labour

No.			Price (SGD)
1		TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION. TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIRED / REPLACEMENT PARTS.	\$ 2,200.00
2		CARRY OUT SPRAY PAINTING OF ACCIDENT AFFECTED AREA.FRT BUMPER , FRT BONNET , FRT FENDER LH , FRT FENDER RH , FRT DOOR RH , FRT DOOR LH	\$ 2,100.00
3		TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	\$ 120.00
4		TO REMOVE AND REFIT AIRCON CONDENSOR , VACUUM , REFILL AND CHECK AIR CON GAS SYSTEM	\$ 300.00
5		TO REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00
6		TO CONDUCT RESET OF ENGINE LIGHT ON	\$ 350.00

Labour Total : \$ 5,150.00

Other

No.			Price (SGD)
1	1	FRONT NUMBER PLATE	\$ 35.00
2	1	POWER STEERING FLUID	\$ 20.00
3	1	RADIATOR COOLANT	\$ 20.00

Other Total : \$ 75.00

Total : \$ 14,284.20
 Amount as agree : \$ 11,650.00
 Excess: \$ 375.00
 GST (7%) : \$ 789.25
 Grand Total : \$ 12,064.25

Yours Faithfully,

Kelvin Chew
 Service Advisor

Tel: 68441985 Fax:68445185

Please check and finalize with me

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS19009032/ATD3N2

Date: 16/07/2019

REFERENCE

Insured/Claimant: SEW-EURODRIVE PTE LTD Policy No: MCV18A00038900

Date of Loss: 14/05/2019

Nature of Claim: OD

Claim No: DMCV1900024H/JG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH4360T	Engine No:	263A90008105265
Make & Model:	OPEL COMBO, 1.6 (M)	Chassis No:	W0L6WZS1BJ9624858
Reg. Date:	31/05/2018 (Man. Year: 2017)	Odometer:	9455 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	S\$56,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/ 60R16	Rear Tyre Size:	195/ 60R16
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	12,968.60	9,134.20	3,834.40	29.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,550.00	5,150.00	2,400.00	31.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,518.60	14,284.20	6,234.40	30.38
Approved Total (Overridden) (S\$)		11,650.00		
- Excess (S\$)	375.00	375.00	0.00	0.00
(S\$)	20,143.60	11,275.00	8,868.60	44.03
+ GST 7.00/7.00% (S\$)	1,410.05	789.25	620.80	44.03
Nett Amount (S\$)	21,553.65	12,064.25	9,489.40	44.03

INSPECTION

Date of Assignment: 22/05/2019

Date Inspected: 23/05/2019 Inspected At:

First Autoworks Pte Ltd (HQ)
23 KAKI BUKIT AVE 4 #04-01 SOUTH
WING
Singapore 415933

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Jul 2019)
Parts:	144	OPEL COMBO 1.6 (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH4360T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Distorted	662.00 FL	*662.00 FL
2	1		*FRONT BONNET HINGE RH	Bent	122.00 FL	*122.00 FL
3	1		*FRONT BONNET HINGE LH	Bent	184.00 FL	*184.00 FL
4	1		*FRONT BONNET STOPPED SET	Not Necessary	112.00 FL	*- FL
5	1		*FRONT BONNET VEHICLE MODEL LABEL	Necessary	30.00 FL	*30.00 FL
6	1		*FRONT BONNET VEHICLE PAINT LABEL	Necessary	42.00 FL	*42.00 FL
7	1		*FRONT BONNET INSULATOR	Crumpled	154.00 FL	*154.00 FL
8	1		*FRONT BONNET INSULATOR ENGINE EARNING LABEL	Necessary	48.00 FL	*48.00 FL
9	10		*FRONT BONNET INSULATOR CLIP	Necessary	65.00 FL	*30.00 FL
10	1		*FRONT BONNET LOCK	Damaged	142.00 FL	*142.00 FL
11	1		*FRONT BONNET LOCK CABLE	Not Necessary	115.00 FL	*- FL
12	1		*FRT BUMPER	Distorted	1,194.00 FL	*1,194.00 FL
13	1		*FRT BUMPER FOG LAMP LH	Not Necessary	196.00 FL	*- FL
14	1		*FRT BUMPER FOG LAMP RH	Not Necessary	196.00 FL	*- FL
15	10		*FRT BUMPER CLIP	Necessary	65.00 FL	*40.00 FL
16	1		*FRT BUMPER SPONGE	Cracked	160.00 FL	*160.00 FL
17	1		*FRT BUMPER REINFORCEMENT	Bent	362.00 FL	*362.00 FL
18	1		*FRT BUMPER NUMBER PLATE BASE	Cracked	58.00 FL	*58.00 FL
19	1		*FRT BUMPER SIDE RETAINER RH	Necessary	18.00 FL	*18.00 FL
20	1		*FRT BUMPER SIDE RETAINER LH	Necessary	18.00 FL	*18.00 FL
21	1		*FRT BUMPER TOP CENTRE RETAINER	Damaged	112.00 FL	*112.00 FL
22	1		*FRT BUMPER LOW LIP	Not Necessary	174.00 FL	*- FL
23	1		*FRT GRILLE ASSY	Cracked	364.00 FL	*364.00 FL
24	1		*FRT HEADLAMP RH	Cracked	678.00 FL	*678.00 FL
25	1		*FRT HEADLAMP LH	Cracked	678.00 FL	*678.00 FL
26	1		*A/C CONDENSOR	Dented	1,178.00 FL	*1,178.00 FL
27	1		*A/C PIPE SUCTION (COIL TO CONDENSOR)	Not Necessary	578.00 FL	*- FL
28	1		*A/C PIPE DISCHARGE (CONDENSOR TO COMPRESSOR)	Not Necessary	578.00 FL	*- FL
29	1		*A/C CONDENSOR AIR GUIDE TOP	Cracked	110.00 FL	*110.00 FL
30	1		*A/C CONDENSOR AIR GUIDE LOW	Cracked	167.00 FL	*167.00 FL
31	1		*RADIATOR	Dented	1,170.00 FL	*1,170.00 FL
32	2		*RADIATOR TOP MOUNTING	Not Necessary	12.00 FL	*- FL
33	2		*RADIATOR LOW MOUNTING	Not Necessary	16.00 FL	*- FL
34	1		*RADIATOR INLET HOSE	Not Necessary	116.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
35	1		*RADIATOR OUTLET HOSE	Not Necessary	108.00 FL	*- FL
36	1		*RADIATOR FAN COWLING	Cracked	336.00 FL	*336.00 FL
37	1		*RADIATOR FAN BLADE & MOTOR	Damaged	907.00 FL	*907.00 FL
38	1		*RADIATOR SPARE TANK	Not Necessary	294.00 FL	*- FL
39	1		*RADIATOR SPARE TANK HOSE INLET	Not Necessary	86.00 FL	*- FL
40	1		*RADIATOR SPARE TANK HOSE OUTLET	Not Necessary	98.00 FL	*- FL
41	1		*RADIATOR SUPPORT PANEL TOP CENTRE	Bent	510.00 FL	*510.00 FL
42	1		*FRT HEADLAMP LOW PANEL LH	Not Necessary	220.00 FL	*- FL
43	1		*FRT HEADLAMP LOW PANEL RH	Not Necessary	220.00 FL	*- FL
44	1		*P.S.F COOLER PIPE	Not Necessary	389.00 FL	*- FL
45	1		*TURBO INTAKE COOLER	Dented	1,146.00 FL	*1,146.00 FL
46	1		*TURBO INTAKE COOLER HOSE INLET	Not Necessary	292.00 FL	*- FL
47	1		*TURBO INTAKE COOLER HOSE OUTLET	Not Necessary	216.00 FL	*- FL
48	1		*FRT FENDER RH	Buckled	352.00 FL	*352.00 FL
49	1		*FRT FENDER INNER SHIELD RH	Not Necessary	220.00 FL	*- FL
50	10		*FRT FENDER INNER SHIELD CLIP	Not Necessary	65.00 FL	*- FL
51	1		*FRT FENDER LH	Buckled	352.00 FL	*352.00 FL
52	1		*FRT FENDER INNER SHIELD LH	Not Necessary	220.00 FL	*- FL
53	1		*FRT WIPER GARNISH	Not Necessary	212.00 FL	*- FL
54	1		*FRT NUMBER PLATE	Cracked	35.00 FS	*35.00 FS
55	1		*POWER STEERING FLUID	Necessary	20.00 FS	*20.00 FS
56	1		*RADIATOR COOLANT	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,192.00	11,399.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,223.40	2,264.80
Total Parts (\$\$)	12,968.60	9,134.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION, TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS.	New	3,300.00	2,200.00
2	CARRY OUT SPRAY PAINTING ON AFFECTED AREAS, FRT BUMPER, FRT BONNET, FRT SUPPORT PANEL, FRT FENDER LH, FRT FENDER RH, FRT DOOR RH, FRT DOOR LH.	New	3,000.00	2,100.00
3	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR.	New	180.00	120.00
4	TO REMOVE AND REFIT AIRCON CONDENSOR, VACUUM, REFILL AND CHECK AIR CON GAS SYSTEM.	New	600.00	300.00
5	TO REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST.	New	120.00	80.00
6	TO CONDUCT RESET OF ENGINE LIGHT ON.	New	350.00	350.00
Gross Labour Cost (S\$)			7,550.00	5,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >