

2306/2019

ASS. REC. BY:

Surveyor: Hwa JieFrom (Person): Thelma Choo

Estimated Cont:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 6425Cat Workshop in/s: SMART Automotiveof NO 61 Woodlands Industrial Park EQ #04-08Policy No: D19 MTPV 01000837

Sum Insured:

Make of Veh:
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 23.5.2019 4:56 PM

Person Contacted:

Shanti

Vehicle IN/OUT

H.O.D. Endorsement:

D.O.A. 19.5.2019

Excess:

Claim No: CM1D1902469Insured: SDP 424Tel: 68662671

ASSIGNMENT (Office)

of SMDDate/Time: 22.5.19 16:47 PM

Special Instructions:

REF: CS / SMD 19009034 / AS d307

Date/Time Action/Instruction (✓) Estimate

SHD 6425C - N2 / IN 19020627 / 6425C

SDP 424 - X

D.O.A. - 11/11/2019

28/05/19 @ 11:46 am revised ZA to Thelma Choo via meriner.

25/06/19 @ 14:24 pm (Celine information, Hwa Jie mentioned
Thi Yeng Gypow) agreed report the vehicle not
exceeding \$42K on part by part basis.

DATE: 23/5/2019
REF: SMO

ASSIGNMENT

Front: Date: 23.5.2019
Estimated Cost:
OD TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SHD 6425C
at Workshop m/s: SMRT Automotive
of: M61 Woodland Industrial Park E9 # 04-04
Insured:
Policy No:
Claims No:
Sum Insured: Excess:
(Client's Record)
Make of Veh:

Veh No: SHD6425C Yr Regn: 1 Nov/2017
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or:
Make: Toyota Prius C.C. 1798
Colour: maroon A/C: Insured / Std / Nil / NA
Sp. Reading: - T/Radio: Insured / Std / Nil / NA
Eng/No:
C/No: JTDKB3FU903573380
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Insured / Jammed / Leaked / Burnt or
Brake: Insured / Jammed / Leaked / Burnt or
Mod: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 195 / 65 R15
R: -

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: days Res.: Yes or No
Lum Sum: % 3 Val: Yes or No
CA / REV / REP. / 24 HRS "wp"
Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Westlake
Front: Roar:
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 19/5/19 D.O.L. 23/5/19
Survey held at Smrt
Des. of Damages: Frt Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	23/7/19, Final amount \$39,603.85, 18 days 05/19/2080
	Huaz Jie,
	PLS check repair margin.
24/07/19	Confirmed p/p \$ 30,603.85 @ 18 days with Steve. (\$ 61,676.04 Red - 67%)
	RECEIVED 26 JUL 2019

Date/Time, File Pass to:
25/07/19
Type:
Date/Time, File Return to:

☐ : Prel. Report
☒ : Final Report

Days Of Repair: 18
Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:
Transportation:
Photos:
Others:
TOTAL

150
11
161

Report Format:
Lump Sum (L.B.) (\$ 30,603.85 p/p)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 May 2019		22 May 2019 16:47 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	VARDZA RAJU S/O NALLU, ID: S2585410A								
Main Claimant:	SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K								
Vehicle Reg. No.:	SHD6425C	Date of Loss:	19/05/2019 04:00 - :59						
Claim Type:	TP / CMTD1902465	Policy/Cover Note No.:	D19MTPV01000837 (Comprehensive)						
Vehicle Reg. No. (Insured):	SDP42Y	Policy No. (Claimant):							
		Excess:							
Repairer:	Smrt Automotive Services Pte Ltd (HQ) No. 61 Woodlands Industrial Park E9, #04-04 Premium Building, 757047 Woodlands - Tel:								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Theima Choo - 6322 4681]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 31/05/2019]								
Adj Asg. Remarks:	WS: SHANTI 6866 2671/2 -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	5369K

Vehicle Details

Vehicle No.:	SHD6425C
Vehicle to be Exported:	No
Intended Deregistration Date:	24 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZR5100502
Chassis No.:	JTDKB3FU903573380
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	01 Nov 2017
First Registration Date:	01 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Oct 2025
PARF Rebate Amount:	\$3,750.00

Intended COE Rebate Details

COE Expiry Date:	31 Oct 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$33,596.00
COE Rebate Amount:	\$27,025.00
Total Rebate Amount:	\$30,775.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 24 May 2019

OK

$$\$86,222.92 \div 96 \text{ month} = 898.20$$

$$\$898.20 \times 77 \text{ month} = \$69,161.40$$

$$\$69,161.40 + \$3,750 = \$72,911.40$$

$$\$72,911.40 - \$40,775 = 42,136.40/- \text{ (repair limit)}$$

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 25 July 2019 11:05 AM
To: 'Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)'
Cc: SUR; CS A Team
Subject: RE: SHD6425C

Hi Poh Suan,

Finalize amount confirmed.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25
| S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Tuesday, 16 July 2019 5:12 PM
To: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: SHD6425C

Hi All,

Attached herewith the repair estimate of SHD 6425C having Case No:
TAX/05/19/2080.

There is no change to the approved amount of \$30,603.85 @ 18 working days under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards

Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)
Sent: Tuesday, 16 July 2019 5:11 PM
To: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)
Subject: Scan Data from FX-D421D6

Shirley Hiew (LKK Auto)

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) <YeoPohsuan@smrt.com.sg>
Sent: Tuesday, 16 July 2019 5:12 PM
To: SUR; CS A Team
Subject: SHD6425C
Attachments: img-716171100-0001.pdf; DSCN5618.jpg; DSCN5619.jpg; DSCN5620.jpg; DSCN5621.jpg; DSCN5630.jpg; DSCN5631.jpg; DSCN5632.jpg; DSCN5633.jpg; DSCN5634.jpg; DSCN5635.jpg

Hi All,

Attached herewith the repair estimate of SHD 6425C having Case No: TAX/05/19/2080.

There is no change to the approved amount of \$30,603.85 @ 18 working days under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)
Sent: Tuesday, 16 July 2019 5:11 PM
To: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)
Subject: Scan Data from FX-D421D6

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 24 June 2019 11:59 AM
To: 'Choo, Thelma'
Cc: SUR
Subject: SHD 6425C TP / CMTD1902465

Hi Thelma,

Book value - \$ 72,911.40 (Estimate)
LTA- \$ 30,775.00
Nett - \$ 42,136.40 (Estimate)

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shirley Hiew (LKK Auto)

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) <YeoPohsuan@smrt.com.sg>
Sent: Monday, 24 June 2019 9:54 AM
To: Shirley Hiew (LKK Auto)
Subject: FW: SHD 6425C

FYI.

From: Phua Zhi Yang (Auto Svcs/ARC/AR & SC/Taxis)
Sent: Wednesday, 12 June 2019 9:16 AM
To: Hwee Jie (LKK Auto)
Cc: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis); Kok Tuck Foo (Auto Svcs/ARC/AR & SC/Taxis); Chin Kim Ming (Auto Svcs/ARC/AR & SC/Taxis)
Subject: RE: SHD 6425C

Hi Hwee Jie,

The purchase value for this vehicle *SHD6425C* \$86,222.92. ✓

Thanks,
zhiyang

From: Hwee Jie (LKK Auto) [<mailto:hweejie@lkkauto.com>]
Sent: Wednesday, 12 June, 2019 9:15 AM
To: Phua Zhi Yang (Auto Svcs/ARC/AR & SC/Taxis)
Subject: RE: SHD 6425C

Hi zhiyang,

I'm unable to comment whether this vehicle is safe/unsafe to repair, with the purchase value of this vehicle I only can comment whether the vehicle is economical/uneconomical for repair.

Best Regards,
Hwee Jie | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 9180 3151 | Email: Hweejie@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Phua Zhi Yang (Auto Svcs/ARC/AR & SC/Taxis) [<mailto:ZhiYang.Phua@smrt.com.sg>]
Sent: Tuesday, 11 June, 2019 10:52 AM
To: Hwee Jie (LKK Auto)
Cc: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis); Kok Tuck Foo (Auto Svcs/ARC/AR & SC/Taxis); Chin Kim Ming (Auto Svcs/ARC/AR & SC/Taxis)
Subject: RE: SHD 6425C

Hi Hwee Jie,

Please advise whether the vehicle is safe or unsafe first, before we provide you the purchase value.

Thanks,
zhiyang

From: Hwee Jie (LKK Auto) [<mailto:hweejie@lkkauto.com>]
Sent: Friday, 7 June, 2019 9:07 AM
To: Phua Zhi Yang (Auto Svcs/ARC/AR & SC/Taxis)
Cc: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)
Subject: RE: SHD 6425C

Hi zhiyang,

Please provide me purchase value before i can comment.

Best Regards,
Hwee Jie | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 9180 3151 | Email: hweejie@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Phua Zhi Yang (Auto Svcs/ARC/AR & SC/Taxis) [<mailto:ZhiYang.Phua@smrt.com.sg>]
Sent: Tuesday, 4 June, 2019 10:20 AM
To: Hwee Jie (LKK Auto)
Cc: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis); Kok Tuck Foo (Auto Svcs/ARC/AR & SC/Taxis); Chin Kim Ming (Auto Svcs/ARC/AR & SC/Taxis); Gerald Tan Chwee Hock (Auto Svcs/ARC/AR & SC/Buses)
Subject: SHD 6425C

Hi Hwee Jie,

Kindly please comment this vehicle whether is safe or unsafe for repair.

Thanks,
zhiyang

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompso Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Thelma Choo

Date: 25 Jun 2019

Preliminary Advice

Insured Vehicle No	: SDP42Y	Accident Date	: 19/05/2019
TP Vehicle No	: SHD6425C	Assignment Date	: 22/05/2019
Make	: TOYOTA PRIUS TAXI		
Date of Inspection	: Smrt Automotive Services Pte Ltd (HQ) No. 61 Woodlands Industrial Park E9, #04-04 Premium Building Singapore 757047	Est. Duration of Repair	: 10 days
Inspection At	: 25/05/2019		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front & rear portion, n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	76,328.84
Revised Amount	:S\$	19,966.57
Check Items (Estimated)	:S\$	44,867.52
Total	:S\$	64,834.09
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Book Value	:S\$	72,911.40
COE / PARF Rebate	:S\$	30,775.00
Salvage Value	:S\$	
Margin for Repair	:S\$	42,136.40

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP Repairer able to undertake the repair cost not exceeding \$ 42,000.00 on part by part basis.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompso Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Thelma Choo

Date: 28 May 2019

Preliminary Advice

Insured Vehicle No	: SDP42Y	Accident Date	: 19/05/2019
TP Vehicle No	: SHD6425C	Assignment Date	: 22/05/2019
Make	: TOYOTA PRIUS TAXI	Est. Duration of Repair	: 10 days
Date of Inspection	: 23/05/2019		
Inspection At	: Smrt Automotive Services Pte Ltd (HQ) No. 61 Woodlands Industrial Park E9, #04-04 Premium Building Singapore 757047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front & rear portion, n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	76,328.84
Revised Amount	:S\$	19,966.57
Check Items (Estimated)	:S\$	44,867.52
Total	:S\$	64,834.09

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/05/2019 10:36
Date Of Accident	19/05/2019 04:45
Exact Location Of Accident	AYE (TUAS) SLIP ROAD TO CLEMENTI AVE 6
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD6425C
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	

Driver

Name of Driver	LIM TOW SENG
NRIC No	S18081701
Date Of Birth	23/03/1967
Occupation	OUTDOOR
Date Of Driving Pass	03/11/1987
Driving Experience	31 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 603
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (Including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 3
 Passenger 1 NAME: : UNKNOWN
 GENDER: : MALE
 Passenger 2 NAME: : UNKNOWN
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name SENGKANG NPC
 Police Station Address ROAD: 2 SENGKANG SQUARE #01-02 , POSTCODE: 545025 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: - FAX NO:
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT - T/20190519/2072

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SDP42Y
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver

NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	LIM TOW SENG
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SHD6425C
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 21/5/19 0900

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

A-SHA6425C
B-SAP42Y



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT - 7/20190519/2072

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
if driver is not the policyholder
Date & Time 21/5/19 0900

Reporting Centre Personnel's Signature
Name: [Signature]
ICRC/NPI No: 21/5/19



**SINGAPORE
POLICE FORCE**



T/20190519/2072

1 of 3

Report No. T/20190519/2072

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 19/05/2019 16:31		Vide Report No.: D/20190519/0034		Station Diary No.: 100	
Informant's Particulars					
Name of Informant: LIM TOW SENG			Address: APT BLK 603A PUNGGOL ROAD #13-700 SINGAPORE 821603		
ID Type / ID No.: NRIC NO / S18081701			Contact No.: Home/Office: Mobile: 98329439		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 52	Date of Birth: 23/03/1967	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Taxi Driver			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 19/05/2019 04:50	Type of Location: Bend
Location: Along Road 1 Traveling Toward Road 2 AYER RAJAH EXPRESSWAY CLEMENTI AVENUE 6 AYE (Tuas) towards Clementi Avenue 6				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control:	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
SDP42Y	Car	TOYOTA	Camry	Silver	Seriously Damaged	0
SHD6425C	Car	TOYOTA	Prius	Brown	Seriously Damaged	2

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190519/2072

2 of 3

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

Report No. T/20190519/2072

CONTINUATION OF REPORT

Driver			
Name	LIM TOW SENG	ID No.	S18081701
Related Vehicle	SHD6425C (Car)	Contact No.	983294392
Hospital/Clinic	SENGKANG GENERAL HOSPITAL PTE. LTD.	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	19/05/2019	Date Discharge	19/05/2019
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On 19/05/2019 at about 0445hrs, I was driving my taxi bearing registration number SHD6425C together with two passengers (A Chinese couple in their 20s) along AYE (TUAS) towards Clementi Avenue 6. Out of sudden, there was a hard impact coming from the rear right side of my taxi. Due to the impact, it has caused my taxi to swerve in a clockwise direction and mounted a nearby kerb. Upon stopping my taxi, I checked with my passengers and they informed that they were not injured. At that point of time, I was in shock and I did not feel any pain. After which I established that earlier the front portion of one vehicle bearing registration number SDP42Y had collided on the rear right portion of my taxi. I then approached the driver of the said to check on him and fortunately he was okay. Shortly, ambulance and Traffic police arrived at scene. There was no one conveyed to the hospital. Due to the collision, the rear right portion of my taxi was heavily dented. As for the other vehicle, the front portion and the rear portion were heavily damage.

While I was waiting for the tow truck to tow away my taxi, I suddenly felt bodily. Thereafter, my friend came and sent me to SKGH. I was then received 3 days of MC. That is all



**SINGAPORE
POLICE FORCE**



T/20190519/2072

3 of 3

Report No. T/20190519/2072

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: F / Sr Staff Sgt MOHAMAD AZHAR BIN ABDUL AZIZ	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 19/05/2019 16:31
Officer In Charge Of Case: TP / GIT / SI MOHAMMAD ABDILLAH BIN PALIL Contact No.: 65476248 SN 085	Classification Of Case:
Authentication Stamp NP168  Signature:  Singapore Police Force	



Case Details

Case Reference Number :
TAX/05/19/2080

Type of Repair : Accident Repair

Vehicle Registration Number :
SHD6425C

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-6957-ID

Assigned By : Taxi Claims Manager
Team

Insurance Company Name : Sompo Insurance Singapore Pte.
Ltd

Accident Date and Time : 18/05/2019 08:45 PM

Vehicle Age(In Months) : 18

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	317.92	Replace	OK
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace	OK
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 1	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	OK
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 2	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	OK
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 3	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	OK
One Time Key In	Main			SEAL, RR BUMPER ARM, RH & LH	2	11.00	22.00	25.00	16.50	Replace	2	16.50	Replace	OK
One Time Key In	Main			FILLER, RR BUMPER , LH	1	119.90	119.90	25.00	89.93	Replace	0	0	Check	X AM
One Time Key In	Main			FILLER, RR BUMPER , RH	1	119.90	119.90	25.00	89.93	Replace	1	89.93	Replace	MIS
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	0	0	Check	X AM

1063.90

Total Spare Part Cost 63,792.84

Surveyor Total 11,426.57

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 63,792.84

Final Sur Total 11,426.57

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace	• BR
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	• NPC
One Time Key In	Main			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	1	83.63	Replace	• BR
One Time Key In	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	1	84.53	Replace	• MIS
One Time Key In	Main			STOPPER, RR BUMPER, RH & LH	2	4.30	8.60	25.00	6.45	Replace	2	6.45	Replace	• NPC
One Time Key In	Main			SEAL, RR BUMPER, RH	1	85.20	85.20	25.00	63.90	Replace	1	63.90	Replace	• TN
One Time Key In	Main			SEAL, RR BUMPER, LH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Give	• NMI X
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	1	418.72	Replace	• CUT
One Time Key In	Main			COVER, GUARD RR BUMPER LOWER	1	14.80	14.80	25.00	11.10	Replace	1	11.10	Replace	• MIS
One Time Key In	Main			PAD, RR BUMPER, CTR	3	2.20	6.60	25.00	4.95	Replace	3	4.95	Replace	• NPC
One Time Key In	Main			LENS & BODY ASSY, RR BUMPER, RH	1	486.80	486.80	10.00	438.12	Replace	1	438.12	Replace	• BR
One Time Key In	Main			REAR BUMPER GROMMET SCREW	2	2.20	4.40	25.00	3.30	Replace	2	3.30	Replace	• NPC
One Time Key In	Main			WIRE, LUGGAGE ROOM	1	143.50	143.50	10.00	129.15	Replace	0	0	Check	• X NMI
One Time Key In	Main			COVER, REAR FLOOR UNDER, RH	1	169.50	169.50	25.00	127.13	Replace	1	127.13	Replace	• MIS
One Time Key In	Main			COVER, REAR FLOOR UNDER, LH	1	234.30	234.30	25.00	175.73	Replace	0	0	Check	• X NMI

2321.40

Total Spare Part Cost 63,792.84

Surveyor Total 11,426.57

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 63,792.84

Final Sur Total 11,426.57

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, REAR FLOOR UNDER CENTER	1	222.60	222.60	25.00	166.95	Replace	0	0	Check	* X NN
One Time Key In	Main			CLIP, FLOOR UNDER COVER, NO.1	10	2.60	25.00	25.00	19.50	Replace	10	19.50	Replace	* hpc
One Time Key In	Main			CLIP, FLOOR UNDER COVER, NO.2	10	3.20	32.00	25.00	24.00	Replace	10	24.00	Replace	* APC
One Time Key In	Main			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	929.60	25.00	697.20	Replace	1	697.20	Replace	* DO
One Time Key In	Main			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	891.20	25.00	668.40	Replace	1	668.40	Replace	* BK
One Time Key In	Main			TAIL GATE BACK DOOR HINGE ASSY, RH & LH	2	59.10	118.20	25.00	88.65	Replace	2	88.65	Replace	* BT
One Time Key In	Main			TAIL GATE LOCK ASSY, BACK DOOR	1	452.10	452.10	10.00	406.89	Replace	0	0	Check	* X NN
One Time Key In	Main			TAIL GATE LOCK COVER, BACK DOOR	1	25.30	25.30	25.00	18.98	Replace	0	0	Check	* X NN
One Time Key In	Main			TAIL GATE STAY ASSY, BACK DOOR, RH	1	235.00	235.00	25.00	176.25	Replace	0	0	Not Give	* X NN
One Time Key In	Main			TAIL GATE STRIKER ASSY, BACK DOOR	1	24.90	24.90	25.00	18.67	Replace	0	0	Not Give	* X NN
One Time Key In	Main			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	2	27.90	55.80	25.00	41.85	Replace	2	41.85	Replace	* APC
One Time Key In	Main			TAIL GATE MOULDING GLASS, BACK DOOR	1	29.70	29.70	25.00	22.27	Replace	1	22.27	Replace	* APC
One Time Key In	Main			TAIL GATE MOULDING LOWER GLASS, BACK DOOR, LH	1	29.90	29.90	25.00	22.42	Replace	1	22.42	Replace	* APC
One Time Key In	Main			TAIL GATE MOULDING LOWER GLASS, BACK DOOR, RH	1	29.90	29.90	25.00	22.42	Replace	1	22.42	Replace	* APC
One Time Key In	Main			TAIL GATE MOULDING LOWER GLASS, BACK DOOR	1	19.70	19.70	25.00	14.77	Replace	1	14.77	Replace	* APC

31/1/20

Total Spare Part Cost 63,792.84

Surveyor Total 11,426.57

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 63,792.84

Final Sur Total 11,426.57

SMRT Recommendation											Surveyor Approval			
BOM Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SEALANT W/SCREEN	3	37.00	111.00	0.00	111.00	Replace	3	111.00	Replace	• APC
One Time Key In	Main			TAIL GATE WEATHERSTRIP, BACK DOOR	1	360.70	360.70	25.00	270.52	Replace	0	0	Check	• X NM
One Time Key In	Main			TAILGATE BOARD, COVER	1	24.10	24.10	25.00	18.08	Replace	0	0	Check	• X NM
One Time Key In	Main			TAILGATE BOARD, HANDLE PULL	1	19.50	19.50	25.00	14.63	Replace	0	0	Check	• X NM
One Time Key In	Main			TAILGATE BOARD ASSY	1	251.50	251.50	25.00	188.63	Replace	0	0	Check	• X NM
One Time Key In	Main			TAILGATE TRIM, LOWER	1	218.50	218.50	25.00	163.88	Replace	0	0	Check	• X NM
One Time Key In	Main			TAILGATE TRIM, RH	1	92.10	92.10	25.00	69.07	Replace	0	0	Check	• X NM
One Time Key In	Main			WIRE, FLOOR	1	3,860.00	3,860.00	10.00	3,474.00	Replace	0	0	Check	• X NM
One Time Key In	Main			SPOILER SUB-ASSY, REAR	1	1,322.10	1,322.10	25.00	991.57	Replace	1	0	Repair	• R X
One Time Key In	Main			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	1	39.22 ₃	Replace	• APC
One Time Key In	Main			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	1	39.22 ₁	Replace	• APC
One Time Key In	Main			EMBLEM SUB-ASSY REAR	1	46.30	46.30	25.00	34.72	Replace	1	34.72 ₃	Replace	• APC
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	• APC
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	• APC
One Time Key In	Main			MEMBER SUB-ASSY, RAIL ROOT SIDE REAR RH	1	279.20	279.20	25.00	209.40	Replace	0	0	Check	• X NM

Total Spare Part Cost 63,792.84

Surveyor Total 11,426.57

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 63,792.84

Final Sur Total 11,426.57

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER SUB-ASSY, REAR QUARTER PILLAR, RH	1	201.30	201.30	25.00	150.98	Replace	0	0	Check	• X / M /
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0	Check	• X / M /
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	0	0	Check	• X / M /
One Time Key In	Main			END PANEL SUBASSY, BODY LOWER BACK	1	629.80	629.80	25.00	472.35	Replace	0	0	Check	• X / M /
One Time Key In	Main			END PANEL , COVER, DECK TRIM SERVICE HOLE	1	47.00	47.00	25.00	35.25	Replace	0	0	Check	• X / M /
One Time Key In	Main			END PANEL , COVER, DECK TRIM, REAR	1	122.80	122.80	25.00	92.10	Replace	0	0	Check	• X / M /
One Time Key In	Main			REINFORCEMENT ASSY, REAR FLOOR END PANEL , RH & LH	1	56.70	56.70	25.00	42.53	Replace	0	0	Check	• X / M /
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Check	• X / M /
One Time Key In	Main			SPARE TYRE PANEL , PAN, REAR FLOOR	1	564.80	564.80	25.00	423.60	Replace	0	0	Check	• X / M /
One Time Key In	Main			EXTENSION, REAR FLOOR SIDE PANEL , RH	1	76.20	76.20	25.00	57.15	Replace	0	0	Check	• X / M /
One Time Key In	Main			MEMBER SUB-ASSY, REAR FLOOR SIDE , REAR RH	1	268.60	268.60	25.00	201.45	Replace	0	0	Check	• X / M /
One Time Key In	Main			CARRIER, SPARE WHEEL	1	20.00	20.00	25.00	15.00	Replace	0	0	Check	• X / M /
One Time Key In	Main			PANEL, QUARTER WHEEL HOUSE , OUTER RH	1	286.80	286.80	25.00	215.10	Replace	1	215.10	Replace	• 00
One Time Key In	Main			PANEL QUARTER WHEEL HOUSE , INNER RH	1	527.00	527.00	25.00	395.25	Replace	0	0	Check	• X / M /
One Time Key In	Main			BOARD, REAR FLOOR, NO.1	1	502.20	502.20	25.00	376.65	Replace	0	0	Check	• X / M /

3369-60

Total Spare Part Cost 63,792.84

Surveyor Total 11,426.57

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 63,792.84

Final Sur Total 11,426.57

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BOX, DECK FLOOR, LH	1	303.40	303.40	25.00	227.55	Replace	0	0	Check	• X NM
One Time Key In	Main			BOX, DECK FLOOR, RH	1	304.00	304.00	25.00	228.00	Replace	0	0	Check	• X NM
One Time Key In	Main			PANEL ASSY, DECK TRIM SIDE, RH	1	344.70	344.70	25.00	258.52	Replace	0	0	Check	• X NM
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP , RH	1	438.10	438.10	10.00	394.29	Replace	1	394.21	Replace	• MIS
One Time Key In	Main			COVER, REAR COMBINATION LAMP, RH	1	54.00	54.00	25.00	40.50	Replace	1	40.50	Replace	• MIS
One Time Key In	Main			TROUGH, BACK DOOR , RH	1	99.80	99.80	25.00	74.85	Replace	1	74.85	Replace	• MSC
One Time Key In	Main			PANEL SUB-ASSY, FENDER REAR RH	1	824.80	824.80	25.00	618.60	Replace	1	618.61	Replace	• DD
One Time Key In	Main			DUCT ASSY, QUARTER VENT , RH & LH	1	65.00	65.00	25.00	48.75	Replace	1	48.75	Replace	• BR
One Time Key In	Main			LINER, REAR FENDER , RH	1	135.80	135.80	25.00	101.85	Replace	1	101.81	Replace	• TM
One Time Key In	Main			RETAINER, BACK DOOR SIDE STOPPER , RH & LH	1	14.70	14.70	25.00	11.02	Replace	0	0	Check	• X NM
One Time Key In	Main			REINFORCEMENT SUB-ASSY, ROCKER PANEL , RH	1	332.30	332.30	25.00	249.23	Replace	0	0	Check	• X NM
One Time Key In	Main			EXTENSION, ROOF SIDE , INNER FRONT RH	1	56.10	56.10	25.00	42.08	Replace	0	0	Check	• X NM
One Time Key In	Main			PANEL, ROOF SIDE OUTER RH	1	111.00	111.00	25.00	83.25	Replace	0	0	Check	• X NM
One Time Key In	Main			REINFORCEMENT, BELT ANCHOR TO ROOF SIDE INNER RH	1	104.60	104.60	25.00	78.45	Replace	0	0	Check	• X NM
One Time Key In	Main			REINFORCEMENT, ROOF SIDE , INNER RH	1	65.00	65.00	25.00	48.75	Replace	0	0	Check	• X NM

2777.10

Total Spare Part Cost 63,792.84

Surveyor Total 11,426.57

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 63,792.84

Final Sur Total 11,426.57

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			PANEL, ROOF SIDE , INNER FRONT RH	1	240.20	240.20	25.00	180.15	Replace	0	0	Check	• X N/A
One Time Key In	Main			REINFORCEMENT, BACK DOOR OPENING SIDE , RH	1	83.30	83.30	25.00	62.47	Replace	0	0	Check	• X N/A
One Time Key In	Main			PANEL SUB-ASSY, ROOF SIDE , INNER FRONT RH	1	83.30	83.30	25.00	62.47	Replace	0	0	Check	• X N/A
One Time Key In	Main			EXTENSION, QUARTER PANEL , REAR RH	1	57.20	57.20	25.00	42.90	Replace	0	0	Check	• X N/A
One Time Key In	Main			RETAINER, BACK DOOR STAY , RH	1	13.60	13.60	25.00	10.20	Replace	0	0	Check	• X N/A
One Time Key In	Main			EXTENSION, QUARTER PANEL , FRONT RH	1	56.70	56.70	25.00	42.53	Replace	0	0	Check	• X N/A
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	1	126.74	Replace	• TN
One Time Key In	Main			WHEEL, DISC	1	1,555.10	1,555.10	25.00	1,166.32	Replace	1	1,166.32	Replace	• OR
One Time Key In	Main			CARRIER SUB-ASSY, REAR AXLE, RH	1	802.70	802.70	25.00	602.03	Replace	0	0	Check	• X N/A
One Time Key In	Main			HUB & BEARING ASSY WITH SPEED SENSOR , REAR AXLE , RH & LH	1	610.20	610.20	25.00	457.65	Replace	0	0	Check	• X N/A
One Time Key In	Main			DISC BRAKE , REAR	1	373.90	373.90	25.00	280.42	Replace	0	0	Check	• X N/A
One Time Key In	Main			COVER, DISC BRAKE DUST, REAR RH	1	56.40	56.40	25.00	42.30	Replace	0	0	Check	• X N/A
One Time Key In	Main			MOUNTING, REAR DISC BRAKE CYLINDER, RH & LH	1	163.60	163.60	25.00	122.70	Replace	0	0	Check	• X N/A
One Time Key In	Main			CYLINDER ASSY, DISC BRAKE, REAR RH	1	834.20	834.20	25.00	625.65	Replace	0	0	Check	• X N/A
One Time Key In	Main			BRAKE HOSE, FLEXIBLE(FOR REAR RH & LH)	1	69.80	69.80	25.00	52.35	Replace	0	0	Check	• X N/A

5126.94

Total Spare Part Cost 63,792.84

Surveyor Total 11,426.57

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 63,792.84

Final Sur Total 11,426.57

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			ABSORBER SET, SHOCK, REAR RH & LH	1	116.80	116.80	25.00	87.60	Replace	0	0	Check	• X / N
One Time Key In	Main			ARM ASSY, UPPER CONTROL, REAR RH	1	352.40	352.40	25.00	264.30	Replace	0	0	Check	• X / N
One Time Key In	Main			INSULATOR, REAR COIL SPRING, UPPER RH & LH	1	16.60	16.60	25.00	12.45	Replace	0	0	Check	• X / N
One Time Key In	Main			SPRING, COIL, REAR RH & LH	1	193.10	193.10	25.00	144.82	Replace	0	0	Check	• X / N
One Time Key In	Main			INSULATOR, REAR COIL SPRING, LOWER RH & LH	1	11.70	11.70	25.00	8.77	Replace	0	0	Check	• X / N
One Time Key In	Main			CAM SUB-ASSY, REAR SUSPENSION TOE ADJUST	1	26.40	26.40	25.00	19.80	Replace	0	0	Check	• X / N
One Time Key In	Main			ARM ASSY, TRAILING, REAR RH	1	239.70	239.70	25.00	179.77	Replace	0	0	Check	• X / N
One Time Key In	Main			ARM ASSY, REAR SUSPENSION, NO.1 RH & LH	1	200.80	200.80	25.00	150.60	Replace	0	0	Check	• X / N
One Time Key In	Main			BRACKET, REAR SUSPENSION TRAILING ARM, RH	1	88.20	88.20	25.00	66.90	Replace	0	0	Check	• X / N
One Time Key In	Main			COVER, REAR SUSPENSION ARM, RH	1	41.60	41.60	25.00	31.20	Replace	0	0	Check	• X / N
One Time Key In	Main			LINK ASSY, REAR STABILIZER, RH & LH	1	149.40	149.40	25.00	112.05	Replace	0	0	Check	• X / N
One Time Key In	Main			BAR, STABILIZER, REAR	1	286.30	286.30	25.00	214.73	Replace	0	0	Check	• X / N
One Time Key In	Main			BUSH, STABILIZER, REAR	1	59.70	59.70	25.00	44.78	Replace	0	0	Check	• X / N
One Time Key In	Main			BRACKET, REAR STABILIZER BAR	1	9.60	9.60	25.00	7.20	Replace	0	0	Check	• X / N
One Time Key In	Main			ARM ASSY, REAR SUSPENSION, NO.2 RH & LH	1	497.50	497.50	25.00	373.13	Replace	0	0	Check	• X / N

2296.80

Total Spare Part Cost 63,792.64

Surveyor Total 11,426.57

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 63,792.64

Final Sur Total 11,426.57

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SENSOR SUB-ASSY, HEIGHT CONTROL, REAR LH	1	661.10	661.10	10.00	594.99	Replace	0	0	Check	* X / / /
One Time Key In	Main			PANEL SUB-ASSY, REAR DOOR, RH	1	1,243.90	1,243.90	25.00	932.93	Replace	1	0	Repair	* R x
One Time Key In	Main			DOOR LOCK REAR, RH	1	544.70	544.70	10.00	490.23	Replace	0	0	Not Give	* X / / /
One Time Key In	Main			DOOR LOCK STRIKER	1	38.00	38.00	25.00	28.50	Replace	0	0	Not Give	* X / / /
One Time Key In	Main			PANEL SUB-ASSY, FENDER REAR LH	1	824.80	824.80	25.00	618.60	Replace	1	0	Repair	* R x
One Time Key In	Main			LINER, REAR FENDER, LH	1	135.80	135.80	25.00	101.85	Replace	0	0	Not Give	* X / / /
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	1	126.74	Replace	* C/T
One Time Key In	Main			WHEEL, DISC	1	1,355.10	1,355.10	25.00	1,166.32	Replace	1	1,166.32	Replace	* C/T
One Time Key In	Main			ABSORBER SET, SHOCK, REAR RH & LH	1	115.80	115.80	25.00	87.60	Replace	0	0	Check	* X / / /
One Time Key In	Main			ARM ASSY, UPPER CONTROL, REAR LH	1	352.40	352.40	25.00	264.30	Replace	0	0	Check	* X / / /
One Time Key In	Main			ARM ASSY, TRAILING, REAR LH	1	239.70	239.70	25.00	179.77	Replace	0	0	Check	* X / / /
One Time Key In	Main			ARM ASSY, REAR SUSPENSION, NO.1 RH & LH	1	200.80	200.80	25.00	150.60	Replace	0	0	Check	* X / / /
One Time Key In	Main			ARM ASSY, REAR SUSPENSION, NO.2 RH & LH	1	497.50	497.50	25.00	373.13	Replace	0	0	Check	* X / / /
One Time Key In	Main			CARRIER SUB-ASSY, REAR AXLE, LH	1	802.70	802.70	25.00	602.03	Replace	0	0	Check	* X / / /
One Time Key In	Main			MOULDING ASSY, BODY ROCKER PANEL, LH	1	576.00	576.00	25.00	432.00	Replace	0	0	Check	* X / / /

29/6/04

Total Spare Part Cost 63,792.84

Surveyor Total 11,426.57

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 63,792.84

Final Sur Total 11,426.57

SMRT Recommendation											Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks	
One Time Key In	Main			MOULDING ASSY, BODY ROCKER PANEL , RH	1	576.00	576.00	25.00	432.00	Replace	0	0	Check	• X / M	
One Time Key In	Main			PLATE, REAR WHEEL HOUSE, FRONT RH	1	26.80	26.80	25.00	20.10	Replace	0	0	Check	• X / M	
One Time Key In	Main			PLATE, REAR WHEEL HOUSE, FRONT LH	1	26.80	26.80	25.00	20.10	Replace	0	0	Check	• X / M	
One Time Key In	Main			COVER, FRONT FLOOR UNDER , RH	1	427.30	427.30	25.00	320.48	Replace	0	0	Check	• X / M	
One Time Key In	Main			COVER, FRONT FLOOR UNDER , LH	1	425.50	425.50	25.00	319.13	Replace	0	0	Check	• X / M	
One Time Key In	Main			COVER ASSY, CENTER FLOOR UNDER , RH	1	306.90	306.90	25.00	230.17	Replace	0	0	Check	• X / M	
One Time Key In	Main			COVER ASSY, CENTER FLOOR UNDER , LH	1	390.20	390.20	25.00	292.65	Replace	0	0	Check	• X / M	
One Time Key In	Main			EXHAUST HEAT SHIELD INSULATOR, FRONT FLOOR , NO.2	1	228.50	228.50	25.00	171.38	Replace	0	0	Check	• X / M	
One Time Key In	Main			EXHAUST HEAT SHIELD INSULATOR, MAIN MUFFLER REAR	1	137.00	137.00	25.00	102.75	Replace	0	0	Check	• X / M	
One Time Key In	Main			PIPE ASSY, EXHAUST, FRONT	1	2,495.00	2,495.00	25.00	1,871.25	Replace	0	0	Check	• X / M	
One Time Key In	Main			SUPPORT, EXHAUST PIPE NO.5	2	41.10	82.20	25.00	61.65	Replace	0	0	Check	• X / M	
One Time Key In	Main			SUPPORT, EXHAUST PIPE NO.4	2	41.10	82.20	25.00	61.65	Replace	0	0	Check	• X / M	
One Time Key In	Main			GASKET, EXHAUST PIPE , TAIL	1	44.80	44.80	25.00	33.60	Replace	0	0	Check	• X / M	
One Time Key In	Main			GASKET, EXHAUST PIPE , FRONT	1	83.90	83.90	25.00	62.93	Replace	0	0	Check	• X / M	
One Time Key In	Main			PIPE ASSY, EXHAUST, TAIL	1	1,173.90	1,173.90	25.00	880.43	Replace	1	880.43	Replace	• 00	

6507

Total Spare Part Cost 63,792.84

Surveyor Total 11,426.57

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 63,792.84

Final Sur Total 11,426.57

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dia(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			REAR MEMBER SUB-ASSY, RR	1	2,171.70	2,171.70	25.00	1,628.77	Replace	0	0	Check	• X IN
One Time Key In	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	371.63	Replace	• CRU
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace	• MC
One Time Key In	Main			GRILLE SUB-ASSY	1	335.60	335.60	25.00	251.70	Replace	0	0	Not Give	• X IN
One Time Key In	Main			GRILLE, RADIATOR	1	165.00	165.00	25.00	123.75	Replace	0	0	Not Give	• X IN
One Time Key In	Main			SUPPORT, FR BUMPER LH	1	82.30	82.30	25.00	61.72	Replace	1	61.72	Replace	• UR
One Time Key In	Main			ABSORBER, FR BUMPER	1	70.30	70.30	25.00	52.72	Replace	0	0	Check	• X IN
One Time Key In	Main			REINFORCEMENT FRONT UPPER	1	691.10	691.10	25.00	518.33	Replace	0	0	Check	• X IN
One Time Key In	Main			ABSORBER, FR BUMPER LOWER	1	117.00	117.00	25.00	87.75	Replace	0	0	Check	• X IN
One Time Key In	Main			REINFORCEMENT FRONT LOWER	1	238.50	238.50	25.00	178.88	Replace	0	0	Check	• X IN
One Time Key In	Main			EXTENSION SUBASSY, LH	1	116.30	116.30	25.00	87.22	Replace	0	0	Check	• X IN
One Time Key In	Main			EXTENSION SUBASSY, RH	1	116.30	116.30	25.00	87.22	Replace	0	0	Not Give	• X IN
One Time Key In	Main			LAMP ASSY, FOG, LH	1	910.20	910.20	10.00	819.18	Replace	1	819.18	Replace	• CUT
One Time Key In	Main			COVER ASSY, ENGINE	1	180.10	180.10	25.00	135.07	Replace	0	0	Not Give	• X IN
One Time Key In	Main			SUPPORT S/A UPPER	1	364.90	364.90	25.00	273.67	Replace	0	0	Not Give	• X IN

6069.80

Total Spare Part Cost 63,792.84

Surveyor Total 11,426.57

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 63,792.84

Final Sur Total 11,426.57