

SMRT Recommendation												Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks	
One Time Key In	Main			SUPPORT SUB-ASSY LOWER	1	397.40	397.40	25.00	298.05	Replace	0	0	Check	• X MM	
One Time Key In	Main			BRACE, HOOD LOCK SUPPORT	1	76.20	76.20	25.00	57.15	Replace	0	0	Not Give	• X MM	
One Time Key In	Main			SUPPORT, RADIATOR UPPER LH	1	78.70	76.70	25.00	57.53	Replace	0	0	Not Give	• X MM	
One Time Key In	Main			UNIT, HEADLAMP , LH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	0	0	Check	• X MM	
One Time Key In	Main			SUPPORT S/A LH	1	237.00	237.00	25.00	177.75	Replace	0	0	Check	• X MM	
One Time Key In	Main			GUIDE, RADIATOR AIR,	1	93.90	93.90	25.00	70.43	Replace	0	0	Check	• X MM	
One Time Key In	Main			FRONT REINFORCEMENT SIDE RH	1	128.20	128.20	25.00	96.15	Replace	0	0	Check	• X MM	
One Time Key In	Main			FRONT REINFORCEMENT SIDE LH	1	129.30	129.30	25.00	96.98	Replace	0	0	Check	• X MM	
One Time Key In	Main			FRONT CROSSMEMBER	1	2,502.10	2,502.10	25.00	1,876.57	Replace	0	0	Check	• X MM	
One Time Key In	Main			COVER ASSY, ENGINE UNDER CENTER SET	1	452.80	452.80	25.00	339.60	Replace	0	0	Check	• X MM	
One Time Key In	Main			COVER, ENGINE UNDER SIDE LH	1	76.90	76.90	25.00	57.68	Replace	0	0	Check	• X MM	
One Time Key In	Main			ENGINE OIL	4	15.00	60.00	0.00	60.00	Replace	0	0	Not Give	• X MM	
One Time Key In	Main			PAN SUB-ASSY, OIL	1	218.10	218.10	25.00	163.57	Replace	0	0	Not Give	• X MM	
One Time Key In	Main			PUMP ASSY, OIL	1	403.70	403.70	25.00	302.77	Replace	0	0	Not Give	• X MM	
One Time Key In	Main			AIR CON CONDENSER ASSY	1	1,317.70	1,317.70	25.00	988.28	Replace	0	0	Not Give	• X MM	

328.90

Total Spare Part Cost 63,792.84

Surveyor Total 11,426.57

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 63,792.84

Final Sur Total 11,426.57

SMRT Recommendation												Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TUBE & ACCESSORY	1	574.40	574.40	25.00	430.80	Replace	0	0	Not Give	• X N/A
One Time Key In	Main			HOSE SUB-ASSY, DISCHARGE	1	337.10	337.10	25.00	252.83	Replace	0	0	Not Give	• X N/A
One Time Key In	Main			AIR CON COMPRESSOR ASSY	1	2,887.80	2,887.80	10.00	2,599.02	Replace	0	0	Check	• X N/A
One Time Key In	Main			COOLANT	1	12.30	12.30	0.00	12.30	Replace	0	0	Check	• X N/A
One Time Key In	Main			RADIATOR ASSY	1	1,841.10	1,841.10	25.00	1,380.82	Replace	0	0	Check	• X N/A
One Time Key In	Main			GROMMET (FOR RADIATOR LOWER SUPPORT)	2	12.70	25.40	25.00	19.05	Replace	0	0	Check	• X N/A
One Time Key In	Main			CUSHION, (FOR RADIATOR UPPER SUPPORT)	2	9.80	19.60	25.00	14.70	Replace	0	0	Check	• X N/A
One Time Key In	Main			FAN RADIATOR , LH	1	181.80	181.80	25.00	136.35	Replace	0	0	Check	• X N/A
One Time Key In	Main			FAN RADIATOR , RH	1	233.00	233.00	25.00	174.75	Replace	0	0	Check	• X N/A
One Time Key In	Main			FAN SHROUD RADIATOR	1	219.30	219.30	25.00	164.48	Replace	0	0	Check	• X N/A
One Time Key In	Main			MOTOR, COOLING FAN , LH	1	543.50	543.50	10.00	489.15	Replace	0	0	Check	• X N/A
One Time Key In	Main			MOTOR, COOLING FAN , RH	1	443.40	443.40	10.00	399.06	Replace	0	0	Check	• X N/A
One Time Key In	Main			INVERTER WATER PUMP ASSY	1	432.00	432.00	10.00	388.80	Replace	0	0	Check	• X N/A
One Time Key In	Main			WIRE, ENGINE ROOM MAIN	1	6,138.00	6,138.00	10.00	5,524.20	Replace	0	0	Check	• X N/A
One Time Key In	Main			WIRE, AIR CONDITIONER	1	445.70	445.70	10.00	401.13	Replace	0	0	Check	• X N/A

16,774.40

Total Spare Part Cost 63,792.84

Surveyor Total 11,426.57

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 63,792.84

Final Sur Total 11,426.57

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			LINER, FR FENDER, RH	1	198.40	198.40	25.00	148.80	Replace	0	0	Not Give	* X JH
One Time Key In	Main			PAD, FR WHEEL RH	1	57.70	57.70	25.00	43.28	Replace	0	0	Not Give	* X JH
One Time Key In	Main			FENDER SUB-ASSY, FR, LH	1	933.10	933.10	25.00	699.83	Replace	1	0	Repair	* X R
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	52.90	25.00	39.67	Replace	1	39.67	Replace	* JPS
One Time Key In	Main			LINER, FR FENDER, LH	1	194.30	194.30	25.00	145.73	Replace	0	0	Check	* X JH
One Time Key In	Main			PAD, FR WHEEL LH	1	57.70	57.70	25.00	43.28	Replace	0	0	Check	* X JH
One Time Key In	Main			APRON SUB-ASSY, FRONT FENDER, LH	1	944.20	944.20	25.00	708.15	Replace	0	0	Check	* X JH
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	1	126.74	Replace	* CHT
One Time Key In	Main			WHEEL, DISC FRONT	1	1,555.10	1,555.10	25.00	1,166.32	Replace	1	1,166.32	Replace	* CHT
One Time Key In	Main			ABSORBER SET, SHOCK, FRONT LH	1	398.10	398.10	25.00	298.58	Replace	0	0	Check	* X JH
One Time Key In	Main			LINK ASSY, FRONT STABILIZER, RH & LH	1	196.70	196.70	25.00	147.52	Replace	0	0	Check	* X JH
One Time Key In	Main			LOWER ARM SUBASSY, FRONT LH	1	631.60	631.60	25.00	473.70	Replace	0	0	Check	* X JH
One Time Key In	Main			JOINT ASSY, LWR BALL, RH & LH	1	200.10	200.10	25.00	150.07	Replace	0	0	Check	* X JH
One Time Key In	Main			KNUCKLE, STEERING, LH	1	555.20	555.20	25.00	416.40	Replace	0	0	Check	* X JH
One Time Key In	Main			END SET, TIE ROD, LH	1	155.90	155.90	25.00	116.93	Replace	0	0	Check	* X JH

6352.94

Total Spare Part Cost 63,792.84

Surveyor Total 11,426.57

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 63,792.84

Final Sur Total 11,426.57

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			HUB & BEARING ASSY, RH & LH	1	554.20	554.20	25.00	415.65	Replace	0	0	Check	• X MM
One Time Key In	Main			BRACKET, FRONT STABILIZER, NO.1 RH & LH	1	45.90	45.90	25.00	34.42	Replace	0	0	Check	• X MM
One Time Key In	Main			INSULATOR, FRONT COIL SPRING, LOWER LH & RH	1	27.30	27.30	25.00	20.48	Replace	0	0	Check	• X MM
One Time Key In	Main			SHAFT ASSY, FRONT DRIVE, LH	1	1,175.10	1,175.10	25.00	881.32	Replace	0	0	Check	• X MM
One Time Key In	Main			OIL SEAL, FRONT DRIVE SHAFT, LH	1	32.50	32.50	25.00	24.38	Replace	0	0	Check	• X MM
One Time Key In	Main			ATF OIL	1	25.00	25.00	0.00	25.00	Replace	0	0	Check	• X MM
One Time Key In	Main			GEAR ASSY, STEERING	1	1,620.70	1,620.70	25.00	1,215.53	Replace	0	0	Check	• X MM

Total Spare Part Cost 63,792.84

Surveyor Total 11,426.57

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 63,792.84

Final Sur Total 11,426.57

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT LH PORTION	1,014.00	500 ✓	
2	Main	TO REPAIR RH REAR PORTION	1,690.00	1,200 ✓	
Total:			2,704.00	1,700.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200 ✓	
2	Main	TO RESPRAY FRONT SUPPORT PANEL	180.00	0	
3	Main	TO RESPRAY RADIATOR SUPPORT LOWER	180.00	0	
4	Main	TO RESPRAY FRONT FENDER LH	378.00	200 ✓	
Total:			8,066.00	1,700.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
5	Main	TO RESPRAY APRON PANEL LH	180.00	0	
6	Main	TO RESPRAY RIM	360.00	50 ✓	
7	Main	TO RESPRAY ROCKER PANEL MOULDING	360.00	0	
8	Main	TO RESPRAY REAR BUMPER	378.00	200 ✓	
9	Main	TO RESPRAY FILLER RR BUMPER LH	180.00	0	
10	Main	TO RESPRAY FILLER RR BUMPER RH	180.00	50 ✓	
11	Main	TO RESPRAY BUMPER BEAM	180.00	0	
12	Main	TO RESPRAY REAR PANEL	180.00	0	
13	Main	TO RESPRAY TAIL GATE	378.00	200 ✓	
14	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100 ✓	
15	Main	TO RESPRAY REAR SPOILER	180.00	100 ✓	
16	Main	TO RESPRAY REAR SPARE TYRE PANEL	180.00	0	
17	Main	TO RESPRAY REAR FLOOR SIDE PANEL RH	180.00	0	
18	Main	TO RESPRAY RH REAR WHEEL HOUSE	180.00	0	
19	Main	TO RESPRAY RH RAIL ROOF SIDE	180.00	0	
20	Main	TO RESPRAY TROUGH BACK DOOR RH	180.00	0	
21	Main	TO RESPRAY REAR MEMBER RH	180.00	0	
22	Main	TO RESPRAY REAR FENDER RH	378.00	200 ✓	
23	Main	TO RESPRAY REAR FENDER LH	378.00	200 ✓	
24	Main	TO RESPRAY RH REAR DOOR	378.00	200 ✓	
Total:			4,066.00	1,700.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			3,766.00	720.00	

S.No.	Costing Type	Job Scope	SMART Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	126.00	0	90 ✓
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	40 ✓	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	300.00	80 ✓	
4	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
5	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	50 ✓	
6	Main	TO TOP UP A/C GAS	120.00	0	
7	Main	TO REMOVE / REFIT SEAT	120.00	0	
8	Main	TO ALIGN CHASSIS	350.00	0	
9	Main	TO REMOVE & REFIT EXHAUST	120.00	40 ✓	
10	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	50 ✓	
11	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20 ✓	
12	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	120.00	40 ✓	
13	Main	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30 ✓	
14	Main	TO REMOVE AND REFIX REAR WINDSCREEN	240.00	120 ✓	
15	Main	TO REMOVE AND REFIT WIRE HARDESS	250.00	30 ✓	
16	Main	TO REMOVE AND REFIX UNDERCARRIAGE	350.00	100 ✓	
17	Main	TO REMOVE AND REFIX OIL SUMP	120.00	0	
18	Main	TO REMOVE AND REFIX FRT CROSS MEMBER	120.00	0	
19	Main	TO REMOVE AND REFIT REAR CROSSMEMBER	120.00	0	
20	Main	TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	120.00	0	
21	Main	TO CHECK & RESET SYSTEM FUNCTION	350.00	120 ✓	
22	Main	TO REPLACE SUNDRY PARTS	100.00	0	
23	Main	TO WASH AND VACUUM	60.00	0	
Total:			3,766.00	720.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	63,792.84	11,426.57
Total Labour Cost	2,704.00	1,700.00
Total Spray Painting	6,066.00	1,700.00
Other	3,766.00	720.00
Overall Total	76,328.84	15,546.57
Lump Sum Repair Option		
Lump Sum Total	0.00	15,546.57
Surveyor Approved Amount		15,546.57
No of Repair Days*	20	10
Remarks		p/p repair, photo before paint.
Surveyor Name	Here is	
Signature	 28/5/19	
Survey Date	23/05/2019	Save Clear

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company



Acknowledged by Repairer

Signature:

Date:

Section A - Accident Details

Registration Number	SHD6425C
Case Reference Number	TAX/05/19/2080
Registration Date	1/11/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	LIM TOW SENG
Type of Accident	Head to Rear
Accident Date and Time	19/5/2019 4:45 AM
Accident Reported Date and Time	21/5/2019 8:55 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	19/5/2019 5:40 AM
Replacement Vehicle issued?	No
Job Card Number	24101567
Special Instruction to ARC, if any	TOWED IN \$90
Prepared Date and Time	22/5/2019 1:44 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$3,715.00	\$2,550.00
Total Spray Cost	\$6,965.00	\$2,200.00
Total Spare Part Cost	\$77,099.89	\$24,733.85
Total Other Cost	\$4,496.00	\$1,120.00
TOTAL COST	\$92,279.89	\$30,603.85 (PIP)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	20.0	18.0
Prepared / Adjusted By	Chew Tuck Loong Kelvin #	Hwee Jie (LKK) / Sompo
ARC / Surveyor Sign Off Date		31/05/2019 3:49 PM
Signature		
Remarks		p/p repair, photo before paint.



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 50 Woodlands Industrial Park E4, Singapore 751705
 FAX Number: 63855532
 Estimate Telephone Number: 65002523
 Accident Reporting Number: 65002573

Date Generated: 16/07/2019
 User ID: 1 PubliScan

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1907-0256	Invoice Number	
Quotation Date	16.07.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$1,014.00	\$500.00 /
TO REPAIR RH REAR PORTION	\$1,690.00	\$1,200.00 /
TO REPAIR REAR PORTION	\$1,014.00	\$650.00 / (L)
Total Labour	\$3,718.00	\$2,550.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00 /
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO RESPRAY RADIATOR SUPPORT LOWER	\$180.00	\$0.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00 /
TO RESPRAY APRON PANEL LH	\$180.00	\$0.00
TO RESPRAY RIM	\$360.00	\$50.00 /
TO RESPRAY ROCKER PANEL MOULDING	\$380.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$100.00 (1) A
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$100.00 (2) A
TO RESPRAY RH REAR WHEEL HOUSE	\$180.00	\$100.00 (3) A
TO RESPRAY FRT MEMBER, LH	\$180.00	\$100.00 (4) A
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$100.00 (5) A
TO RESPRAY REAR BUMPER	\$378.00	\$200.00 /
TO RESPRAY FILLER RR BUMPER LH	\$180.00	\$0.00
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$50.00 /
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00 /
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$100.00 /
TO RESPRAY REAR SPOILER	\$180.00	\$100.00 /
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$0.00
TO RESPRAY REAR FLOOR SIDE PANEL RH	\$180.00	\$0.00
TO RESPRAY RH REAR WHEEL HOUSE	\$180.00	\$0.00
TO RESPRAY RH RAIL ROOF SIDE	\$180.00	\$0.00
TO RESPRAY TROUGH BACK DOOR RH	\$180.00	\$0.00
TO RESPRAY REAR MEMBER, RH	\$180.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00 /



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 63 Woodlands Industrial Park EA, Singapore 757196
 FAX Number: 63855642
 Estimator Telephone Number: 68826223
 Accident Reporting Number: 68000012

Date Generated: 16/01/2018
 User ID: 1 PubSeen

TO RESPRAY REAR FENDER LH	\$378.00	\$200.00 /
TO RESPRAY RH REAR DOOR	\$378.00	\$200.00 /
Total Spray Painting & Panel Beating	\$6,966.00	\$2,200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$126.00	\$90.00 /
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$40.00 /
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$300.00	\$80.00 /
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$50.00 /
TO TOP UP A/C GAS	\$120.00	\$0.00
TO REMOVE / REFIT SEAT	\$120.00	\$0.00
TO ALIGN CHASSIS	\$350.00	\$0.00
TO REMOVE & REFIT EXHAUST	\$120.00	\$40.00 /
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$50.00 /
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00 /
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$40.00 /
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$30.00 /
TO REMOVE AND REFIX REAR WINDSCREEN	\$240.00	\$120.00 /
TO REMOVE AND REFIT WIRE HARDESS	\$250.00	\$30.00 /
TO REMOVE AND REFIX UNDERCARRIAGE	\$350.00	\$100.00 /
TO REMOVE AND REFIX OIL SUMP	\$120.00	\$0.00
TO REMOVE AND REFIX FRT CROSS MEMBER	\$120.00	\$0.00
TO REMOVE AND REFIT REAR CROSSMEMBER	\$120.00	\$0.00
TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	\$120.00	\$0.00
TO CHECK & RESET SYSTEM FUNCTION	\$350.00	\$120.00 /
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$50.00 / ⑥
TO TOP UP A/C GAS	\$120.00	\$50.00 / ⑦
TO REMOVE AND REFIT FRONT CROSSMEMBER	\$120.00	\$50.00 / ⑧
TO REMOVE AND REFIT REAR CROSSMEMBER	\$120.00	\$50.00 / ⑨
TO REMOVE AND REFIX UNDERCARRIAGE	\$250.00	\$100.00 / ⑩
Total Other Costs	\$4,496.00	\$1,120.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159479 13	COVER, RR BUMPER ASSY	1.00	\$423.90	25.00	\$317.93	Replace	Replace /
		52161160 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace /
		52462470 30	PAD, RR BUMPER, RH & LH, 1	2.00	\$3.80	25.00	\$5.70	Replace	Replace /
		52462470 20	PAD, RR BUMPER, RH & LH, 2	2.00	\$3.80	25.00	\$5.70	Replace	Replace /



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 50 Woodlands Industrial Park 5A, Singapore 757125
 Fax Number: 63655382
 Estimate Telephone Number: 68602223
 Accident Reporting Number: 69062072

Date Generated: 16/07/2019

User ID: PehBuen

52462470 10	PAD, RR BUMPER, RH & LH, 3	2.00	\$3.80	25.00	\$5.70	Replace	Replace	✓
52191470 30	SEAL, RR BUMPER ARM, RH & LH	2.00	\$11.00	25.00	\$16.50	Replace	Replace	✓
52566479 00	FILLER, RR BUMPER, LH	0.00	\$119.90	0.00	\$0.00	Replace	Check	X
52565479 00	FILLER, RR BUMPER, RH	1.00	\$119.90	25.00	\$89.93	Replace	Replace	✓
52023470 30	REAR BUMPER REINFORCEMENT	0.00	\$318.80	0.00	\$0.00	Replace	Check	X
	SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace	✓
	PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	✓
52576470 40	RETAINER, RR BUMPER, LH	1.00	\$111.50	25.00	\$83.63	Replace	Replace	✓
52575470 40	RETAINER, RR BUMPER, RH	1.00	\$112.70	25.00	\$84.53	Replace	Replace	✓
52599580 30	STOPPER, RR BUMPER, RH & LH	2.00	\$4.30	25.00	\$6.45	Replace	Replace	✓
52591470 50	SEAL, RR BUMPER, RH	1.00	\$65.20	25.00	\$63.90	Replace	Replace	✓
52592470 40	SEAL, RR BUMPER, LH	0.00	\$65.20	0.00	\$0.00	Replace	Not Given	X
52453470 10	GUARD, RR BUMPER, LOWER	1.00	\$556.30	25.00	\$418.73	Replace	Replace	✓
52169470 20	COVER, GUARD RR BUMPER LOWER	1.00	\$14.80	25.00	\$11.10	Replace	Replace	✓
52451470 10	PAD, RR BUMPER, CTR	3.00	\$2.20	25.00	\$4.95	Replace	Replace	✓
81551470 10	LENS & BODY ASSY, RR BUMPER, RH	1.00	\$486.80	10.00	\$438.12	Replace	Replace	✓
90189060 29	REAR BUMPER GROMMET SCREW	2.00	\$2.20	25.00	\$3.30	Replace	Replace	✓
82183470 20	WIRE, LUGGAGE ROOM	0.00	\$143.50	0.00	\$0.00	Replace	Check	X
58398470 50	COVER, REAR FLOOR UNDER, RH	1.00	\$169.50	25.00	\$127.13	Replace	Replace	✓
58399470 30	COVER, REAR FLOOR UNDER, LH	0.00	\$234.30	0.00	\$0.00	Replace	Check	X
66259470 10	COVER, REAR FLOOR UNDER CENTER	0.00	\$222.80	0.00	\$0.00	Replace	Check	X
90467170 26A0	CLIP, FLOOR UNDER COVER, NO 1	10.00	\$2.60	25.00	\$19.50	Replace	Replace	✓
90467170 27C0	CLIP, FLOOR UNDER COVER, NO 2	10.00	\$3.20	25.00	\$24.00	Replace	Replace	✓
67005474 40	TAIL GATE PANEL SUB-ASSY, BACK DOOR	1.00	\$929.60	25.00	\$697.20	Replace	Replace	✓
76801471 10A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	1.00	\$891.20	25.00	\$668.40	Replace	Replace	✓
68810470 61	TAIL GATE BACK DOOR HINGE ASSY, RH & LH	2.00	\$59.10	25.00	\$88.65	Replace	Replace	✓
69350470 50	TAIL GATE LOCK ASSY, BACK DOOR	0.00	\$452.10	0.00	\$0.00	Replace	Check	X
69321470 10	TAIL GATE LOCK COVER, BACK DOOR	0.00	\$25.30	0.00	\$0.00	Replace	Check	X
689500W 860	TAIL GATE STAY ASSY, BACK DOOR, RH	0.00	\$235.00	0.00	\$0.00	Replace	Not Given	X
69430520 50	TAIL GATE STRIKER ASSY, BACK DOOR	0.00	\$24.90	0.00	\$0.00	Replace	Not Given	X
56117501 40	TAIL GATE DAM, BACK DOOR GLASS UPPER	2.00	\$27.90	25.00	\$41.65	Replace	Replace	✓
75571470 10	TAIL GATE MOULDING GLASS, BACK DOOR	1.00	\$29.70	25.00	\$22.28	Replace	Replace	✓
75574470 40	TAIL GATE MOULDING LOWER GLASS, BACK	1.00	\$29.90	25.00	\$22.43	Replace	Replace	✓
75573471 10	TAIL GATE MOULDING LOWER GLASS, BACK	1.00	\$29.90	25.00	\$22.43	Replace	Replace	✓
75575470 51	TAIL GATE MOULDING LOWER GLASS, BACK	1.00	\$19.70	25.00	\$14.76	Replace	Replace	✓
	SEALANT W/SCREEN	3.00	\$37.00	0.00	\$111.00	Replace	Replace	✓
67881470 50	TAIL GATE WEATHERSTRIP, BACK	0.00	\$360.70	0.00	\$0.00	Replace	Check	X
64721470 50C0	TAILGATE BOARD, COVER	0.00	\$24.10	0.00	\$0.00	Replace	Check	X
74811470 20C0	TAILGATE BOARD, HANDLE PULL	0.00	\$19.50	0.00	\$0.00	Replace	Check	X
67750470 80C0	TAILGATE BOARD ASSY	0.00	\$251.50	0.00	\$0.00	Replace	Check	X
67751471 10C0	TAILGATE TRIM, LOWER	0.00	\$216.50	0.00	\$0.00	Replace	Check	X



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park East, Singapore 737704
Fax Number: 63993332
Estimate Telephone Number: 65602623
Accident Reporting Number: 65602673

Date Generated: 16/07/2016
User ID: Pabhuu

67937470 50C0	TAILGATE TRIM, RH	0.00	\$92.10	0.00	\$0.00	Replace	Check	X
6216147N 40	WIRE, FLOOR	0.00	\$3,860.00	0.00	\$0.00	Replace	Check	X
76085479 16	SPOILER SUB-ASSY, REAR	1.00	\$1,322.10	100.00	\$0.00	Replace	Repair	X
75441470 90	NAME PLATE (HYBRID), LUGGAGE COMPARTMENT	1.00	\$52.30	25.00	\$39.23	Replace	Replace	X
75442471 30	NAME PLATE (PRIUS), LUGGAGE COMPARTMENT	1.00	\$52.30	25.00	\$39.23	Replace	Replace	X
75403480 10	EMBLEM SUB-ASSY REAR	1.00	\$46.30	25.00	\$34.73	Replace	Replace	X
	SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	X
	STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	X
61017470 10	MEMBER SUB-ASSY, RAIL	0.00	\$279.30	0.00	\$0.00	Replace	Check	X
62505470 11	COVER SUB-ASSY, REAR QUARTER PILLAR, RH	0.00	\$201.30	0.00	\$0.00	Replace	Check	X
	SMRT LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Check	X
	STICKER DECAL 6555 8888	0.00	\$21.60	0.00	\$0.00	Replace	Check	X
56307470 90	END PANEL SUBASSY, BODY LOWER BACK	0.00	\$629.80	0.00	\$0.00	Replace	Check	X
64718470 80C0	END PANEL, COVER, DECK TRIM SERVICE	0.00	\$47.00	0.00	\$0.00	Replace	Check	X
64716471 30C0	END PANEL, COVER, DECK TRIM, REAR	0.00	\$122.80	0.00	\$0.00	Replace	Check	X
56350470 10	REINFORCEMENT ASSY, REAR FLOOR END PANEL	0.00	\$56.70	0.00	\$0.00	Replace	Check	X
	SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Check	X
56311471 30	SPARE TYRE PANEL, PAN, REAR FLOOR	0.00	\$564.80	0.00	\$0.00	Replace	Check	X
56315470 20	EXTENSION, REAR FLOOR SIDE PANEL, RH	0.00	\$76.20	0.00	\$0.00	Replace	Check	X
57603470 60	MEMBER SUB-ASSY, REAR FLOOR SIDE, REAR RH	0.00	\$268.60	0.00	\$0.00	Replace	Check	X
51931470 30	CARRIER, SPARE WHEEL	0.00	\$20.00	0.00	\$0.00	Replace	Check	X
61631470 70	PANEL, QUARTER WHEEL HOUSE, OUTER RH	1.00	\$286.80	25.00	\$215.10	Replace	Replace	X
61607479 00	PANEL QUARTER WHEEL HOUSE, INNER RH	0.00	\$527.00	0.00	\$0.00	Replace	Check	X
58415471 10C2	BOARD, REAR FLOOR, NO.1	0.00	\$502.20	0.00	\$0.00	Replace	Check	X
64997470 60	BOX, DECK FLOOR, LH	0.00	\$303.40	0.00	\$0.00	Replace	Check	X
64995470 50	BOX, DECK FLOOR, RH	0.00	\$304.00	0.00	\$0.00	Replace	Check	X
64730472 40C2	PANEL ASSY, DECK TRIM SIDE, RH	0.00	\$344.70	0.00	\$0.00	Replace	Check	X
61551472 81	LENS & BODY, REAR COMBINATION LAMP, RH	1.00	\$438.10	10.00	\$394.29	Replace	Replace	X
61497470 20	COVER, REAR COMBINATION LAMP, RH	1.00	\$54.00	25.00	\$40.50	Replace	Replace	X
61621470 50	TROUGH, BACK DOOR, RH	1.00	\$99.80	25.00	\$74.85	Replace	Replace	X
61601471 50	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$824.80	25.00	\$618.60	Replace	Replace	X
02940470 10	DUCT ASSY, QUARTER VENT, RH & LH	1.00	\$65.00	25.00	\$48.75	Replace	Replace	X
65637470 60	LINER, REAR FENDER, RH	1.00	\$135.80	25.00	\$101.85	Replace	Replace	X
61777280 30	RETAINER, BACK DOOR SIDE STOPPER, RH & LH	0.00	\$14.70	0.00	\$0.00	Replace	Check	X
61401470 20	REINFORCEMENT SUB-ASSY, ROCKER PANEL	0.00	\$332.30	0.00	\$0.00	Replace	Check	X
61715470 10	EXTENSION, ROOF SIDE, INNER FRONT RH	0.00	\$56.10	0.00	\$0.00	Replace	Check	X
61711470 40	PANEL, ROOF SIDE OUTER RH	0.00	\$111.00	0.00	\$0.00	Replace	Check	X
61766470 40	REINFORCEMENT, BELT ANCHOR TO ROOF SIDE	0.00	\$104.60	0.00	\$0.00	Replace	Check	X
61737470 40	REINFORCEMENT, ROOF SIDE, INNER RH	0.00	\$65.00	0.00	\$0.00	Replace	Check	X
61733470 30	PANEL, ROOF SIDE, INNER FRONT RH	0.00	\$240.20	0.00	\$0.00	Replace	Check	X
61743470 20	REINFORCEMENT, BACK DOOR OPENING SIDE, RH	0.00	\$83.30	0.00	\$0.00	Replace	Check	X



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 52 Woodlands Industrial Park St, Singapore 757708
 FAX Number: 63685562
 Evaluator Telephone Number: 98922223
 Accident Reporting Number: 98922272

Date Generated: 18/07/2018

User ID: PehBuan

61707470 20	PANEL SUB-ASSY, ROOF SIDE, INNER FRONT RH	0.00	\$83.30	0.00	\$0.00	Replace	Check	X
61625470 80	EXTENSION, QUARTER PANEL, REAR RH	0.00	\$57.20	0.00	\$0.00	Replace	Check	X
68981470 40	RETAINER, BACK DOOR STAY, RH	0.00	\$13.60	0.00	\$0.00	Replace	Check	X
61623470 20	EXTENSION, QUARTER PANEL, FRONT RH	0.00	\$56.70	0.00	\$0.00	Replace	Check	X
	TYRE	1.00	\$126.74	0.00	\$126.74	Replace	Replace	/
42611474 50	WHEEL, DISC	1.00	\$1,555.10	25.00	\$1,166.33	Replace	Replace	/
42304470 50	CARRIER SUB-ASSY, REAR AXLE, RH	0.00	\$802.70	0.00	\$0.00	Replace	Check	X
42450760 20	HUB & BEARING ASSY WITH SPEED SENSOR	0.00	\$610.20	0.00	\$0.00	Replace	Check	X
42431123 10	DISC BRAKE, REAR	0.00	\$373.90	0.00	\$0.00	Replace	Check	X
47881470 10	COVER, DISC BRAKE DUST, REAR RH	0.00	\$56.40	0.00	\$0.00	Replace	Check	X
47821471 10	MOUNTING, REAR DISC BRAKE CYLINDER, RH & CYLINDER ASSY, DISC BRAKE, REAR RH	0.00	\$163.80	0.00	\$0.00	Replace	Check	X
47830471 10	BRAKE HOSE FLEXIBLE(FOR REAR RH & ABSORBER SET, SHOCK, REAR RH & LH	0.00	\$834.20	0.00	\$0.00	Replace	Check	X
9094702H 48	ARM ASSY, UPPER CONTROL, REAR RH	0.00	\$69.80	0.00	\$0.00	Replace	Check	X
48530807 91	INSULATOR, REAR COIL SPRING, UPPER RH & LH	0.00	\$116.80	0.00	\$0.00	Replace	Check	X
48770470 10	SPRING, COIL, REAR RH & LH	0.00	\$352.40	0.00	\$0.00	Replace	Check	X
48257470 20	INSULATOR, REAR COIL SPRING, LOWER RH & LH	0.00	\$16.60	0.00	\$0.00	Replace	Check	X
48231471 70	CAM SUB-ASSY, REAR SUSPENSION TOE ADJUST	0.00	\$193.10	0.00	\$0.00	Replace	Check	X
48258470 10	ARM ASSY, TRAILING, REAR RH	0.00	\$11.70	0.00	\$0.00	Replace	Check	X
48409470 11	ARM ASSY, REAR SUSPENSION, NO.1 RH & LH	0.00	\$26.40	0.00	\$0.00	Replace	Check	X
48760470 10	BRACKET, REAR SUSPENSION TRAILING	0.00	\$239.70	0.00	\$0.00	Replace	Check	X
48710470 10	COVER, REAR SUSPENSION ARM, RH	0.00	\$200.80	0.00	\$0.00	Replace	Check	X
48717470 20	LINK ASSY, REAR STABILIZER, RH & LH	0.00	\$89.20	0.00	\$0.00	Replace	Check	X
48753470 10	BAR, STABILIZER, REAR	0.00	\$41.60	0.00	\$0.00	Replace	Check	X
48630470 10	BUSH, STABILIZER, REAR	0.00	\$149.40	0.00	\$0.00	Replace	Check	X
48812470 40	BRACKET, REAR STABILIZER BAR	0.00	\$266.30	0.00	\$0.00	Replace	Check	X
48818470 10	ARM ASSY, REAR SUSPENSION, NO.2 RH & LH	0.00	\$59.70	0.00	\$0.00	Replace	Check	X
48832470 10	SENSOR SUB-ASSY, HEIGHT CONTROL, REAR	0.00	\$9.60	0.00	\$0.00	Replace	Check	X
48730470 10	PANEL SUB-ASSY, REAR DOOR, RH	0.00	\$497.50	0.00	\$0.00	Replace	Check	X
89408470 20	DOOR LOCK REAR, RH	0.00	\$661.10	0.00	\$0.00	Replace	Check	X
67003472 10	DOOR LOCK STRIKER	1.00	\$1,243.90	100.00	\$0.00	Replace	Repair	/
89050522 50	PANEL SUB-ASSY, FENDER REAR LH	0.00	\$544.70	0.00	\$0.00	Replace	Not Given	X
89410201 10	LINER, REAR FENDER, LH	0.00	\$38.00	0.00	\$0.00	Replace	Not Given	X
61602471 60	TYRE	1.00	\$824.80	100.00	\$0.00	Replace	Repair	/
65638470 60	WHEEL, DISC	0.00	\$135.60	0.00	\$0.00	Replace	Not Given	X
	TYRE	1.00	\$126.74	0.00	\$126.74	Replace	Replace	/
42611474 50	WHEEL, DISC	1.00	\$1,555.10	25.00	\$1,166.33	Replace	Replace	/
48530807 91	ABSORBER SET, SHOCK, REAR RH & LH	0.00	\$116.80	0.00	\$0.00	Replace	Check	X
48790470 10	ARM ASSY, UPPER CONTROL, REAR LH	0.00	\$352.40	0.00	\$0.00	Replace	Check	X
48780470 10	ARM ASSY, TRAILING, REAR LH	0.00	\$239.70	0.00	\$0.00	Replace	Check	X
48710470 10	ARM ASSY, REAR SUSPENSION, NO.1 RH & LH	0.00	\$200.80	0.00	\$0.00	Replace	Check	X
48730470 10	ARM ASSY, REAR SUSPENSION, NO.2 RH & LH	0.00	\$497.50	0.00	\$0.00	Replace	Check	X

SMRT Accident Vehicle Repair Estimates

42305470	CARRIER SUB-ASSY, REAR	0.00	\$802.70	0.00	\$0.00	Replace	Check	X
50	AXLE, LH							
75860479	MOULDING ASSY, BODY	0.00	\$576.00	0.00	\$0.00	Replace	Check	X
00	ROCKER PANEL, LH							
75850479	MOULDING ASSY, BODY	0.00	\$576.00	0.00	\$0.00	Replace	Check	X
10	ROCKER PANEL, RH							
65631470	PLATE, REAR WHEEL	0.00	\$26.80	0.00	\$0.00	Replace	Check	X
80	HOUSE, FRONT RH							
65632470	PLATE, REAR WHEEL	0.00	\$26.80	0.00	\$0.00	Replace	Check	X
80	HOUSE, FRONT LH							
58165470	COVER, FRONT FLOOR	0.00	\$427.30	0.00	\$0.00	Replace	Check	X
30	UNDER, RH							
58168470	COVER, FRONT FLOOR	0.00	\$425.50	0.00	\$0.00	Replace	Check	X
30	UNDER, LH							
58390470	COVER ASSY, CENTER	0.00	\$306.90	0.00	\$0.00	Replace	Check	X
10	FLOOR UNDER, RH							
57628470	COVER ASSY, CENTER	0.00	\$390.20	0.00	\$0.00	Replace	Check	X
20	FLOOR UNDER, LH							
58153470	EXHAUST HEAT SHIELD	0.00	\$228.50	0.00	\$0.00	Replace	Check	X
50	INSULATOR, FRONT							
58327470	EXHAUST HEAT SHIELD	0.00	\$137.00	0.00	\$0.00	Replace	Check	X
40	INSULATOR, MAIN							
1741037B	PIPE ASSY, EXHAUST,	0.00	\$2,495.00	0.00	\$0.00	Replace	Check	X
70	FRONT							
17565220	SUPPORT, EXHAUST PIPE	0.00	\$41.10	0.00	\$0.00	Replace	Check	X
40	NO.5							
17565280	SUPPORT, EXHAUST PIPE	0.00	\$41.10	0.00	\$0.00	Replace	Check	X
10	NO.4							
17451230	GASKET, EXHAUST PIPE	0.00	\$44.80	0.00	\$0.00	Replace	Check	X
42	TAIL							
17451280	GASKET, EXHAUST PIPE	0.00	\$83.90	0.00	\$0.00	Replace	Check	X
40	FRONT							
17430377	PIPE ASSY, EXHAUST, TAIL	1.00	\$1,173.90	25.00	\$680.43	Replace	Replace	X
30								
51206470	REAR MEMBER SUB-ASSY,	0.00	\$2,171.70	0.00	\$0.00	Replace	Check	X
12	RR							
52119479	COVER, FR BUMPER	1.00	\$495.50	25.00	\$371.63	Replace	Replace	X
62								
52151160	CLIPS PIECE, FRT & RR	10.00	\$1.50	25.00	\$11.25	Replace	Replace	X
10	BUMPER							
53101470	GRILLE SUB-ASSY	0.00	\$335.60	0.00	\$0.00	Replace	Not Given	X
80								
53112472	GRILLE, RADIATOR	0.00	\$165.00	0.00	\$0.00	Replace	Not Given	X
40								
52116470	SUPPORT, FR BUMPER LH	1.00	\$62.30	25.00	\$61.73	Replace	Replace	X
50								
52611471	ABSORBER, FR BUMPER	0.00	\$70.30	0.00	\$0.00	Replace	Check	X
40								
52021471	REINFORCEMENT FRONT	0.00	\$691.10	0.00	\$0.00	Replace	Check	X
10	UPPER							
52618470	ABSORBER, FR BUMPER	0.00	\$117.00	0.00	\$0.00	Replace	Check	X
90	LOWER							
52132470	REINFORCEMENT FRONT	0.00	\$238.50	0.00	\$0.00	Replace	Check	X
10	LOWER							
52103470	EXTENSION SUBASSY, LH	0.00	\$118.30	0.00	\$0.00	Replace	Check	X
10								
52102470	EXTENSION SUBASSY, RH	0.00	\$118.30	0.00	\$0.00	Replace	Not Given	X
20								
81220470	LAMP ASSY, FOG, LH	1.00	\$510.20	10.00	\$819.18	Replace	Replace	X
20								
51420470	COVER ASSY, ENGINE	0.00	\$180.10	0.00	\$0.00	Replace	Not Given	X
30								
53205479	SUPPORT S/A UPPER	0.00	\$364.90	0.00	\$0.00	Replace	Not Given	X
00								
53026470	SUPPORT SUB-ASSY	0.00	\$397.40	0.00	\$0.00	Replace	Check	X
10	LOWER							
53217470	BRACE, HOOD LOCK	0.00	\$76.20	0.00	\$0.00	Replace	Not Given	X
30	SUPPORT							
53214470	SUPPORT, RADIATOR	0.00	\$76.70	0.00	\$0.00	Replace	Not Given	X
50	UPPER LH							
81185476	UNIT, HEADLAMP, LH	0.00	\$2,558.90	0.00	\$0.00	Replace	Check	X
91								
53203479	SUPPORT S/A LH	0.00	\$237.00	0.00	\$0.00	Replace	Check	X
01								
16592370	GUIDE, RADIATOR AIR,	0.00	\$93.90	0.00	\$0.00	Replace	Check	X
20								
51107470	FRONT REINFORCEMENT	0.00	\$128.20	0.00	\$0.00	Replace	Check	X
20	SIDE RH							
51108470	FRONT REINFORCEMENT	0.00	\$129.30	0.00	\$0.00	Replace	Check	X
20	SIDE LH							
51201470	FRONT CROSSMEMBER	0.00	\$2,502.10	0.00	\$0.00	Replace	Check	X
71								



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 90 Woodlands Industrial Park E4, Singapore 731108
 FAX Number: 63995552
 Estimator Telephone Number: 63962523
 Accident Reporting Number: 66952672

Date Generated: 18/07/2016
 User ID: PuliBee

51410470 20	COVER ASSY, ENGINE UNDER CENTER SET	0.00	\$452.80	0.00	\$0.00	Replace	Check	X
51444470 10	COVER, ENGINE UNDER SIDE LH	0.00	\$76.90	0.00	\$0.00	Replace	Check	X
	ENGINE OIL	0.00	\$15.00	0.00	\$0.00	Replace	Not Given	X
12102370 10	PAN SUB-ASSY, OIL	0.00	\$218.10	0.00	\$0.00	Replace	Not Given	X
15100370 60	PUMP ASSY, OIL	0.00	\$403.70	0.00	\$0.00	Replace	Not Given	X
88460103 20	AIR CON CONDENSER ASSY	0.00	\$1,317.70	0.00	\$0.00	Replace	Not Given	X
88710471 60	TUBE & ACCESSORY	0.00	\$574.40	0.00	\$0.00	Replace	Not Given	X
88703470 60	HOSE SUB-ASSY, DISCHARGE	0.00	\$337.10	0.00	\$0.00	Replace	Not Given	X
88370470 92	AIR CON COMPRESSOR ASSY	0.00	\$2,887.80	0.00	\$0.00	Replace	Check	X
	COOLANT	0.00	\$12.30	0.00	\$0.00	Replace	Check	X
16400373 10	RADIATOR ASSY	0.00	\$1,841.10	0.00	\$0.00	Replace	Check	X
90480400 21	GROMMET (FOR RADIATOR LOWER	0.00	\$12.70	0.00	\$0.00	Replace	Check	X
16523370 10	CUSHION, (FOR RADIATOR UPPER SUPPORT)	0.00	\$9.80	0.00	\$0.00	Replace	Check	X
16361370 60	FAN RADIATOR, LH	0.00	\$181.80	0.00	\$0.00	Replace	Check	X
16361370 70	FAN RADIATOR, RH	0.00	\$233.00	0.00	\$0.00	Replace	Check	X
16711371 60	FAN SHROUD RADIATOR	0.00	\$219.30	0.00	\$0.00	Replace	Check	X
16363370 60	MOTOR, COOLING FAN, LH	0.00	\$543.50	0.00	\$0.00	Replace	Check	X
16363361 60	MOTOR, COOLING FAN, RH	0.00	\$443.40	0.00	\$0.00	Replace	Check	X
G904047 040	INVERTER WATER PUMP ASSY	0.00	\$432.00	0.00	\$0.00	Replace	Check	X
8211147J 21	WIRE, ENGINE ROOM MAIN	0.00	\$6,138.00	0.00	\$0.00	Replace	Check	X
821H2470 10	WIRE, AIR CONDITIONER	0.00	\$445.70	0.00	\$0.00	Replace	Check	X
53875470 70	LINER, FR FENDER, RH	0.00	\$198.40	0.00	\$0.00	Replace	Not Given	X
53851470 61	PAD, FR WHEEL RH	0.00	\$57.70	0.00	\$0.00	Replace	Not Given	X
53802471 00	FENDER SUB-ASSY, FR, LH	1.00	\$933.10	100.00	\$0.00	Replace	Repair	X
75374471 40	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$52.90	25.00	\$39.68	Replace	Replace	X
53876471 10	LINER, FR FENDER, LH	0.00	\$194.30	0.00	\$0.00	Replace	Check	X
53852470 41	PAD, FR WHEEL LH	0.00	\$57.70	0.00	\$0.00	Replace	Check	X
53702471 01	APRON SUB-ASSY, FRONT FENDER, LH	0.00	\$844.20	0.00	\$0.00	Replace	Check	X
	TYRE	1.00	\$126.74	0.00	\$126.74	Replace	Replace	X
42611- 47450	WHEEL, DISC FRONT	1.00	\$1,555.10	25.00	\$1,166.33	Replace	Replace	X
48520804 92	ABSORBER SET, SHOCK, FRONT LH	0.00	\$398.10	0.00	\$0.00	Replace	Check	X
48820470 40	LINK ASSY, FRONT STABILIZER, RH & LH	0.00	\$198.70	0.00	\$0.00	Replace	Check	X
48069470 60	LOWER ARM SUBASSY, FRONT LH	0.00	\$631.60	0.00	\$0.00	Replace	Check	X
43330191 15	JOINT ASSY, LWR BALL, RH & LH	0.00	\$200.10	0.00	\$0.00	Replace	Check	X
43212470 40	KNUCKLE, STEERING, LH	0.00	\$555.20	0.00	\$0.00	Replace	Check	X
45047491 55	END SET, TIE ROD, LH	0.00	\$155.90	0.00	\$0.00	Replace	Check	X
43550470 20	HUB & BEARING ASSY, RH & LH	0.00	\$554.20	0.00	\$0.00	Replace	Check	X
48824470 20	BRACKET, FRONT STABILIZER, NO.1 RH & LH	0.00	\$45.90	0.00	\$0.00	Replace	Check	X
48815470 40	INSULATOR, FRONT COIL SPRING, LOWER LH & RH	0.00	\$27.30	0.00	\$0.00	Replace	Check	X
43420470 40	SHAFT ASSY, FRONT DRIVE, LH	0.00	\$1,175.10	0.00	\$0.00	Replace	Check	X
90311500 45	OIL SEAL, FRONT DRIVE SHAFT, LH	0.00	\$32.50	0.00	\$0.00	Replace	Check	X



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 52 Woodlands Industrial Park 54, Singapore 757705
 FAX Number: 63685562
 Estimate Telephone Number: 66620323
 Accident Reporting Number: 66620373

Date Generated: 16/07/2016
 User ID: PAB000

		ATF OIL	0.00	\$25.00	0.00	\$0.00	Replace	Check	X
	45510471 40	GEAR ASSY, STEERING	0.00	\$1,620.70	0.00	\$0.00	Replace	Check	X
Total				\$80,056.62		\$11,426.71			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
	*	53876471 10	LINER, FR FENDER, LH	1.00	\$194.30	25.00	\$145.73	Replace	Replace	✓ A TN
	*	48520804 92	ABSORBER SET, SHOCK, FRONT LH	1.00	\$398.10	25.00	\$298.58	Replace	Replace	✓ A BT
	*	48069470 60	LOWER ARM SUB-ASSY, FRONT LH	1.00	\$631.60	25.00	\$473.70	Replace	Replace	✓ A BT
	*	43330191 15	JOINT ASSY, LWR BALL, RH & LH	1.00	\$200.10	25.00	\$150.08	Replace	Replace	✓ A NEL
	*	43212470 40	KNUCKLE, STEERING, LH	1.00	\$555.20	25.00	\$416.40	Replace	Replace	✓ A BT
	*	43550470 20	HUB & BEARING ASSY, RH & LH	1.00	\$554.20	25.00	\$415.65	Replace	Replace	✓ A NEL
	*	17700373 30	AIR CLEANER ASSY	1.00	\$956.20	25.00	\$717.15	Replace	Replace	✓ A BR
	*	52023470 30	REAR BUMPER REINFORCEMENT	1.00	\$318.80	25.00	\$239.10	Replace	Replace	✓ A DD
	*	66259470 10	COVER, REAR FLOOR UNDER CENTER	1.00	\$222.60	25.00	\$166.95	Replace	Replace	✓ A CRU
	*	67861470 50	TAIL GATE WEATHERSTRIP, BACK	1.00	\$360.70	25.00	\$270.53	Replace	Replace	✓ A TN
	*	58307470 80	END PANEL SUB-ASSY, BODY LOWER BACK	1.00	\$629.80	25.00	\$472.35	Replace	Replace	✓ A DD
	*	64716471 30C0	END PANEL, COVER, DECK TRIM, REAR	1.00	\$122.80	25.00	\$92.10	Replace	Replace	✓ A CRU
	*	58315470 20	EXTENSION, REAR FLOOR SIDE PANEL, RH	1.00	\$76.20	25.00	\$57.15	Replace	Replace	✓ A DD
	*	64995470 50	BOX, DECK FLOOR, RH	1.00	\$304.00	25.00	\$228.00	Replace	Replace	✓ A CRU
	*	64730472 40C2	PANEL ASSY, DECK TRIM SIDE, RH	1.00	\$344.70	25.00	\$258.53	Replace	Replace	✓ A CRU
	*	42304470 50	CARRIER SUB-ASSY, REAR AXLE, RH	1.00	\$602.70	25.00	\$602.03	Replace	Replace	✓ A BT
	*	43550470 20	HUB & BEARING ASSY, RH & LH	1.00	\$554.20	25.00	\$415.65	Replace	Replace	✓ A NEL
	*	48530807 91	ABSORBER SET, SHOCK, REAR RH & LH	1.00	\$116.80	25.00	\$87.60	Replace	Replace	✓ A BT
	*	48770470 10	ARM ASSY, UPPER CONTROL, REAR RH	1.00	\$352.40	25.00	\$264.30	Replace	Replace	✓ A BT
	*	48760470 10	ARM ASSY, TRAILING, REAR RH	1.00	\$239.70	25.00	\$179.78	Replace	Replace	✓ A BT
	*	48710470 10	ARM ASSY, REAR SUSPENSION, NO.1 RH &	1.00	\$200.80	25.00	\$150.60	Replace	Replace	✓ A BT
	*	48830470 10	LINK ASSY, REAR STABILIZER, RH & LH	1.00	\$149.40	25.00	\$112.05	Replace	Replace	✓ A BT
	*	48812470 40	BAR, STABILIZER, REAR	1.00	\$286.30	25.00	\$214.73	Replace	Replace	✓ A BT
	*	48818470 10	BUSH, STABILIZER, REAR	2.00	\$59.70	25.00	\$89.55	Replace	Replace	✓ A NEL
	*	48730470 10	ARM ASSY, REAR SUSPENSION, NO.2 RH &	1.00	\$497.50	25.00	\$373.13	Replace	Replace	✓ A BT
	*	48780470 10	ARM ASSY, TRAILING, REAR LH	1.00	\$239.70	25.00	\$179.78	Replace	Replace	✓ A BT
	*	48730470 10	ARM ASSY, REAR SUSPENSION, NO.2 RH &	1.00	\$497.50	25.00	\$373.13	Replace	Replace	✓ A BT
	*	51284470 10	COVER, REAR MEMBER SUB-ASSY RH	1.00	\$14.20	25.00	\$10.65	Replace	Replace	✓ A BT
	*	51420470 30	COVER ASSY, ENGINE	1.00	\$180.10	25.00	\$135.08	Replace	Replace	✓ A BR
	*	53205478 00	SUPPORT S/A UPPER	1.00	\$364.90	25.00	\$273.68	Replace	Replace	✓ A DD
	*	53028470 10	SUPPORT SUB-ASSY LOWER	1.00	\$397.40	25.00	\$298.05	Replace	Replace	✓ A DD
	*	53217470 30	BRACE, HOOD LOCK SUPPORT	1.00	\$76.20	25.00	\$57.15	Replace	Replace	✓ A DD
	*	81185476 91	UNIT, HEADLAMP, LH	1.00	\$2,558.90	10.00	\$2,303.01	Replace	Replace	✓ A LW
	*	53203479 01	SUPPORT S/A LH	1.00	\$237.00	25.00	\$177.75	Replace	Replace	✓ A DD
	*	51201470 71	FRONT CROSSMEMBER	1.00	\$2,502.10	25.00	\$1,876.58	Replace	Replace	✓ A BT



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park 64, Singapore 757756
Fax Number: 63666602
Estimated Telephone Number: 93802623
Accident Reporting Number: 93802072

Order Generated: 16/07/2019
User ID: PehBuan

	*	51410470 20	COVER ASSY, ENGINE UNDER CENTER SET	1.00	\$452.80	25.00	\$339.60	Replace	Replace	✓	A MB
	*	51444470 10	COVER, ENGINE UNDER SIDE LH	1.00	\$76.90	25.00	\$57.68	Replace	Replace	✓	A BR
	*	51443470 20	COVER, ENGINE UNDER SIDE RH	1.00	\$76.90	25.00	\$57.68	Replace	Replace	✓	A BR
	*	12102370 10	PAN SUB-ASSY, OIL	1.00	\$218.10	25.00	\$163.58	Replace	Replace	✓	A DD
	*		ENGINE OIL	4.00	\$25.00	0.00	\$100.00	Replace	Replace	✓	A NEL
	*		COOLANT	1.00	\$12.32	0.00	\$12.32	Replace	Replace	✓	A NEL
Total					17,058.82		13,307.14				

24,733.85 / (hotel)
+ 2,550.00 / (hotel)
+ 3,320.00 / (hotel)

30,603.85

REQUEST FOR SUPPLYMENT PARTS

Contractor:			
Accident Case Number	TAX/05/19/2080	Date of Collection	/ /
Vehicle No	SHD 6425 C	Date of Request	28/05/2019
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend (If any)	18

S/N	Part Number	Part Description	Quantity	Unit Price	
		REAR BUMPER REINFORCEMENT	1pc	- DD	239.10
		COVER, REAR FLOOR UNDER (CENTER)	1pc	- CR	166.95
		TAILGATE WEATHERSTRIP BASIC DOOR	1pc	- TA	270.53
		END PANEL SUB ASSY, LOWER BASIC	1pc	- DD	472.35
		END PANEL, COVER DECK TRIM REAR	1pc	- CR	92.10
		EXTENSION, REAR FLOOR SIDE PANEL RH	1pc	- R	57.15

<<<Please submit photographs for damaged parts>>>

I, (Name) _____

(Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration
[to be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

P9/10

REQUEST FOR SUPPLYMENT PARTS

Contractor:			
Accident Case Number	TAX/05/19/2080	Date of Collection :	/ /
Vehicle No	SHD 6425 C	Date of Request	28/05/2019
Vehicle Model	TOLEVA PRINS	Number of Days to Extend (If any)	X 8

S/N	Part Number	Part Description	Quantity	Unit Price	
		BOX, DECK FLOOR RH	1pc	/ CRV	228
		PANEL Assy. DECK TRIM SIDE RH	1pc	- CRV	258.53
		CARRIER SUB Assy. REAR AXLE RH	1pc	/ BT	602.03
		HUB & BEARING Assy. REAR RH	1pc	- RUC	415.65
		REAR SHOCK ABSORBER RH	1pc	- BT	87.60
		ARM Assy. UPPER REAR RH	1pc	- BT	264.30

<<<Please submit photographs for damaged parts>>>

I, (Name) _____

(Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

.....
Signature of person making this declaration
(to be signed in front of an authorised witness)

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

P30/10

REQUEST FOR SUPPLEMENTARY PARTS

Contractor:			
Accident Case Number	TAX/05/19/2080	Date of Collection	1 1
Vehicle No	SND 6425 C	Date of Request	28/05/2019
Vehicle Model	TOYOTA PRIMA	Number of Days to Expend (If any)	12.8

S/N	Part Number	Part Description	Quantity	Unit Price	
		ARM ASSY, TRAILER REAR RH	1pc	- GT	179.78
		ARM ASSY, REAR Suspension MOD RH 1pc	1pc	- GT	159.60
		REAR STAB LINK RH	1pc	- GT	112.95
		REAR STAB BAR	1pc	- GT	214.75
		REAR STAB BUSH	2pcs	- ARC	89.55
	48730-4A010	REAR LOWER ARM RH	1pc	- GT	373.13

<<<Please submit photographs for damaged parts>>>

I, (Name) _____

(Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration
[to be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

P33/10