Windin:	KAK	ABSTERMEN OF M	TT (Office)		22/5/1985.22
stimated Cost:			Bill to:		
o Inspect Veh	TP RES / OD RES / E	SIG 7835G	In	sarred: <u>SD</u>	×23262
t Workshop m	/8	SICTIVADO	MIODI 16	1cr	210140
£		Bulcitavo a	Claim No:	502277	1 344 800.17
	28880426			593612	
Sum Insured: Make of Veh: Client's Record			Excess:	D.O.A	7/05/2019
	REP. / REV 24 HRS			H.O.D. End	orsement:
1 1 1 1 1 1 1 1 1 1			thou 1 .	Valida IN	OUT
		Person Contacted: _	" reysee	· · · · · · · · · · · · · · · · · · ·	
Date/Time: 5	pros selslig		* payree		
Date/Time: 5	Action/Instruction	stimate (Dia: 411/2019
Date/Time: 5	Action/Instruction FS	stimate 1			
Date/Time: 5	Action/Instruction	stimate 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	352 /h4	3	FIA. 411/2019
	Action/Instruction FS S J G 7835 G - N	stimate 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	352 /h4	3	FIA. 411/2019

ASSIGNMENT

From:	Dale: 23 5 19	Veh No: SJG 783	Yr Regn.	16/1/08
stimated Cost:		Type: M.Carl M.Cycle / Bu	s / Van / Lorry / Taxi / Pr	rime Mo ve r /
TP) WS / TP RES / O	DD RES / EVA / INV / MV	Truck / Trailer or		
o Inspect Vehicle No:		Make: Toyota V	105 E	0.0 1497
Workshop m/s	SJG 7835G SK Automobile	Colour Black		sured / Std / NI / NA
The state of the substitute of the state of	uit Ave 4 #08-46 pre	miersp.Reading 97642	 T/Radio; tr 	sured / Std / NI / NA
isured.	11 NVE 4 1108 1101	Eng/No:		
olicy No.		C/No: MRQS.	3 H14930507165	9
laims No.		Gen. Cond: Good (Fair) P		
um Insured:	Excess:	Steering: Inorder/ Jamme	d / Leaked / Burnt or	
(Client's Record)		Brake: Unprdor / Jamme	d / Leaked / Burnt or	
Nake of Veh:		Modi: Nil (S/Rin) / ST	D A/Rim or	
		Tyre Size: F:	185/GORIS	
(Policy Condition)		R:	n	
Remark: The veh had con	nmenced its N/S C	DIS BS / DUN / EXNOVA / GY		U / PIR / SUMI L
repair at the tim	transfer and the second state of the second st	TOYO / YOKO or	HIFIY	(*)(
Bal, or Market Value:		Front	Rear	
DAC Accident Rport:	Consistent? : Yes or No	R/Bal. 7	mm R/Bal.	7
GIA / PR Seen:	Consistent? : Yes or No	L/Bal.	mm L/Bal.	7 m
Est. Repairs:	days Res.: Yes or No	- D.O.A. 17/5/19	D.O.I.	23/5/19
Lum Sum:	% 3 Val.: Yes or No	Survey held at	SK	1.7
Julii Sunt.	(1.82	Des. of Damages : Frt I(R	<u> </u>	/ Roofton or
CA / REV / REP. /	24 HRS Vehicle: IN /		1013 / 1110 / 010	1 Hoonop 5
Date: Pe	rson Contacted:		me / Body Structure a	affected due to collision
Date / Time Action /	/ Instruction			hopean
	Steve,			1 1
	PS.	check parts	bucos.	V 50/PI
10/06/19 Confir	med 215 \$ 4,400/ 8,449.53 Red -	- 0 7 days w	the steve	m
(¢	8,449.53 Red -	66%)	1 ()	
	RECEIVED 2 1 JUN	2019	V	28/5
	RECEIVED 4 1 300			
- I			_	
Date/Time, File Pass to?	: Prell. Report	Days Of Repair:	+.	panerum arrena
Typist	: Final Report	. Resurvey No. of Trip:	Survey F	
Date/Time, File Return to?	10,000-00	F	Transporta	
3	Add	Fee: Site Insp (\$)8÷RS	SI
27' (CE72D 50	82.5	: Interview (\$) Photos	-
Report Format :	1	: Tech, Invs 6)) Oliver	-
ump Sup / LB.J; 65	\$ 4.400/- 45	: West end G	1	
			70181.	211

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Pauline Tham

Date: 28 May 2019

Preliminary Advice

Insured Vehicle No : SDX2326Z

TP Vehicle No

: SJG7835G

Accident Date

: 17/05/2019

Make

: TOYOTA VIOS EA

Assignment Date

: 22/05/2019

Est. Duration of Repair

: 7 days

Inspection At

Date of Inspection : 23/05/2019

: Sk Automobile Pte Ltd

8 Kaki Bukit Ave 4, #08-46 Premier @ Kaki Bukit

Singapore 415875

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,849.53
Revised Amount	:S\$	8,683.30
Check Items (Estimated)	:S\$	0.00
Total	:S\$	8,683.30

:S\$ Lump Sum Repair

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The veh	icle is	economi	cal/not	economical	tor	repair.
---	-----------	---------	---------	---------	------------	-----	---------

(X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(Pending for Survey Report)

	OLDER TRA			Taur mas	Adi Subi	mitted.	Ins Auth'ed	Status		
Case	Notified	Est Submitted		Adj Rpt	MG1.5G0	DIRECTO.	1113-NOUT 60	_	ng for Sur	vev
Main	17 May 2019		22 May 2019 17:22					Repor		
505300			Edit Adj Rpt					Cance	Case	
	Main	Re	eference		Claim Details		Documen	ts		how All
CLATM SII	BFOLDER DE	TATIS	TO SERVICE OF SERVICE OF	Manhaut and State	Na line was read to be a	[Creat	ed by insurer]	OVER THE REAL PROPERTY.	S. St. Commission of the Commi	OCC SALES
Insured:		AJAH S/O SELV	ARAJAH. ID: S	1599588B.	Tel: +6590026	850, Er	mail: skanlaw@yaho	o.co.uk		
Main Claimant:	1 35 45 53 53 54 54	KHIONG, ID: S	CONTRACTOR CONTRACTOR							
Vehicle Reg	SJG783	5G		Date of Loss: 17/05/2019 13:00 - :59 [130 Months and 1 Days From LTA Reg Date (M.					Man Yr)]	
Claim Type	TP / 593	372			Policy/Cover Note No.:	er 28880426 (Comprehensive) Coverage: 28/01/2019 - 27/01/2020				
Vehicle Reg No. (Insured):	SDX2326	z			Policy No. (Claimant):					
(1.1001.00)					Excess:					
Repairer:							5875 Kaki Bukit - Te			
Handling Insurer:	The second secon						d by Pauline Than	the second second second second	The second secon	
Adjuster:	23/05/2	Consultants Pto 019]	e Ltd (HQ) - Tel	: 6256-3561	[Handled by	XING G	UO QIANG] [Im	ım.Adv	ice aue	
Driver/Cus dian (Insured):	SKANDAR	AJAH S/O SELVAR	AJAH (55 / Male)), NRIC: S	S1599588B, Te	l: +6590	026850 Email: skar	nlaw@yah	oo.co.uk	
ASSOCIA	TED MAIL RE	CEIVED						View All	Compose	Case M
There are i	no mail for this	case.								
ALL ASS	CIATED TAS	sks⊡				View	All Search Tasks	Create	New Task	Comple
			Group Sub	viect Har	ndler Assia	ned By	Completed O	n Cr	eated On	Don
	e Priority	Type Tasi	Group Suc	1000						
Due Dat		C CLASSING CALCOR	Group Sub	oject Har	ndler Assign	View ned By			_	

Shirley Hiew (LKK Auto) SK Admin <admin@skauto.com.sg> From: Friday, 21 June 2019 2:43 PM Sent: Shirley Hiew (LKK Auto) To: simon koh; JING XIONG KHOO; KY Leong; Tyson Koh; Admin A; SUR; Steve Chen Cc: (LKK Auto) Re: SJG7835G----FINALIZE Subject: Dear Shirley, Thanks for your reply. We confirmed accept COR@S\$4,400.00-7 days Regards, Huey Lee SK Automobile Pte Ltd On Thu, Jun 20, 2019 at 3:34 PM Shirley Hiew (LKK Auto) < Shirley Hiew@lkkauto.com > wrote: Dear Huey Lee, Please re-confirm final fig \$ 4,400.00 (lump sum) @ 7 days of repairs. Thank you. Best Regards, Shirley Hiew | Case Handler LKK Auto Consultants Pte Ltd Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	
Owner ID:	
Vehicle Details	
Vehicle No.:	

Vehicle No.:
Vehicle to be Exported:
Intended Deregistration Date:

Vehicle Make: Vehicle Model: Primary Colour: Manufacturing Year: Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid: Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date: PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date: COE Category: COE Period(Years):

PQP Paid: COE Rebate Amount: Total Rebate Amount: Message Singapore NRIC 2043E

SJG7835G No

21 May 2019 TOYOTA VIOS E AUTO Black 2008

1NZX778254 MR053HY9305071659 80.0 kW (107 bhp) \$12,344.00 16 Jul 2008

16 Jul 2008

\$12,344.00

Forfeited

\$0.00

15 Jul 2023


A - Car (1600cc & below)

5 \$18,583.00 \$15,418.00 **\$15,418.00**

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 21 May 2019

OK





Toyota Vios 1.5A E (COE \$21,800 \$5,900/yr 29-Jan-2008 1,497 cc 99,000 km Sedan Available till 01/2023)

100% Loan. Low Instalment. Very Well Maintained By Careful Owner. Great Fuel Consumption. Original Paint, 100% Accident Free! Low Mileage Easy To Drive And Very Smooth Transmission! Contact Us Now.

Posted: 20-May-2019 Tags: 2008 Toporta Vius, 2008 toporta vius, Toyota Vius, myota vius, Toyota Vius, vius, Used Toyota

Toyota Vios 1.5A E (COE \$27,800 \$6,590 /yr till 08/2023)

08-Aug-2008 1,497 cc 139,000 km

Available

Sedan

Consignment Unit, Call To Arrange A Test Drive Today!

CONSIGNMENT

(CONSIGNMENT)

Car Search

Pasied: 09-Apr-2019 Tags: 2008 Toyots Vins, 2008 toyota vins, Toyota Vios, tayota vins, Toyota Vios, vins, Used Toyota



Toyota Vios 1.5A J (COE \$44,800 \$4,700 /yr 26-Nov-2008 1,497 cc 73,500 km Sedan Available till 11/2028)

Renewed 10 Years COE! One Of The Most Reliable And Fuel Efficient Ride! Well Maintained By Previous Owner! Good Condition Suitable For All Ages! Flexible Loan Scheme Provided, Consignment Unit, Call A...

Car Search

Posted: 20-Mar-2019 Tags: 2008 Toyota Vios, 2008 toyota vios, Toyota Vios, tayota vios, Toyota, Vios, vios, Used Tayota



Stand out with a bidded car plate number!

Bring luck and prosperity with an auspicious car licence plate number starting from only \$2,3xx!

MVA319064431 / VAC - KaK BUKII ENTRY DATE & TIME: 17/05/2018 16:49 SUBMITTED BY: SITI FADHLON BTE ABDUL KADER

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Please report correctly the details of the accident to speed up the claims process.

This Form must be completed by the Policyholder and/or the Authorised Oriver.

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any faise reporting may be referred to the Police for Investigation.

This report will be forwarded by the incurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made svallable upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available.

	ACC	JIDEN	SIAI	EMEN
--	-----	-------	------	------

Date Of Report

17/05/2019 16:49

Date Of Accident

17/05/2019 13:35

Exact Location Of Accident

SERANGOON NORTH AVE 1 TWRDS AMK(JUNCTION)

SINGAPORE Country/State of Loss

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SJG7835G

Insured/Policyholder

Name Of Registered Owner

NG KING KHIONG

NRIC No

S1532043E

Emall Address

NOEMAIL

Mobile Phone No

(LOCAL) +65-90012947

Alternative Phone No.

OTHERS-90012947

Vehicle Particulars

Manufacturer

TOYOTA

Model

VIOS E AUTO

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage

COMPREHENSIVE

Fleet Policy

NO

Policy Number

5044718682-08

Cover Note Number

Driver

NG KING KHIONG Name of Driver

S1532043E NRIC No 10/05/1962 Date Of Birth OUTDOOR Occupation 18/05/1991 Date Of Driving Pass

27 YEARS AND 11 MONTHS **Driving Experience**

Gender

MALE

Mobile Number

(LOCAL) +65-90012947

Fax Number

Contact Number

OTHERS-90012947

EMail Address

NOEMAIL

×

Address

BLK 261A #12-343 PUNGGOL WAY PUNGGOL TOPAZ

Postcode

821261

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

.

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

2

involved in the accident

YES

Was any body injured in the Accident? Was any injured conveyed to hospital by

NO

ambulance?

YES

Was any other material or property damaged?

I have been approached by unknown person(s)

NO

soliciting/offering accident claims assistance.

1

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

YES.

If Yes, Please state which Police Station Police Station Name

THOMSON NEIGHBOURHOOD POLICE POST ROAD: BLK 25 SIN MING ROAD , POSTCODE: 570025 , COUNTRY:

Police Station Address SINGAPORE

Police Station Contact

TEL NO: 1800-4529999 - FAX NO: 6 5535740

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

AS PER POLICE REPORT No.T/20190517/2113;

Attachment(s)

YES

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

WITH DRIVER

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SDX2326Z

Vehicle Make/Model/Colour

OPEL ZAFIRA TOURER

Details Of Properties

Remarks/ Reasons:

Vehicle Category

PRIVATE CAR

Name of Driver

SKANDARAJAH

NRIC/Passport Number

S1599588B

Contact Number

90028850

Address

Postcode

Insurance Company Name

MSIG INSURANCE (SINGAPORE) PTE. LTD.



No. Of Passenger (Including Driver)

Name NG KING KHIONG Approximate Age Injuries Sustain Injured person in which vehicle? Were seat belts worn? Was this injured conveyed to hospital by ambulance? Address Postcode DETAILS OF INJURED PERSON 1 NG KING KHIONG SJG7835G YES BLK 261A #12-349 PUNGGOL WAY PUNGGOL TOPAZ 821261

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The Issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centra established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I undofstand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (I) processing, handling and/or dealing with my claims including the settlement of the daims and any necessary Investigations relating to the claims;
 - (II) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by ma;
 - (b) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agontelincluding their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (I) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (II) for complying with requirements under any regulations, laws or court orders.

1 7 MAY 2019

IDAC KAKI BUKIT(VAC) 23 KAKI BUKIT AVE 4 Singapore 415933

Policyholder's Signature

Orlver's Signature

(if driver is not the policyholder)

Date & Time:

Reporting Centre Personnel 9 54 1997 Name: Fax: 67492305

NRIC/FIN No. Email: vackb@singnet.com.sg

totologic Stistabilitationen, Vil

Date & Time:



KETCH PLAN	a con a processor a la conficial de la Cal
Sarari6000 North A	(P) 574 18356 (P) 51X 23269-
DESCRIBE CIRCUMSTANCES OF THE ACCIDENT	a lands rate in the land of th
Refer to Police Report	No:
	57 tv-t
1 12 170	
112	
No.	1.2%
	9
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	W 10 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
10.00	
1 de 80 40 40 60	
A 10 2 10 10	
	- 14
100000000000000000000000000000000000000	
DECLARATION	

I/We declare the foregoing particulars are true in every respect.

Pollcyholder's Signature Date & Time:

Graduiti W. Schill of Sept. VX

Driver's Signatures (If driver is not the policyholder) Date & Time:

Reporting Centre Percond Pulls And E 4
Name: Singapore 415933
NRIC/FIN No.: Tel: 67416697
Fax: 67492305;
Email: vackb@singnet.com.sg

Sketch Plan #4 Pg. 1



T/20190517/2113

Police Station Of Origin: Thomson NPP 25 Sin Ming Road #01-180 SINGAPORE 570025 Tel No: 1800-4529999 2 of 4 Report No. T/20190517/2113

CONTINUATION OF REPORT

No. of Pedestrian	THE RESIDENCE OF THE PROPERTY OF THE PARTY O	U)se of Ped	estrian	Cross	Ing: NA
UMANE AND	SKANDARAJAH			ID No.		S1599588B
Related Vehicle	SDX2326Z (Car)			Conlact No.		90026850
Hespital/Clinic	NIL .	10	12	Class Orlving Licence Explry	88	Class: NIL Date of Expiry: NIL
	NIL .		Date Disci	harge	NIL	
No. of Days gran	ted Medical Leave NIL		Degree of	Injury	NIL	ennakan serakan pada
biliyeka in ta			是因為是行	de vers		
Name	NG KING KHIONG		8	ID No.	200	S1532043E
Related Vehicle	SJG7835G (Car)			Contact No.		90012947
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL			Class of Driving Licence & Explry Date		Class: 3 Date of Expiry: NIL
Date Treatment			Date Disc			5/2019
No. of Days gran	ited Medical Leave 05		Degree of	Injury	NIL	

Brief Details.

On 17th May 2019 at 1.30pm, I was driving my vehicle registration number: SJG 7835G along Serangeon North Avenue 1 towards Ang Mo Kio. It was 5 lane road and I was travelling in the centre lane.

Upon reaching the junction of Upper Serangoon North Avenue 1/3, there was a vehicle shead of me slopped due to the traffic light showed red, I applied brake and managed to stop on time. I pulled up my handbrake and was in the stationary position.

Then, there was an impact coming from my rear portion. I realised that there was another vehicle registration number: SDX2326Z (V2) had collided to my vehicle. I alighted from my vehicle and asked V2 (Driver). V2 mentioned that he admitted collision to my vehicle.

At that point of time, I was in pain and managed to take down his details. After which, I went to seek medical attention and was given 5 days MC. I was advised to lodge a report. There was a CCTV inbuilt in my vehicle.

Sketch Plan #3 Pg. 1





Police Stallon Of Origin: Thomson NPP 25 Sin Ming Road #01-180 SINGAPORE 570025 Tel No: 1800-4529999 1 of 4 Report No. T/20190517/2113

REPORT OF A TRAFFIC ACCIDENT Vide Report No.: Station Dlary No.: Date/Time Report Made: 17/05/2019 16:51 31 Informants Particulars Name of Informent: NG KING KHIONG Address: APT BLK 261A PUNGGOL WAY #12-343 SINGAPORE 821261 ID Type / ID No.: NRIC NO / \$1532043E Contact No .: Mobile: 90012947 Home/Office: Nationality: SINGAPORE CITIZEN Emall: Date of Birth: 10/05/1962 Type of Informant: Age: Sex: Driver Male 57 Institution / School Name: Language: Race: English Chinese Driving Licence information: Occupation: Date of Explry: SELF EMPLOYED Class: 3

Type of Accident.	Inners		Date/Time of : Accident: - 17/05/2019 13:30	Type of Location: X-Junction	
SERANGOO SERANGOO	oed 1 and Road 2 N AVENUE 3 N NORTH AVENUE	1 Road Surface:		Road Speed Limit:	
Weather; Clear		Dry			
Traille From		Traffic Control: Traffic Light - W	orking	Traffic Volume: Moderate	
Type of Colli	nlan:	.0%		Anyona conveyed by	

Dotalls of V	High Involve	h. is	Missia	la de la constant	Le ou altion	No of Post
SDX2326Z	Car	OPEL	ZAFIRA TOURER	Brown		0
SJG7835G	Саг	TOYOTA	VIOS E AUTO	Black		0

Details of W	hildig lead Mahree		e de visit	
Virgilia More	mala la piano mala la piano	Thursday,	TENEX TO THE	AFIOTIONS
SJG7835G	NTUC Income Insurance Co-Operative	6044718662-08	16/07/2018	15/07/2018

Sketch Plan #5 Pg. 1



Police Station Of Origin: Thomson NPP 25 Sln Ming Road #01-180 SINGAPORE 570025 Tel No: 1800-4529999

5/11/07.1



3 of 4 Report No. T/20190517/2113

CONTINUATION OF REPORT

Sketch Plan #6 Pg. 1



7/20190517/2113

Police Station Of Origin: Thomson NPP 25 Sin Ming Road #01-180 SINGAPORE 570025 Tel No: 1800-4529999 4 of 4 Report No. T/20190517/2113

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report: E / Sr Staff Sgt MOHAMAD FARID BIN JAMAL	Signature Of Informant:	
Signature Of Interpreter:	Date/Time: 17/05/2019 16:51	13
Officer In Charge Of Case:	Classification Of Case:	
Sgt 2 SHARIFAH NOR FARIZAN BINTE STEE	POLICE PONLE	610
MOHD SAID Contact No.: 65476172		V 177
Authentication Stamp	- 7/	

SK Automobile Pte Ltd
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4, #03-01
Vicom Inspection Centre (\$415933)
Tel: 6789 5155 Fax: 6783 5155

Tel: 6789 5155 Fax: 6783 5155

TO

: MSIG

DATE

: 21-May-19

ATTENTION

: MOTOR CLAIMS DEPT

JOB TYPE : T/P CLAIM

ESTIMATE REPORT

OWNER'S PARTICULAR

VEHICLE DETAILS

NAME

VEHICLE NO : SJG7835G

ADDRESS

MODEL

: TOYOTA VIOS

TOTAL LIST

TEL. NO.

CHASSIS NO :

OWNER'S INSURANCE :

POLICY NO.

DATE :

ACCIDENT DETAILS

TIME :

THIRD PARTY REQUESTOR / CONTACT : DAUD/93911482

QUOTATION SUMMARY

CLAIM DETAIL: PARTS

S/N	DESCRIPTION		UNIT LIST PRICE		PRICE		
1	BOOT LID / DD	1	s	698.00	\$	698.00	5881
2	BOOT LID OUTER MOULDING X NN	1	s	289.00	S	289.00	×
3	BOOT LID TOP LOCK / DT	1	s	298.00	\$	298.00	98/
4	BOOT LID LOWER LOCK X NN	1	\$	35.00	\$	35.00	X
5	BOOT LID WEATHER STRIP / TN	1	\$	192.00	\$	192.00	/
6	BOOT LID HINGE X	2	\$	70.00	\$	140.00	Х
7	BOOT LID LOGO / AILC	.13	\$	60.00	\$	60.00	/
8	BOOT LID EMBLEM VIOS' / // F	1	\$	54.90	\$	54.90	
9	BOOT LID EMBLEM 'SPORTS' / NEC	1	\$	55.90	\$	55.90	/
10	BOOT LID EMBLEM 'E' / ////	1	s	29.60	s	29.60	/
11	REAR BUMPER / 00	1	\$	591.00	S	591.00	4/1
12	REAR BUMPER REFLECTOR / BK	2	\$	90.00	S	180.00	
13	REAR BUMPER SIDE RETAINER (FRONT) / //	2	\$	98.00	\$	196.00	1
14	REAR BUMPER SIDE RETAINER (REAR) X NN	2	\$	55.00	s	110.00	×
15	TAIL LAMP Y \\\	2	\$	498.00	\$	996.00	X
16	TAIL LAMP PANEL X K	2	\$	276.20	\$	552.40	×
17	REAR FENDER INNER COWLING X NN	2	s	79.20	\$	158.40	X
18	REAR FENDER INNER TRIM - TN	2	s	26321:00	\$	642.00	528/
19	REAR FENDER AIR VENT X	2	s	64.30	\$	128.60	X
20	REAR END PANEL / DD	1	s	620.00	s	620.00	/
21	REAR END PANEL TOP GARNISH - BL	1	\$	230.00	s	230.00	/
22	REAR FLOOR PANEL / 1)1)	1	s	987.90	s	987.90	863

				n		
23	REAR FLOOR PANEL TOP SPONGE (SIDE)	t	s	221.10	\$	442.20
24	REAR FLOOR PANEL TOP SPONGE (INNER) X NN	1	s	298.10	S	298.10
	REAR SPARE TYRE BOLT X	1	\$	48.00	s	48.00
	REAR EXHAUST MOUNTING X	2	\$	25.00	\$	50.00
27	REAR EXHAUST INSULATOR X ////	:1:	\$	261.70	\$	261.70
28	REAR EXHAUST PIPE WITH BOX X	1	\$	780.00	\$	780.00
		TOTA	AL PF	RICE	\$	9,124.70
		LESS 25%		S	2,281.18	
		SUB	TOT	AL PRICE	\$	6,843.53

× × × × × 4347.40 × -257 3260.55

180/

s/N	DESCRIPTION	QTY	UNI	T S/NETT	тот	AL S/NETT
1	REAR NUMBER PLATE X	1	\$	50.00	\$	50.00
2	REAR BUMPER CLIPS / //LC	10	\$	6.50	\$	65.00
3	BOOT LID SEALANT / //	1	\$	80.00	\$	80.00
4	BOOT LID OUTER MOULDING CLIP X AMA	4	\$	6.50	\$	26.00
5	REAR FENDER INNER COWLING CLIPS × MM	18	s	6.50	s	117.00
6	REAR FENDER INNER TRIM CLIPS, X / ///	18	s	6.50	s	117.00
7	TAIL LAMP CLIPS X	4	s	8.00	s	32.00
8	TAIL LAMP PANEL SEALANT X MA	2	s	80.00	\$	160.00
9	REAR END PANEL TOP GARNISH CLIPS / JIF (6	\$	6.50	\$	39.00
10	REAR END PANEL INSULATION SEAL / J/L(1	\$	120.00	\$	120.00
11	REAR FLOOR PANEL INSULATION SEAL / M/L	1	\$	150.00	\$	150.00
12	REAR FLOOR PANEL TOP BOARD X	1	\$	400.00	\$	400.00
13	REVERSE SENSOR	1	\$	220.00	\$	220.00

TOTAL 1,576.00

340/

S/N	M DETAILS: LABOUR AND SPRAY PAIN JOB DESCRIPTION		PRICE	ADJUSTED COST	APPROVED
1	TO PANEL BEAT, WELD, CUT, KNOCK, GRAZE, ADJUST, REPLACE NEW PARTS	\$	1,800.00	1000	
2	TO PUTTY, SPRAY PAINT, POLISH, WAX ADJACENT PANELS	s	1,600.00	700	
3	TUFF COAT	\$	200.00	30	
4	WIRING/BULB CHECKING	s	80.00	30	
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$	180.00	50	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$	80.00	20	
7	REMOVE AND REFIX REAR EXHAUST	s	150.00	×	
8	TRANSFER BOOT LID MECHANISM	s	80.00	30	
9	TO CONDUCT WATER LEAKAGE TEST	\$	80.00	30	

TO CHECK DIAGNOSTICS OF VEHICLE			
MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO 10 SPECIFICATION ETC.	\$ 180.00	X	

TOTAL

\$ 4,430.00

1890/

ESTIMATE REPORT

TOTAL PARTS COST : \$ 8,419.53
TOTAL LABOUR COST : \$ 4,430.00
TOTAL REPAIR COST : \$ 12,849.53

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS:
RE-SURVEY :
PART BY PART OR LUMP SUM
DATE & TIME OF SURVEY
SURVEYED BY
CONTACT NUMBER
FAX NUMBER

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

7 days

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Email: sur@lkkauto.com;assignments@lkkauto.com Tel: 6256-3561 Fax: 6844-8805

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG19009041/ESD3N2

Date:

28/06/2019

REFERENCE

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

28880426

Claimant

SJG7835G Vehicle No:

Insured Vehicle No:

SDX2326Z

Date of Loss:

17/05/2019

Nature of Claim:

TP

Claim No: 593872

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SJG7835G

Make & Model:

TOYOTA VIOS EA, 1.5 (A) 16/07/2008 (Man. Year: 2008) Engine No: Chassis No: Odometer:

1NZX778254 MR053HY9305071659

276420 km

Reg. Date: Colour:

Black 1497 cc

Engine Capacity:

Market Value/New Car

N/A

Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Yes Engine Modification:

Yes Footbrake (Serviceable): No Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES Front Tyre Size:

185/60 R15

Rear Tyre Size:

Front Left Side:

185/60 R15 HIFLY 7 mm

Front Right Side:

HIFLY 7 mm

Rear Left Side: Rear Right Side:

HIFLY 7 mm

HIFLY 7 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,419.52	3,600.55	4,818.97	57.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,430.00	1,890.00	2,540.00	57.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,849.52	5,490.55	7,358.97	57.27
Approved Total (Overridden) (S\$)		4,400.00		
(S\$)	12,849.52	4,400.00	8,449.52	65.76
+ GST 7.00/7.00% (S\$)	899.47	308.00	591.47	65.76
Nett Amount (S\$)	13,748.99	4,708.00	9,040.99	65.76

INSPECTION

Date of Assignment:

22/05/2019

Date Inspected:

23/05/2019 Inspected At:

Sk Automobile Pte Ltd

8 Kaki Bukit Ave 4, #08-46 Premier @

Kaki Bukit

Singapore 415875

Estimated Period of Repair:

7.0 days

Manager: Hiew May Fung Adjuster: CHEN TSUE YEE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Referen	ce				
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jun 2019)			
Parts:	143	TOYOTA VIOS EA 1.5 (A) (Catalogue:Merimen Singapore 1.0)			
Labour:	Repairer's	(Price-denominated Standard List)			
Print Code:	(Unsubmitted,	no print-code for SJG7835G)			
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running property with the END OF ESTIMATES marker on the last estimate page					

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

No.		mended Parts Part No. Particulars	Condition	Repairer's	Amount
1	1	*BOOT LID	Dented	698.00 FL	*588.00 FL
2	1	*BOOT LID OUTER MOULDING	Not Necessary	289.00 FL	*-FL
3	1	*BOOT LID TOP LOCK	Bent	298.00 FL	*98.00 FL
4	1	*BOOT LID WEATHER STRIP	Torn	192.00 FL	*192.00 FL
5	2	*BOOT LID HINGE	Not Necessary	140.00 FL	*-FL
6	1	*BOOT LID LOGO	Necessary	60.00 FL	*60.00 FL
7	1	*BOOT LID EMBLEM VIOS	Necessary	54.90 FL	*54.90 FL
8	1	*BOOT LID EMBLEM SPORTS	Necessary	55.90 FL	*55.90 FL
9	1	*BOOT LID EMBLEM E	Necessary	29.60 FL	*29.60 FL
10	1	*REAR BUMPER	Dented	591.00 FL	*472.00 FL
11	2	*REAR BUMPER REFLECTOR	Broken	180.00 FL	*180.00 FL
12	2	*REAR BUMPER SIDE RETAINER (FRONT)	Broken	196.00 FL	*196.00 FL
13	2	*REAR BUMPER SIDE RETAINER (REAR)	Not Necessary	110.00 FL	*-FL
14	2	*TAIL LAMP	Not Necessary	996.00 FL	*-FL
15	2	*TAIL LAMP PANEL	Repair	552.40 FL	*-FL
16	2	*REAR FENDER INNER COWLING	Not Necessary	158.40 FL	*-FL
17	2	*REAR FENDER INNER TRIM	Torn	642.00 FL	*528.00 FL
18	2	*REAR FENDER AIR VENT	Not Necessary	128.60 FL	*- FL
19	1	*REAR END PANEL	Dented	620.00 FL	*620.00 FL
20	1	*REAR END PANEL TOP GARNISH	Broken	230.00 FL	*230.00 FL
21	1	*REAR FLOOR PANEL	Dented	987.90 FL	*863.00 FL
22	1	*REAR FLOOR PANEL TOP SPONGE (SIDE)	Broken	442.20 FL	*180.00 FL
23	1	*REAR FLOOR PANEL TOP SPONGE (INNER)	Not Necessary	298.10 FL	*-FL
24	1	*REAR SPARE TYRE BOLT	Not Necessary	48.00 FL	*-FL
25	2	*REAR EXHAUST MOUNTING	Not Necessary	50.00 FL	*-FL
26	1	*REAR EXHAUST INSULATOR	Not Necessary	261.70 FL	*-FL
27	1	*REAR EXHAUST PIPE WITH BOX	Not Necessary	780.00 FL	*-FL
28	1	*BOOT LID TOP LOCK	Not Necessary	35.00 FL	*-FL
29	1	*REAR NUMBER PLATE	Not Necessary	50.00 FS	*-FS
30	10	*REAR NUMBER CLIPS	Necessary	65.00 FS	*30.00 FS
31	1	*BOOT LID SEALANT	Necessary	80.00 FS	*20.00 FS
32	4	*BOOT LID OUTER MOULDING CLIP	Not Necessary	26.00 FS	*-FS
33	18	*REAR FENDER INNER COWLING CLIPS	Not Necessary	117.00 FS	*-FS
34	1	*REAR FENDER INNER TRIM CLIPS (18pcs)	Necessary	117.00 FS	LEADER CORRESPOND
35	4	*TAIL LAMP CLIPS	Not Necessary	32.00 FS	
36	2	*TAIL LAMP PANEL SEALANT	Not Necessary	160.00 FS	
37	1	*REAR END PANEL TOP GARNISH CLIPS (6pcs)	Necessary	39.00 FS	
38	1	*REAR END PANEL INSULATION SEAL	Necessary	120.00 FS	*20.00 FS
39	1	*REAR FLOOR PANEL INSULATION SEAL	Necessary	150.00 FS	
40	1	*REAR FLOOR PANEL TOP BOARD	Not Necessary	400.00 FS	*-FS
41	4	*REVERSE SENSOR	Broken	220.00 FS	*200.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
			Sub Total (S\$)	10,700.70	4,687.40
			- List Item Discount on L Items 25.00/25.00% (S\$)		1,086.85
			Total Parts (S\$)	8,419.52	3,600.55
			Report was unsubmitted during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			60 Hallacourts
1	TO PANEL BEAT, WELD, CUT, KNOCK, GRAZE, ADJUST, REPLACE NEW PARTS.	New	1,800.00	1,000.00
2	TO PUTTY, SPRAY PAINT, POLISH, WAX ADJACENT PANELS.	New	1,600.00	700.00
3	TUFF COAT.	New	200.00	30.00
4	WIRING / BULB CHECKING.	New	80.00	30.00
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR.	New	180.00	50.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.	New	80.00	20.00
7	REMOVE AND REFIX REAR EXHAUST.	New	150.00	0.00
8	TRANSFER BOOT LID MECHANISM.	New	80.00	30.00
9	TO CONDUCT WATER LEAKAGE TEST.	New	80.00	30.00
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/ CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	New	180.00	0.00
	Gross Labour	Cost (S\$)	4,430.00	1,890.00
	Report was unsubmitted durin	g this print-out.	(

< END OF ESTIMATES >