

Surveyor:

Kenneth

DOI:

ASSIGNMENT

20/7/19

Date / Time:

24/5/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHD 5935D

Name of Insured:

TIC SVS P/L

Insured Tel No.:

Excess Sec II :S5

\$5,000.00

HP:

D.O.A:

21/5/19

Claim No.:

sqmn 034

Policy No.:

Make / Model:

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

LHmk



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

SHF 9992m, X;
 SHD 5935D - C111-016001576/Kg6n2: 001-21/1/19
 - C03/PC/115013380/Kg6n2, 11/1/19
 21/8/19 - Email LOI.
 - Rec COR to TP (Pending LOD)
 12/9/19 - TO seek mandate.
 16/9 - Pending mandate approval (Approved)
 17/10 - Settle @ \$2935.49. File past Su to send
 W.

PENDING SURVEY.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

</

2040 (kg).

Kenneth

N/S	O/S

Front
R/Bal. S mm
L/Bal. S mm
D.O.A. 21/5/19

Rear
R/Bal. 6 mm
L/Bal. 6 mm
D.O.I. 30/7/19

Survey held at _____

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
O/S Rear body

The U/C / Chassis frame / Body Structure affected due to collision.

P/P \$2400 - (Red = \$300 / 11%)

* 5 repair days + 1 Sunday + 1 hrs = 7 days

Date/Time, File Pass to? ☐ : Prel. Report
 1) ☐ : Final Report

Days Of Repair: _____
Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$
☐ : Interview (\$
☐ : Tech Invs (\$
☐ : Weekend (\$

Survey Fee: _____
 Transportation: _____
 _____ \$ - RS _____ \$
 Fuel _____ \$
 Others _____ \$

Report Format :
Lump Sum / I.B.I: (\$

DIGITAL

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST No: EST0022297
Yeo Chuan Kiong

Page 1 of 1
Your ref: TP-SHD/593/D AXA
Job No: 70520
Our ref: 10 05 37
Payment Date: 22/5/2019

Att: Not Authorised
Vehicle No: SCF 5902M
Vehicle Model: Mazda 3
Accident at: 21/5/2019

Resurvey on 01/09/2019
1420 5 days
82400 ✓

Quantity	Unit	Description	Unit price	Disc. pct	Amount
		Supply of Parts			
1.00	Pc	Rear door RH	1,050.00	20.00	840.00 ✓
		Labour & Misc			840
1.00		To check wheel alignment (computers)	80.00		80.00 60
1.00		To knock dents on rear fender LH, to repair rear bumper, rear bumper spoiler RH and renew of parts	600.00		600.00 ✓
1.00		To spray paint on rear sport rim RH	185.00	na	185.00 X
1.00		To spray paint (Pearl) to blend front door RH	1,000.00		1,000.00

9000

1560

Sub Total
GST 7.00%

1,000.00
107.00

Total


S\$

1,007.00

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

Cecilia



WTS Engineering Pte Ltd

8 Gul Circle, Singapore 629564 Tel: 65598984 Fax: 68622163

Company Registration Number: 200505706E

Quotation

DATE: 04/07/19
VEHICLE NO: PC6031R
DRIVER: PEH SAN LENG
ATTENTION TO:
PREPARED BY: Chan Soo Lye

LOCATION: Gul Workshop
Q REF No: Q19/07/1039
DEPARTMENT: WTS Bus Department
ACCIDENT DATE: 01/07/19
REF No: JW-0719-404

S/N	Description	Qty	Cost per Unit	Amount S\$
Labour Costs				
1	TO PANEL BEAT RHS REAR PANEL	1	400	400.00 300
2	TO REMOVE AND REPLACE RHS REAR PANEL STICKER	1	1200	1,200.00 950
Spray Paint				
1	Spray Painting	1	600	600.00 450
	TO PUTTY AND SPRAY PAINTING RHS REAR PANEL			
TOTAL:				2,200.00
Total Amount				SGD 2,200.00

Remarks:

Signature of Workshop Dpt

Signature of Department Head

Signature of Claim Department

LKK Auto Consultants hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work(s) must be resurveyed and is subject to final approval from Insurance Company

Accepted by Reparer
Signature: _____
Date: _____

Surveyor Sign: [Signature]
Surveyor Name: Rahul
Date: 09/07/19 @ 14:00hrs

3 days

P/P

Reply after repair

LKK

67418434

Summer

90010068

來發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267

GST No: M2-0128609-3

UEN: 199407592C

ESTIMATE

EST No EST0022297
Yeo Choon Kiong

Page 1 of 1
Your ref TP-SHD 5935D AXA
Job No 70520
Our ref 19 05.37
Payment
Date 22/5/2019

Attn

Vehicle No SGF 9992M
Vehicle Model Mazda 3
Accident on 21/5/2019

*Not withonw
Return By 5 days*

Quantity	Unit	Description	Unit price	Disc. pct	Amount
Supply of Parts:					
1.00	Pc	Rear door RH	1,050.00	20.00	840.00 ✓
Labour & Misc:					
1.00		To check wheel alignment (computerised)	80.00		80.00 ✓
1.00		To knock dents on rear fender LH, to repair rear bumper, rear bumper spoiler RH and renew of parts	600.00		600.00 ✓
1.00		To spray paint on rear sport rim RH	180.00		180.00 X
1.00		To spray paint (Pearl / to blend front door RH)	1,000.00		1,000.00

Sub-Total
GST 7.00%
Total

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

2,700.00
189.00
SS 2,889.00

Acknowledged by Repairer:

Signature:

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大快修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

MAZDA AUTO PROTECTOR PRIVATE VEHICLE

The following risk described on this Cover Note is hereby HELD COVERED on the terms and conditions of the policy issued to the Policyholder

Name of Policyholder : Yeo Choon Klong
Period of Insurance : 29 Jun 2018 to 28 Jun 2020
Engine No. : P520500020
Chasis No. : JM6BN22A8J0209851

Vehicle No. : SGF9992M
Cover Note No. : 1800077108
Endorsement No. :
Issued Date : 28 Jun 2016

ABOUT THE COVER

Make/Model : MAZDA 3 1.5 SKYACTIV

Engine Capacity/Tonnage : 1,496.00 CC

Sum Insured : Market Value

First Year of Registration : 2018

Driver Restriction : NA

Off Peak Car : No

Insuring with COE/PARF ☐ Yes

Person or Classes of Persons Entitled to Drive*

at The Publisher

b) Any other person who is driving on the Policyholder's order or with his/her permission.

This Policy will implement the Policyholder's duty only if he/she meets the specified age condition.

You have to pay an additional sum of \$1,000 as "Young and Impulsive" Dinner Access (YIDA) if you are in your University Dinner (named or unnamed) is under the age of 21 and/or has less than 2 years' dining experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for legal, domestic and pleasure purposes and for the Purcell's business

This Policy does not cover use for fire or sound, driving tuition, driving test, racing, pack-racing, reliability trial or speed-testing, the carriage of goods other than animals in accordance with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc Optional

⁴ Lookouts rendered *ineffective* by Section 4 of the Motor Vehicles (Third-Party Risks and Compensation) Act 1991 and Section 86 of the Road Transport Act, 1997 (S.86(1)(c)), are not to be included under these headings.

EXCESS

Section 1

Fig - \$0 Own Damage - \$600 Theft - \$5 Flood Cover - \$0

Section 2

Property Earnout = 30

Widecten: 110

Named Driver and Excess (where applicable)

Two Classes Going - \$600 (Over \$4000)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Zhang Euphonia Pte Ltd. Add: 8 Ubi Close. Singapore 408096 93060006

For other Approved Repairing Centres/AIO Authorised Repairs, please contact our 24-hour accident emergency helpline at +65 8108 8268. Alternatively, you may refer to AIO website www.aio.com.sg or AIO 80 Mobile App. Simply search and download "AIO 80" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: HONG LEONG FINANCE LTD

If you do not receive your Certificate of Insurance and policy documents within 30 days from the inception date stated on this cover note, please contact AIG immediately.
We hereby certify that this Cover Note is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks) Rules, 1939 (Malaysia). For Corporate Policies, this Cover Note is valid for 60 days from the commencement date of the period of insurance.

05534501-90

ARF (AF) PTE LTD - MAJDA

7 MAXWELL ROAD #01-100 ANNEX S MNO COMPLEX

SINGAPORE 059111

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORIZED REPRESENTATIVE

Best Value Choice

◀ Service Request Details

Claim

S9M01O34

Reference

None 

Loss Date

21 May 2019

Report Date

22 May 2019 10:29:00 AM

Request Date

22 May 2019

Due Date

29 May 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

P: Jenny

T: 1144a-m

V: Out

E: ✓

Actions

Next Step

Agree to perform service

Vehicle Information

Incident Vehicle Registration #

SGF9992M

INVOICE

3 1.5 SKYACTIV

Service Address

...

Primary Contact/Insured

TRANS-CAB SERVICES PTE LTD

No.2 ANG MO KIO STREET 63, 569111, Singapore

Claim Handler

NG Stacey

6568804351

stacey.ng@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Catherine Chong (LKK Auto)

From: Jenny Lim <jenny.lim@laihuat.com.sg>
Sent: Wednesday, 22 May, 2019 9:47 AM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: Third Party Claim - Your Ref: SHD5935D / Our Ref: SGF 9992M (Date of Accident: 21.05.2019)
Attachments: 22052019093513.pdf
Categories: Raghav

Dear Sir

We refer to the above matter.

Please can you arrange LKK Auto Consultant to survey our client's vehicle no. SGF 9992M?

Supporting documents are enclosed for your reference.

Thank you.

Kind regards.

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596267



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 16/9/2019

Survey Details:

Date of loss	21-May-19
Date of appointment	22-May-19
Date of survey	30-Jul-19
Location of survey	LAI HUAT (MENG KEE) MOTOR PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SGF9992M
Make and Model	MAZDA3 SEDAN 1.5 AT LED EU6 - 1496cc
Date of registration	19-Jun-18
Parf Rebate	
Market Value	\$ 75,000.00
Parf Rebate	\$ 40,546.00
Nett Loss	\$ 34,454.00

Repair details:

Initial Estimate	2,700.00
------------------	----------

Proposed/Revised repair cost:

Parts	\$ 840.00
Check items (estimate)	\$ -
Labour	\$ 1,560.00
Total	\$ 2,400.00
Lump Sum(if applicable)	

Number of days for repair	5.0
---------------------------	-----



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (665) 62563561 FAX : (665) 62564315

Remarks:

5 RECOMMENDED REPAIR DAYS + 15 SUNDAY + 1 PRS = 7 DAYS

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 2,568.00	W/GST
Loss of use	\$ 420.00	7days x \$60
Loss of rental	\$ -	
Loss of income	\$ -	
LTA search fees	\$ 7.49	
Others	\$ -	
Proposed Total	\$ 2,995.49	



<MANDATE IA> -S9M01034 {ACCIDENT INVOLVING SHD 5935D(OI) & SGF 9992M(TP) ON 21/05/2019}

Type

🔗 Question

Message

LIABILITY: 100% OI MINOR TO MAJOR ROAD - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$2,995.49(CLAIMING LOU). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL / INSTRUCTION. THANKS - CECILIA

Reply

來發 (明 記) 摩 哆 有 限 公 司

LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

TAX INVOICE

EST No. EST0022297

Yeo Choon Kiong

GST Reg No M2-0128609-3

Page 1 of 1

Number INV0023123

Your ref. TP-SHD 5935D AXA

Job No. 70520

Our ref. 19.05.37

Payment

Date 4/9/2019

Attn

Vehicle No SGF 9992M

Vehicle Model Mazda 3

Accident on 21/5/2019

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Rear door RH	1,050.00	20.00	840.00
Labour & Misc:					
1.00		To check wheel alignment (computerised)	60.00		60.00
1.00		To knock dents on rear fender LH, to repair rear bumper, rear bumper spoiler RH and renew of part	600.00		600.00
1.00		To spray paint (Pearl paint / to blend front door RH)	900.00		900.00

Sub-Total 2,400.00
GST 7.00% 168.00
Total S\$ 2,568.00

本公司備有最先進的 CAROLINER MARK IV 機械，可提供給多種款式之車身及給予快速與準確的測量方式和大快修理。除外，還有先進的 SAICO Deluxe 噴漆烘爐。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

« **Re:<MANDATE IA> -S9M01034 {ACCIDENT INVOLVING
SHD 5935D(OI) & SGF 9992M(TP) ON 21/05/2019}**

Type

🔗 Question

Message

Please proceed

Reply

CC4/Asm19009043/Kga3

Cecilia

來發(明記)摩多有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity
160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722
Tel: 64538110 Fax: 64596267
UEN: 199407592C

Your Ref: SHD 5935D
Our Ref: SGF 9992M - 2019/JL

4 September 2019

AXA Insurance (Singapore) Pte Ltd
8 Shenton Way
#27-01
AXA Tower
Singapore 068811
Attention: Motor Claims

WITHOUT PREJUDICE

Dear Sir

ACCIDENT INVOLVING VEHICLE NOS. SGF 9992M AND SHD 5935D ON 21/05/2019 ALONG UPP CROSS STREET (OPP BLK 34)

We refer to the above matter wherein your insured's vehicle no. SHD 5935D was involved in an accident with our client's vehicle no. SGF 9992M.

As the accident was caused by your insured's negligence, our client is now claiming for the following losses:

- Repair cost: \$2,568.00 (include of GST)
- Loss of use: \$ 700.00 (7 days x \$100 per day)
- LTA search fee: \$ 7.49
- Total: \$3,275.49


Relevant documents in support of our client's claim are enclosed for your reference.

Please do not hesitate to contact Jenny Lim at telephone 64533757 or email jenny.lim@laihuat.com.sg should you need any additional information.

Meanwhile, we look forward to receiving your affirmative response soon enough.

Thank you.

Yours faithfully



LAI HUAT (MENG KEE) MOTOR PTE LTD

encs

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19009043/Kga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:STACEY NG

Date : 11-11-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 5935D	Veh. Inspected	SGF 9992M
Policy No.	VPX/P1680520	Coverage (\$)	0.00
Claim No.	S9M01O34	Excess (\$)	0.00
Assign From		Assign Date	22/05/2019

2. Vehicle Particulars & Condition

Make & Model	MAZDA 3 (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JM6BN22A8J0209851	Colour	WHITE
Odometer	74403	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	FALKEN	8 mm
L/H Front Tyre	205/60 R16	FALKEN	8 mm
R/H Rear Tyre	205/60 R16	FALKEN	6 mm
L/H Rear Tyre	205/60 R16	FALKEN	6 mm

4. Description of DamagesTHE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR BODY.
DAMAGES SEE DETAILS.**5. General Information**

Accident Date	21/05/2019	Inspection Date	30/07/2019
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722		

5a. RemarksA)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGF 9992M ✓

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REPLACEMENT OF PARTS	BENT		
	REAR DOOR RH (CONSISTENT)		1,050.00	1,050.00
	LESS 20% DISCOUNT		-210.00	-210.00
			840.00	840.00
	LABOUR	NOT NECESSARY		
	TO CHECK WHEEL ALIGNMENT (COMPUTERISED).		80.00	60.00
	TO KNOCK DENTS ON REAR FENDER LH ,TO REPAIR REAR BUMPER ,REAR BUMPER SPOILER RH AND RENEW OF PARTS.		600.00	600.00
	TO SPRAY PAINT ON REAR SPORT RIM RH .		180.00	-
	TO SPRAY PAINT (PEARL/TO BLEND FRONT DOOR RH).		1,000.00	900.00
			1,860.00	1,560.00
GRAND TOTAL			2,700.00	2,400.00
RECOMMENDED COST OF REPAIRS				2,400.00

Report Ref No. CC4/ASM19009043/Kga3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	59M01034
Reference	CC4/ASM19009043/Kga3a2
Loss Date	21 May 2019
Report Date	22 May 2019 10:29:00 AM
Request Date	22 May 2019
Due Date	

Vendor Name	LK& AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step Wait for: Approve Invoice

Approve Invoice

Vehicle Information

Incident Vehicle Registration #	SGF9992M
Make	TRWD MAZDA
Model	3.5 SKYACTIV
Service Address	

...

Primary Contact/Insured	TRANS-CAB SERVICES PTE LTD No.2 ANG MO KIO STREET 63, 569111, Singapore
-------------------------	--

Claim Handler

NG Stacey
6568804351
stacey.ng@aaa.com.sg

Additional Instructions

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
----------	----------	---------	-----------	------------	---------	-------

Document Type Document Subtype

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LK&Invoice1 (6).pdf	Invoice	Surveyor/ Assessor expense	LK& AUTO CONSULTANTS PTE LTD (TP)	20 November 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LTA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 November 2019
LKK Inspection (3).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 November 2019
LKK Adjustment 1a (4).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 November 2019
PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	20 November 2019
AUTHORIZATION TO ACT FORM.pdf	Forms / Claim Documents	PCA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	20 November 2019
LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	20 November 2019
MANDATE IA DO 16092019.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 September 2019
LOD AND OTHER DOCUMENTS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 September 2019
TP EST LIST MARKED.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 September 2019
LKK RESURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 September 2019
PARF COE REBATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 September 2019
LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 September 2019
LKK SURVEY PHOTO.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	31 July 2019
TP - IA.pdf	Forms / Claim Documents	Assessment	LKK AUTO CONSULTANTS PTE LTD (TP)	31 July 2019

NAME	TYPE	SUB TYPE	AUTHOR	DATE UPLOADED
 SCF 9992M - tp video.mp4	Evidence	Videos	LIX AUTO CONSULTANTS PTE LTD (TP)	26 May 2019
 SHDS935D INSD GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	22 May 2019
 SCF9992M TP GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	22 May 2019
 TP PBI FROM WORKSHOP.png	Letters and Correspondence	Workshop	DHAKAL Raghav	22 May 2019