

# 来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267  
GST No: M2-0128609-3  
UEN: 199407592C

## ESTIMATE

EST. No ..... EST0022297  
Yeo Choon Kiong

Page ..... 1 of 1  
Your ref. .... TP-SHD 5935D AXA  
Job No. .... 70520  
Our ref. .... 19.05.37  
Payment .....  
Date ..... 22/5/2019

Attn .....

Vehicle No .... SGF 9992M  
Vehicle Model .... Mazda 3  
Accident on .... 21/5/2019

*Not Withheld*  
*Recovery B4P6IM*  
*5 days*

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Rear door RH	1,050.00	20.00	840.00 <i>2</i>
Labour & Misc:					
1.00		To check wheel alignment (computerised)	80.00		80.00 <i>60</i>
1.00		To knock dents on rear fender LH, to repair rear bumper, rear bumper spoiler RH and renew of parts	600.00		600.00 <i>✓</i>
1.00		To spray paint on rear sport rim RH	180.00		180.00 <i>✓</i>
1.00		To spray paint (Pearl / to blend front door RH)	1,000.00		1,000.00 <i>900h</i>

Sub-Total  
GST 7.00%  
Total

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

2,700.00  
189.00  
S\$ 2,889.00

Acknowledged by Repairer  
Signature:

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."