Bayenia Kalyin

CC3/ TMI19009049 / KItd3n2

	ASSIGNMENT CUO 3: V 29
From Date	Veh No. SHO 3950 Y Yr Regn. 27 24
EstimatedCost	Type: M.Car / M.Cycle / Bus / Van / Lorry / Tapi / Prime Mover /
OD ITP INS ITP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To inspect Vehicle No:	Make: Hander Gate 0.0 1991
at Workshop m/s	Colour Bhe A/C: Insu@d / Std / NI / NA
of	Sp.Reading 468/32 T/Radio: Insufed / Std / NI / NA
Insured: SGW 1497P	Eng/No:
Policy No. MT104336	CINO: ICMHETRIPBASA 920
Claims No. M1903662	Gen. Cond: Good / Por / Poor / Burnt
Sum Insured: Excess:	Steering: Inorday / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / St A/Rim or
	Tyre Size: F: 2 15/60 116
(Policy Condition)	R:
Remark: The veh had commenced its N/S	S O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHT SU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or Werl-ke
Bal. or Market Value:	· . Fron! Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 7 mm R/Bal. 9 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal 7 mm L/Bal. 7 mm
Est Repairs: V days Res.: Yes or No	D.O.A. 18/5/19 D.O.L. 22/5/19
Lum Sum: % 3 Val.: Yes or No	/:)/-//
	Des. of Damages : Frt. / Rear / Q/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS	e: IN/OUT
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
8HD 3450Y-05/FC[170]	7521 (14m2 BUT-1141/7 TOKS
Sawlan 7p-x	41.
	2 Bs. (led \$1831.72, 82%)
no lump men -	IVED 2 7 MAY 2019
REGE	(24/5 Zais
	(127)
-	4
	N + _
DateTime, File Pass to? : Prell. Report	Days Of Repair:
1) 29/5 MMH : Final Report	Resurvey No. of Trip: Survey Fee: 7ransportation: 250
Date/Time, File Return to?	
2)	Add Fee:
1.50 10	: Interview (\$) Photos
Report Format: MEP TP	: Tech. Invs (\$) Others
Lump Sum / I.B.I: (\$ 410	: Weekend (\$
	707AI 260

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Fax Number Contact Number EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

aforesaid	Normal processing the Contraction of the Market States of the Contract of the
A STATE OF THE PARTY OF THE PAR	ACCIDENT STATEMENT
Date Of Report	21/05/2019 15:01
Date Of Accident	18/05/2019 19:15
Exact Location Of Accident	PIE(TUAS) NEAR TOH GUAN
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SHD3950Y
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	SONATA
Exact Purpose for which vehicle was being use time of accident	ed at
Are you claiming under your own insurance pol for repair to your vehicle?	licy NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	
Driver	
Name of Driver	LEE LIN WANG
NRIC No	S1129732C
Date Of Birth	01/01/1955
Occupation	OUTDOOR
Date Of Driving Pass	12/04/1976
Driving Experience	43 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98937621

LEE_PEKNOI@YAHOO.COM.SG

Address

BLK 436 ANG MO KIO AVENUE 10 #02-1363

Postcode

560436

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

OTHER - TAXI DRIVER

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

3

involved in the accident

NO

Was any body injured in the Accident?

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

NO

soliciting/offering accident claims assistance.

2

Number of Passengers (Including Driver) Passenger 1

NAME:

GENDER:

: MALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLS REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SGW1497P

Vehicle Make/Model/Colour

Details Of Properties

PRIVATE CAR

Vehicle Category Name of Driver

LOH YU SHENG

NRIC/Passport Number

S9019628F

Contact Number

Address

Postcode Insurance Company Name

TOKIO MARINE INSURANCE SINGAPORE LTD

Nature Of Damage

REAR AND FRT

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SLZ8735D

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

KHOO WENJUN LESLIE

NRIC/Passport Number

S8119793H

Contact Number

Address Postcode

Insurance Company Name

Nature Of Damage

FRT

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

MPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material
 facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of
 the report being made available aforesald.
- S. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims:
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling und/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD CO. REG. NO. 199303821R

Policyholder's Signature Outs & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Sign

Names NRIC/FIN No.:

SANKAC SHISSPERICUM, VO

1

CI

PIE (Tuas) Near Tok Grun	A)SHD3950 B)QGW1497P C)SLZ8ZSFE
DESCRIBE CIRCUMSTANCES OF THE ACCIDENT ON 18/4/19 at about 1915 his a Showed down because wellich Showed abown. Weh & collice The rear of my which it	les infront ded onto when I can
uch a was also involved in	
ECLARATION We declare the foregoing particulars are true in every respect. FORT TRANSPORTATION PTE LTD CO. REG. NO. 199303821R	No Pagementy 18

NRIC/FIN No.:

Date & Time:

COMFORTDELGRO ENGINEERING PTE LTD TOKIO MAYINE CLES
VEHICLE NO: SHD 3950Y
MAKE:
MODEL: HYUNDALSONATA

Tyre Vehicle
LKY - Kalvin.

MODEL.

: HYUNDAI SONATA

Tyre Vedlake 215/60 RIG

Labour Charge Panel Beating Spray Painting Charge Wiring Charge Remove/Refix Reverse Sensor TOTAL LABOUR LESS 20% S S TOTAL LABOUR S TOTAL LABOUR	mount
Rear Bumper Reinforcement x x x x x x x x x x x x x x x x x x x	578.40
Rear Bumper Bracket (LH/RH)	483.30
Rear Bumper Sponge Rear Bumper Under Cover X M Rear Panel X M Rear Panel Garnish X SUB TOTAL LESS 20% DISCOUNTED TOTAL Rear Bumper Reverse Sensor Labour Charge Panel Beating Spray Painting Charge Wiring Charge Remove/Refix Reverse Sensor S S S S S S S S S S S S S	22.00
Rear Bumper Under Cover X X Rear Panel X X X SUB TOTAL LESS 20% DISCOUNTED TOTAL Rear Bumper Reverse Sensor X X SUB TOTAL LESS 20% DISCOUNTED TOTAL Labour Charge Panel Beating Spray Painting Charge Wiring Charge Wiring Charge Remove/Refix Reverse Sensor S S	98.00
Rear Panel X Mark Solution Substitution Subs	137.40
Rear Panel X Mark Solution Substitution Subs	185.80
SUB TOTAL LESS 20% DISCOUNTED TOTAL Rear Bumper Reverse Sensor Labour Charge Panel Beating Spray Painting Charge Wiring Charge Remove/Refix Reverse Sensor	391.80
LESS 20% DISCOUNTED TOTAL Rear Bumper Reverse Sensor S Labour Charge Panel Beating Spray Painting Charge Wiring Charge Remove/Refix Reverse Sensor S S S S S S S S S S S S S	95.80
Rear Bumper Reverse Sensor Labour Charge Panel Beating Spray Painting Charge Wiring Charge Wiring Charge Remoye/Refix Reverse Sensor	1,992.50
Rear Bumper Reverse Sensor Labour Charge Panel Beating Spray Painting Charge Wiring Charge Wiring Charge Remove/Refix Reverse Sensor	398.50
Labour Charge Panel Beating Spray Painting Charge Wiring Charge Remove/Refix Reverse Sensor	1,594.00
Panel Beating \$ Spray Painting Charge \$ Wiring Charge \$ Remove/Refix Reverse Sensor	135.70
Remove/Refix Reverse Sensor / Marine Fee TOTAL LABOUR Ka La ICCety ESTIMATE TOTAL S 2	490.00 490.00 50.00
Marine Fee TOTAL LABOUR Kake ICCHY ESTIMATE TOTAL S S	120.00
Ka Li icley ESTIMATE TOTAL S	10
Kaluicien ESTIMATE TOTAL S	970.00
Ca LL ICCES ESTIMATE TOTAL S	
	2,699.70
1 22/5/19 1030h	
Atta Ruplh	

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive Singapore 508969 Tel: 6214 8300

TP INSURER:

Present Location:

Tokio Marine Insurance Singapore Ltd (HQ)

CTPL

Singapore

PARTICULARS OF CL	AIM		
Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	18/05/2019
Vehicle Reg. No.:	SHD3950Y	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI SONATA, 2.0 D CRDI TURBO (NF) (A)	Vehicle Reg. Date:	29/06/2011
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	D4EAB967981	Chassis No:	KMHET41VMBA811920
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	2		

COST OF CLAIMS		Amount
Parts		1,261.22
Miscellaneous Items		10.00
Labour		970.00
Paintwork Labour		0.00
Towing		0.00
and another a	Gross Total (S\$)	2,241.22
	+ GST 7.00% (S\$)	156.89
	Nett Amount (S\$)	2,398.11

COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

This claim is handled by: LIM TIEN SIONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 23 May 2019)

Parts:

HYUNDAI SONATA 2.0 D CRDi Turbo (NF) (A) (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHD3950Y/23/05/2019 07:16

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty Part No.	Particulars	%Disc	%Depr	Amount
1	1	*REAR BUMPER	20.00	0.00	*578.40 FLXR
2	1	*REAR BUMPER UNDER COVER	20.00	0.00	*185.80 FL/57/4
3	1	*REAR BUMPER REINFORCEMENT	20.00	0.00	*483,30 FL/9VC
4	1	*REAR BUMPER SPONGE	20.00	0.00	*137.40 FL (51/-
5	10	*REAR BUMPER CLIPS	20.00	0.00	*22.00 FL (11)
6	1	*REVERSE SENSOR	0.00	0.00	*135.70 FX
F=Ft/	anchise part. L=ListItem	Disc.			
		Sub Total (S\$)			1,542.60
		- List Item Discount on L Items (S\$)			281.38
		Total Parts (S\$)			1,261.22

ComfortDelGro Engineering Pte Ltd/SHD3950Y/23/05/2019 07:16. Not valid without Reference section. Generated using Merimen e-Claims IEAS

Estimates on	Miscellaneous	Items
--------------	---------------	-------

No Qty Particulars		Amount
Miscellaneous Items 1 1 OD/TP Case (Insurer)		10.00 /
	Sub Total (S\$)	10.00

Estimat	no on	abour
Lauma	les uii	Labour

No Particulars				Amount	
Lab	oour Items				
1	PANEL BEATING	New	700	400.00	
2	SPRAY PAINTING	New	200	400.00	
3	WIRING CHECK	New		50.00×11×	
4		New		120.00 mv	
		Gross Labour Cost (S\$)		970.00	

ComfortDelGro Engineering Pte Ltd/SHD3950Y/23/05/2019 07:16. Not valid without Reference section. Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

OMFORTDELGRO ENGINEERING

COMFORTDELGRO

Date/Time: 21.05.2019 16:04

REGN NO. SHD3950Y

HYUNDAI

Page : 1

Team:

ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JONO: 305296886

MILEAGE

HUEL

MER

(p)

P

COMFORT TRANSPORTATION PTE LTD

7010045

383 SIN MING DRIVE

Singapore SINGAPORE 575717

65508755

MODEL SONATA 21.05.2019 10:45

YR OF MANU 29.06.2011

TARGET DATE

CHASSIS C KMHET41VMBA811920

MAKE

COMPLETION DATE:TIME

JOB DESCRIPTION


Accident Date: 18.05.2019

NA RE: 3P 18.05.19

S/NO

LABOR CODE

DESCRIPTION



KED & PASSED OUT BY

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

sogement Stip

SHD3950Y

LIMTS

Vehicle No.:

Exit Plass

SHD3950Y

Service Advisor

Signature/Date

Name of Service Advisor

Date

COMFORTDELGRO ENGINEERING PTE LTD

Date: 23.05.2019 Time: 09:16:10

REPAIR ESTIMATE

Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO REGN NO MILEAGE MAKE MODEL

305296886 : SHD3950Y 0000000000 HYUNDAI SONATA DATE OF REGN : 29.06.2011

DATE/TIME IN ACCIDENT DATE : 18.05.2019

21.05.2019 10:45

JOB / PARTS DESCRIPTION

OTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

SUB-TOTAL: 0.00

JOB NATURE

0000 PB

PANEL BEATING

200.00

0001 SP

SPRAYPAINT CHARGE

200.00

10.00

0002 20-05

DATE:

TP MERIMEN

AUTHORISED: YES / NO

SUB-TOTAL: 410.00

MVA NAME & SIGNATURE

TOTAL : 410.00

SURVEYOR NAME & SIGNATURE

DATE:

COMFORTDELGRO

ENGINEERING 305296886 Our Job Ref No : ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969 Fax: 6546 8156 23/05/19 Date FINALIZATION FORM LKK Fax: KALVIN ANG Attn : Vehicle Reg No. : SHD3950Y Date of Accident : 18-May-19 The survey and estimates of the repairs of the above-mentioned vehicle are as follows:- The repair job shall bill to: TOKIO MARINE --- SGW1497P The finalized amount shall be: Spare Parts after List discount NIL (a) (b) Labour Charges \$410.00 \$410.00 Total for Part-By-Part Repair Cost (c.) Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less: 20% Final Lumpsum Repair cost 3. Estimated normal period for repairs: 2 working days. 4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days We confirm the estimates and 5. Thank you for your assistance. finalized amount Signature : Signature KALVIN : LIMTS Name Name 62148398 Tel Date 65468156 Fax For Official Use Only

	Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1.	Rental Rate P/Day		YES		
2	Loss of Income Paid		NO		
3.	Survey Fees				
4.	LTA Search Fee	\$7.49			
5.	Medical Fees (on behalf of driver, if applicable)				
6	Overrun				

Remarks					
					-

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/TMI19009049/K1TD3N2

Date:

29/05/2019

REFERENCE

Handling Insurer:

Tokio Marine Insurance Singapore Ltd

Policy No:

MT104336

Claimant Vehicle No :

SHD3950Y

Insured Vehicle No:

SGW1497P

Date of Loss:

18/05/2019

Nature of Claim:

TP

Claim No: M1903662

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SHD3950Y

Make & Model:

HYUNDAI SONATA, 2.0 D CRDi Turbo (NF) (A)

Engine No:

D4EAB967981

Reg. Date:

29/06/2011 (Man. Year: 2011)

Chassis No: Odometer:

KMHET41VMBA811920 468132 km

Colour: **Engine Capacity:**

1991 cc

Market Value/New Car

N/A

Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Yes

Good Steering (Serviceable): Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes Good

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size:

215/60R16

Rear Tyre Size:

215/60R16

Front Left Side:

West Lake 7 mm

Rear Left Side:

No

West Lake 7 mm

Front Right Side:

West Lake 7 mm

Rear Right Side:

West Lake 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,261.22	0.00	1,261.22	100.00
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	970.00	400.00	570.00	58.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S	\$) 2,241.22	410.00	1,831.22	81.71
+ GST 7.00/7.00% (S	\$) 156.89	28.70	128.19	81.71
Nett Amount (S	\$) 2.398.11	438.70	1,959,41	81.71

INSPECTION

Date of Assignment:

23/05/2019 Present Location:

ComfortDelGro Engineering Pte Ltd

(Loyang)

Date Inspected:

22/05/2019 Inspected At:

ComfortDelGro Engineering Pte Ltd

(Loyang)

59 Loyang Drive Singapore 508969

Estimated Period of Repair:

2.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

REPAIR DETAILS

Referen	ce			
Part Source:	: MRM-SG	Version: 1.0 (Last Synchronised: 29 May 2019)		
Parts:	143	HYUNDAI SONATA 2.0 D CRDi Turbo (NF) (A) (Catalogue:Merimen Singapore 1.0)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	(Unsubmitted	(Unsubmitted, no print-code for SHD3950Y)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info:	Items/values	not in reference catalogue are prefixed with an asterisk *.		

_				-	
Rec	omr	nen	ded	Part	2

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	578.40 FL	*-FL
2	1		*REAR BUMPER UNDER COVER	Serviceable	185.80 FL	*-FL
3	1		*REAR BUMPER REINFORCEMENT	Serviceable	483.30 FL	*-FL
4	1		*REAR BUMPER SPONGE	Serviceable	137.40 FL	*-FL
5	10		*REAR BUMPER CLIPS	Not Necessary	22.00 FL	*-FL
6	1		*REVERSE SENSOR	Serviceable	135.70 F	*-F8
F=Fra	nchise	part. S=SpcNe	ett. L=ListItemDisc.	12		
				Sub Total (S\$)	1,542.60	0.00
			- List Item Discount on L Ite	ems 20.00/20.00% (S\$)	281.38	0.00
				Total Parts (S\$)	1,261.22	0.00
			Report was unsubmitted dur	ing this print-out.		

Re No	commended Miscellaneous It Qty Particulars	ems	Repairer's	Amount
Misc	cellaneous Items			
1	1 OD/TP Case (Insurer)		10.00	10.00
		Sub Total (S\$)	10.00	10.00
Re	commended Labour			
No	Particulars	Lab.Type	Repairer's	Amount
Labe	our Items			
1	PANEL BEATING	New	400.00	200.00
2	SPRAY PAINTING	New	400.00	200.00
3	WIRING CHECK	New	50.00	0.00
4	R/I REVERSE SENSOR	New	120.00	0.00
		Gross Labour Cost (S\$)	970.00	400.00
	Report was a	unsubmitted during this print-out.		

< END OF ESTIMATES >