

ASS. REC. BY:

REF: TM1/CC3/TM19069057/K10302Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

QD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. MJ001088Claims No. M1903702

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 845K

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Soon: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or NoLum Sum: 20% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHF577BYr Regn: 06, 14Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: RenaultLatitude c.c. 1995Colour: N.White / Red

A/C: Insured / Std / NI / NA

Sp. Reading: 808048

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: VFIABL15AUC278416Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_

R: \_\_\_\_\_

215/60R16BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or Giti

Front

Rear

R/Bal. 8 mmR/Bal. 8 mmL/Bal. 8 mmL/Bal. 8 mmD.O.A. 20/5/19D.O.I. 22/5/19

Survey held at \_\_\_\_\_

Des. of Damages: Fit / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1File pass to11km 85650k (Red & 77066.21, 80%)SHF577B-05/FCL19005005/K10302SKJ TO LTZ -XD.O.A - 17/05/2019

RECEIVED 27 MAY 2019

Date/Time, File Pass to?

☐

: Prel. Report

11/27/18 TM1918☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

Fuel:

Others:

TOTAL

25010260Report Format: MER-TPLump Sum / I.B.I. (\$ 5650)

## Shiau Chan (LKKAuto)

---

**From:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Sent:** Friday, 24 May 2019 7:29 PM  
**To:** Shiau Chan (LKKAuto)  
**Subject:** RE: TP VEHICLE SHF 577B (DOA: 20/05/2019) -- AAD1905-164  
**Attachments:** image001.wmz

Hi Shiau Chan

We agree the COR amount \$5,650.00 (b4 GST).

Thank You  
Best Regards,  
**Ng Wai Yin**  
Finance Department  
TEL: 6603 1265 Ext.308

**\*\*\* Please be reminded that all claims correspondence to be send to [claims@transcab.com.sg](mailto:claims@transcab.com.sg)**



**TRANS-CAB SERVICES PTE LTD**  
No. 2 Ang Mo Kio Street 63, Singapore 569111  
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764  
Website: [www.transcab.com.sg](http://www.transcab.com.sg)

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

---

**From:** Shiau Chan (LKKAuto) [mailto:[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)]  
**Sent:** Friday, 24 May, 2019 10:12 AM  
**To:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Subject:** TP VEHICLE SHF 577B (DOA: 20/05/2019)

Dear Wai Yin,

Based on our surveyor's estimate marking, the calculation of repair cost will be at Lump Sum \$5,650.00 and 3 repair days.

Kindly check.

Best Regards,  
**Shiau Chan (Ms) | Case Handler**  
**LKK Auto Consultants Pte Ltd**  
Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

## **Shiau Chan (LKKAuto)**

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Thursday, 23 May 2019 2:00 PM  
**To:** Motor Claims  
**Cc:** SUR  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP -TRANS-CAB AUTO SERVICES PTE LTD, DOA: 20/05/2019, SHF 577B (TP VEHICLE), SKJ 7069Z (OI VEHICLE)  
**Attachments:** SHF577 EST.pdf; SHF577 GIA.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHF 577B at M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 22/05/2019.

Enclosed herewith a copy of TP's GIA report and estimated cost of repair .

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	21/05/2019 13:32
Date Of Accident	20/05/2019 17:20
Exact Location Of Accident	BLK 80 RED HILL LANE CARPARK
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SHF577B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666
<b>Vehicle Particulars</b>	
Manufacturer	RENAULT
Model	LATITUDE-2.0 D DCI (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
<b>Insurance Company</b>	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	
<b>Driver</b>	
Name of Driver	TAN AI BOON
NRIC No	S1287842G
Date Of Birth	15/07/1958
Occupation	OUTDOOR
Date Of Driving Pass	09/10/1979
Driving Experience	39 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91599261
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	APT BLK 37 TANGLIN HALT ROAD #07-143
Postcode	140037
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

ON 20/05/2019 AT ABOUT 1720HRS, I WAS STATIONARY AT THE CARPARK OF BLK 80 RED HILL LANE CARPARK WAITING FOR A PARKING LOT TO PARK MY VEHICLE. SUDDENLY, I FELT AN IMPACT FROM THE REAR PORTION OF MY TAXI. VEHICLE B(SKJ7069Z) HAS FAILED TO STOP IN TIME AND COLLIDED ONTO THE REAR RIGHT PORTION OF MY TAXI.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE SIZE TOO LARGE
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKJ7069Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name TAN AI BOON

Approximate Age

Injuries Sustain

Injured person in which vehicle? SHF577B

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

Sketch Plan Pg. 1

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**E. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



## Sketch Plan #2 Pg. 1

### SKETCH PLAN

Parking lot  
 →  
 A  
 B  
 Parking lot  
 A: SHFS77B  
 B: SKS70642  
 BK 80, Red Hill Lane, Carpark.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to GIA Report.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature \_\_\_\_\_

Date &amp; Time:

Setback Control#Uniform\_VA

Driver's Signature \_\_\_\_\_

(if driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

**Naïveté:**

SRIC/FIN No.:

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF 577B****AAD1905-164***Not Authored  
V/Sing 856501*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date Of Registration:

**SHF 577B**

VF1ABL15AUC278416

RENAULT

LATITUDE

20.5.19

**TOKIO MARINE**

20/6/2014

**PART****LIST**

1	1	BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46 ✓
2	1	BUMPER LOWER REAR	\$	<i>Ad 10.11</i> 768.84 ✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>SL</i> 113.47 X
4	1	BUMPER BRACKET SIDE RH REAR	\$	<i>SL</i> 135.97 X
5	1	BUMPER RETAINER RH REAR	\$	<i>SL</i> 44.99 X
6	1	BUMPER REFLECTOR RH	\$	<i>SL</i> 43.61 X
7	1	BUMPER BRACKET SIDE LH REAR	\$	<i>SL</i> 135.97 X
8	1	BUMPER RETAINER LH REAR	\$	<i>SL</i> 44.99 X
9	1	BUMPER REFLECTOR LH	\$	<i>SL</i> 43.61 X
10	1	BUMPER BEAM REAR	\$	<i>R</i> 777.52 ✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95 X
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95 X
13	1	OUTER PANEL REAR (End Panel)	\$	<i>R</i> 1,471.77 X
14	1	OUTER PANEL REAR (End Panel)TRIM	\$	<i>CM</i> 404.56 ✓
15	1	TAILLAMP RH	\$	<i>SL</i> 552.55 X
16	1	TAILLAMP PANEL RH	\$	<i>R</i> 986.70 X
17	1	TAILLAMP LH	\$	<i>SL</i> 552.55 X
18	1	TAILLAMP PANEL LH	\$	<i>R</i> 986.70 X
19	1	BOOT REAR	\$	<i>B</i> 2,872.68 ✓
20	1	BOOT FINISHER	\$	<i>SL</i> 470.06 X
21	1	BOOT WHEATERSTRIP	\$	<i>SL</i> 323.05 X
22	1	BOOT REFLECTOR LAMP LH	\$	<i>SL</i> 493.35 X
23	1	BOOT REFLECTOR LAMP RH	\$	<i>SL</i> 493.35 X
24	1	BOOT BADGE 'RENAULT'	\$	<i>SL</i> 225.36 ✓
25	1	BOOT BADGE	\$	<i>SL</i> 225.36 ✓
26	1	BOOT STRUT LH	\$	<i>SL</i> 276.08 X
27	1	BOOT STRUT RH	\$	<i>SL</i> 276.08 X
28	1	BOOT HINGE LH	\$	<i>R</i> 367.84 X
29	1	BOOT HINGE RH	\$	<i>R</i> 367.84 X
30	1	BOOT INNER TRIM	\$	<i>SL</i> 586.45 X

**Trans-cab Auto Services Pte Ltd**

AAD1905-164

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 577B

31	1	BOOT SWITCH	\$	<i>Per</i>	168.13	X
32	1	BOOT LOCK	\$	<i>R</i>	202.67	X
33	1	BOOT LOCK CATCH	\$	<i>R</i>	74.40	X
<b>TOTAL</b>			<b>\$</b>		<b>16,046.87</b>	
<b>10%</b>			<b>\$</b>		<b>1,604.69</b>	
			<b>\$</b>		<b>14,442.19</b>	

**Special Nett**

1	1SET	PARKING AID	\$	<i>Per</i>	700.00	X
2	1SET	REAR BUMPER CLIP	\$	<i>Per</i>	66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>Per</i>	33.00	✓
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	<i>Per</i>	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	<i>Per</i>	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	<i>Per</i>	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	<i>Per</i>	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	<i>Per</i>	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	<i>Per</i>	66.00	✓
10	1	BOOT STICKER "Trans-cab"	\$	<i>Per</i>	30.00	✓
11	1	BOOT STICKER "6555-3333"	\$	<i>Per</i>	30.00	✓
12	1	EXHAUST MOUNTING REAR	\$	<i>Per</i>	17.82	} X
13	2	REAR WINDSCREEN SEALANT	\$	<i>Per</i>	80.00	
14	1	WINDSCREEN MOULDING	\$	<i>Per</i>	100.00	
15	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>Per</i>	100.00	
16	1	BOOT INNER TRIM CLIP	\$	<i>Per</i>	45.00	
17	1SET	BOOT FINISHER CLIP	\$	<i>Per</i>	24.20	
18	1	TAILLAMP CLIP LH	\$	<i>Per</i>	5.00	
19	1	TAILLAMP CLIP RH	\$	<i>Per</i>	5.00	
<b>TOTAL</b>			<b>\$</b>		<b>1,384.02</b>	
<b>TOTAL PARTS</b>			<b>\$</b>		<b>15,826.21</b>	

**LABOUR**

To Check Electrical Lighting Concerned.	\$	170.00	<i>20%</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,500.00	<i>400%</i>

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF 577B****AAD1905-164**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>un</i> 380.00 <i>X</i>
Putty And Spray Painting Of The Affected Portion.	\$	4,500.00 <i>500</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>un</i> 170.00 <i>X</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00 <i>30</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>60</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 <i>60</i>
To repair and realign rear exhaust pipe.	\$	<i>un</i> 170.00 <i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>un</i> 170.00 <i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>un</i> 170.00 <i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>un</i> 170.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>un</i> 220.00 <i>X</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>un</i> 380.00 <i>X</i>
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>un</i> 380.00 <i>X</i>

**TOTAL \$ 11,890.00****Over All Total \$ 27,716.21****LUMP SUM ( REPAIR DAY)***15 DAYS*  
*3 day*

hence notify  
the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey form & "Without Prejudice" basis
- No legal responsibility is altered
- Subsequent to the completion of the repair and
- Is subject to time and cost

Acknowledged by Repairer  
Signature:  
Date:

## LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19009057/KTD3N2

Date: 30/05/2019

## REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MJ001088
Claimant Vehicle No :	SHF577B	Insured Vehicle No :	SKJ7069Z
Date of Loss:	20/05/2019	Nature of Claim:	TP
		Claim No:	M1903742

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SHF577B	Engine No:	M9R8839C001647
Make & Model:	RENAULT LATITUDE, 2.0 D dCi (A)	Chassis No:	VF1ABL15AUC278416
Reg. Date:	20/06/2014 (Man. Year: 2014)	Odometer:	808048 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Giti 8 mm	Rear Left Side:	Giti 8 mm
Front Right Side:	Giti 8 mm	Rear Right Side:	Giti 8 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	15,826.19	5,969.50	9,856.69	62.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,890.00	1,070.00	10,820.00	91.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>27,716.19</b>	<b>7,039.50</b>	<b>20,676.69</b>	<b>74.60</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,650.00</b>		
(S\$)	27,716.19	5,650.00	22,066.19	79.61
+ GST 7.00/7.00% (S\$)	1,940.13	395.50	1,544.63	79.61
<b>Nett Amount (S\$)</b>	<b>29,656.32</b>	<b>6,045.50</b>	<b>23,610.82</b>	<b>79.61</b>

## INSPECTION

Date of Assignment:	23/05/2019	
Date Inspected:	22/05/2019	Inspected At: Trans Cab Auto Services Pte Ltd - Amk (HQ) No 2 Ang Mo Kio St 63 Singapore 569111
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 30 May 2019)
<b>Parts:</b>	143	RENAULT LATITUDE 2.0 D dCi (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHF577B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	1,108.46 FL	*1,108.46 FL
2	1		*BUMPER LOWER REAR	Dented/Distorted	768.84 FL	*768.84 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
9	1		*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*- FL
10	1		*BUMPER BEAM REAR	Bent	777.52 FL	*777.52 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	225.95 FL	*- FL
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	225.95 FL	*- FL
13	1		*OUTER PANEL REAR (END PANEL)	Repair	1,471.77 FL	*- FL
14	1		*OUTER PANEL REAR (END PANEL) TRIM	Cracked	404.56 FL	*404.56 FL
15	1		*TAILLAMP RH	Serviceable	552.55 FL	*- FL
16	1		*TAILLAMP PANEL RH	Repair	986.70 FL	*- FL
17	1		*TAILLAMP LH	Serviceable	552.55 FL	*- FL
18	1		*TAILLAMP PANEL LH	Repair	986.70 FL	*- FL
19	1		*BOOT REAR	Bent	2,872.68 FL	*2,872.68 FL
20	1		*BOOT FINISHER	Serviceable	470.06 FL	*- FL
21	1		*BOOT WEATHERSTRIP	Serviceable	323.05 FL	*- FL
22	1		*BOOT REFLECTOR LAMP LH	Serviceable	493.35 FL	*- FL
23	1		*BOOT REFLECTOR LAMP RH	Serviceable	493.35 FL	*- FL
24	1		*BOOT BADGE RENAULT	Necessary	225.36 FL	*225.36 FL
25	1		*BOOT BADGE	Necessary	225.36 FL	*225.36 FL
26	1		*BOOT STRUT LH	Serviceable	276.08 FL	*- FL
27	1		*BOOT STRUT RH	Serviceable	276.08 FL	*- FL
28	1		*BOOT HINGE LH	Repair	367.84 FL	*- FL
29	1		*BOOT HINGE RH	Repair	367.84 FL	*- FL
30	1		*BOOT INNER TRIM	Serviceable	586.45 FL	*- FL
31	1		*BOOT SWITCH	Serviceable	168.13 FL	*- FL
32	1		*BOOT LOCK	Repair	202.67 FL	*- FL
33	1		*BOOT LOCK CATCH	Repair	74.40 FL	*- FL
34	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
35	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
36	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
37	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
38	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
39	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
40	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
41	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
42	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
43	1		*BOOT STICKER TRANS-CAB	Necessary	30.00 FS	*30.00 FS
44	1		*BOOT STICKER 6555-3333	Necessary	30.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*EXHAUST MOUNTING REAR	Not Necessary	17.82 FS	*- FS
46	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
47	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
48	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
49	1		*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*- FS
50	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
51	1		*TAILLAMP CIP LH	Not Necessary	5.00 FS	*- FS
52	1		*TAILLAMP CIP RH	Not Necessary	5.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc

<b>Sub Total (\$\$)</b>	<b>17,430.88</b>	<b>6,607.78</b>
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,604.69	638.28
<b>Total Parts (\$\$)</b>	<b>15,826.19</b>	<b>5,969.50</b>

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	4,500.00	400.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,500.00	500.00
5	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	0.00
6	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
7	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
8	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
9	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
10	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
11	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
12	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
13	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
14	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
15	TO TRANSFER OF REAR BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
Gross Labour Cost (S\$)			11,890.00	1,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >