

VIC

新合利服務公司

Sin Hup Lee Service Co.

Block 1005 Bukit Merah Lane 2 #01-20

Singapore 159761

Tel: 6278 2482 Fax: 6271 9802

Email: sinhuplee@gmail.com

Reg. No. 083995/00E

LBN/PAU/CONSULTANTS/REPAIR/REPAIR

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:
Date:

Attn: Motor Claim Department
AIG Asia Pacific Insurance Pte. Ltd
AIG Building
78 Shenton Way #07-16
Singapore 079120

20 May 2019
22/5/19, 12.15 pm
Stereo (LKK) with repair 5 days
8322 8813 L/S
Stereo @ LKK auto - rm Ry AL Sky

Chan Yin Jet
c/o Sin Hup Lee Service Co.
Block 1005 Bukit Merah Lane 2 #01-20
Singapore 159761

Dear Sir/Ms,

Re: Road Traffic on 06 May 2019 at West Coast Highway, involving vehicle SMH7836M /
SGK5681K

Quotation for Repair Vehicle No: SGK5681K, NISSAN SYLPHY (Third Party Claim)

Quantity	Nett Item	
1	Rear Door LH / DD	\$ 960.00 ✓
1	Rear Door Moulding LH / cut	\$ 150.00 ✓
		\$ 1,110.00
	Less 10%	\$ 111.00
		\$ 999.00 ✓
Labour		
1	To cut-weld Locker Panel, Rear Fender, remove and re-fix damaged parts, straighten and realign affected areas.	\$ 750.00 600

2	To spray affected areas	\$	700.00	600
3	To remove and re-fix Rear Door Mechanism. Check & test Wiper Motor and Centre Locking System	\$	100.00	50
4	Check Water Seepage and rustproof affected areas	\$	150.00	30
Total Amount		\$	2,699.00	1280

Kindly arrange your surveyor to survey my vehicle.

We look forward to hear from you soon.a

Thank you.

Yours Faithfully

Mr Wong

81122116

P- 999
L- 1280
2279
L/S- 1823.20
= 1800