

新合利服務公司

Sin Hup Lee Service Co

Block 1005 Bukit Merah Lane2 #01-20

Singapore 159761

Tel: 6278 2482 Fax: 6271 9802

Email: sinhuplee@gmail.com

Reg. No. 083995/00E

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Attn: Motor Claim Department  
AIG Asia Pacific Insurance Pte. Ltd  
AIG Building  
78 Shenton Way #07-16  
Singapore 079120

Steve (LKK)  
8322 8813  
sterechin@lkk.com

WPL 20 May 2019  
22/5/19, 12.15 pm  
5 days  
L/S  
Ry AL SH

Chan Yin Jet  
c/o Sin Hup Lee Service Co.  
Block 1005 Bukit Merah Lane 2 #01-20  
Singapore 159761

Dear Sir/Ms,

Re: Road Traffic on 06 May 2019 at West Coast Highway, involving vehicle SMH7836M /  
SGK5681K

Quotation for Repair Vehicle No: SGK5681K, NISSAN SYLPHY (Third Party Claim)

Quantity	Nett Item		
1	Rear Door LH ✓ <i>DD</i>	\$	960.00
1	Rear Door Moulding LH ✓ <i>CUT</i>	\$	150.00
		\$	1,110.00
		Less 10%	\$ 111.00
		\$	999.00

Labour

1	To cut-weld Locker Panel, Rear Fender, remove and re-fix damaged parts, straighten and realign affected areas.	\$	750.00 <i>600</i>
---	--	----	-------------------

2	To spray affected areas	\$	700.00	600
3	To remove and re-fix Rear Door Mechanism. Check & test Wiper Motor and Centre Locking System	\$	100.00	50
4	Check Water Seepage and rustproof affected areas	\$	150.00	30
<b>Total Amount</b>		\$	2,699.00	

Kindly arrange your surveyor to survey my vehicle.

We look forward to hear from you soon.a

Thank you.

Yours Faithfully

Mr Wong

81122116