

2/2 \$1471.00
28/5/18
Take ph. Aftering
2dy.

YP5051P UD Trucks MKB8ELN5AA

No	Qty	Parts Description		Estimated Parts Price	
1	1	Front bumper assy (outer)	11	\$ 1,678.00	X
2	1	Front bumper reinforcement	11	\$ 392.00	X
3	1	Front bumper reinforcement left side bracket	11	\$ 125.00	X
4	1	Front bumper left bracket	11	\$ 91.00	X
5	3	Front bumper left side stay	11	\$ 149.00	X
6	1	Front grille assy	11	\$ 552.00	X
7	1	Front left corner panel	11	\$ 832.00	X
8	1	Front left headlamp	11	\$ 1,280.00	X
9	1	Front left headlamp bracket	11	\$ 220.00	X
10	1	Front left headlamp holder	11	\$ 65.00	X
11	1	Front left headlamp wire harness	11	\$ 650.00	X
12	1	Front left signal lamp	502	\$ 185.00	✓
13	1	Front left step garnish (upper)	11	\$ 675.00	X
14	1	Front left step garnish (lower)	11 (One)	\$ 695.00	X
15	1	Front left foot step (upper)	11	\$ 393.00	X
16	1	Front left foot step (lower)	11	\$ 393.00	X
17	1	Front left step garnish bracket	11	\$ 98.00	X
18	1	Front left step garnish reflector	11	\$ 98.00	X
19	1	Front left door panel assy	11	\$ 3,675.00	X
20	1	Front left door MK11250 emblem	11	\$ 180.00	✓
21	2	Front left door hinges	11	\$ 265.00	X
22	1	Front left door lock	11	\$ 195.00	X
23	1	Front left door weatherstrip	11	\$ 388.00	X
24	1	Front left door inner insulation	11	\$ 260.00	X
25	1	Front left door inner rubber	11	\$ 128.00	X
26	1	Front left door regulator with motor	11	\$ 495.00	X
27	1	Front left door reflector	11	\$ 250.00	X
28	1	Front left door protector	grand	\$ 205.00	✓
				\$ 14,612.00	
Less 10%				\$ 1,461.20	
				\$ 13,150.80	

Special Nett Items

1	16	Front bumper clips	11	\$ 80.00	X
2	1	Front bumper top protector sealant	11	\$ 80.00	X
3	10	Front grille clips	11	\$ 60.00	X
4	8	Front left door inner insulation clips	11	\$ 30.00	X
5	8	Front left fender inner shield clips	11	\$ 40.00	X
6	1set	Front left door sticker	11	\$ 350.00	3005.2
7	1	Front left wheel rim	11	\$ 1,200.00	X
8	1	Front left tyre	11	\$ 600.00	X
9	1	Front no plate	11	\$ 80.00	X
				\$ 2,520.00	

\$ 15,670.80

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522

YP5051P UD Trucks MKB8ELN5AA

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front left affected area and replace front left damaged parts.	\$ 3,000.00 400
2	To putty and spray painting front left affected portion.	\$ 3,000.00 400
3	To remove and install front left door lock mechanism.	\$ 11 250.00 X
4	To check door central locking for function.	\$ 11 80.00 X
5	To apply anti rust proofing to front left affected area.	\$ 11 150.00 X
6	To transfer front left door glass to new door.	\$ 11 120.00 X
7	To check wiring and focus front headlamp.	\$ 50.00 20
8	To balance front left tyre.	\$ 11 80.00 X
9	To conduct wheel alignment.	\$ 11 250.00 X
		<u>\$ 6,980.00</u>

Total parts : \$ 15,670.80

Total labour : \$ 6,980.00

Total repair cost : \$ 22,650.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

p-390
 102
 p-351
 SN-300
 1000 820
 1471.00