INV. CAM, OWNER	ENTENMUD CC 4/AIG1900	1080,6	War. 9 LIKE
Staveyor:	MYCUS DOL ASSIGN	MENT	Dusc/Time: Wholen.
Pre-ussign / CCU	(UE 5137M	Claim No.	W by 660 ~ 7059
Name of Insured.	AM CHOON YEN GIND	Pulicy No. :	MO0476795
Excess Sec II :SS Is drayer the owner		Place of Acciden	
IFNO. Driver Nam Driver Tel		Of GIA REPORT	T: YES / NO : TP GIA REPORT: YES / NO : # Final ? Yes / No
INSES THAT WEST THAT Tel: Liability: On RMAS	UNSRS: WSP Tel: Liability RMKS:	INSRS: WSP Yel: Liability: RMKS:	INSRS WSP Tel Liability RMKS
Date/ Time	Journal D. X and 5/39 to	-1	STAGE DATE/PIC
	HINAUSED		Non-Reporting by (2nd) Non-Reporting by (2nd) Non-Reporting by (2nd)
	TO CLAIM IN NOW 1890ES.  TO LOD IN BY BUMIL OI VIDEO SHOWS OID IN ESTIN	HEN CHNES	Antherication To Act  Release Vouchur  Final Repair Bill  Car Rental Invince  Final Repair Bill
tala ka	S de OL 24440 Let Grafe	60%.	TA/GIAL
18િલ્લીવ	- TO CLOSE.		Medical Bill:  PIR:  Mandate/Reject Instruction:  LOD
RELIMINARY ADVICE	Date/Time: Sent By:		Payment Breakdown Form: Post-Repair Photos: Others:
INALIZATION epair Cost. PP	Date/Time: Confirm with SS 1471-90 / 2 days Reduction:		Confirm by:
PAL SETTLEMENT	Date/Time: 2910719 Confirm with		Email Cal
3(97) \$1,545.97 (97)	11 50 (A (Ca) / Assessed) BOLA S/N No.: 55 786.99 55 767.50 ( Z. dzys) × 4150	NIL	HINO OF B 28. AM. LIB BOTH CHANGED CHANGE HINO OF B 28. AM. LIB
ons of Use (LDU): — cos of Income (LDU): — CR only  LDU only LALTA Seatch	\$\$(\$ x	one)	Mala
Medical – lisbursement – cyal Cist –	55 — (c.g. Tow/ Independ	ont )	1) Claim status: Normal/Reject/Private Settle 2) Report Format: 3) Survey fee: \$510.00
TNAL PAYMENT	SS 1,056. 49 Global Sum SS: — Data/Time: Confirm with:		Emuil Call
layee 1:	SS 1,086.49 Name 1: THINK		OCURA LAR PAR
ager 2. (Stilke ICN A.)	\$5 Name 2	_	
Spec 3: (Strike (CNA))	SS Name 3	_	

TOTAL

# No.18 Defu Avenue 2 Singapore 539522

VP5051P IID Trucks MKR8FLN5AA

YP505	51P UI	D Trucks MKB8ELN5AA		Take phi mais
100	STATE OF THE PARTY		The state of the s	Estimated
No	Otv	Parts Description		arts Price
1	1	Front bumper assy (outer)	118	1,678.00 🗶
2	1	Front bumper reinforcement	175	392.00 ×
3	1	Front bumper reinforcement left side bracket	115	125.00 X
4	1	Front bumper left bracket	17 S	91.00 🗶
5	3	Front bumper left side stay	115	149.00 ✗
6	1	Front grille assy	175	552.00 人
7	1	Front left corner panel	115	832.00 ×
8	1	Front left headlamp	115	1,280.00 🔨
9	1	Front left headlamp bracket	17 \$	220.00∝
10	1	Front left headlamp holder	11 \$	65.00
11	1	Front left headlamp wire harness	175	650.00
12	1	Front left signal lamp	Set 8	185.00
13	1	Front left step garnish (upper)	1/11/5	675.00人
14	1	Front left step garnish (lower)	11(0m s	695.00 ×
15	1	Front left foot step (upper)	17 \$	393.00 🗶
16	1	Front left foot step (lower)	11 5	393.00 ×
17	1	Front left step garnish bracket	11 \$	98.00
18	1	Front left step garnish reflector	17 \$	98.00
19	1	Front left door panel assy	R S	3,675.00 乂
20	1	Front left door MK11250 emblem	where s	180.00
21	2	Front left door hinges	115	265.00 🗶
22	1	Front left door lock	175	195.00 🗶
23	1	Front left door weatherstrip	11 5	388.00 X
24	1	Front left door inner insulation	118	260.00 💸
25	1	Front left door inner rubber	115	128.00 🗶
26	1	Front left door regulator with motor	175	495.000
27	1	Front left door reflector	17,5	250.00 🗓
28	1	Front left door protector	grand 5	205.00
			\$	14,612.00
		Less 10%	\$	1,461.20
			_ \$	13,150.80
		S 4002 S		
	recor	Special Nett Items	19/19/11/12	
1	16	Front bumper clips	1-1 5	80.00 🗶
2	1	Front bumper top protector sealant	115	80.00 X
3	10	Front grille clips	175	60.00 ×
4	8	Front left door inner insulation clips	475	30.00 X
5	8	Front left fender inner shield clips	11 5	40.00 ×
6		Front left door sticker	ru s	350.00 3005.~
7	1	Front left wheel rim	415	1,200.00 ×
8	1	Front left tyre	17 5	600.00
9	1	Front no plate		80.00
			_\$_	2,520.00

# Think One Autocare Pte Ltd No.18 Defu Avenue 2 Singapore 539522

# YP5051P UD Trucks MKB8ELN5AA

No	Description		Labour Charges	
1	Labour for panel beating, cut, weld, straighten front left affected area and replace front left damaged parts.	S	3,000.00	400
2	To putty and spray painting front left affected portion.	S	3,000.00	4,27
3	To remove and install front left door lock mechanism.	S	1/1 250.00	
4	To check door central locking for function.	S	20.00	
5	To apply anti rust proofing to front left affected area.	S	17 150.00	
6	To transfer front left door glass to new door.		11 120.00	
7	To check wiring and focus front headlamp.	S	50.00	
8	To balance front left tyre.		A1 80.00	
9	To conduct wheel alignment.	\$	A 250.00	2
		2	6,980.00	

Total parts: \$ 15,670.80 Total labour: \$ 6,980.00 Total repair cost: \$ 22,650.80

Tay July a renderey	nof the following: hant, over very pointing
Previous tass	is, du. a tredriey
The second secon	- TOUR TOUR
A TOTAL SECTION CONTRACT	
	and the second section of the second section of the second

9-390 9-35/1 5N-300 1/21.00

# Think One Autocare Pte Ltd No.18 Defu Avenue 2 Singapore 539522

YP5051P UD Trucks MKB8ELN5AA

YP505	51P UI	Trucks MKB8ELN5AA		Take phi Maria
				Estimated
No	Qty	Parts Description	P	arts Price
1	1	Front bumper assy (outer)	115	1,678.00
2	1	Front bumper reinforcement	175	392.00 ×
3	1	Front bumper reinforcement left side bracket	115	125.00 X
4	1	Front bumper left bracket	7 5	91.00 🗴
5	3	Front bumper left side stay	115	149.00 ✗
6	1	Front grille assy	775	552.00 人
7	1	Front left corner panel	115	832.00 ✗
8	1	Front left headlamp	115	1,280.00 人
9	1	Front left headlamp bracket	175	$220.00$ $\propto$
10	1	Front left headlamp holder	11 5	65.00
11	1	Front left headlamp wire harness	175	650.00 🗶
12	1	Front left signal lamp	Set s	185.00
13	1	Front left step garnish (upper)	11.115	675.00 🗶
14	1	Front left step garnish (lower)	M((Om s	695.00 ×
15	1	Front left foot step (upper)	175	393.00 🗶
16	1	Front left foot step (lower)	11 5	393.00 🗴
17	1	Front left step garnish bracket	11 5	98.00
18	1	Front left step garnish reflector	17 8	98.00
19	1	Front left door panel assy	R S	3,675.00 ×
20	1	Front left door MK11250 emblem	ner s	180.00
21	2	Front left door hinges	125	265.00 X
22	1	Front left door lock	175	195.00 ⊀
23	1	Front left door weatherstrip	11 5	388.00 x
24	1	Front left door inner insulation	11 S	260.00 🗴
25	1	Front left door inner rubber	11 8	128.00 🗴
26	1	Front left door regulator with motor	178	495.00
27	1	Front left door reflector	17,5	250.00 X
28	1	Front left door protector	grand S	205.00
			S	14,612.00
		Less 10%	S	1,461.20
			S	13,150.80
		Special Nett Items		200
1	16	Front bumper clips	17 \$	80.00 🗶
2	1	Front bumper top protector sealant	17 8	80.00 🗶
3	10	Front grille clips	175	60.00 ×
4	8	Front left door inner insulation clips	U7 S	30.00 🗡
5	8	Front left fender inner shield clips	11 8	40.00 ×
6	1set	Front left door sticker	sec s	350.00 3005.~
7	1	Front left wheel rim	41 S	1,200.00 🗶
8	1	Front left tyre	17 \$	600.00 🗶
9	1	Front no plate	178	80.00
			S	2,520.00

# Think One Autocare Pte Ltd No.18 Defu Avenue 2 Singapore 539522

### YP5051P UD Trucks MKB8ELN5AA

No	Description		Labour Charges	
1	Labour for panel beating, cut, weld, straighten front left affected area and replace front left damaged parts.	5	3,000.00	4
2	To putty and spray painting front left affected portion.	\$	3,000.00	40
3	To remove and install front left door lock mechanism.	S	<b>イイ 250.00</b>	
4	To check door central locking for function.	S	11 80.00	X
5	To apply anti rust proofing to front left affected area.	S	17 150.00	X
6	To transfer front left door glass to new door.	S	11 120.00	X
7	To check wiring and focus front headlamp.	S	50.00	20
8	To balance front left tyre.	S	A1 80.00	X
9	To conduct wheel alignment.	S	A 250.00	X
		S	6,980.00	

Total parts: \$ 15,670.80

Total labour: \$ 6,980.00

Total repair cost: \$ 22,650.80



P-390 P-35/ SN-300 Idm 820

#### PRE-REPAIR INSPECTION REQUEST - YP5051P vs SLE5137M (OI) on D.O.A.: 16/05/2019

Franci Hor. Yinnul

\_assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)

O: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur

5/22/2019 10:27:23 AM

Attachments: T YPS051P vs SLES137M PDF

Hi.

To

Please refer to the enclosed request from Thisk One Autocare Pte Ltd.

: 2464660270SG003

Case Owner

: BERNARD JI QIAN LER

If you have any queries/concerns, please let us know.

Kindly assist to assign Marcus Chua as Single Joint Expert as requested.

Thanks & Regards,

Yin Rul, Hor (Viviane)

Claim Adjuster II, Singapore FNOL, Claims Operations - Auto

Yinnul Hortitaig.com | www.aig.sg

From: karentan@thinkone.com.sg [mailto:karentan@thinkone.com.sg]

Sent: Wednesday, May 22, 2019 10:20 AM

To: Har, Yinrul

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLE5137M AND YP5051P ON 16/05/2019

Hi Yinrul,

We would like to proceed with LKK Auto Consultants Pte Ltd , Marcus Chua

From: Hor, Yinrul

Sent: Wed, 22 May 2019 01:35:07 +0000

To: karentan@thinkone.com.sg

Cc: Fong, Andy-SY, Fan, Winnie-LW, Kaur, Baljit, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithousingh,

Aashweenjeetkaur

Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLES137M AND YP5051P ON 16/05/2019

#### Without Prejudice

Your Reference

: YP5051P

Our Reference

: 2464660270SG003

Dear Sir/Madam

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert;

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd

1.55pme 22/5/2019 persone karen vehicle not In

Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soor HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

#### Thanks & Regards,

Yin Rul, Hor (Viviane)
AIG
Claim Adjuster It, Singapore FNOL, Claims Operations – Auto
Yinni HoriBaig.com | www.aig.sg

#### IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

#### IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

# **DISCHARGE \ SATISFACTION VOUCHER**

I WE THINKONE LEAS	SING PTE LID	NRIC/ ROC 20115609 M
THE THINKSHO SETT	000 0 0 0	national services
nereby state that the repairs to vel	hicle no YN 5051 P	have been carried out to my/our entire
atisfaction and I/We agree that th	ne discharge to the account	of Think One Auto Care Pte Ltd
shall be in full discharge of all of	laims under policy no	107728339
with regards to the damage to my		accident which occurred on at around 14.00 hv
(date)	- 11.00	at around (time)
	Vehicle Owner	
		HINEONE LEASING PTE LTD
	Name 7	HINEONE LEASING PTE LTD
	Name 7	
	Name 7	20115609M
	Name 7	20115609M 201 UBI ROAD 4 #02-06
	Name 7	20115609 M 20, UBI ROAD 4 #02-06 THINK ONE BUILDING

( with company stamp if applicable)



## THINK ONE AUTOCARE PTE LTD

RCB: 201322501G GST: 201322501G No 18 Defu Avenue 2, Singapore 539522 Tel: (65)6844 3300 Fax: (65)6842 4988 Email: enquiry: autocare@thinkone.com.sq

Our Ref

: YP5051P

Your Ref

Date

: 23.07.2019

AIG ASIA PACIFIC INSURANCE PTE LTD 78 SHENTON WAY #07-16 SINGAPORE 079120

Dear Sirs.

Accident Involving YP5051P & SLE5137M along LOYANG AVENUE on 16.05.2019 14.00hrs

We are authorized by the owner THINK ONE LEASING PTE LTD of vehicle YP5051P to claim damages and loses against your insured in connection with the above road traffic accident.

Our client's vehicle was damaged and our client has been put to loss and expenses, particular of which are as follows:

Cost of Repair (inc 7%gst)

\$1,573.97

Loss of Rental (\$250 x 2.00 days) inc 7%gst

\$535.00

LTA SERACH FEE

\$2.00

:

Total

\$2,110.97

We enclose herewith the supporting documents for your perusal.

Please let us have your cheque payment made in favour of 'Think One Autocare Pte Ltd'

Yours Faithfully

Think One Autocare Pte Lta 18 Defu Lane Avenue 2 Singapore 539522

Tel: 6844 3300 Fax: 6842 4988

Michael Ng Claim Advisor HP: 91288488

DID: 68443300

michaelng@thinkone.com.sg



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

24 JULY 2019

SIM CHOON YEN GINA BLOCK 219 PASIR RIS STREET 21 #12-164 SINGAPORE 510219

Dear Sir/Madam,

OUR REF

: CC4/AIG19009080/Uhb3

YOUR REF

: SLE 5137M

ACCIDENT INVOLVING SLE 5137M AND YP 5051P ALONG LOYANG ROAD ON 16.05.2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of YP 5051P against your motor insurance policy.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant. Unless proven otherwise.

Please be informed that your No Claim Discount (NCD – if applicable) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to <a href="mailto:vicalpeh@lkkauto.com">vicalpeh@lkkauto.com</a> within 10 days from the date of this letter if not provided at AIG's reporting centre. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- · Coloured photographs of accident scene (if any)
- · Coloured photographs of damage to all vehicles involved (If any)



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

- Video footage of accident (if any)
- · Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6841 2096 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Vic Alpeh Case Handler DID: 6841 2096 FAX: 6741 4108

C.C.

Email: vicalpeh@lkkauto.com

AIG Asia Pacific Insurance Pte Ltd (Motor Claims Dept)

# **AUTHORISATION TO ACT**

-	CR44 - 444-4	ug Prett		_	(nddeneral)
		party claimant			(address) YP505(P
IHINKONS	E BULLDING S	PORE YES	1024	owner of	(vehicle number)
ereby author	rised THINK ON	E AUTOCA	RE PTE. LT	D ("the workshop)	to act for me
ith respect t	to my claim for r	epair costs	and/or renta	and/or loss o	f use ("claim") for my
ehicle no.	YP5051P	tř	nat was dam	aged pursuant	to the accident which
occurred on	16.5. 2019 (date)	_along =	THE ST SE		
	nicle number(s)				("the other party").
madania					
/We further	authorised the v	vorkshop to	settle my at	ove mentione	d claim in a manner that
					ment further to settlement
of my claim	with payment ch	eque(s) bei	ng made in t	avour of the w	orkshop.
Title from	s selenaudadea th	at any cottl	nmont the w	adichon mai e	asah an mu hahalf ir an
The second second					each on my behalf is on
a without pr	ejudice and with	out admissi	on of liability	basis insofar	as the driver / owner /
insurers of t	the other vehicle	(s) Is concer	med.		
	e case could not i				d Think One Autocare to iled,
proceed wit		CINIC Des	1.46		
	WILL BUTE LEA	12//// 1-7/6	170		
I/We 7H	HINK ONE LEA			d by Think One	agreed and will bear / pa
I/We 7F				d by Think One	agreed and will bear / page Autocare Pte Ltd
I/We 7F				d by Think One	
I/We 7/1 all the repa		al fees costs	due inccure	Deline Delinionation	Autocare Pte Ltd
I/We 7F		al fees costs	due inccure	Deline Delinionation	
I/We 7/1 all the repa		al fees costs	due inccure	Deline Delinionation	Autocare Pte Ltd
I/We 7F all the repa		al fees costs	May	(month)	20 19 (year)
I/We 7F all the repa		al fees costs	May	(month) Think One Au	20 19 (year)
I/We 7F all the repa		al fees costs	May	(month) Think One Au	20 19 (year)
I/We 7/1 all the repa		al fees costs	May	(month) Think One Au	20 /9 (year)
I/We 7/1 all the repa		al fees costs	May	(month) Think One Au	20 /9 (year)
I/We 7H all the reparation of		(day) of	May	(month) Think One Au 18 Defu La Singapo Tel: 6844 3300	20 /9 (year)

# RELEASE VOUCHER (AIG Asia Pacific - Express Third Party Claim)

"We/I, THINK ONE AUTOCARE PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for \$\frac{\\$5\\$786.99}{\\$6\\$99} (Repair Cost), \$\frac{\\$5\\$267.50}{\\$6\\$000} (Loss of Rental/Use), \$\frac{\\$5\\$2.00}{\\$000} (Disbursement), for vehicle no. \$\frac{\\$YP}{\\$5\\$5\\$1P} that was damaged pursuant to the accident which occurred on \$\frac{16\\$05\\$2019}{\\$6\\$1000} (date) along \$\frac{\\$COYANG ROAD}{\\$6\\$1000} (location) involving vehicle no/s \$\frac{\\$SLE 5137M}{\\$6\\$1300}. This is pursuant to the inspection conducted on \$\frac{28\\$05\\$2019}{\\$6\\$1000} (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner <u>THINK ONE LEASING PTE LTD</u> ("the third party claimant") of vehicle no. <u>YP 5051P</u> make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to <u>YP</u> 5051P (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 29th (day) of July. (month) 2019 (year)

Signed by appointed surveyor

Think One Autocare Pte Ltd

18 Defu Lane Avenue 2

Singapore 539522

Tel: 6844 3300 Fax: 6862 4988

Signed by "the workshop" (with chop)



Attn

Tel

HP

# THINK ONE AUTOCARE PTE LTD

RCB: 201322501G GST: 201322501G No 18 Defu Avenue 2. Singapore 539522 Tel: (65)6844 3300 Fax: (65)6842 4988 Email: enquiry\_autocare@thinkone.com.sg

: AIG ASIA PACIFIC INSURANCE PTE LTD

Address: 78 SHENTON WAY #07-16

: 6419 - 3000

:6419 - 3000

SINGAPORE 079120

Invoice Ref : JO201907-0365

Date : 23/07/2019

: YP5051P Vehicle Num

Make/Model : UD MKB8ELN

: NSP

Mileage(km) : 0.00

Staff ID

Remarks/Ref :

S/N Unit Price Disc % Description Oty Amount SS FINAL REPAIR BILL 1,471.00 0.00 1,471.00

Fax: 64153723

E & O.E.

SUB TOTAL

1,471.00

102.97

GST 7%

102.97

TOTAL SGD

1,573,97

Think One Autocare Pte Ltd 18 Defu Lane Avenue 2 Singapore 539522

Tel: 6844 3300 Fax: 6842 4988





Attu Tel

HP

# THINK ONE LEASING PTE LTD

Fax:

(of Think One Group of Companies)
20 Ubi Road 4 #02-06 Think One Building Singapore 408622
Tel: (65) 6844 3300 24/7 roadside asst: 9678 8488 Fax: +65 6844 4164 Email: <a href="mailto:mfo@tol.com.sg">mfo@tol.com.sg</a> Website: www.tol.com.sg
ROC No.: 201115609M GST Reg No.: 20-1115609M

BILL TO : AIG ASIA PACIFIC INSURANCE PTE LTD

Address: 78 SHENTON WAY #07-16

SINGAPORE 079120

: MOTOR CLAIMS DEPT

Invoice Ref : JO201638-3122 Date : 23/07/2019

Vehicle Num : YN5559C

Make/Model : NISSAN UD TRUCK

Mileage(km) : 0.00

Staff ID : MICHAEL

Remarks/Ref

 
 S/N
 Description
 Qty
 Unit Price
 Disc %
 Amount SS

 1
 BEING RENTAL OF NISSAN UD TRUCK YN5559C FOR 2DAYS FROM 28.5, 2019 TO 30.5, 2019
 2
 250.00
 0.00
 500.00

E & O.E.

SUB TOTAL

500.00

GST 7%

35.00

TOTAL SGD

535.00





Think One Leasing Pte Ltd
(of Think One Group of Companies)
20 Ubi Road 4 #02-06 Think One Building Singapore 408622
Tel: +65 6844 3300 24/7 roadside asst: 9678 8488 Fax: +65 6844 4164 Ensail: info@tol.com.sg Website: www.tol.com.sg

ROC No.: 201115609M GST Reg. No.: 20-1115609M

Date: 27-5-2019 .

#### QUOTATION NO:

## LEASING AGREEMENT NO: HA/

#### SCHEDULE

This is a lessing Agreement made between us. THINK ONE LEASING PTE LTD (hereinafter referred to as "TOL" which shall include its successors-in-title and assigns), identified as the Lessor and having our registered address 20, UBI ROAD 4 #02-06 THINK ONE BUILDING, SINGAPORE 408622

	1MA)	RC/RB No: 51791962 H	
Address: BIK 864 JURON	19 WEST 5781 #1	03-519 STARE 640 86	4
		Person in Charge:	
Name of Driver (1) (in full): AS A	BOVE	NRIC/Passport No:	Date of Birth: 12-4. 1967
Driving Licence No. \$17919	62H	Issue/Expiry Date: 29.6 - 20 [ (	Country of Issue: SPORE
Name of Driver (2) (in full):		NRIC/Passport No:	Date of Birth:
Driving Licence No:		Issue/Expiry Dute:	Country of Issue:
1. DESCRIPTION OF VEHICLE (	"THE VEHICLE")		
Registration No: YN 5559 C	Make/Model UD TRUC	Colour: Engine N	la:
Chassis No:		senger / Commercial* Spare Tyre: Y / N*	CD/DVD Player: Y / Nº
CHINESIDE CONT.	placement For		
Collection Date / Time and Mileage: 28-5-2019 (une) 7-00			
			(hine) (minage)
Petrol Out: Empty / 1/4 tank / 1/2 tank / 3	/4 tank / Full* (Vehicle must )	be returned with same level of petrofy	
LEASE CHARGES FOR RENTAL	L OF VEHICLE	nencement Date") to 30.5, 2019 ("L	
("Monthly Lease Charges")	_ per month including/exclud	ing* Vehicle Parking Certificates ("VPC") e	actude Goods and Services Tax ("US1
Note: The above Monthly Lease Char at least 2 weeks in advance before the will be charged accordingly.	rges are for rental of the Vehicle e most tax for the Vehicle exp	le only. Where Monthly Lease Charges do no irea, failing which TOL will purchase the VP	t include VPC, you are to submit the VI C on your behalf at market price and you
L DEPOSIT			
		of Monthly Lease Charge exclusive of GS	T)
Cush/Cheque*	Date: _		
<ol> <li>INSURANCE Subject to the payment of the Excess claims (unlimited), and (b) Third Part Excess Amount: S5 200 : 01</li> </ol>		insurance for the rental of the Vehicle will or um of \$\$500,000.00), Additional charges will in Signature.	nly cover (a) Third Party injury and dea il apply for additional insurance coverag
		(per air side) Others	(specify); S\$
		for Commercial Vehicles. 20,000 km/year	
			for Passenger Vehicles. Addition charg
6. MAXIMUM MILEAGE Maxim	Additional 10,000 km or part thereof	Type of Vehicle	
<ol> <li>MAXIMUM MILEAGE Maximu (see below):-</li> </ol>	Additional 10,000 km or part thereof \$\$500.00 \$\$700.00 \$\$900.00		Additional 10,000 k or part thereof \$\$1,100.00 \$\$1,400.00
6. MAXIMUM MILEAGE Maxim (see below):- Type of Vehicle  (a) Life Style Van / Goods Van / Panel Van / 10 ft Lorry (b) 14 ft Lorry (c) 24 ft 6 Ton Lorry (d) 24 ft 10 Ton Lorry / Prime Move	Additional 10,000 km or part thereof \$\$500.00 \$\$700.00 \$\$900.00 \$\$1.200.00	Type of Vehicle  (e) Passenger Vehicle below 1,6cc (f) Passenger Vehicle 1,6cc to 1,99cc	Additional 10,000 k or part thereof S\$1,100.00 S\$1,400.00 S\$2,500.00
6. MAXIMUM MILEAGE Maxim (see below):-  Type of Vehicle  (a) Life Style Van / Goods Van / Panel Van / 10 ft Lorry (b) 14 ft Lorry (c) 24 ft 6 Ton Lorry (d) 24 ft 10 Ton Lorry / Prime Move The Agreement herein comprises the sel and agreed to the terms of this Agreem	Additional 10,000 km or part thereof  \$\$500.00 \$\$700.00 \$\$900.00 \$\$1,200.00 hedule above and the Terms ent. IN WITNESS whereof	(e) Passenger Vehicle below 1.6cc (f) Passenger Vehicle 1.6cc to 1.99cc (g) Passenger Vehicle 2.0cc and above	Additional 10,000 k or part thereof S\$1,100.00 S\$1,400.00 S\$2,500.00
6. MAXIMUM MILEAGE Maxim (see below):- Type of Vehicle  (a) Life Style Van / Goods Van / Panel Van / 10 ft Lorry (b) 14 ft Lorry (c) 24 ft 6 Ton Lorry (d) 24 ft 10 Ton Lorry / Prime Move	Additional 10,000 km or part thereof  \$\$500.00 \$\$700.00 \$\$900.00 \$\$1,200.00 hedule above and the Terms ent. IN WITNESS whereof	Type of Vehicle  (e) Passenger Vehicle below 1,6cc (f) Passenger Vehicle 1,6cc to 1,99cc (g) Passenger Vehicle 2,0cc and above and Conditions annexed hereto. The Hire the Parties hereto have set their hands the	Additional 10,000 k or part thereof \$\$1,100.00 \$\$1,400.00 \$\$2,500.00

"delete where inapplicable



# GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffies Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm GST Registration No: M400017735

# Third Party Insurer Enquiry

Our Ref No:

GR-19-078287

Date of Request:

16/05/2019

Your Ref No:

Online Purchase

Think One Autocare Pte Ltd No. 18 Defu Avenue 2 Singapore 539522

Dear Sir/Madam,

**Enquiry Date** 

16/05/2019

Enquiry By

Tan Hui Kiang Karen

TP Vehicle No.

SLE5137M

Accident Date

16/05/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLE5137M	AIG Asia Pacific Insurance Pte. Ltd.	25/07/2018-24/07/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm

RECORDS MANAGEMENT CENTRE

GST Registration No: M400017735

# TAX INVOICE

Our Ref No:

GR-19-078287

Date of Request:

16/05/2019

Your Ref No:

GENERAL INSURANCE ASSOCIATION OF SINGAPORE

Online Purchase

Think One Autocare Pte Ltd No. 18 Defu Avenue 2 Singapore 539522

Dear Sir/Madam.

**Enquiry Date** 

16/05/2019

Enquiry By

Tan Hui Kiang Karen

TP Vehicle No.

SLE5137M

Accident Date

16/05/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

[X] GIRO [] Cash [] Cheque

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj:	Submitted	Ins Auth'ed	Status	
Main	22 May 2019 Edit Reg	May 2019 2		S\$1,471.00 Edit Estimates	1,471.00 S\$1, Edit Estimates Vie			Pending for Report Cancel Case	Survey
	Main	R	eference	Claim I	etalls		Document		Show All
CLAIM SU	BFOLDER DE	TAILS				[Created	by adjuster]		
Insured:	SIM CHO	ON YEN GINA,	ID: 57438175H						
Main Claimant:	THINK OF	NE LEASING PTE	LTD, Co. Reg. No	a.: 201115609M					
Vehicle Req No.:	YP5051	Р		Date	of Loss:	16/05/2019 [29 Months	9 00:00 - :59 s and 9 Days Fro	m LTA Reg Date (M	an Yr)]
Claim Type	TP / 246	TP / 2464660270SG		Polici Note	/Cover No.:	(Comprehe	nsive)		
Vehicle Reg No. (Insured):	SLE5137	4		Policy (Clair	No. nant):	5107728339			
				Exce	ss:				
Repairer:			td (HQ) No. 18 De						
Handling Insurer:		Pacific Insuranc lan.Ler@aig.com	e Pte. Ltd. (Expre	ss) - Tel: 65-6419	-3000	. [Handled b	y Ler, Bernard-	JQ]	
Claimant's Insurer:	720000.000000		Co-operative Ltd (						
Adjuster:	LKK Auto	Consultants Pto	Ltd (HQ) - Tel; 62	56-3561 [Hand	fied by M	ARCUS CHI	JA] [Final R	pt due 03/06/2	019]
ASSOCIA	TED MAIL RE	CEIVED					Vi	ew All Composi	Case Mail
AlG_SG	(24/05/2019)	Request To Up	load TP GIA Repo	t					
ALL ASSO	CLATED TAS	KSE				View All	Search Tasks	Create New Task	Complete
Due Dat	e Priority	NATURE OF THE PARTY OF THE PART	Group Subje	ct Handler	Assign	.,	Completed On		1000000

### Claim Documents

\*YP5051P (24646602705G) [SLE5137M]
TP
THINK ONE LEASING PTE LTD May 16 2019 12:00AM [SIM CHOON YEN GINA] Think One Autocare Pte Ltd

Vide	eo		1 per	page 🔻	80
Nio	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Prin
1	25/07/19 11:16	Video - Accident From:OD - Reg. No: SLES137M, Claimant: SIM CHOON YEN GINA	0	Load MP4	
Lett	ters/Corresponder	ices	1 per	page 🔽	82
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
1	(Draft)	Third Party Express Settlement - Payment Breakdown	0	Edit	1
Pho	otos/Images		3 per	page 🔽	<b>V</b>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	National	Thumbnail	-
1	22/07/19 08:47	Chassis Number	0	Load 3PG	Z
2	22/07/19 08:47	Odometer Reading	0	Load 3PG	Ø
3	22/07/19 08:48	General View	0	Load JPG	Ø
4	22/07/19 08:48	General View	0	Load JPG	W
		Novel Department (Internal Control	0	Load JPG	V
5	22/07/19 08:48	General View	0	Load JPG	12
6	22/07/19 08:48	General View			
7	22/07/19 08:48	General View	0	Load JPG	120
8	22/07/19 08:48	General View	0	Load JPG	M
9	22/07/19 08:48	General View	0	Load JPG	M
10	22/07/19 08:48	General View	0	Load JPG	V
11	22/07/19 08:48	General View	0	Load JPG	2
12	22/07/19 08:48	General View	0	Load JPG	12
13	22/07/19 08:48	General View	0	Load JPG	N
14	22/07/19 08:48	General View	0	Load JPG	
15	22/07/19 08:48	General View	0	Load JPG	
16	22/07/19 08:48	General View	0	Load JPG	
17	22/07/19 08:48	General View	0	Load JPG	V
18	22/07/19 08:48	General View	0	Load JPG	12
1427	and the second s	General View	0	Load JPG	W
19	22/07/19 08:48	100 m (100 m) 100 m (100 m)	0	Load JPG	V
20	22/07/19 08:48	General View		- CARRIER SE	12
21	22/07/19 08:48	General View	0	Load JPG	-
22	22/07/19 08:48	General View	0	Load JPG	8
23	22/07/19 08:48	General View	0	Load JPG	80
24	22/07/19 08:48	General View	0	Load JPG	V
25	22/07/19 08:48	Reinspection Photo	0	Load JPG	82
26	22/07/19 08:48	Reinspection Photo	0	Load JPG	N
Doc	cumentation		1 per	page 🔽	Ø
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnall	-
1	23/05/19 15:13	EMAIL FROM AIG DD 22052019	0	Load PDF	
2	23/05/19 15:13	WKSP NOTICE	0	Load PDF	
3	29/05/19 18:02	TP ESTIMATE- MARKED	0		-
4	29/05/19 18:02	TP GIA REPORT	0	Load PDF	-
5	25/07/19 09:51	TP ESTIMATE - FINALIZED	0	+	+
6	25/07/19 10:25	WORKSHOP INVOICE	6	Load PDF	-
7 B	27/09/19 11:49	AUTHORISATION TO ACT FORM	0	Load PDF	
M.	27/09/19 11:49	Release Voucher	ő	Load PDF	-

Vide	eo		1 per page:		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbr	nail Print	
10	27/09/19 11:49	RENTAL RECEIPT	Load Pt	OF.	
11	27/09/19 11:49	LOD	8 Load PC	DF	
12	27/09/19 11:49	GIA SEARCH	■ Load Pt	DF.	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (5G)	Thumbr	nail Print	
1	24/05/19 10:50	OI GIA REPORT	■ Load Pi	DF T	

## **Documents Checklist**

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Handling Insurer  Note: Remarks are private unless you show it to other parties.	

NOTE:	TO BE	COMPI	ETED	BY	SURVEYOR

TEAM		

## THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	_	SLE5137M (Insd veh)		Model:		UD TRUCKS MKB8ELN5AA
	YP5051P					7.0 D (M)
Date of Accident:	16/05/2019	9				
					_	
Global Sum Settler	nent : [	] Yes		[X] No	10700	
Repair Estimate			: \$		36.36	
Final Repair Cost			: \$	78	36.99	
Loss of Use			: \$			days at \$0.00 per day
Rental (if any)			: \$	20	37.50	2 days
LTA / GIA Search f	ee		: \$		2.00	
Others:			: \$		0.00	
			: \$			
Final Settlement St	um		\$	1,0	56.49	
Is Third Party Woo below)		20.00.700.27.00	ir .	180 8	- 17	X ] NO (Kindly indicate
A) For Non GIA F	Registered V	Norkshop:		Agreed L		50(%)
B) For GIA Regis	tered Work	shop:		BOLA Ap	plicable	Yes/ No BOLA Scenario No:
BOLA Liability						y (*):(%)
* Assessed Lia	bility to be f	illed only for	cha	in collisions a	nd for c	ases where BOLA does not apply
Remarks						
Payment Instructi	on: Payee's	Breakdow	n		0	
1) Think One Au	tocare Pte L	td			5	1,056.49
2)				:3	5	
3)				: 5	5	
JOANNE	LEE KHANG	MIN		27 Sep 2019		
LKK Auto C	Consultants F	Pte Ltd		Date	-	

Please attach all the supporting documents to the form. (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any)

### LKK Auto Consultants Pte Ltd (Co. Reg. No:199807198R)

51 Ubi Ave 1 #01-25. Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19009080/UHB3Q2

Date:

27/09/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No:

YP5051P

Insured Vehicle No: SLE5137M

Date of Loss:

16/05/2019

Nature of Claim:

TP

Claim No: 2464660270SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

YP5051P

Make & Model:

UD TRUCKS MKB8ELN5AA, 7.0 D (M)

Engine No:

GH7210180

Reg. Date:

07/12/2016 (Man. Year. 2016)

Chassis No: Odometer:

JNCL0D0A9GU007149 103014 km

Colour Engine Capacity: White

7013 cc

Market Value/New Car

Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: Front Left Side:

285/75 R17.5 Double Coin 6 mm

Rear Tyre Size: Rear Left Side:

Rear Right Side:

285/75 R17.5 (D) Double Coin 6/6 mm Double Coin 6/6 mm

Double Coin 6 mm Front Right Side: The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		15,670.80	651.00	15,019.80	95.85
Miscellaneous Items		0.00	0.00	0.00	
Labour		6,980.00	820.00	6,160.00	88.25
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	22,650.80	1,471.00	21,179.80	93.51
	+ GST 7.00/7.00% (S\$)	1,585.56	102.97	1,482.59	93.51
	Nett Amount (S\$)	24,236.36	1,573.97	22,662.39	93.51
			The second second		

+ Car Rental (2.0 x S\$250.00/day + 7.00% GST) (S\$) 535.00

> 2,108.97 (S\$)

1,054,49 Liable Amount (50.00%) (S\$) 2.00 + Doc/Search Fee (S\$)

> Nett Liability (S\$) 1,056.49

INSPECTION

Date of Assignment:

22/05/2019

Date Inspected:

28/05/2019 Inspected At:

Think One Autocare Pte Ltd (HQ)

No. 18 Defu Avenue 2 Singapore 539522

Estimated Period of Repair.

2.0 days

Adjuster: MARCUS CHUA Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

# Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	7-2-11-2-2	*FRONT BUMPER ASSY (OUTER)	Not Necessary	1,678.00 FL	*-FL
2	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	392.00 FL	*-FL
3	1		*FRONT BUMPER REINFORCEMENT LEFT SIDE BRACKET	Not Necessary	125.00 FL	*-FL
4	1		*FRONT BUMPER LEFT BRACKET	Not Necessary	91.00 FL	*-FL
5	1		*FRONT BUMPER LEFT SIDE STAY	Not Necessary	149.00 FL	*-FL
6	1		*FRONT GRILLE ASSY	Not Necessary	552.00 FL	*-FL
7	1		*FRONT LEFT CORNER PANEL	Not Necessary	832.00 FL	*-FL
8	1		*FRONT LEFT HEADLAMP	Not Necessary	1,280.00 FL	*-FL
9	1		*FRONT LEFT HEADLAMP BRACKET	Not Necessary	220.00 FL	*-FL
10	1		*FRONT LEFT HEADLAMP HOLDER	Not Necessary	65.00 FL	*-FL
11	1		*FRONT LEFT HEADLAMP WIRE HARNESS	Not Necessary	650.00 FL	*-FL
12	1		*FRONT LEFT SIGNAL LAMP	Scratched	185.00 FL	*185.00 FL
13	1		*FRONT LEFT STEP GARNISH (UPPER)	Not Necessary	675.00 FL	*-FL
14	1		*FRONT LEFT STEP GARNISH (LOWER) (CRACKED)	Not Consistent With The Impact	695.00 FL	*-FL
15	1		*FRONT LEFT FOOT STEP (UPPER)	Not Necessary	393.00 FL	*-FL
16	1		*FRONT LEFT FOOT STEP (LOWER)	Not Necessary	393.00 FL	*-FL
17	1		*FRONT LEFT STEP GARNISH BRACKET	Not Necessary	98.00 FL	*-FL
18	1		*FRONT LEFT STEP GARNISH REFLECTOR	Not Necessary	98.00 FL	*-FL
19	1		*FRONT LEFT DOOR PANEL ASSY	Repair	3,675.00 FL	*-FL
20	4		*FRONT LEFT DOOR MK 11250 EMBLEM	Not Necessary	180.00 FL	*-FL
21	2		*FRONT LEFT DOOR HINGES	Not Necessary	265.00 FL	*-FL
22	1		*FRONT LEFT DOOR LOCK	Not Necessary	195.00 FL	*-FL
23	1		*FRONT LEFT DOOR WEATHERSTRIP	Not Necessary	388.00 FL	*-FL
24	1		*FRONT LEFT DOOR INNER INSULATION	Not Necessary	260.00 FL	*-FL
25	1		*FRONT LEFT DOOR INNER RUBBER	Not Necessary	128.00 FL	*-FL
26	1		*FRONT LEFT DOOR REGULATOR WITH MOTOR	Not Necessary	495.00 FL	*-FL
27	1		*FRONT LEFT DOOR REFLECTOR	Not Necessary	250.00 FL	*-FL
28	1		*FRONT LEFT DOOR PROTECTOR	Grazed	205.00 FL	*205.00 FL
29	16		*FRONT BUMPER CLIPS	Not Necessary	80.00 FS	*-FS
30	1		*FRONT BUMPER TOP PROTECTOR SEALANT	Not Necessary	80.00 FS	*-FS
31	10		*FRONT GRILLE CLIPS	Not Necessary	60.00 FS	*-FS
32	8		*FRONT LEFT DOOR INNER INSULATION CLIPS	Not Necessary	30.00 FS	*-FS
33	8		*FRONT LEFT FENDER INNER SHIELD CLIPS	Not Necessary	40.00 FS	
34	1		*SET FRONT LEFT DOOR STICKER	Necessary	350.00 FS	*300.00 FS
35	1		*FRONT LEFT WHEEL RIM	Not Necessary	1,200.00 FS	*-FS
36	1		*FRONT LEFT TYRE	Not Necessary	600.00 FS	*-FS
37	1		*FRONT NO PLATE	Not Necessary	80.00 FS	*-F8
F≈Fn	anchise	part. S=	SpcNett. L=ListttemDisc.	Sub Total (S\$)	17,132.00	690.00
			- List Item Discount on I	Litems 10.00/10.00% (S\$)	1,461.20	39.00
				Total Parts (S\$)	15,670.80	651.00

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN FRONT LEFT AFFECTED AREA AND REPLACE FRONT LEFT DAMAGED PARTS	New	3,000.00	400.00
2	TO PUTTY AND SPRAY PAINTING FRONT LEFT AFFECTED PORTION	New	3,000.00	400.00
3	TO REMOVE AND INSTALL FRONT LEFT DOOR LOCK MECHANISM	New	250.00	0.00
4	TO CHECK DOOR CENTRAL LOCKING FOR FUNCTION	New	80.00	0.00
5	TO APPLY ANTI RUST PROOFING TO FRONT LEFT AFFECTED AREA	New	150.00	0.00
6	TO TRANSFER FRONT LEFT DOOR GLASS TO NEW DOOR	New	120.00	0.00
7	TO CHECK WIRING AND FOCUS FRONT HEADLAMP	New	50.00	20.00
8	TO BALANCE FRONT LEFT TYRE	New	80.00	0.00
9	TO CONDUCT WHEEL ALIGNMENT	New	250.00	0.00
	Gross Labo	ur Cost (S\$)	6,980.00	820.00
	Report was unsubmitted dur	ing this print-out.		

< END OF ESTIMATES >