

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 May 2019		24 May 2019 10:49 Edit Adj Rpt	S\$14,600.00 Edit Estimates	S\$14,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	-, Co. Reg. No.: -	
Main Claimant:	RASIDAH BINTE MOHAMAD SHAH , ID: S1592573F	
Vehicle Reg. No.:	SMD7812C	Date of Loss: 22/05/2019 12:00 - :59 [8 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D202300C02	Policy/Cover Note No.: DMB1SN30900118011
Vehicle Reg. No. (Insured):	CB6132S	Policy No. (Claimant): SD18V09559
		Excess: S\$0.00
Repairer:	Ace Autolution Pte Ltd (KAKI BUKIT) 13 Kaki Bukit Road 4, #03-29/30 Bartley Biz Centre, 417807 Kaki Bukit - Tel: 68441184	
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]	
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 04/06/2019]	
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail
There are no mail for this case.		
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete
Due Date	Priority	Type
Task Group	Subject	Handler
Assigned By	Completed On	Created On
Done?		
No results.		

Claim Documents

***SMD7812C (SNM19D202300C02)**
[CB6132S]
TP
RASIDAH BINTE MOHAMAD SHAH
May 22 2019 12:00PM
[-]
Ace Autolution Pte Ltd

View ▼

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	22/05/19 15:31	Accident Statement	Load HTM	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	22/05/19 15:30	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	22/05/19 15:30	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	22/05/19 15:30	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	22/05/19 15:30	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	22/05/19 15:30	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	22/05/19 15:30	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
2	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
3	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
4	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
5	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
6	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
7	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
8	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
9	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
10	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
11	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
12	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
13	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
14	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
15	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
16	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
17	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
18	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
19	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
20	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
21	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
22	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
23	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
24	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
25	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
26	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
27	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
28	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
29	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
30	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
31	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
32	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
33	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
34	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
35	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
36	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
37	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
38	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
39	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
40	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
41	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
42	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
43	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
44	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
45	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
46	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
47	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
48	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
49	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
50	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
51	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
52	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
53	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
54	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
55	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
56	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
57	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
58	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
59	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
60	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
61	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
62	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
63	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
64	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
65	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
66	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
67	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
68	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
69	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
70	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
71	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
72	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
73	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
74	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
75	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
76	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
77	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
78	19/05/20 12:28	General View	Load JPG	<input checked="" type="checkbox"/>
79	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
80	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
81	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
82	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
83	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
84	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
85	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
86	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
87	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
88	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
89	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
90	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
91	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
92	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
93	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
94	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
95	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
96	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
97	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
98	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
99	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
100	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
101	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
102	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
103	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
104	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
105	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
106	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
107	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
108	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
109	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
110	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
111	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
112	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
113	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
114	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
115	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
116	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
117	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
118	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
119	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
120	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
121	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
122	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
123	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
124	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
125	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
126	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
127	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
128	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
129	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
130	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
131	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
132	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
133	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
134	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
135	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
136	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
137	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
138	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
139	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
140	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
141	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
142	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
143	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
144	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
145	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
146	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
147	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
148	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
149	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
150	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
151	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
152	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
153	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
154	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
155	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
156	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
157	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
158	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
159	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
160	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
161	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
162	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
163	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
164	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
165	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
166	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
167	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
168	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
169	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
170	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
171	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
172	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
173	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
174	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
175	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
176	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
177	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
178	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
179	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
180	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
181	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
182	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
183	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
184	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
185	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
186	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
187	19/05/20 12:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)		Thumbnail Print
188	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
189	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
190	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
191	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
192	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
193	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
194	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
195	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
196	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
197	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
198	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
199	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
200	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
201	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
202	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
203	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
204	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
205	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
206	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
207	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
208	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
209	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
210	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
211	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
212	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
213	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
214	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
215	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
216	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
217	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
218	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
219	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
220	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
221	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
222	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
223	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
224	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
225	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
226	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
227	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
228	19/05/20 12:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	24/05/19 10:49	pri contact		Load PDF <input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)		Thumbnail Print
1	22/05/19 15:28	Sketch Plan [Linked Accident Report Documents]		Load TIF <input checked="" type="checkbox"/>
2	22/05/19 15:28	Sketch Plan #2 [Linked Accident Report Documents]		Load TIF <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	28/05/20 08:18	SUPPLEMENTARY		Load PDF <input checked="" type="checkbox"/>

Linked Accident Report Documents

View [View in Browser](#) ▼

Assessment Reports				1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)		Thumbnail	Print
1	04/09/19 01:03	Accident Statement		Load HTM	

Photos/Images				3 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)		Thumbnail	Print
1	22/05/19 15:30	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	22/05/19 15:30	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	22/05/19 15:30	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	22/05/19 15:30	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	22/05/19 15:30	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	22/05/19 15:30	Accident Photo		Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)		Thumbnail	Print
1	22/05/19 15:28	Sketch Plan		Load TIF	
2	22/05/19 15:28	Sketch Plan #2		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI19009081/AQD3S2**Date:** 28/05/2020REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SN30900118011		
Claimant Vehicle No :	SMD7812C	Insured Vehicle No :	CB6132S		
Date of Loss:	22/05/2019	Nature of Claim:	TP	Claim No:	SNM19D202300C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD7812C		Engine No:	2ZR8284022
Make & Model:	TOYOTA C-HR, 1.8 HYBRID ICON/DYNAMIC (A)		Chassis No:	ZYX102091656
Reg. Date:	04/09/2018 (Man. Year: 2017)		Odometer:	27619 km
Colour:	Silver			
Engine Capacity:	1797 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,863.05	14,996.50	17,866.55	54.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,400.00	3,310.00	2,090.00	38.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	38,263.05	18,306.50	19,956.55	52.16
Approved Total (Overridden) (S\$)		14,600.00		
Nett Amount (S\$)	38,263.05	14,600.00	23,663.05	61.84

INSPECTION

Date of Assignment:	24/05/2019	
Date Inspected:	23/05/2019 Inspected At:	Ace Autolution Pte Ltd (KAKI BUKIT) 13 Kaki Bukit Road 4, #03-29/30 Bartley Biz Centre Singapore 417807
Estimated Period of Repair:	11.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 27 May 2020)**Parts:** M1-SUV TOYOTA C-HR 1.8 HYBRID ICON/DYNAMIC (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SMD7812C)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,025.00 FL	*930.00 FL
2	1		*FRONT BUMPER GRILLE	Cracked	481.50 FL	*434.00 FL
3	1		*FRONT BUMPER LOWER GRILLE	Deformed	355.00 FL	*355.00 FL
4	1		*FRONT BUMPER CENTRE GRILLE	Deformed	210.00 FL	*210.00 FL
5	1		*FRONT BUMPER REINFORCEMENT BAR	Not Necessary	781.00 FL	*- FL
6	2		*FRONT BUMPER SIDE RETAINER LH & RH	Necessary	270.00 FL	*185.00 FL
7	1		*FRONT BUMPER FOGLAMP RH	Cracked	192.00 FL	*192.00 FL
8	1		*FRONT BUMPER TOW COVER	Not Necessary	85.90 FL	*- FL
9	2		*FRONT BUMPER SIDE COVER LH & RH	Deformed	260.00 FL	*104.00 FL
10	1		*FRONT BUMPER LICENSE INNER GARNISH	Deformed	105.00 FL	*105.00 FL
11	1		*FRONT CENTRE LOGO	Cut	152.00 FL	*152.00 FL
12	1		*FRONT BONNET	Not Necessary	1,852.00 FL	*- FL
13	1		*FRONT BONNET INNER SPONGE	Not Necessary	212.00 FL	*- FL
14	1		*FRONT BONNET LOCK	Not Necessary	199.00 FL	*- FL
15	2		*FRONT HEADLAMP LH & RH	Cracked	3,770.00 FL	*3,770.00 FL
16	2		*FRONT FENDER RH	Repair	880.00 FL	*- FL
17	1		*FRONT FENDER HYBRID EMBLEM	Necessary	73.00 FL	*73.00 FL
18	2		*FRONT FENDER INNER SHIELD LH & RH	Not Necessary	500.00 FL	*- FL
19	1		*FRONT SUPPORT PANEL	Repair	1,114.00 FL	*- FL
20	1		*FRONT HON	Not Necessary	143.00 FL	*- FL
21	1		*FRONT RADIATOR	Not Necessary	1,115.00 FL	*- FL
22	1		*FRONT A/C CONDENSER	Not Necessary	1,315.00 FL	*- FL
23	1		*REAR TAILGATE	Distorted	1,180.00 FL	*1,180.00 FL
24	2		*REAR TAILGATE HINGE LH & RH	Not Necessary	170.00 FL	*- FL
25	1		*REAR TAILGATE LOCK	Damaged	412.50 FL	*412.50 FL
26	1		*REAR TAILGATE LOCK HANDLE	Not Necessary	95.00 FL	*- FL
27	2		*REAR TAILGATE DAMPER LH & RH	Not Necessary	700.00 FL	*- FL
28	1		*REAR TAILGATE CENTRE PANEL GARNISH	Cracked	745.00 FL	*661.00 FL
29	1		*REAR TAILGATE CENTRE PANEL TOP COVER	Missing	321.00 FL	*195.00 FL
30	1		*REAR TAILGATE CHR EMBLEM	Necessary	87.00 FL	*55.00 FL
31	1		*REAR TAILGATE HYBRID SYNERGY DRIVE EMBLEM	Necessary	95.00 FL	*65.00 FL
32	1		*REAR TAILGATE LOGO	Necessary	75.00 FL	*75.00 FL
33	1		*REAR TAILGATE UPPER SPOILER	Cracked	453.00 FL	*453.00 FL
34	1		*REAR TAILGATE THIRD BRAKE LAMP	Not Necessary	155.00 FL	*- FL
35	1		*REAR TAILGATE WEATHERSTRIP	Cut	375.00 FL	*375.00 FL
36	1		*REAR TAILGATE INNER BOARD	Cracked	594.00 FL	*594.00 FL
37	2		*REAR TAILGATE CAR PLATE LAMP LH & RH	Not Necessary	191.20 FL	*- FL
38	2		*REAR TAILGATE LAMP LH & RH	Cracked	1,620.00 FL	*707.00 FL
39	1		*REAR TAILGATE WIPER	Not Necessary	111.00 FL	*- FL
40	1		*REAR TAILGATE WIPER MOTOR	Not Necessary	321.00 FL	*- FL
41	1		*REAR BUMPER	Distorted	1,071.00 FL	*948.00 FL
42	1		*REAR BUMPER LOWER	Distorted	644.00 FL	*475.00 FL
43	1		*REAR BUMPER REINFORCEMENT	Bent	782.10 FL	*398.00 FL
44	1		*REAR BUMPER TOW COVER	Missing	95.00 FL	*55.00 FL
45	2		*REAR BUMPER SIDE RETAINER LH & RH	Necessary	243.00 FL	*170.00 FL
46	2		*REAR BUMPER REFLECTOR LH & RH	Not Necessary	620.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	2		*REAR BUMPER REFLECTOR COVER LH & RH	Deformed	202.00 FL	*202.00 FL
48	1		*REAR BUMPER LOWER LAMP	Cracked	410.00 FL	*125.00 FL
49	1		*REAR END PANEL	Dented	890.00 FL	*725.00 FL
50	1		*REAR END PANEL TOP GARNISH	Cracked	275.00 FL	*275.00 FL
51	1		*REAR SPARE TYRE PANEL	Repair	985.00 FL	*- FL
52	1		*REAR SPARE TYRE PANEL TOP BOARD	Deformed	559.00 FL	*385.00 FL
53	1		*REAR SPARE TYRE PANEL SPONGE TRAY	Deformed	441.00 FL	*299.00 FL
54	2		*REAR SIDE SPONGE RR FLOOR LH & RH	Deformed	796.00 FL	*410.00 FL
55	2		*REAR UPPER & LOWER SPACER FLOOR LH & RH	Not Necessary	862.00 FL	*- FL
56	1		*REAR CHASSIS MEMBER RH	Repair	1,015.00 FL	*- FL
57	2		*REAR TAILLAMP LH & RH	Cracked	1,480.40 FL	*1,250.00 FL
58	1		*REAR EXHAUST SILENCER	Not Necessary	980.00 FL	*- FL
59	1		*REAR EXHAUST SILENCER MOUNTING	Not Necessary	70.00 FL	*- FL
60	1		*REAR EXHAUST SILENCER CHROME	Not Necessary	98.00 FL	*- FL
61	1		*REAR EXHAUST HEAT COVER	Not Necessary	168.30 FL	*- FL
62	1		*REAR ROOF	Repair	1,215.90 FL	*- FL
63	2		*REAR FENDER RH	Repair	930.10 FL	*- FL
64	2		*REAR FENDER INNER BOARD LH & RH	Cracked	1,592.60 FL	*844.00 FL
65	1		*REAR FENDER AIR VENT RH	Not Necessary	127.40 FL	*- FL
66	1		*REAR WINDSCREEN MOULDING	Necessary	320.00 FL	*185.00 FL
67	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
68	1		*SET FRONT BONNET INSULATOR CLIPS	Not Necessary	100.00 FS	*- FS
69	1		*SET FRONT CAR PLATE WITH HOLDER	Cracked	70.00 FS	*50.00 FS
70	1		*COOLANT	Not Necessary	100.00 FS	*- FS
71	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
72	1		*REVERSE CAMERA	Not Necessary	410.00 FS	*- FS
73	1		*SET REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
74	1		*SET REAR CAR PLATE WITH HOLDER	Bent	320.00 FS	*30.00 FS
75	1		*SET REAR TAILLAMP CLIPS	Necessary	100.00 FS	*20.00 FS
76	1		*SET REAR TAILGATE INNER BOARD CLIPS	Necessary	80.00 FS	*30.00 FS
77	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	80.00 FS	*10.00 FS
78	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
79	1		*REAR WINDSCREEN INNER SEAL	Necessary	100.00 FS	*40.00 FS
80	1		*REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
81	1		*SET FRONT BUMPER SENSORS	Damaged	280.00 FS	*200.00 FS
82	1		*SET SPARE TYRE PANEL SOUND INSULATION	Necessary	280.00 FS	*200.00 FS
83	1		*FRONT BUMPER UPPER SPONGE	Deformed	89.80 FL	*89.80 FL
84	1		*FRONT BUMPER LOWER SPONGE	Deformed	87.20 FL	*87.20 FL
85	1		*FRONT SUPPORT PANEL TOP COVER	Cracked	195.90 FL	*195.90 FL
86	1		*TAILGATE LOCK COVER	Cracked	29.40 FL	*29.40 FL
87	1		*TAILGATE LOCK ANTENNA	Cracked	114.90 FL	*114.90 FL
88	1		*TAILGATE LOCK OPENER SWITCH	Damaged	165.90 FL	*165.90 FL
89	1		*TAILGATE INNER POCKET	Deformed	30.40 FL	*30.40 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	42,957.40	19,682.00
- List Item Discount on L Items 25.00/25.00% (\$)	10,094.35	4,685.50
Total Parts (\$)	32,863.05	14,996.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS.	New	2,200.00	1,500.00
2	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED.	New	1,800.00	1,400.00
3	TO REMOVE, REFIX WIRING SYSTEM AT ACCIDENT DAMAGE AREAS AND CHECK FOR PROPER FUNCTION.	New	150.00	60.00
4	TO REMOVE AND REPLACE WITH CHECK HEADLAMP BEAM.	New	120.00	0.00
5	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS.	New	270.00	100.00
6	CAVITY TREATMENT ON NEW PARTS.	New	120.00	0.00
7	TO TOP UP COOLANT.	New	150.00	0.00
8	TO REMOVE AND REFIX REAR WINDSCREEN.	New	230.00	120.00
9	TO WATER SEEPAGE TEST.	New	120.00	0.00
10	TO TRANSFER REAR BOOT MECHANISM.	New	120.00	80.00
11	TO REMOVE AND REPLACE REVERSE SENSOR.	New	120.00	50.00
Gross Labour Cost (S\$)			5,400.00	3,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >