



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel: 6702 4282 Fax: 6702 4202

21X10251656

Page No. 1

TP China.
Xiao Chen.

Vehicle No. SMD7812C TOYOTA CHR

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (\$)	SURVEYOR ADJUSTMENT
	<u>PARTS (LIST ITEMS)</u>			930.
1	FRONT BUMPER <i>deformed</i>		1025.00	
1	FRONT BUMPER GRILLE <i>cracked</i>		481.50	434
1	FRONT BUMPER <i>Lower</i> GRILLE <i>deformed</i>		355.00	✓
1	FRONT BUMPER <i>CENTRE</i> GRILLE <i>deformed</i>		210.00	✓
1	FRONT BUMPER REINFORCEMENT BAR <i>ntm</i>		781.00	x
2	FRONT BUMPER SIDE RETAINER LH & RH @ \$135.00 <i>Nec</i>		270.00	185
1	FRONT BUMPER FOGLAMP RH <i>cracked</i>		192.00	✓
1	FRONT BUMPER TOW COVER <i>Nec Nec</i>		85.90	x
2	FRONT BUMPER SIDE COVER LH & RH @ \$130.00 <i>deformed</i>		260.00	104.
1	FRONT BUMPER LICENSE INNER GARNISH <i>deformed</i>		105.00	✓
1	FRONT CENTRE LOGO <i>nt</i>		152.00	✓
1	FRONT BONNET <i>ntm</i>		1852.00	x
1	FRONT BONNET INNER SPONGE <i>ntm</i>		212.00	x
1	FRONT BONNET LOCK <i>ntm</i>		199.00	x
2	FRONT HEADLAMP LH & RH @ \$1885.00 <i>cracked</i>		3770.00	✓
2	FRONT FENDER RH <i>Repair</i>		880.00	x
1	FRONT FENDER "HYBRID" EMBLEM <i>new</i>		73.00	✓
2	FRONT FENDER INNER SHIELD LH & RH @ \$250.00 <i>ntm</i>		500.00	x
1	FRONT SUPPORT PANEL <i>Repair</i>		1114.00	x
1	FRONT HON <i>Nec Nec</i>		143.00	x
1	FRONT RADIATOR		1115.00	+
1	FRONT A/C CONDENSER		1315.00	+
1	REAR TAILGATE <i>Distorted</i>		1180.00	✓
2	REAR TAILGATE HINGE LH & RH @ \$85.00 <i>Nec Nec</i>		170.00	x
1	REAR TAILGATE LOCK <i>Damaged</i>		412.50	✓
1	REAR TAILGATE LOCK HANDLE <i>x6 ntm</i>		95.00	+
2	REAR TAILGATE DAMPER LH & RH @ \$350.00 <i>ntm</i>		700.00	+
1	REAR TAILGATE CENTRE PANEL GARNISH <i>cracked</i>		745.00	661
1	REAR TAILGATE CENTRE PANEL TOP COVER <i>Missing</i>		321.00	195
1	REAR TAILGATE "CHR" EMBLEM <i>new</i>		87.00	55
1	REAR TAILGATE "HYBRID SYNERGY DRIVE" EMBLEM <i>new</i>		95.00	65
1	REAR TAILGATE LOGO <i>new</i>		75.00	✓
1	REAR TAILGATE UPPER SPOILER <i>cracked</i>		453.00	✓
1	REAR TAILGATE THIRD BRAKE LAMP <i>new</i>		155.00	+
1	REAR TAILGATE WEATHERSTRIP <i>nt</i>		375.00	✓
1	REAR TAILGATE INNER BOARD <i>cracked</i>		594.00	✓
1	REAR TAILGATE CAR PLATE LAMP LH & RH @ \$95.50 <i>ntm</i>		191.20	x
2	REAR TAILGATE LAMP LH & RH @ \$810.00 <i>cracked</i>		1620.00	707
1	REAR TAILGATE WIPER <i>3rd</i>		111.00	+
1	REAR TAILGATE WIPER MOTOR <i>new</i>		321.00	+
1	REAR BUMPER <i>Distorted</i>		1071.00	948
1	REAR BUMPER LOWER <i>Distorted</i>		644.00	475
1	REAR BUMPER REINFORCEMENT <i>Best</i>		782.10	398
1	REAR BUMPER TOW COVER <i>Missing</i>		95.00	55
2	REAR BUMPER SIDE RETAINER LH & RH @ \$121.50 <i>new</i>		243.00	170

2	REAR BUMPER REFLECTOR LH & RH @\$310.00 <i>xHP nec</i>		620.00	X
2	REAR BUMPER REFLECTOR COVER LH & RH @\$101.00 <i>del</i>		202.00	✓
1	REAR BUMPER LOWER LAMP <i>Cracked</i>		110.00	125
1	REAR END PANEL <i>Dented</i>		890.00	725
1	REAR END PANEL TOP GARNISH <i>Cracked</i>		275.00	✓
1	REAR SPARE TYRE PANEL <i>Repair</i>		985.00	X
1	REAR SPARE TYRE PANEL TOP BOARD <i>del</i>		259.00	385
1	REAR SPARE TYRE PANEL <i>SPONGE TRAY del</i>		411.00	299
2	REAR SIDE <i>SPONGE</i> RR FLOOR LH & RH @\$398.00 <i>del</i>		796.00	✓ 410
2	REAR UPPER & LOWER SPACER FLOOR LH & RH @\$431.00 <i>HP nec</i>		862.00	X
1	REAR CHASSIS MEMBER RH <i>Repair</i>		1015.00	X
2	REAR TAILLAMP LH & RH @\$740.20 <i>cracked</i>		1480.40	1250
1	REAR EXHAUST SILENCER		980.00	X
1	REAR EXHAUST SILENCER MOUNTING <i>HP nec</i>	1802850	70.00	X
1	REAR EXHAUST SILENCER CHROME		98.00	X
1	REAR EXHAUST SILENCER CHROME	1352137	168.30	X
1	REAR EXHAUST HEAT COVER <i>HP nec</i>		1215.90	X
1	REAR ROOF <i>Repair</i>		930.10	X
2	REAR FENDER RH <i>Repair</i>		1592.60	844
2	REAR FENDER INNER BAORD LH & RH @\$796.30 <i>cracked</i>		127.40	X
1	REAR FENDER AIR VENT RH <i>HP nec</i>		320.00	185
1	REAR WINDSCREEN MOULDING <i>Nec</i>			
			39663.90	
less 25%			9915.98	25%
			29747.93	
SPECIAL NETT ITEMS				
1 SET	FRONT BUMPER CLIPS <i>Nec</i>		80.00	30
1 SET	FRONT BONNET INSULATOR CLIPS <i>HP nec</i>		100.00	X
1 SET	FRONT CAR PLATE WITH HOLDER <i>Cracked</i>		70.00	50
1	COOLANT <i>HP nec</i>		100.00	X
1 SET	REVERSE SENSOR <i>Damaged</i>		280.00	200
1	REVERSE CAMERA <i>HP nec</i>		410.00	X
1 SET	REAR BUMPER CLIPS <i>Nec</i>		100.00	30
1 SET	REAR CAR PLATE WITH HOLDER <i> Bent</i>		320.00	30
1 SET	REAR TAILLAMP CLIPS <i>Nec</i>		100.00	20
1 SET	REAR TAILGATE INNER BOARD CLIPS		80.00	30
1 SET	REAR END PANEL TOP GARNISH CLIPS <i>HP nec</i>		80.00	10
1	REAR END PANEL SEALANT <i>Nec</i>		100.00	60
1	REAR WINDSCREEN INNER SEAL <i>HP nec</i>		100.00	40
1	REAR WINDSCREEN SEALANT		100.00	40
Total Parts			31767.93	

1set Front Bumper Sensors *Damaged* 280 200
 1set Spare Tyre Panel Sound Insulation *Nec* 280 200

940.



ACE AUTOLUTION PTE LTD
 13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
 Singapore 417807
 Tel:6702 4282 Fax:6702 4202

Vehicle No. SMD7812C TOYOTA CHR

S/N	DESCRIPTION	REPAIRER'S ESTIMATE	OUR ASSESSMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	2200.00	1500
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1800.00	1400
3	To remove, refix wiring system at accident damage areas and check for proper function	150.00	60
4	To remove and replace with check headlamp beam	120.00	x.
5	To perform anti-rust treatment on affected areas	270.00	100
6	Cavity treatment on New parts	120.00	x
7	To top up coolant	150.00	x
8	To remove and refix rear windscreen	230.00	120
9	To water seepage test	120.00	x
10	To transfer rear boot mechanism	120.00	80
11	To remove and replace reverse sensor	120.00	50
	Labour Total :	5400.00	
TOTAL (PARTS & LABOUR) :		37167.93	

3310

Supplementary : 535.12

total 18306.49

L/S: 14.6K

11 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

14.6K

SMD 7812C Supplementary

Front Bumper Upper Sponge	Deformed	89.80	✓
Front Bumper Lower Sponge	Deformed	87.20	✓
Front Support Panel Top Cover	cracked	195.90	✓

Tailgate Lock Cover	cracked	29.40	✓
Tailgate Lock Antenna	cracked	114.90	✓
Tailgate Lock Operer Switch	Damaged	165.90	✓
Tailgate Limes Pocket	Deformed	30.40	✓

713.50

Supplementary: 535.12