

SMD 7812C Supplementary

Front Bumper Upper Sponge	Deformed	89.80	✓
Front Bumper Lower Sponge	Deformed	87.20	✓
Front Support Panel Top Cover	cracked	195.90	✓

Tailgate Lock Cover	cracked	29.40	✓
Tailgate Lock Antenna	cracked	114.90	✓
Tailgate Lock Operer Switch	Damaged	165.90	✓
Tailgate Inner Pocket	Deformed	30.40	✓

713.50

Supplementary: 535.12