

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

22-May-19

## ESTIMATE REPAIR BILL FOR HYUNDAI I30 WAGON REGN NO: SHD 1573 R

1 pc	Rear bumper	✓	\$	447.00
1 pc	Rear bumper inner sponge	?	\$	129.00
1 pc	Rear bumper beam	?	\$	270.00
1 pc	Rear bumper tow hook cap	X	\$	38.20
2 pcs	Rear bumper o/s & n/s stay	@ \$79.00 ?	\$	158.00
1 pc	Rear bumper beam lower bracket - centre	?	\$	13.70
2 pcs	Rear bumper beam lower bracket - RH & LH	@ \$16.20 ?	\$	32.40
2 pcs	Rear bumper beam o/s & n/s upper bracket	@ \$13.70 ?	\$	27.40
2 pcs	Rear bumper o/s & n/s side bracket	@ \$16.00 ?	\$	32.00
2 pcs	Rear bumper o/s & n/s side upper bracket	@ \$15.20 ?	\$	30.40
2 pcs	Rear bumper o/s & n/s upper bracket	@ \$13.30 ?	\$	26.60
1 pc	Rear bumper lower cover	X repl	\$	62.40
1 pc	Rear o/s tail lamp	X	\$	477.50
1 pc	End panel	X repl	\$	470.60
1 pc	End panel top garnish	?	\$	55.60
1 pc	Rear floorboard panel	X repl	\$	607.50
1 pc	Rear o/s side panel	X repl	\$	168.40
1 pc	Rear o/s luggage tray	X	\$	158.00
1 pc	Rear o/s inner trim	X	\$	153.70
1 pc	Rear luggage tray top covering	X	\$	298.50
1 pc	Rear luggage tray centre	X	\$	120.50
1 pc	Tail gate	✓	\$	1,667.40
1 pc	Tail gate glass moulding	✓	\$	48.80
1 pc	Tail gate emblem	✓	\$	31.20
1 pc	Tail gate "CRDi"	✓	\$	28.70
			\$	5,553.50
		Less 20%	\$	1,110.70
			\$	4,442.80

### S/NETT

1 set	Rear bumper clips	✓	\$	48.00
1 set	Reverse sensor	✓	\$	280.00 200
1 pc	Tailgate stickers	✓	\$	100.00
1 pc	Rear number plate with casing	X no casing	\$	50.00 25

22-May-19

**ESTIMATE REPAIR BILL FOR HYUNDAI I30 WAGON REGN NO: SHD 1534 D**

Sundry	\$	<del>50.00</del> 20
To Dismantle and replace reverse sensor and test system	\$	<del>80.00</del> 30
To dismantle and refit the rear windscreen	\$	<del>120.00</del> 600
To dismantle and refit the inner component of tailgate into new shell, test water etc	\$	<del>80.00</del> 50
To labour charge for dismantle and renew the accident damaged parts. To cut off/heat and weld on the end panel, floorboard panel. Including to knock-out, straighten, repair, reshape and adjust of the same.	\$	<del>2,500.00</del> 800
To putty and spray painting on the rear bumper, end panel, tailgate, tailgate lower garnish, floorboard panel,	\$	<del>1,000.00</del> 900
To apply rustproofing on the repaired and replaced panels	\$	<del>300.00</del> 50
<b>Total</b>	\$	<b>9,050.80</b>

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.**

Kahin LKK  
22/5/19 17:50 hr  
4 Dgys.  
L/s  
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey damaged part(s) during resurvey
- To display damaged part(s) for confirmation
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer  
Signature:  
Date: