

Think One Autocare Pte Ltd  
 No.18 Defu Avenue 2  
 Singapore 539522  
 Tel: 6844 3300 Fax: 6842 4988

PC4039H Isuzu LT134P

No	Qty	Parts Description	Estimated Parts Price
1	1	Front bumper complete assy <i>repair</i>	\$ 3,800.00
2	1	Front bumper right bracket <i>X</i>	\$ 350.00
3	1	Front bumper lower fog lamp <i>X</i>	\$ 280.00
4	1	Front right headlamp <i>X</i>	\$ 1,214.00
5	1	Front right lower panel assy <i>repair</i>	\$ 4,567.00
6	1	Front right lower panel reflector <i>X</i>	\$ 120.00
7	2	Front right lower panel cover <i>&amp; repair</i>	\$ 280.00
8	1	Rear right lower panel assy <i>repair</i>	\$ 4,570.00
9	1	Rear right lower panel cover <i>repair</i>	\$ 280.00
			<hr/>
			\$ 15,461.00
Less 10%			\$ 1,546.10
			<hr/>
			\$ 13,914.90

Special Nett Items

1	1set	Rear right panel sticker <i>X</i>	\$ 450.00
			<hr/>
			\$ 450.00

**Total parts**

**\$ 14,364.90**

Think One Autocare Pte Ltd  
No.18 Defu Avenue 2  
Singapore 539522  
Tel: 6844 3300 Fax: 6842 4988

PC4039H Isuzu LT134P

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front right affected area and replace front right damaged parts.	\$ 1,000.00 <del>800</del> 400
2	To putty and spray painting front right portion.	\$ 1,000.00 <del>800</del> 600
3	To apply anti rust proofing to front right affected area.	\$ 120.00 60
4	To check wiring and focus front headlamp.	\$ 50.00 X
5	Labour for panel beating, cut, weld, straighten rear right affected area and replace rear right damaged parts.	\$ 1,000.00 400
6	To putty and spray painting rear right portion.	\$ 1,000.00 500
Total labour :		\$ 4,170.00

Total parts : \$ 14,364.90

Total labour : \$ 4,170.00

Total repair cost : \$ 18,534.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resu  
Hp 90010068

6 days

P/P

24/05/19 @ 9.00h

Resu after repair