

W

AUTOLUTION INDUSTRIAL PTE. LTD.
18 UBI ROAD 4
SINGAPORE 408623

AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0276/19
DATE : 21 MAY 2019

AAA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE
TEL : 68604741
FAX : 68609838
ATTN: MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : MR SHENG HONGJIN
ADDRESS : BLK 506D ANG MO KIO STREET 52
#21-309
SINGAPORE
TELEPHONE NO : 92960505

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 1800126634
VEHICLE NO : SM7203X
REG. CODE : TCMR02E12EDAP5202
MODEL/YEAR : NISSAN NOTE 1.2 (V) MY 2018
ENGINE NO : HR1223441J
CHASSIS NO : JN1TAR1220962369
MILEAGE : 9254 KM
DATE IN : 21/05/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : TLMR
ACCIDENT DATE : 21/05/2019

Not Authorized
HWA
marcus
24/5/19
the above signature
4 day.
P/P #180652

9645 0084 elmu@fanchong

L&K Auto Consulting has notified the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work(s) must be approved and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMF203H

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	22/001	LABOR CHARGES TO REPAIR REAR END PANEL,RENEW HATCH BACK DOOR & RR BUMPER	1400.00	700 -
2	22/002	CHARGES TO SPRAY PAINTING SAME	1000.00	600 -
3	22/003	REMOVE AND INSTALL REVERSE CAMERA	1-1 240.00	X
4	22/004	REMOVE AND INSTALL RR WINDSCREEN GLASS	1-1 180.00	X
5	22/005	APPLY SEALANT TO RR WINDSCREEN GLASS	1-1 100.00	X
6	22/006	APPLY SEALANT TO RR END PANEL & HATCHBACK DOOR	1-1 200.00	X
7	22/007	TRENEW REVERSE SENSOR	55.00	/
8	22/008	REMOVE AND INSTALL BOTH RR COMBINATION LAMP TO FACILITATE RR BUMPER REPLACEMENT	48.00	/
9	22/009	RENEW REVERSE SENSOR	55.00	/
10	22/10	SUPPLY RR LICENSE PLATE		
		TOTAL LABOUR CHARGES	3278.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SP203X

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	REAR BUMPER	85022-3VADA 20/12	414.00		✓
2	CLIP RR BUMPER & SGO \$1.25 EACH	01563-10501 121	7.20		✓
3	LH SIDE BRACKET RR BUMPER	85221-3VADA 17	45.40		X
4	RH SIDE BRACKET RR BUMPER	85220-3VADA 17	45.40		X
5	ENERGY ABSORBER RR BUMPER	85090-3VADA 17	111.90		X
6	STRIP-RR BUMPER & SGO \$86.00 EACH	85212-1HJDA 12	172.00		X
7	HATCHBACK DOOR	40104-3VADA 12	975.40		X
8	HATCHBACK DOOR GARNISH	90810-3VADA 1-1	243.90		X
9	WEATHER STRIP HATCHBACK DOOR	90800-3VADA 1-1	64.80		X
10	HATCHBACK DOOR LOCK	90502-1HJDA 1-1	114.80		X
11	STRIKER-HATCHBACK DOOR	90570-1HJDA 17	31.10		X
12	EMBLEM-BACK DOOR NISSAN	90890-3VADA 121	59.70		✓
13	ORNAMENT-BACK DOOR NOTE	90892-3VADA 121	71.60		✓
14	PLATE-LUGGAGE RR GARNISH	84990-3VADA 17	63.50		X
15	UPPER MOULDING RR WINDSCREEN GLASS	90352-3VADA 1-1	65.70		X
16	REAR W/SCREEN SEALANT	SEALANT - 4		1-1 90.00	X
17	SENSOR-REVERSE	SENSOR		17 250.00	X
18	SUNROOFS	NRW		17 50.00	X
19	REAR LICENCE PLATE	RLP		17 60.00	X
SUB TOTAL			2489.40	0.00	440.00
LESS DISCOUNT (NETT 20.00%, LIST 30.00%, S/NETT 0.00%)			497.88	0.00	0.00
GRAND TOTAL			1991.52	0.00	440.00
OVERALL TOTAL			2431.52		

(LEGEND: REMARKS (X) = APPROVED, REMARKS (X) = NOT APPROVED)

AUTOLITION INDUSTRIAL PTE. LTD.

FINALIZED : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0274/19

DATE : 21-MAY-2019

AAA INSURANCE PTE LTD

B SHENTON WAY

#27-01 AAA TOWER

50688111

TEL : 6864741

FAX : 6864838

ATTN:MOTOR CLAIM MANAGER VALENCIA

SURVEYOR MARCUS
4 DAYS

OWNER'S NAME : MR SHENG HENGBIN

ADDRESS : BLK 596D ANG MO KIO STREET 52

#23-309

S(564596)

TELEPHONE NO : 92960505

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM

POLICY NO : 1800126678

VEHICLE NO : 5MF2038

MODEL CODE : TOWARDZE12EDAYS207

MODEL/YEAR : NISSAN NOTE 1.2 (V) MY 2018

ENGINE NO : HR12233441J-E125

CHASSIS NO : JN1TAAE1220982369

MILEAGE : 10962 KM

DATE IN : 21/05/2019

LIABILITY : 0.00

EXCESS CLAUSE : 0.00

ESTIMATE BY : ELMER

ACCIDENT DATE : 21/05/2019

LABOUR CHARGES FOR ACCIDENT VEHICLE REGD NO SM2008

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 ZZ/001	LABOR CHARGES TO REPAIR REAR END PANEL & HATCH BACK DOOR,RENEW REAR BUMPER	1400.00	700.00
2 ZZ/002	CHARGES TO SPRAY PAINTING SAME	1000.00	600.00
3 ZZ/003	REMOVE AND INSTALL REVERSE CAMERA	240.00	.00
4 ZZ/004	REMOVE AND INSTALL RR WINDSCREEN GLASS	180.00	.00
5 ZZ/005	APPLY SEALANT TO RR WINDSCREEN GLASS	100.00	.00
6 ZZ/006	APPLY SEALANT TO RR END PANEL & HATCHBACK DOOR	200.00	.00
7 ZZ/007	RENEW REVERSE SENSOR	55.00	55.00
8 ZZ/008	REMOVE AND INSTALL BOTH RR COMBINATION LAMP TO FACILITATE RR BUMPER REPLACEMENT	48.00	48.00
9 ZZ/009	RENEW REVERSE SENSOR	55.00	55.00
10 ZZ/10	SUPPLY RR LICENSE PLATE		
	TOTAL LABOUR CHARGES	3278.00	1458.00
	ADDITIONAL DISCOUNT(5.00%)		72.90
	FINAL LABOUR CHARGES		1385.10

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SHF2023

DAMAGED PARTS & PRICES

S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1	REAR BUMPER	85022-3VAGH	434.00			OK
2	CLIP RR BUMPER @ SGD \$1.20 EACH	01553-1C501	7.20			OK
3	LH SIDE BRACKET RR BUMPER	85221-3VAGH	45.40			X
4	RR SIDE BRACKET RR BUMPER	85220-3VAGH	45.40			X
5	ENERGY ABSORBER RR BUMPER	85090-3VAGH	111.90			X
6	STAY-RR BUMPER @ SGD \$86.00 EACH	85212-1HJ0R	172.00			X
7	HATCHBACK DOOR	8010H-3VAGH	976.40			X
8	HATCHBACK DOOR GARNISH	90810-3VAGH	243.90			X
9	WEATHER STRIP HATCHBACK DOOR	90830-3VAGH	64.80			X
10	HATCHBACK DOOR LOCK	90502-1HJ0R	114.80			X
11	STRIKER-HATCHBACK DOOR	90570-1HJ0R	31.10			X
12	EMBLEM-BACK DOOR NISSAN	90890-3VAGH	59.70			OK
13	ORNAMENT-BACK DOOR NOTE	90892-3VAGH	73.60			OK
14	PLATE-LUGGAGE RR GARNISH	84992-3VAGH	63.50			X
15	UPPER MOULDING RR WINDSCREEN GLASS	90352-3VAGH	65.70			X
16	REAR W/SCREEN SEALANT	SEALANT - 4			60.00	X
17	SENSOR-REVERSE	SENSOR			250.00	X
18	SUNORIES	SPH			50.00	X
19	REAR LICENCE PLATE	RLP			60.00	X
SUB TOTAL			554.50	0.00	0.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			110.90	0.00	0.00	
GRAND TOTAL			443.60	0.00	0.00	
ADDITIONAL DISCOUNT (NETT-5.00%, LIST-5.00%, S/NETT-.00%)			22.18	0.00	0.00	
OVERALL TOTAL			421.42			

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SHF203P

DAMAGED PARTS & PRICES

S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
------	-------------------	--------------	------	------	----------------

LEGEND: REMARKS (X 1) = APPROVED, REMARKS (X 2) = NOT APPROVED

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SHF203M

NETT ITEM	554.50
LESS POLISH	-110.90
NETT AMOUNT	443.60
ADDITIONAL DISCOUNT(5.00%)	-22.18
FINAL AMOUNT	421.42
LIST ITEM	0.00
LESS 30.00%	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	0.00
LESS .00%	0.00
SPECIAL NETT AMOUNT	0.00
TOTAL LABOUR CHARGES	1385.10
TOTAL SPARE PARTS CHARGES	421.42
TOTAL CHARGES	1806.52
ADD 7 % GST	126.48
GRAND TOTAL	1932.98