

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9888 FAX: 6848 7477

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0274/19
DATE : 21-MAY-2019

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : MR SHENG HONGBIN
ADDRESS : BLK 596D ANG MO KIO STREET 52
#23-309
S(564596)
TELEPHONE NO : 92960505

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 1800126674
VEHICLE NO : SMF203X
MODEL CODE : TDWARDZE12EDAY520Z
MODEL/YEAR : NISSAN NOTE 1.2 (V) MY 2018
ENGINE NO : HR1223441J
CHASSIS NO : JN1TAAE12Z0982369
MILEAGE : 9254 KM
DATE IN : 21/05/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : ELMER
ACCIDENT DATE : 21/05/2019

not Authorized
Nile
mercus
24/5/19
the the before repair.
4 day.

9645 0084 elmer@fanchong

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMF203X

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 ZZ/001	LABOR CHARGES TO REPAIR REAR END PANEL,RENEW HATCH BACK DOOR & RR BUMPER	1400.00	700
2 ZZ/002	CHARGES TO SPRAY PAINTING SAME	1000.00	600
3 ZZ/003	REMOVE AND INSTALL REVERSE CAMERA	11 240.00	X
4 ZZ/004	REMOVE AND INSTALL RR WINDSCREEN GLASS	11 180.00	X
5 ZZ/005	APPLY SEALANT TO RR WINDSCREEN GLASS	11 100.00	X
6 ZZ/006	APPLY SEALANT TO RR END PANEL & HATCHBACK DOOR	11 200.00	X
7 ZZ/007	TRENEW REVERSE SENSOR	55.00	✓
8 ZZ/008	REMOVE AND INSTALL BOTH RR COMBINATION LAMP TO FACILITATE RR BUMPER REPLACEMENT	48.00	✓
9 ZZ/009	RENEW REVERSE SENSOR	55.00	✓
10 ZZ/10	SUPPLY RR LICENSE PLATE		
	TOTAL LABOUR CHARGES	3278.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMF203X

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/NETT REMARKS
		NETT	LIST		
1 REAR BUMPER	85022-3VA0H <i>DO/RE</i>	414.00			
2 CLIP RR BUMPER @ SGD \$1.20 EACH	01553-10501 <i>RE</i>	7.20			
3 LH SIDE BRACKET RR BUMPER	85221-3VA0A	45.40		?	
4 RH SIDE BRACKET RR BUMPER	85220-3VA0A	45.40		?	
5 ENERGY ABSORBER RR BUMPER	85090-3VA0A	111.90		?	
6 STAY-RR BUMPER @ SGD \$86.00 EACH	85212-1HJ0A	172.00		?	
7 HATCHBACK DOOR	K010M-3VAMA <i>RE</i>	976.40		X	
8 HATCHBACK DOOR GARNISH	90810-3VA5B <i>11</i>	243.90		X	
9 WEATHER STRIP HATCHBACK DOOR	90830-3VA0A <i>11</i>	64.80		X	
10 HATCHBACK DOOR LOCK	90502-1HM0A <i>11</i>	114.80		X	
11 STRIKER-HATCHBACK DOOR	90570-1HM0B <i>11</i>	31.10		X	
12 EMBLEM-BACK DOOR NISSAN	90890-3VA0A <i>RE</i>	59.70			
13 ORNAMENT-BACK DOOR NOTE	90892-3VA0A <i>RE</i>	73.60			
14 PLATE-LUGGAGE RR GARNISH	84992-3VA0A <i>11</i>	63.50		X	
15 UPPER MOULDING RR WINDSCREEN GLASS	90352-3VA0A <i>11</i>	65.70		X	
16 REAR W/SCREEN SEALANT	SEALANT - 4			<i>11</i>	80.00 X
17 SENSOR-REVERSE	SENSOR				250.00 ?
18 SUNDRIES	NPN				50.00 ?
19 REAR LICENCE PLATE	RLP			<i>11</i>	60.00 X
SUB TOTAL		2489.40	0.00		440.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		497.88	0.00		0.00
GRAND TOTAL		1991.52	0.00		440.00
OVERALL TOTAL		2431.52			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED