

輝陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

21/05/2019

Owner: CHOW MUN CHOON

SUPPLEMENTARY TO REPAIR MAZDA 3 - SLS697Y

1pc	front bonnet inner rubber	CM	\$ 188.50	✓
1pc	front centre grille top garnish 338.50	CM	\$ 385.50	✓
1pc	front centre grille LH side cover	CM	\$ 55.00	✓
3pcs	front centre grille LH side garnish (short) @\$95.50	DI	\$ 286.50	✓
3pcs	front centre grille lower garnish (long) @\$125.50	CM	\$ 376.50	✓
1pc	front centre grille inner LH side bracket (long)	DI	\$ 85.00	✓
1pc	front centre grille inner LH side bracket	B	\$ 65.00	✓
1pc	front bumper inner garnish	CM	\$ 168.80	✓
1pc	front support panel lower reinforcement garnish	CM	\$ 195.80	✓
1pc	front support panel lower reinforcement LH side bracket	B	\$ 155.00	✓

less 20%

\$ 1,961.60
\$ 392.32
\$ 1,569.28

