

INS. CASE OWNER:

Cynthia

CC 4 ASM AXA1900 4107 E plb3

LKK
IDAT

Surveyor:

Steve

DOI:

ASSIGNMENT

22/5/19

Date / Time:

22/5/19

Registered in Merit:

Pre-assign / CCU / FTE



Insured Vehicle No.:

S LR 6942B

Name of Insured:

LAK TZE MENN

Insured Tel No.:

HP: 94660470

Excess Sec II :\$5

D.O.A: 12/4/19

Is driver the owner?

YES / NO

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L) YES / NO

Claim No.:

3 AMO 206m / 117264

Policy No.:

GA 3749471

Make / Model:

VOLVO

Place of Accident:

POTTERSON HILL

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

SME 24/7M

INSRS:
WSP:
Tel:
Liability:
RMKS:

Hin Lung

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

SME 24/7M - X

SME 24/7M - X

STAGE

DATE / PIC

Non-Reporting 1st (1st)

Non-Reporting 1st (2nd)

Non-Reporting 1st (Final)

Notification 1st (if non-pickup)

Call OI

After call 1st to OI

22/5/19

Documentation Check List: Handler Typist

Notification 1st (if non-pickup)

After call 1st to OI

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

Agreed / Assessed

BOLA S/N No.:

27

Repair Cost:

\$5

3680.74

Loss of Rental (LOR):

\$5

days)

Loss of Use (LAI):

\$5

300.00

(S)

x

days)

Loss of Income (LOI):

\$5

(S)

x

days)

LOR only

LOI only

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

GIA/LTA Search

\$5

2.00

Medical:

\$5

Disbursement:

\$5

(e.g. Tow/ Independent)

Legal Cost:

\$5

Total:

\$5

3982.74

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5

3982.74

Name 1:

Hin Lung Workshop

Payee 2 (Strike if N.A.)

\$5

Name 2:

Payee 3 (Strike if N.A.)

\$5

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$ 350.00

COPY SENT
10/3/19

TOTAL



[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0278K
Vehicle Details	
Vehicle No.:	SME2417M
Vehicle to be Exported:	No
Intended Deregistration Date:	27 May 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	ML300
Primary Colour:	Brown
Manufacturing Year:	2011
Engine No.:	27294531830554
Chassis No.:	WDC1641822A717077
Maximum Power Output:	170.0 kW (227 bhp)
Open Market Value:	\$55,459.00
Original Registration Date:	16 Aug 2011
First Registration Date:	16 Aug 2011
Transfer Count:	2
Actual ARF Paid:	\$55,459.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Aug 2021
PARF Rebate Amount:	\$33,275.00
Intended COE Rebate Details	
COE Expiry Date:	15 Aug 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$70,890.00
COE Rebate Amount:	\$15,721.00
Total Rebate Amount:	\$48,996.00

The information contained herein is correct as at 27 May 2019

OK

HIN LUNG WORKSHOP
1008 Bukit Merah Lane 3, #01-20
159722

Claim Reference:
Assessment number: HLW00044
Version: 1810
Date calculated: 22/05/2019 5:53 PM

Full Report
Registration: SME2417M TP
Printed: 22/05/2019 5:53 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	JOON LIAN TAN	Currency:	SGD
Claim Reference:		Date of Incident:	17/05/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES-BENZ
Model:	ML-CLASS (W164)
Sub Model:	ML 300 CDI 4-MATIC
Model Sheet Number:	03 46 14
Registration:	SME2417M TP
VIN number:	WDC1641822A717077
Odometer:	95907

Model Specs

FROM VIN A661926	MODEL CHANGE 2011	BLUE TINT WINDOWS	RAIN SENSOR
DIPPING DOOR MIRROR	B-XENON/CORNERING LA	HEADLAMP WASHER UNIT	ALCANTARA TRIM
INTERIOR LAMP PACK	SPORTS PACK EXTERIOR	SPORTS PACK INTERIOR	FOLDING DOOR MIRRORS
ASHTRAY PACKAGE	WOOD EQUIPM POPLAR	AUTO TAILGATE CONTR	ELEC DRIVER SEAT MEM
NECK-PRO HEADREST	PRE-SAFE SYSTEM	FRT SPORT SEATS	LUGGAGE COVER
BOOT PARTITION NET	7-SPEED AUTOMATIK	PARAMETER STEERING	TYRE PRESSURE SENSOR
TYRES 285/45 ZR 19	WHEELS 8.5J X 19 ALU	SPARE WHEEL	AUDIO SYSTEM 20 CD
PARKTRONIC	MEDIA INTERFACE	STEP BOARDS ST/STEEL	UNDERBODY PROTECTION
ROOF RAILS	TWO COAT PEARL/MICA		

HIN LUNG WORKSHOP
1008 Bukit Merah Lane 3, #01-20
159722

Claim Reference:
Assessment number: HLW00044
Version: 1810
Date calculated: 22/05/2019 5:53 PM

Full Report
Registration: SME2417M TP
Printed: 22/05/2019 5:53 PM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
88-8802 01	R + R REAR BUMPER		8.0	36.00
88-8909 01	ADDITION TO R + R REAR BUMPER (VEHICLE WITH PARKTRONIC)		1.0	4.50
88-8805 02	DIS + ASS REAR BUMPER AFTER FINDING: RENEW PARTS (REMOVED)		8.0	36.00
88-8883 01	ADDITIONAL FOR DISS/ASS REAR BUMPER (VEHICLE WITH PARK ASSISTENT)		3.0	13.50
88-8956 02	R + R REAR LOWER BUMPER CROSSMEMBER (BUMPER REMOVED)		13.0	58.50
88-1052 01	R + R REAR NUMBER PLATE		2.0	9.00
72-4573 01)	R + R TAILGATE LOCK STRIKER		3.0	13.50
68-3080 01	R + R CENTRE REAR PANEL TRIM		3.0	13.50
82-4905 01	R + R BOTH REAR LAMP UNITS		4.0	18.00
54-7989 01	R + R BATTERY EARTH CABLE (WHEN DISCONNECTING ELECTRIC PLUG AND SOCKET CONNECTIONS)		3.0	13.50

HIN LUNG WORKSHOP
1008 Bukit Merah Lane 3, #01-20
159722

Claim Reference:
 Assessment number: HLW00044
 Version: 1810
 Date calculated: 22/05/2019 5:53 PM

Full Report
 Registration: SME2417M TP
 Printed: 22/05/2019 5:53 PM

Code	Description	WU	Price SGD
49-4965 01	R + R RIGHT REAR SILENCER	8.0	36.00
49-8415 01	R + R R/R EXHAUST COVER	2.0	9.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		5.80	58.0
Total of Labour			261.00

243

Paint

Code	Description - TWO COAT PEARL/MICA	WU	Price SGD
	RR UPP BUMPER COVER NEW PART PAINT K1R	10.0	
	LWR RR BUMPER COVER NEW PART PAINT K1R	8.0	
	RR TOWING LUG COVER NEW PART PAINT K1R	3.0	
	L/R OUTER SENSOR NEW PART PAINT K1R	3.0	

Paint Material Per Part

Code	Description	Price SGD
2583	RR UPP BUMPER COVER NEW PART PAINT K1R	44.77
2585	LWR RR BUMPER COVER NEW PART PAINT K1R	34.44
2597	RR TOWING LUG COVER NEW PART PAINT K1R	0.49
2669	L/R OUTER SENSOR NEW PART PAINT K1R	0.49

Labour Cost - Paint		Hrs	WU	Price SGD
Factor	45.00 SGD/h		24.0	
Time Paint				
Preparation Comp. Work Plastic		0.90	9.0	40.50
Total	10 WU/h	3.30	33.0	148.50

Material Cost - Paint		Price SGD
New Part Painting - Plastic K1R		80.19
Material-constant Plastic		16.20
Total		96.39

Spare Parts

prices as at 2015-06-01

HIN LUNG WORKSHOP

1008 Bukit Merah Lane 3, #01-20
159722

Claim Reference:
Assessment number: HLW00044
Version: 1810
Date calculated: 22/05/2019 5:53 PM

Full Report
Registration: SME2417M TP
Printed: 22/05/2019 5:53 PM

Code	Description	Part Number	Supplier	Price SGD
2583	RR UPP BUMPER COVER	164 880 2940 9999	✓ (UT)	1,265.00
2585	LWR RR BUMPER COVER	164 885 6925	✓ (UT)	500.00
		7C45		
2593	BUMPER COVER CAP	164 885 3323	✗ (Chm) - DD / UT	645.00
2597	RR TOWING LUG COVER	164 885 3223 9999	✗ ?	40.00
2600	RR BUMPER CTR COVER	164 880 0111	✗ (Chm) - nn	150.00
2618	R/R BUMPER BRACKET	164 885 2865	✗	80.00
2625	L/R C-MEMBER	164 640 1131	x	200.00
	CONSOLE			
2626	R/R C-MEMBER	164 640 1231	✗	200.00
	CONSOLE			
2640	REAR BUMPER C-MEMBER	164 619 0122	✗	450.00
2641	RR INNER BUMPER PART	164 885 1765	✗	210.00
2669	L/R OUTER SENSOR	221 542 0417	✗	165.00
2681	L/R OUT SPACER RING	221 542 0051	✗	8.00
2682	R/R OUT SPACER RING	221 542 0051	✗	8.00
2813	L/R GASKET FLANGE	164 619 0098	✗	32.00
2814	R/R FLANGE GASKET	164 619 0098	✗	32.00
3282	R/R LAMP	164 906 4300	✗ nn	500.00
3286	R/R REFLECTOR	164 820 1574	✗ nn OR	42.00
8828	R/R SILENCER	164 490 8415	✗ nn	1,010.00
8848	R/R END PIPE	164 490 2327	✗ (UT)	240.00
2584	L/R BUMPER CONSOLE	164 885 0031	✗	55.00
2585	R/R BUMPER CONSOLE	164 885 0131	✗	55.00
2586	R/R OUT SENSOR BRKT	221 542 0417	✗	0.00
f: OEM Parts				0.00
n: Non-OEM Parts				5,887.00
u: Used parts				883.05
Savings				
Subtotal				
Addition(+15.00%)				
Total				6,770.05

Extras

Code	Description	Price SGD
2583	[S]: RR UPP BUMPER C OVER: INCLUDES	0.00*
2583	REAR BUMPER PDC SENS OR	0.00*

HIN LUNG WORKSHOP

1008 Bukit Merah Lane 3, #01-20
159722

Claim Reference:
Assessment number: HLW00044
Version: 1810
Date calculated: 22/05/2019 5:53 PM

Full Report
Registration: SME2417M TP
Printed: 22/05/2019 5:53 PM

Final Calculation

	SGD	SGD
Parts	5,887.00	
Addition(+15.00%)	883.05	
Total Parts		6,770.05
Labour Time Base 10 WU/h		
Total 58.0 WU X 45.00 SGD/h	243 261.00	
Total of Labour		261.00
Total Of Extras		0.00
Paint Work Time Base 10 WU/h		
Labour Cost 33.0 WU X 45.00 SGD/h	148.50	
Material Cost	96.39	
Total Paint Including Material		244.89
Repair Cost Excludes GST		7,275.94
GST (+7.00%)		509.32
Repair Cost Included GST		7,785.26

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Steve (LKK) in ALI 27/5/19, 11:00 am
8322 8813 3 day
P/P
Ry before spy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

HIN LUNG WORKSHOP
1008 Bukit Merah Lane 3, #01-20
159722

Claim Reference:
Assessment number: HLW00044
Version: 1810
Date calculated: 14/06/2019 2:41 PM

Full Report
Registration: SME2417M TP
Printed: 14/06/2019 2:41 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	JOON LIAN TAN	Currency:	SGD
Claim Reference:		Date of Incident:	17/05/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES-BENZ
Model:	ML-CLASS (W164)
Sub Model:	ML 300 CDI 4-MATIC
Model Sheet Number:	03 46 14
Registration:	SME2417M TP
VIN number:	WDC1641822A717077
Odometer:	95907

Model Specs

FROM VIN A661926	MODEL CHANGE 2011	BLUE TINT WINDOWS	RAIN SENSOR
DIPPING DOOR MIRROR	B-XENON/CORNERING LA	HEADLAMP WASHER UNIT	ALCANTARA TRIM
INTERIOR LAMP PACK	SPORTS PACK EXTERIOR	SPORTS PACK INTERIOR	FOLDING DOOR MIRRORS
ASHTRAY PACKAGE	WOOD EQUIPM POPLAR	AUTO TAILGATE CONTR	ELEC DRIVER SEAT MEM
NECK-PRO HEADREST	PRE-SAFE SYSTEM	FRT SPORT SEATS	LUGGAGE COVER
BOOT PARTITION NET	7-SPEED AUTOMATIK	PARAMETER STEERING	TYRE PRESSURE SENSOR
TYRES 285/45 ZR 19	WHEELS 8.5J X 19 ALU	SPARE WHEEL	AUDIO SYSTEM 20 CD
PARKTRONIC	MEDIA INTERFACE	STEP BOARDS ST/STEEL	UNDERBODY PROTECTION
ROOF RAILS	TWO COAT PEARL/MICA		

HIN LUNG WORKSHOP
1008 Bukit Merah Lane 3, #01-20
159722

Claim Reference:
Assessment number: HLW00044
Version: 1810
Date calculated: 14/06/2019 2:41 PM

Full Report
Registration: SME2417M TP
Printed: 14/06/2019 2:41 PM

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
88-8802 01	R + R REAR BUMPER		8.0	36.00
88-8909 01	ADDITION TO R + R REAR BUMPER (VEHICLE WITH PARKTRONIC)		1.0	4.50
88-8805 02	DIS + ASS REAR BUMPER		8.0	36.00
	AFTER FINDING: RENEW PARTS (REMOVED)			
88-8883 01	ADDITIONAL FOR DISS/ASS REAR BUMPER (VEHICLE WITH PARK ASSISTENT)		3.0	13.50
88-8956 02	R + R REAR LOWER BUMPER CROSSMEMBER (BUMPER REMOVED)		13.0	58.50
88-1052 01	R + R REAR NUMBER PLATE		2.0	9.00
72-4573 01)	R + R TAILGATE LOCK STRIKER		3.0	13.50
68-3080 01	R + R CENTRE REAR PANEL TRIM		3.0	13.50
60-2430 01	R + R BOTH REAR LAMP UNITS		3.0	13.50
49-4965 01	R + R RIGHT REAR SILENCER		8.0	36.00
49-8415 01	R + R R/R EXHAUST COVER		2.0	9.00
2584	L/R BUMPER CONSOLE 164 885 0031			

HIN LUNG WORKSHOP

1008 Bukit Merah Lane 3, #01-20
159722

Claim Reference:
Assessment number: HLW00044
Version: 1810
Date calculated: 14/06/2019 2:41 PM

Full Report
Registration: SME2417M TP
Printed: 14/06/2019 2:41 PM

Code	Description	WU	Price SGD
2585	R/R BUMPER CONSOLE 164 885 0131		
	Labour Cost	Hrs	WU
	Panel / Mechanical Labour	5.40	54.0
	Total of Labour		243.00

Paint

Code	Description - TWO COAT PEARL/MICA	WU	Price SGD
	RR UPP BUMPER COVER NEW PART PAINT K1R	10.0	
	LWR RR BUMPER COVER NEW PART PAINT K1R	8.0	
	RR TOWING LUG COVER NEW PART PAINT K1R	3.0	
	L/R OUTER SENSOR NEW PART PAINT K1R	3.0	

Paint Material Per Part

Code	Description	Price SGD
2583	RR UPP BUMPER COVER NEW PART PAINT K1R	44.77
2585	LWR RR BUMPER COVER NEW PART PAINT K1R	34.44
2597	RR TOWING LUG COVER NEW PART PAINT K1R	0.49
2669	L/R OUTER SENSOR NEW PART PAINT K1R	0.49

Labour Cost - Paint	Hrs	WU	Price SGD
Factor	45.00 SGD/h		
Time Paint		24.0	
Preparation Comp. Work Plastic	0.90	9.0	40.50
Total	10 WU/h	3.30	148.50

Material Cost - Paint	Price SGD
New Part Painting - Plastic K1R	80.19
Material-constant Plastic	16.20
Total	96.39

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01 Price SGD
------	-------------	-------------	----------	--------------------------------------

HIN LUNG WORKSHOP

1008 Bukit Merah Lane 3, #01-20
159722

Claim Reference:
Assessment number: HLW00044
Version: 1810
Date calculated: 14/06/2019 2:41 PM

Full Report
Registration: SME2417M TP
Printed: 14/06/2019 2:41 PM

Code	Description	Part Number	Supplier	Price SGD
2583	RR UPP BUMPER COVER	164 880 2940 9999		1,100.00 ✓
2585	LWR RR BUMPER COVER	164 885 6925		500.00 ✓
		7C45		
2593	BUMPER COVER CAP	164 885 3323		645.00 ✓
2597	RR TOWING LUG COVER	164 885 3223 9999		40.00 ✓
3286	R/R REFLECTOR	164 820 1574		42.00 ✓
8848	R/R END PIPE	164 490 2327		240.00 ✓
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			2,567.00
u: Used parts	Addition(+15.00%)			385.05
	Total			2,952.05

Final Calculation

	SGD	SGD
Parts	2,567.00	
Addition(+15.00%)	385.05	
Total Parts		2,952.05
Labour Time Base 10 WU/h		
Total 54.0 WU X 45.00 SGD/h	243.00 ✓	
Total of Labour		243.00
Paint Work Time Base 10 WU/h		
Labour Cost 33.0 WU X 45.00 SGD/h	148.50 ✓	
Material Cost	96.39 ✓	
Total Paint Including Material		244.89
Repair Cost Excludes GST		3,439.94 ✓
GST (+7.00%)		240.80
Repair Cost Included GST		3,680.74

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

TAX INVOICE

INVOICE NO. **8148909**

DATE	29/05/2019	PAGE	1
TERM	30 Days Net	SALESMAN	Ong Hai Choon
CUSTOMER REF.	SME2417M TP	OUR REF.	42717

GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E

ACCOUNT NUMBER: HINLUNG1 TIME:11:19
 HIN LUNG WORKSHOP
 BLK 1008, BUKIT MERAH LANE 3,
 #01-20
 SINGAPORE 159722
 Telephone No : 68583000

ROUTE:
 BRBM2

DELIVER TO:

HIN LUNG WORKSHOP
 BLK 1008, BUKIT MERAH LANE 3,
 #01-20
 SINGAPORE 159722



PART NO.	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
1 MBA164 880 29 40 9999	TRIM BUMPER C 2 5 8 3)	4B-01AA	1 PC	1,100.00	1,100.00
2 MBA164 885 69 25 7C45	PANELLING C 2 5 8 5)	3C-1C	1 PC	500.00	500.00
3 MBA164 885 33 23	PANELING C 2 5 4 3)	3C-1C	1 PC	645.00	645.00
4 MBA164 820 15 74	REFLECTOR RH C 2 2 8 6)	1B-6F	1 PC	42.00	42.00
5 MBA164 490 23 27	TAILPIPE C 5 8 4 5)		1 PC	240.00	240.00
6 MBA164 885 32 23 9999	COVER, TOWING EYE C 2 5 4 7)		1 PC	40.00	40.00
				TOTAL	2,567.00
				ADD GST	179.69
				AMOUNT DUE	2,746.69

GOODS RECEIVED IN GOOD ORDER AND CONDITION

*GOODS SOLD ARE NOT RETURNABLE.
 *OVERDUE ACCOUNTS SHALL BEAR INTEREST AT UOB'S PREVALING LENDING RATE
 *CASH INVOICE MUST BE PAID WITHIN 7 DAYS FROM DATE OF INVOICE

Exclusive Distributor



Payment via telegraphic transfer to
 Name of Bank: United Overseas Bank
 Account Name: Min Ghee Auto Pte Ltd
 Branch Code: 046
 Account No.: 508-309-511-3
 *Please send a screenshot of your payment/transfer confirmation to
 account@minghee.com.

SIGN & COMPANY'S STAMP



DATE
 *ALL CHEQUES MUST BE MADE PAYABLE TO
 MIN GHEE AUTO PTE. LTD.

For MIN GHEE AUTO PTE. LTD.

500+ dealers
competed to
buy my car!



- Sell ur Car for More Cash
- Highest Price or Get \$100 Free
- Get Paid Now, Handover Later

[SELL YOUR CAR](#)


Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Years Car Renewal Toyota Altis 1.8i



2011 Toyota Altis 1.8i
Price: \$11,990
GV Credit Pte Ltd


[Browse by Category](#)
[Sort by Date Posted](#) 20 results/page

1 vehicles

mercedes benz ml300

Advanced Search

Model	Model	Price	Depreciation	Reg Cost	Eng Cap	Mileage	Veh Type	Status
Search Selection	mercedes benz ml300	Any	Any	2011	Any	Any	Any	Available
	Mercedes-Benz M-Class ML300	\$80,888	\$21,270 /yr	01-Nov-2011	2,996 cc	121,000 km	SUV	Available
Well Maintained, Just Done Major Servicing, All Necessary Oil And Parts Are Replaced, Motor Oil/Filter, AT Fluid/Filter, Air And Cabin Filters, Spark Plugs, Power Steering Pump/Fluid, Brake Pads/Senso...								
Posted: 04-Apr-2019		Tags: 2011 Mercedes-Benz ML300, 2011 mercedes-benz ml300, Mercedes-Benz ML300, mercedes-benz ml300, Mercedes-Benz, ML300, ml300, Used Mercedes-Benz						

Save this search criteria, to get email alerts whenever a match is found.

For old advertisements, view [Expired ads](#)

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sports cars, luxury cars, cars or station wagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car trends, carpark rate insurance. Find buy used mercedes benz ml300, mercedes benz ml300 Singapore, used mercedes benz ml300 Singapore, used mercedes benz ml300, used vehicles Singapore or even buy mercedes benz ml300 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launch, new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable. Full insurance can be that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of any information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

Company

Hsiao Tong (LKKAuto)

From: hlungws <hlungws@singnet.com.sg>
Sent: Thursday, 20 June 2019 11:50 AM
To: Hsiao Tong (LKKAuto)
Subject: Re : SME2417M - Finalisation Documents
Attachments: MEMO.jpg; TAX INVOICE.jpg; ATA.jpg; GIA 2.jpg

Dear Hsiao Tong,

We refer to above subject and attached final documents for your reference.

Thanks & Regards,
Anna
Hin Lung Workshop
Tel: 6858 3000 Fax: 6476 0075
Address: Blk 1008 Bukit Merah Lane 3 #01-20 Singapore 159722

From: Steve Chen (LKK Auto) [mailto:SteveChen@lkkauto.com]
Sent: Thursday, 20 June 2019 10:11 AM
To: hlungws <hlungws@singnet.com.sg>
Subject: Re : SME2417M - Finalise Cost Of Repair

Hi Anna,

Sent to my office to Hsiao Tong.

Thanks

Best Regards,
Steve Chen | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: hlungws [mailto:hlungws@singnet.com.sg]
Sent: Thursday, June 20, 2019 10:09 AM
To: Steve Chen (LKK Auto)
Cc: Hsiao Tong (LKKAuto)
Subject: Re : SME2417M - Finalise Cost Of Repair

Dear Steve,

We accept your finalize amount of \$3,439.94 (P/P, before GST) with 3 repair days.

Do we email you the documents or mail out the original copies to who?

Thanks & Regards,
Anna
Hin Lung Workshop
Tel: 6858 3000 Fax: 6476 0075
Address: Blk 1008 Bukit Merah Lane 3 #01-20 Singapore 159722

From: Steve Chen (LKK Auto) [<mailto:SteveChen@lkkauto.com>]
Sent: Wednesday, 19 June 2019 8:38 PM
To: hlungws <hlungws@singnet.com.sg>
Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: SME2417M - Finalise Cost Of Repair

Dear Sir,

We confirm the finalize \$3,439.94 (P/P, before GST). 3 repair days.

Thanks

Best Regards,

Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



<TP - Mandate IA> - S9M01O5M [ACCIDENT INVOLVING SLR 6952B(OI) & SME 2417M(TP) ON 17/05/2019]

Type

🔗 Question

Message

Liability: 100%. Insured rear-ended third party. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate at \$3,982.74(all-in). TP-Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong - 21 June 2019

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 21/06/2019

Survey Details:

Date of loss	17-May-19
Date of appointment	23-May-19
Date of survey	27-May-19
Location of survey	HIN LUNG WORKSHOP

Vehicle Details:

Claim Type:	Third party
Vehicle number	SME 2417M
Make and Model	MERCEDES BENZ ML300
Date of registration	16/8/2011
Excess	
Market Value	\$70,000
Part Rebate	\$48,996
Nett Loss	\$21,004

Repair details:

Initial Estimate	\$ 7,275.94
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 2,952.05
Check items (estimate)	NIL
Labour	\$ 487.89
Total	\$ 3,439.94
Lump Sum(if applicable)	\$ -

Number of days for repair	3
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

--

Mandate:

Liability(TP)		100%
Proposed repair cost (w/GST)	\$	3,680.74
Loss of use	\$	300.00 (3days x \$100.00)
Loss of rental		NIL
Loss of income		NIL
LTA search fees	\$	2.00
Others		NIL
Proposed Total	\$	3,982.74

Hsiao Tong (LKKAuto)

From: Shu Pei (LKKAuto)
Sent: Tuesday, 25 June 2019 9:27 AM
To: Hsiao Tong (LKKAuto)
Subject: RE: New message for service request 117244, vehicle number SME2417M

☐ ESTIMATE & SURVEYOR ASSGNMENT PAPER PASS TO HANDLER	LSP	29/5/2019 10:19:02 AM
☐ finalize \$3,439.94 (P/P, before GST). 3 repair days.	CTY	19/6/2019 8:28:33 PM
☐ REC'D TP ESTIMATE_F FROM STEVE**PASS TO HSIAO TONG	STU	20/6/2019 2:17:28 PM
☐ Message Liability: 100%. Insured rear-ended third party. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate at \$3,982.74(all-in). TP-Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong – 21 June 2019	CHT	21/6/2019 3:53:16 PM
☐ 6/24/19 3:52 PM LOH Cynthia ———APPROVED	LSP	25/6/2019 9:13:59 AM

Best Regards,
Shu Pei | Admin
LKK Auto Consultants Pte Ltd
Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Admin-D (LKKAuto)
Sent: Monday, 24 June 2019 3:57 PM
To: Admin A <admin-a@lkkauto.com>
Subject: FW: New message for service request 117244, vehicle number SME2417M

Best Regards,
Summer Lee | Admin
LKK Auto Consultants Pte Ltd
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: cynthia.loh@axa.com.sg [mailto:cynthia.loh@axa.com.sg]
Sent: Monday, 24 June, 2019 3:53 PM
To: admin-d@lkkauto.com
Subject: New message for service request 117244, vehicle number SME2417M

AXA Insurance has sent you a message for claim number S9M0105M.
Please click here <https://vp.smartclaims.axa.com.sg/claim-portal/> to view the message in Vendor Portal.

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

Hsiao Tong (LKKAUTO)

From: hlungws <hlungws@singnet.com.sg>
Sent: Monday, 1 July 2019 9:20 AM
To: Hsiao Tong (LKKAUTO)
Subject: Re : SME2417M - Finalisation Documents

Dear Hsiao Tong,

We accept the settlement amount of \$3,982.74.

Thanks & Regards,
Anna
Hin Lung Workshop
Tel: 6858 3000 Fax: 6476 0075
Address: Blk 1008 Bukit Merah Lane 3 #01-20 Singapore 159722

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: Saturday, 29 June 2019 2:42 PM
To: hlungws <hlungws@singnet.com.sg>
Subject: RE: Re : SME2417M - Finalisation Documents

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$ 3,680.74
2. Loss of Use (3days x \$100.00)	\$ 300.00
3. LTA/ GIA Search Fee	\$ 2.00
Total	\$ 3,982.74

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,
Hsiao Tong, Chew | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: hlungws <hlungws@singnet.com.sg>
Sent: Thursday, 20 June 2019 11:50 AM
To: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Subject: Re : SME2417M - Finalisation Documents

Dear Hsiao Tong,

We refer to above subject and attached final documents for your reference.

Thanks & Regards,

Anna

Hin Lung Workshop

Tel: 6858 3000 Fax: 6476 0075

Address: Blk 1008 Bukit Merah Lane 3 #01-20 Singapore 159722

From: Steve Chen (LKK Auto) [<mailto:SteveChen@lkkauto.com>]

Sent: Thursday, 20 June 2019 10:11 AM

To: hlungws <hlungws@singnet.com.sg>

Subject: Re : SME2417M - Finalise Cost Of Repair

Hi Anna,

Sent to my office to Hsiao Tong.

Thanks

Best Regards,

Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: hlungws [<mailto:hlungws@singnet.com.sg>]

Sent: Thursday, June 20, 2019 10:09 AM

To: Steve Chen (LKK Auto)

Cc: Hsiao Tong (LKKAuto)

Subject: Re : SME2417M - Finalise Cost Of Repair

Dear Steve,

We accept your finalize amount of \$3,439.94 (P/P, before GST) with 3 repair days.

Do we email you the documents or mail out the original copies to who?

Thanks & Regards,

Anna

Hin Lung Workshop

Tel: 6858 3000 Fax: 6476 0075

Address: Blk 1008 Bukit Merah Lane 3 #01-20 Singapore 159722

From: Steve Chen (LKK Auto) [<mailto:SteveChen@lkkauto.com>]

Sent: Wednesday, 19 June 2019 8:38 PM

To: hlungws <hlungws@singnet.com.sg>

Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: SME2417M - Finalise Cost Of Repair

Dear Sir,

We confirm the finalize \$3,439.94 (P/P, before GST). 3 repair days.

Thanks

Best Regards,

Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Service Request Details

Claim

S9M01O5M

Reference

None

Loss Date

17 May 2019

Report Date

23 May 2019 8:55:00 AM

Request Date

23 May 2019

Due Date

30 May 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

P: Susan

T: 9.55 am

E: ✓

V: Out

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SME2417M

PROJECT

ML300-3.0

Service Address

...

Primary Contact/Insured

LAK TZE MENG

33 JURONG WEST STREET 41, #03-54, 649413, Singapore
94560270Claim Handler

LOH Cynthia

6568804843

cynthia.loh@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Catherine Chong (LKK Auto)

From: hlungws <hlungws@singnet.com.sg>
Sent: Wednesday, 22 May, 2019 6:07 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: Re : SMF2417M / SLR6952B , DOA : 17/05/2019 , TP Survey & Liability

Categories: Shekhar

Dear Sirs,

We refer to the above subject and we are the authorized representative for owner of motor vehicle no. SME2417M to resolve the above matter.

Please arrange for survey and for your information, we have already submitted Estimate repair through Audatex System on 22/05/2019.

Kindly take note that the **vehicle is not in workshop** and we need to arrange with the owner.

Please let us hear from you and we wish to know on the **liability**.

Thanks & Regards,
Anna / Susan
Hin Lung Workshop
Tel: 6858 3000 Fax: 6476 0075
Address: Blk 1008 Bukit Merah Lane 3 #01-20 Singapore 159722

HIN LUNG WORKSHOP
BLK 1008 BUKIT MERAH LANE 3 #01-20
SINGAPORE 159722
TEL: 68583000 FAX: 64760075
GST Regn. No : M2-0065859-X
Business Reg. No:52861067L

DATE : 20/06/2019

AXA Insurance Pte Ltd
8 Shenton Way, AXA Tower, #24-01
Singapore 068811
Motor Claims Department

Dear Sirs,

Accident on : 17/05/2019
Involving : SME2417M / SLR6952B

We now enclose herewith the Final repair Invoice, GIA search fee, Authorization To Act and Satisfaction Certificate for your file after being survey by your appointed surveyor LKK Auto Consultants Pte Ltd, Mr Steve Chen on 27/05/2019.

We quantify our client's claim as follows:

1) Cost of repairs	\$ 3,680.74
2) Loss of use for 3 days at \$180 per days	\$ 540.00
3) GIA search	\$ 2.00
	\$ 4,222.74

Kindly let us hear from you.

Hin Lung Workshop





Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

28 MAY 2019

LAK TZE MENG
33 JURONG WEST STREET 41
#03-54
SINGAPORE 649413

Dear Sir/ Mdm

OUR REF : CC4/ASM19009103/pb3
YOUR REF : SLR 6952B
ACCIDENT INVOLVING SLR 6952B AND SME 2417M ALONG/AT TOWARDS
PATERSON HILL ON 17/05/2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from HIN LUNG WORKSHOP acting on behalf of the owner of **SME 2417M** against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour as it is head-to-rear collision. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to cliewht@lkauto.com within 10 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6742 3197 or email us at chewht@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely



Chew Hsiao Tong
Case Handler
DID: 6742 3197
FAX: 6741 4108
EMAIL: chewht@lkkauto.com

Cc *AXA Insurance Pte Ltd*
(Motor Claims Dept)

AUTHORIZATION TO ACT

I, Smitech Engineering Pte Ltd ("the third party claimant")
of 30 Ubi Crescent #01-02 Ubi Technopark, S 408566 (address),
owner of SME 2417M (vehicle no.) hereby authorize

Hin Lung Workshop

("the workshop") to act for me with respect to my claim for repair costs and / or
rental and / or loss of use ("claim") for my vehicle no. SME 2417M

that was damaged pursuant to the accident which occurred on 17/05/2019


(date) along Patersea Road Towards Orchard Blvd. (location)

involving vehicle no/s S2R6952B ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner
that they deem fit and the workshop is further authorized to receive payment
further to settlement of my claim with payment cheque/s being made in favour of
the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf
is on a without prejudice and without admission of liability basis insofar as the
driver / owner / insurers of the other vehicle/s is concerned.

Dated this 18 day of May (month) 20 19 (year)



Signed by "the third party claimant"



Signed by "the workshop"



AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	SLR 6952B (Insd veh)	Model: Mercedes Benz (2996cc)
	SME 2417M (TP veh)	
Date of Accident/ Time:	17/05/2019	

Repair Estimate	: \$	7,785.26	
Final Repair Cost (w/GST)	: \$	3,680.74	
Loss of Use	: \$	300.00	3 days at \$100.00 per day
Rental (if any)	: \$	-	days at \$ per day
LTA / GIA Search Fee	: \$	2.00	
Others:	: \$	-	
	: \$		
Final Settlement Sum	: \$	3,982.74	

Payee Name : Hin Lung Workshop

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A)	For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B)	For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: <u>27</u>
	BOLA Liability: <u>100</u> (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.		
Remarks:		

NOTE:

- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are *not received within 7 days* of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a full and final settlement that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.



Signature of Workshop representative / Workshop stamp

Name of Representative: Tay Giok Chai

Date: 08/07/2019



Signature of Witness / Workshop stamp (if applicable)

Name of Witness: Lai Kwong Min

Date: 08/07/2019



Signature of AXA's surveyor/representative:

Name of AXA's surveyor /Representative:

Date:

HIN LUNG WORKSHOP

Blk 1008 Bukit Merah Lane 3 #01-20, S'pore 159722. Tel: 68583000 Fax: 64760075
Website: www.hinlung.com.sg GST Regn. No: M2-0065859-X

TAX INVOICE

M/s AXA INSURANCE PTE LTD
8 SHENTON WAY, #24-01 AXA TOWER
SINGAPORE 068811

INVOICE NO. : TP482
Acc/Rep Date: 17/05/2019
Policy No. : GA434876
Model : ML300 0
Veh Reg. No.: SME2417M
Invoice Date: 20/06/2019 Page: 1

<u>REPLACEMENT OF PARTS</u>		
1	RR UPP BUMPER COVER	1,100.00
1	LWR RR BUMPER COVER	500.00
1	BUMPER COVER CAP	645.00
1	RR TOWING LUG COVER	40.00
1	R/R REFLECTOR	42.00
1	R/R END PIPE	240.00
SUB-TOTAL		2,567.00
1	ADDITION (+15.00%)	385.05
Total		2,952.05

<u>LABOUR CHARGES</u>	
TOTAL OF LABOUR	243.00
TOTAL PAINT INCLUDING MATERIAL	244.89
Nett Total Before GST	3,439.94
Add GST @ 7%	240.80
Nett Total After GST	3,680.74

(Three Thousand Six Hundred Eighty and Cents Seventy-Four Only)



HIN LUNG WORKSHOP
(Workshop Manager)

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-079120

Date of Request: 18/05/2019

Your Ref No: Online Purchase

Hin Lung Workshop
Blk 1008 Bukit Merah Lane 3
#01-20
Singapore 159722

Dear Sir/Madam,

Enquiry Date 18/05/2019
Enquiry By Susan Tan Huay
TP Vehicle No. SLR6952B
Accident Date 17/05/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19009103/Epb3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN: CYNTHIA LOH

Date : 15-07-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLR 6952B	Veh. Inspected	SME 2417M
Policy No.	GA374943/1	Coverage (\$)	0.00
Claim No.	S9M01O5M	Excess (\$)	0.00
Assign From		Assign Date	23/05/2019

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ ML300	c.c	2996
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WDC1641822A717077	Colour	BROWN
Odometer	96441	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	255/50 R19	BRIDGESTONE	7 mm
L/H Front Tyre	255/50 R19	BRIDGESTONE	7 mm
R/H Rear Tyre	255/50 R19	BRIDGESTONE	7 mm
L/H Rear Tyre	255/50 R19	BRIDGESTONE	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	17/05/2019	Inspection Date	27/05/2019
Survey held at	HIN LUNG WORKSHOP BLK 1008 BUKIT MERAH LANE 3 #01-20 SINGAPORE 159722		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SME 2417M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	RR UPP BUMPER COVER (CONSISTENT) (WCP)	CUT	1,265.00	1,100.00
1	LWR RR BUMPER COVER (CONSISTENT) (WCP)	CUT	500.00	500.00
1	BUMPER COVER CAP (CONSISTENT) (WCP)	DENTED / CUT	645.00	645.00
1	RR TOWING LUG COVER (CONSISTENT) (WCP)	BROKEN	40.00	40.00
1	RR BUMPER CTR COVER (CONSISTENT) (WCP)	NOT NECESSARY	150.00	-
1	R/R BUMPER BRACKET (CONSISTENT) (WCP)	NOT NECESSARY	80.00	-
1	L/R C-MEMBER CONSOLE (CONSISTENT) (WCP)	NOT NECESSARY	200.00	-
1	R/R C-MEMBER CONSOLE (CONSISTENT) (WCP)	NOT NECESSARY	200.00	-
1	REAR BUMPER C-MEMBER (CONSISTENT) (WCP)	NOT NECESSARY	450.00	-
1	RR INNER BUMPER PART (CONSISTENT) (WCP)	NOT NECESSARY	210.00	-
1	L/R OUTER SENSOR (CONSISTENT) (WCP)	NOT NECESSARY	165.00	-
1	L/R OUT SPACER RING (CONSISTENT) (WCP)	NOT NECESSARY	8.00	-
1	R/R OUT SPACER RING (CONSISTENT) (WCP)	NOT NECESSARY	8.00	-
1	L/R GASKET FLANGE (CONSISTENT) (WCP)	NOT NECESSARY	32.00	-
1	R/R FLANGE GASKET (CONSISTENT) (WCP)	NOT NECESSARY	32.00	-
1	R/R LAMP (CONSISTENT) (WCP)	NOT NECESSARY	500.00	-
1	R/R REFLECTOR (CONSISTENT) (WCP)	BROKEN	42.00	42.00
1	R/R SILENCER (CONSISTENT) (WCP)	NOT NECESSARY	1,010.00	-
1	R/R END PIPE (CONSISTENT) (WCP)	CUT	240.00	240.00
1	L/R BUMPER CONSOLE (CONSISTENT) (WCP)	NOT NECESSARY	55.00	-
1	R/R BUMPER CONSOLE (CONSISTENT) (WCP)	NOT NECESSARY	55.00	-
1	R/R OUT SENSOR BRKT (CONSISTENT) (WCP) (NPA)	NOT NECESSARY	-	-
	COST PLUS 15%		883.05	385.05
			6,770.05	2,952.05
LABOUR				
	58.0 WU X 45.00 SGD/H.		261.00	243.00
	LABOUR COST 33.0 WU X 45.00 SGD /H .		148.50	148.50
	MATERIAL COST.		96.39	96.39
			505.89	487.89
GRAND TOTAL			7,275.94	3,439.94

Report Ref No. CC4/ASM19009103/Epb3q2



RECOMMENDED COST OF REPAIRS			3,439.94
-----------------------------	--	--	----------

Report Ref No. CC4/ASM19009103/Epb3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKKInvoice 1 (2).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	17 July 2019
LKKInspection (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 July 2019
LKKAdjustment 1a (2).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 July 2019
LKK PHOTO-3 .pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 July 2019
GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 July 2019
PAYMENT BREAKDOWN, EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	17 July 2019
AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	17 July 2019
WORKSHOP INVOICE.pdf	Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (TP)	17 July 2019
LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	17 July 2019
TP-Mandate IA dtd 210619 .pdf	Forms / Claim Documents	Assessment	LKK AUTO CONSULTANTS PTE LTD (TP)	21 June 2019
TNMF_COE REBATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	21 June 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKK Resurvey Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	21 June 2019
 LKK Survey Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	21 June 2019
 TP ESTIMATE_MARKED(FINAL).pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	21 June 2019
 Audaxia Report-SME2417M.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	21 June 2019
 Service appointment in Vendor Portal claim S9H01OSM for vehicle SME2417M.html	[[getDocumentType_AuditItem.documentType]]			23 May 2019
 EMAIL TP MRI .png	Letters and Correspondence	Workshop	VISHNU BATHAM Shakhar	23 May 2019
 GUA SME2417M TP.pdf	Reports & Statement	GUA Report	VISHNU BATHAM Shakhar	23 May 2019