

VOLKSWAGEN CENTRE SINGAPORE

9 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation Non binding - Preview

Page 1/2

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Ms.
CHIA
QIU YI
41 BRIGHT HILL DRIVE
#18-02
Singapore 573893

Document no.
Document date 22-05-2019
Customer no. 5211043795
Customer GST-ID 201009404M
Dealer 39999
Job order number 2019000684/ 1
Job order date 22-05-2019
Service Advisor MEI KWAN KONG

License plate	Model code	First registration	VIN	Model	Mileage
SMG2887D	5T13NZ	13-12-2018	WVGZZZ1TZKW013916	Touran Comfortline 1.4 TSI 110kW DSG	2,703

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
5TA807217AFGRU	Cover For Bumper Primed	1	pcs.	1,136.46	#1	1,136.46	1,216.01
5TA805915E 9B9	Spoiler Satin Black	1	pcs.	220.79	#1	220.79	236.25
5TA807248	Foam Insert	1	pcs.	51.74	#1	51.74	55.36
5TA807109K	Impact Beam	1	pcs.	552.37	#1	552.37	591.04
5TA807651D	Cross Member	1	pcs.	105.24	#1	105.24	112.61
N 90528204	Pop-Rivet	2	pcs.	0.79	#1	1.58	1.69
N 90825902	Hex Socket Head Collared	2	pcs.	2.10	#1	4.20	4.49
N 91234201	Rivetted Cap Nut	2	pcs.	2.85	#1	5.70	6.10
5TA807723	Support Part (BUMPER BRACKET LH)	1	pcs.	41.58	#1	41.58	44.49
5TA807724	Support Part (BUMPER BRACKET RH)	1	pcs.	41.58	#1	41.58	44.49
5TA807049	Guide Piece (BUMPER GUIDE LH)	1	pcs.	37.67	#1	37.67	40.31
5TA807050	Guide Piece (BUMPER GUIDE RH)	1	pcs.	37.67	#1	37.67	40.31
5TA853651L LDB	Radiator Grille With Sati	1	pcs.	377.68	#1	377.68	404.12
5TA821105	Fender (LHF)	1	pcs.	597.28	#1	597.28	639.09
5TA805911D	Wheelhouse Liner	1	pcs.	150.46	#1	150.46	160.99
5TA821135	Cross Support (LHF FENDER BRACKET)	1	pcs.	30.54	#1	30.54	32.68
5TC941113A	Led Headlight (LH)	1	pcs.	1,738.10	#1	1,738.10	1,859.77
5TA941661A	Halogen Fog Lights With S (LH)	1	pcs.	228.17	#1	228.17	244.14
5TA805588C	Lock Carrier With Mountin	1	pcs.	1,004.09	#1	1,004.09	1,074.38
5TA804593A	Bracket (LHF HEADLAMP BRACKE)	1	pcs.	9.26	#1	9.26	9.91
	FRONT NUMBER PLATE	1	pcs.	80.00	#1	80.00	85.60
	LABOUR	6	pcs.	840.00	#1	5,040.00	5,392.80
	Spray Painting	5	pcs.	800.00	#1	4,000.00	4,280.00

Quotation valid till 29-05-2019

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	15,492.16	7%	1,137.65	16,252.16	17,389.81
Total	760.00	15,492.16		1,137.65	16,252.16	17,389.81

- LKK Auto Consultants hence notify the Repairer of the following:**
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Taughtin 17495749
WP 30/5/19 1040
Resurvey before paint.
sure lkkauto.com
5-6 days.

VOLKSWAGEN CENTRE SINGAPORE

9 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 2/2

Document no.
Document date 22-05-2019
Customer no. 5211043795
Customer GST-ID 201009404M
Dealer 39999
Job order number 2019000684/ 1
Job order date 22-05-2019
Service Advisor MEI KWAN KONG

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Ms.
CHIA
QIU YI
41 BRIGHT HILL DRIVE
#18-02
Singapore 573893

License plate	Model code	First registration	VIN	Model	Mileage
SMG2887D	5T13NZ	13-12-2018	WVGZZZ1TZKW013916	Touran Comfortline 1.4 I TSI 110kW DSG	2,703

Customer

Service Advisor

-----VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).-----

LKK Auto Consultants hence notify the Repair of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplemental items must be resurveyed and in subject to final approval from Insurance Company

As recommended by Repairer