

ASS. REC. BY:

REF: CS/ASM19009105/Kgd300 Special Instructions:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Kitty Teo of ASM (AXA) Date/Time: 23/5/2019

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKD 232X Insured: _____at Workshop w/s Vin's Motor Comfort Delgro Tel: 63838115 63837730of 205 Brndell RoadPolicy No: _____ Claim No: S9M01OECSum Insured: _____ Excess: NILMake of Veh: _____ D.O.A. 1e/5/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 2:31pm @ 23/5/19 Person Contacted: Andrew Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate	✓
	SKD 232X - CS/AXA/3000083/Yy/142	D.O.A: 19/3/2013	
24/5/19 @ 1.31pm	Revert to Kitty Teo via Smart Claim. (pending COR, PL, parts price)		
24/5/19 @ 4.37pm	2nd revert to Kitty Teo via Smart Claim. (Kitty said OK)		
06/6/19 @ 1.57pm	3rd revert to Kitty Teo via Smart Claim. (repair agreed @ \$9K PLP)		
	Final Fig \$8000, 6 days (Red \$1183.30, 13%)		

ASS. REC. BY:

REF:

AA1

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$35k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKD 232X Yr Regn: 10.11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Fortune V.c.c 2694

Colour: M.D. Gray A/C: Insured / Std / NI / NA

Sp. Reading: 94187 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MRO 7x696.700104735

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / RIM or

Tyre Size: F: _____

R: 285/65R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Nexen

Front

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 18/5/19

Survey held at

Des. of Damages: Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass to

Workshop unable to repair Lump Sum.

RECEIVED 27 JUN 2019

21/6/2019

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair: 6

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / L.B.I. (\$

Smart Claim

8000

200



Service Request Details

Claim

S9M01OEC

Reference

None 

Loss Date

May 18, 2019

Report Date

May 23, 2019 2:09:08 PM

Request Date

May 23, 2019

Due Date

May 30, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SKD232X



Model

FORTUNER 2.7

Service Address

...

Primary Contact/Insured

JONATHAN ALEXANDER GORDON ALLEN
1 LEYDEN HILL, 298749, Singapore

KERRYJANEALLEN75@GMAIL.COM

Claim Handler

TEO Kitty
6568804602
kitty.teo@axa.com.sg

Additional Instructions

W/S - CDGE PLS GET DL X/S - NIL

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message



Auto
Consultants
Pte Ltd

31 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

6/6/2019

Survey Details:

Date of loss	18-May-19
Date of appointment	23-May-19
Date of survey	23-May-19
Location of survey	COMFORTDELGRO ENGINEERING

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SKD 232X
Make and Model	TOYOTA FORTUNER 2WD AUTO
Date of registration	24/10/2011
Excess	\$ -
Market Value	35,000-40,000
Part Rebate	\$ 30,672.00
Nett Loss	4,328-9,328

Repair details:

Initial Estimate	\$ 9,183.30
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 4,487.30
Check items (estimate)	\$ 2,161.50
Labour	\$ 1,650.00
Total	\$ 8,298.80
Lump Sum(if applicable)	\$ -

Number of days for repair	<u>6</u>
---------------------------	----------



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408953 TEL : (065) 62563564 FAX : (065) 62564315

Remarks:

DAMAGES CONSISTENT. REPAIR COST ECONOMICAL.
REPAIRER AGREED REPAIR COST NOT MORE THAN
\$8,000.00 ON PART BY PART BASIS. WE HAVE AUTHORISE
REPAIR.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564313

Immediate Advice

To : AXA Insurance Pte Ltd

31/5/2019

Survey Details:

Date of loss	18-May-19
Date of appointment	23-May-19
Date of survey	23-May-19
Location of survey	COMFORTDELGRO ENGINEERING

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SKD 232X
Make and Model	TOYOTA FORTUNER 2WD AUTO
Date of registration	24/10/2011
Excess	\$ -
Market Value	\$ 35,000.00
Parf Rebate	\$ 30,672.00
Nett Loss	\$ 4,328.00

Repair details:

Initial Estimate	\$ 6,096.94
------------------	-------------

Proposed/Revised repair cost:

Parts	CTL
Check items (estimate)	\$ -
Labour	\$ -
Total	#VALUE!
Lump Sum(if applicable)	\$ -

Number of days for repair	<u>6</u>
---------------------------	----------



Auto
Consultants
Pte Ltd

81 UBI AVE 1, #01-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

DAMAGES CONSISTENT. REPAIR COST NOT ECONOMICAL.
WE HAVE NOT AUTHORISE REPAIR.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	

DHAKAL Raghav

From: CDGE Braddell Private Cars Crash Repair Operation
<braddell_operation@sparkcarcare.com>
Sent: Thursday, May 23, 2019 1:33 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey; LOW Garnet; NGUETTE Kadi
Cc: CDGE Braddell Private Cars Crash Repair Counter; Patrick Chung Chan Kim; Denis Teo Chin Chye
Subject: SKD232X DOA18052019 OD CLAIM ARRANGE SURVEY
Attachments: SKD232X DOA18052019 SAS.pdf; SKD232X DOA18052019 AUDATEX EST.pdf
Categories: Raghav

Dear Sir / Madam,

Kindly arrange to survey the said vehicle at CDGE Braddell today.
Vehicle in workshop. Please reply with confirmation.

William Wang

Best Regards
External Business | ComfortDelGro Engineering Pte Ltd
Off: 6383 7656 (Ngo - Supervisor) / Off: 6383 8115 (William) / Off: 6383 7362 (Andrew)

Fax: 6281 5767
www.SPARKcarcare.com



Auto
Consultants
Pte Ltd

81 UBI AVE 1, #01-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408903 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

24/5/2019

Survey Details:

Date of loss	18-May-19
Date of appointment	23-May-19
Date of survey	23-May-19
Location of survey	COMFORTDELGRO ENGINEERING

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SKD 232X
Make and Model	TOYOTA FORTUNER 2WD AUTO
Date of registration	24/10/2011
Excess	\$ -
Market Value	\$ 35,000.00
Parf Rebate	\$ 30,672.00
Nett Loss	\$ 4,328.00

Repair details:

Initial Estimate	\$ 6,096.94
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 2,728.50
Check items (estimate)	\$ 1,911.80
Labour	\$ 1,187.34
Total	\$ 5,827.64
Lump Sum(if applicable)	\$ -

Number of days for repair	<u>6</u>
---------------------------	----------



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

DAMAGES CONSISTENT. PENDING FOR SOME PARTS
PRICES AND REPAIR COST FROM REPAIRER. WE HAVE NOT
AUTHORISE REPAIR.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	

[» Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 8453Z

Vehicle Details

Vehicle No.: SKD232X
Vehicle to be Exported: No
Intended Deregistration Date: 24 May 2019
Vehicle Make: TOYOTA
Vehicle Model: FORTUNER 2WD AUTO
Primary Colour: Grey
Manufacturing Year: 2011
Engine No.: ZTR7177200
Chassis No.: MR0ZX69G700104735
Maximum Power Output: 118.0 kW (158 bhp)
Open Market Value: \$25,038.00
Original Registration Date: 24 Oct 2011
First Registration Date: 24 Oct 2011
Transfer Count: 2
Actual ARF Paid: \$25,038.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 23 Oct 2021
PARF Rebate Amount: \$15,022.00

Intended COE Rebate Details

COE Expiry Date: 23 Oct 2021
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$64,889.00
COE Rebate Amount: \$15,650.00
Total Rebate Amount: \$30,672.00

The information contained herein is correct as at 24 May 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/05/2019 08:22
Date Of Accident	18/05/2019 15:40
Exact Location Of Accident	BRADDELL ROAD TOWARDS CTE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKD232X
Insured/Policyholder	
Name Of Registered Owner	JONATHAN ALEXANDER GORDON ALLEN
NRIC No	S6968453Z
Email Address	KERNJJANEALLEN75@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98770291
Alternative Phone No	OTHERS-97401509

Vehicle Particulars

Manufacturer	TOYOTA
Model	FORTUNER 2WD AUTO

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA170228/1
Cover Note Number	

Driver

Name of Driver	KERRY JANE ALLEN
NRIC No	S7588486I
Date Of Birth	19/03/1975
Occupation	INDOOR
Date Of Driving Pass	05/09/2005
Driving Experience	13 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97401509
Fax Number	
Contact Number	
Email Address	KERRYJANEALLEN75@GMAIL.COM

Address	1 LEYDEN HILL
Postcode	298749
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLOUDY
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : MATTHEW GORDON GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ATTACHED .

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBJ3780K
Vehicle Make/Model/Colour	NISSAN NV350
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	DANY
NRIC/Passport Number	S9534798C
Contact Number	85883862
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On Saturday 18th May 2019 at approx. 15.40 I was driving on Braddell Road toward the CTE. Suddenly I realised the vehicle in front of me has stopped because of an earlier collision. I braked very hard to avoid the vehicle in front but I could not stop in time and bumped into the vehicle in front - GBJ3780K. I got out and checked the driver was OK and there was no injuries. No one had any medical issues so we exchanged details and I drove my vehicle to a safe place to arrange a tow truck.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

K. Allen
Driver's Signature
(if driver is not the policyholder)
Date & Time:
20/5/2019
0830

[Signature]
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



redefining / insurance

AXA Insurance Pte Ltd
 1800 680 4888 (Within Singapore)
 (65) 6880 4888 (International)
 (65) 6880 4740
 customer.care@axa.com.sg
 www.axa.com.sg

account number
 15276

Certificate of Insurance

-Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) - Motor Vehicles (Third-Party Risks and Compensation) Rules, 1967 (Road Transport Act, 1967 (Malaysia))
 -Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Policy details

Policyholder name	JONATHAN ALEXANDER GORDON ALLEN	Certificate number	GA170228 / 1
Cover	Comprehensive	Chassis number	MROZX69G700104735
Plan name	Peace	Engine number	21R7177200
NCD applicable	50%		
Vehicle registration number	SKD232X		
Period of insurance	from 24/04/2019 to 23/04/2020 (both dates inclusive)		
Finance loan company	Nil		

Persons or classes of persons entitled to drive*

- (a) The Policyholder
 (b) Any Named Driver as stated in the Policy:
 1. KERRY JANE ALLEN
 (c) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1967 (Malaysia), are not to be included under these headings.

EXCESS Windscreen Excess

Not Applicable

An Additional Excess is applicable as follows:

1. S\$500 for unnamed *Authorized Driver*
2. S\$500 for declared *Young and Inexperienced Driver*
3. S\$5,000 for undeclared *Young and Inexperienced Drivers*. This additional excess is reduced to S\$2,500 if You have chosen AXA Premium Workshops.

Additional clauses & endorsements to your policy

Nil

[We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1967 (Malaysia).

AXA Insurance Pte Ltd

Authorized signature

Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189).
 The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, endorsement etc.

AXA Insurance Pte Ltd (199903512M)
 8 Shenton Way, #24-01, AXA Tower,
 Singapore 068811
 Customer Centre, #B1-01

1 of 3

ComfortDelGro Engineering Pte Ltd

Claim Reference:

Assessment number: 005858

Version: 1810

Date calculated: 23/05/2019 1:25 PM

Full Report

Registration: SKD232X

Printed: 23/05/2019 1:25 PM

Summary Information

Claim

Location: Singapore (SG)
Printed by: Toh Wee Ngo
Claim Reference:
Estimated Repair Time:
Actual Repair Days:

Work Provider: AXA Insurance Pte Ltd
Currency: SGD
Date of Incident: 18/05/19
Hire Car Start:
Hire Car End:

Vehicle Details

Vehicle

Manufacturer: TOYOTA
Model: FORTUNER
Sub Model: FORTUNER
Model Sheet Number: 70 64 02
Registration: SKD232X
VIN number: MR0ZX69G700104735
Odometer:

Model Specs

FROM 07/2011 2.7 LTR 118KW 4-SPEED AUTOMATIC PRODUCT THAILAND
TWO COAT METALLIC PREPARE OFF VEHICLE

154

Not Notified
21 May 87
Permanently After Pain
Ex nil
Fax: 62564315
6 days
May not be able to C/Rep, still
checking for parts.

LINK Auto Consultants hence notify the Repairer of the following:

- To survey before/after some painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal consultation is advised
- Supplemental survey may be requested and is subject to prior approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

ComfortDelGro Engineering Pte Ltd

Claim Reference:

Assessment number: 005858

Version: 1810

Date calculated: 23/05/2019 1:25 PM

Full Report

Registration: SKD232X

Printed: 23/05/2019 1:25 PM

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
B140	RENEW FRONT PANEL		34.0	153.00
B110	RENEW L/F WING		6.0	27.00
B110	RENEW R/F WING		6.0	27.00
NO NUMBER	R + R L/R FRONT FOGLAMP		1.0	4.50
B040	RENEW BOTH HEADLAMPS		5.0	22.50
	INCLUDES: ADJUST HEADLAMPS			
B020	RENEW FRONT BUMPER (REMOVED)		10.0	45.00
	INCLUDES: REQUIRED ATTACHED PARTS			
	REMOVE AND REFIT			
	NOT INCLUDED: RADIATOR GRILLE R + R			
NO NUMBER	R + R FRONT BUMPER REINFORCEMENT		2.0	9.00
B030	R + R RADIATOR GRILLE		2.0	9.00
B060	R + R BONNET		2.0	9.00
B080	R + R BONNET HINGES		1.0	4.50
B070	RENEW BONNET		6.0	27.00
	(REMOVED)			

ComfortDelGro Engineering Pte Ltd

Claim Reference:

Assessment number: 005858

Version: 1810

Date calculated: 23/05/2019 1:25 PM

Full Report

Registration: SKD232X

Printed: 23/05/2019 1:25 PM

Code	Description	WU	Price SGD
	INCLUDES: RENEW WASHER JET AND BONNET INSULATION		
530111)	R + R BONNET LOCK	2.0	9.00
530121	RENEW BONNET LOCK RELEASE CABLE	4.0	18.00
NO NUMBER	R + R BONNET STAY	1.0	4.50
NO NUMBER	R + R LANDING PANEL SUPPORT	2.0	9.00
M020	R + R RADIATOR	7.0	31.50
	INCLUDES: BLEED COOLING SYSTEM		
160101)	RENEW UPPER RADIATOR HOSE	4.0	18.00
160111)	RENEW LOWER RADIATOR HOSE	5.0	22.50
160021	R + R OVERFLOW TANK	4.0	18.00
161011	R + R WATER PUMP	12.0	54.00
161011K	ADDITIONAL WORK FOR VEHICLE WITH AIR	2.0	9.00
111261)	DETACH + REFIT L/F ENGINE SUPPORT	2.0	9.00
111261)	R + R LEFT FRONT ENGINE MOUNTING	2.0	9.00
111261)	DETACH + REFIT R/F ENGINE SUPPORT	2.0	9.00
111261)	R + R RIGHT FRONT ENGINE MOUNT	2.0	9.00
NO NUMBER	R + R TRANSMISSION BRACKET	3.0	13.50
NO NUMBER	R + R OIL PAN PROTECTION PANEL	2.0	9.00
M010	RENEW CONDENSER	10.0	45.00
NO NUMBER	R + R CONDENSOR / COMPRESSOR PIPE	2.0	9.00
NO NUMBER	R + R CONDENSER/EVAPORATOR HOSE	3.0	13.50
NO NUMBER	R + R EVAPORATOR-/COMPRESSOR HOSE	3.0	13.50
NO NUMBER	REFILL AIR CONDITIONING	4.0	18.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		15.30	153.0
Total of Labour			688.50

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h	
Code	Description - TWO COAT METALLIC	WU	Price SGD
	BONNET NEW PART PAINTING	23.0	
	L/F WING NEW PART PAINTING	11.0	
	R/F WING NEW PART PAINTING	11.0	
	LOCK CARRIER SUPPORT SURFACE PAINT	4.0	
	FRONT PANEL CPL SURFACE PAINT	7.0	

ComfortDelGro Engineering Pte Ltd

Claim Reference:

Assessment number: 005858

Version: 1810

Date calculated: 23/05/2019 1:25 PM

Full Report

Registration: SKD232X

Printed: 23/05/2019 1:25 PM

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	74.82
0741	L/F WING NEW PART PAINTING	24.25
0742	R/F WING NEW PART PAINTING	24.25
0988	LOCK CARRIER SUPPORT SURFACE PAINT	1.99
1009	FRONT PANEL CPL SURFACE PAINT	16.43

Labour Cost - Paint

Factor	45.00 SGD/h	Hrs	WU	Price SGD
Time Paint			56.0	
Preparation Main Work Metal		2.50	25.0	112.50
Total	10 WU/h	8.10	81.0	364.50

Material Cost - Paint

	Price SGD
New Part Painting	123.32
Surface-/Blend Paint	18.42
Material-constant Metal Preparation	28.60
Total	170.34

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01	Price SGD
0281	FRONT BUMPER	52119 0K989	B ₁		0.00 ✓
0300	FR LWR BUMPER GRILLE	53112 0K140		CN ₂	0.00 ✓
0321	L/F BUMPER BRACKET	52140 0K010			45.00 ?
0322	R/F BUMPER BRACKET	52130 0K010			45.00 ?
0337	L/F UPP BUMPER BRKT	52116 0K080			35.00 ?
0338	R/F UPP BUMPER BRKT	52115 0K080			35.00 ?
0339	FRT BUMPER REINF	52021 0K022		B ₁	0.00 ✓
0350	FRT BUMPER CLAMP KIT	52161 02030		M ₂	16.00 ✓
0410	GRILLE	53111 0K700		B ₂	250.00 ✓
0411	RADIATOR GRILLE TRIM	53121 0K560		M ₁	150.00 ✓
0431	MANUFACTURER BADGE	75311 0K060		M ₁	0.00 ✓
0471	BONNET	53301 0K101		B ₁	380.00 ✓
0475	L/F HINGE	53420 0K020			45.00 ?
0476	R/F HINGE	53410 0K020			45.00 ?
0492	BONNET LOCK	53510 0K271		O ₁	58.00 ✓
0497	BONNET LEVER	53441 0K010			45.00 ?
0500	BONNET CABLE	53630 0K010			45.00 ?

ComfortDelGro Engineering Pte Ltd

Claim Reference:

Assessment number: 005858

Version: 1810

Date calculated: 23/05/2019 1:25 PM

Full Report

Registration: SKD232X

Printed: 23/05/2019 1:25 PM

Code	Description	Part Number	Supplier	Price SGD	
0524	FRONT BONNET SEAL	53381 0K010		45.00	✓
0527	UPP RAD GRILLE SEAL	53397 0K050		20.00	✓
0561	LEFT HEADLAMP ASSY	81150 0K501	CM	300.00	✓
0562	RIGHT HEADLAMP ASSY	81110 0K501	CM	300.00	✓
0637	L/F FOG LAMP CPL	81220 0K080		100.00	✓
0638	R/F FOG LAMP CPL	81210 0K080	Sm	100.00	X
0653	L/FOG LAMP COVER	52128 0K040	Out	45.00	✓
0654	R/FOG LAMP COVER	52127 0K040		45.00	✓
0741	L/F WING	53812 0K110	Bu	200.00	✓
0742	R/F WING	53811 0K110	Bu	200.00	✓
0789	L/F WING CLAMP KIT	91621 40614	Sm	16.00	✓
0790	R/F WING CLAMP KIT	91621 40614	Sm	16.00	✓
0801	L/F W-ARCH MOULDING	53848 0K907		150.00	✓
0802	R/F W-ARCH MOULDING	53847 0K907		150.00	✓
0841	L/W-HOUSE	53806 0K080		90.00	✓
	INSULATION				
0842	R/W-HOUSE	53805 0K080		90.00	✓
	INSULATION				
0988	LOCK CARRIER SUPPORT	53208 0K010		0.00	✓
1009	FRONT PANEL CPL	53201 0K170	Bu	350.00	✓
4465	CONDENSER	88460 0K110	Sm	0.00	✓
4479	COMPR/CONDENSER	88711 0K182		0.00	✓
	TUBE				
4480	EVAP/COMPR PIPE	88704 0K281		0.00	✓
4481	COND/EVAPORATOR	88710 0K390		0.00	✓
	PIPE				
7761	RADIATOR	16400 0L170		0.00	✓
7767	AIR GUIDE PANEL	16711 0C120	Dir	0.00	✓
7773	LWR RADIATOR HOSE	16572 0C070		28.00	✓
7776	UPPER RADIATOR HOSE	16571 0C080	Sm	0.00	X
7787	WASHER BOTTLE	16470 0C060	Sm	0.00	X
7793	COOLING FAN	16361 0C011		80.00	✓
7801	FAN CLUTCH	16210 75120		180.00	✓
7813	WATER PUMP	16100 79445		120.00	✓
7855	WATER PUMP BELT	90916 T2024	Sm	70.00	X
8631	L/RUBBER BUSH	12306 75040		65.00	✓
8632	R/RUBBER BUSH	12305 75100		65.00	✓
8780	FRT ENG PROT PANEL	51410 0K021		90.00	✓
8911	LWR GEARBOX CARRIER	12371 0C091		70.00	✓
1003	F BUMPER PIECE	521610K040		10.00	✓
1004	ENG UNDER CVR CLIP	521610K050	u	20.00	X
1005	L/F AIR GUIDE	532940K060	CM	45.00	✓
1006	R/F AIR GUIDE	532930K060	CM	45.00	✓

ComfortDelGro Engineering Pte Ltd

Claim Reference:

Assessment number: 005858

Version: 1810

Date calculated: 23/05/2019 1:25 PM

Full Report

Registration: SKD232X

Printed: 23/05/2019 1:25 PM

Code	Description	Part Number	Supplier	Price SGD
1007	F AIR GUIDE CLIPS	90467T0007		14.00 ✓
1008	BONNET STAND GROMMET	90480T0006		5.00 ✓
1009	BONNET STAND HOLDER	534520K010		8.00 ✓
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			4,326.00
u: Used parts	Addition(+10.00%)			432.60
	Total			4,758.60

Extras

Code	Description	Price SGD
1000	F NO PLATE W CASING	35.00* ✓
1001	COOLANT	30.00* 201 ✓
1002	AIRCON GAS	50.00* ✓
	Total Extras	115.00

Final Calculation

	SGD	SGD
Parts		
Addition(+10.00%)	4,326.00	
Total Parts	432.60	4,758.60
Labour Time Base 10 WU/h		
Total 153.0 WU X 45.00 SGD/h	688.50	
Total of Labour		688.50
Total Of Extras		115.00
Paint Work Time Base 10 WU/h		
Labour Cost 81.0 WU X 45.00 SGD/h	364.50	
Material Cost	170.34	
Total Paint Including Material		534.84
Repair Cost Excludes GST		6,096.94
GST (+7.0%)		426.79
Repair Cost Included GST		6,523.73

ComfortDelGro Engineering Pte Ltd

Claim Reference:

Assessment number: 005858

Version: 1810

Date calculated: 23/05/2019 1:25 PM

Full Report

Registration: SKD232X

Printed: 23/05/2019 1:25 PM

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

Vin's

AUTOMOTIVE GROUP

6456 5062
6786 1111

Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722

6453 2121 (4 lines) / 6458 1111 (24 hrs)

6459 9795 / 6459 0433

admin@vinsautogroup.com.sg

www.vinsautogroup.com.sg

Our Ref : OD/062019/3899

Accident date: 18/5/2019

Your Ref : GA170228/1

Tax Invoice :

Date : 3/6/2019

Not Authorised

MOTOR CLAIM DEPARTMENT

AXA INSURANCE (S) PTE LTD

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

ESTIMATE COST OF REPAIRS

Vehicle No. : SKD232X

Model : TOYOTA FORTUNER 2WD AUTO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1	pc	Front bonnet	\$	<i>As</i>	360.00	✓
2	pcs	Front bonnet hinge @ \$45.00	\$		90.00	?
1	pc	Front bonnet rubber	\$		45.00	?
1	pc	Front bonnet lower lock	\$	<i>Dis</i>	58.00	✓
1	pc	Front grille	\$	<i>mit</i>	240.00	✓
1	pc	Front grille chrome	\$	<i>mit</i>	150.00	✓
1	pc	Front grille emblem	\$	<i>mit</i>	180.00	✓
2	pcs	Front headlamp @ \$280.00	\$	<i>CM</i>	560.00	✓
1	pc	Front bumper (special order)	\$	<i>As</i>	480.00	✓
1	pc	Front bumper centre grille (special order)	\$	<i>CM</i>	190.00	✓
1	pc	Front bumper LH fog lamp	\$		100.00	?
2	pcs	Front bumper fog lamp cover @ \$45.00	\$	<i>dis ?</i>	90.00	✓
2	pcs	Front bumper side retainer @ \$45.00	\$	<i>Dis</i>	90.00	✓
1	pc	Front bumper reinforcement (special order)	\$	<i>As</i>	190.00	✓
2	pcs	Front bumper reinforcement bracket @ \$35.00	\$		70.00	?
2	pcs	Front fender @ \$180.00	\$	<i>As</i>	360.00	✓
2	pcs	Front fender inner sheild @ \$90.00	\$	<i>Sm</i>	180.00	X
20	pcs	Front fender inner sheild clips @ \$2.00	\$	<i>new</i>	40.00	X ✓
		Balance C/F	\$		3,473.00	

* road take photo wear & tear



AUTOMOTIVE GROUP

Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722

6453 2121 (4 lines) / 6458 1111 (24 hrs)

6459 9795 / 6459 0433

admin@vinsautogroup.com.sg

www.vinsautogroup.com.sg

Our Ref : OD/062019/3899

Accident date: 18/5/2019

Your Ref : GA170228/1

Balance B/F

Tax Invoice :

Date : 3/6/2019

\$ 3,473.00

- | | | |
|---|-----|---|
| 1 | pc | Front support panel |
| 1 | pc | Front air cond condenser (special order) |
| 1 | pc | Front air cond condenser receive pipe |
| 1 | pc | Front air cond condenser suction pipe |
| 2 | pcs | Front air cond condenser side guide @ \$45.00 |
| 1 | pc | Front air cond condenser temperature sensor |
| 1 | pc | Front radiator (special order) |
| 1 | pc | Front radiator top hose |
| 1 | pc | Front radiator lower hose |
| 1 | pc | Front radiator fan clutch |
| 1 | pc | Front radiator fan clutch cowl |
| 1 | pc | Front radiator fan blade |
| 1 | pc | Water pump belt |

\$	<i>B1</i>	340.00	✓
\$	<i>Pu</i>	710.00	✓
\$		330.00	?
\$	<i>Sm</i>	270.00	X
\$	<i>cm</i>	90.00	✓
\$		50.00	?
\$		820.00	?
\$	<i>in</i>	30.00	X
\$	<i>in</i>	30.00	X
\$		160.00	?
\$		130.00	?
\$		110.00	?
\$		60.00	?
\$		6,603.00	
\$		660.30	
\$		7,263.30	

Add 10%

- | | | |
|---|----|--------------------|
| 1 | pc | Front number plate |
|---|----|--------------------|

\$	<i>B1</i>	40.00	N	✓
\$		120.00		100%
\$		780.00		650%
\$		980.00		900%
\$		9,183.30		

- | | | |
|--|--|-------------------------|
| | | To refill air cond gas |
| | | To repair front damages |
| | | To spray painting |

VIN'S MOTOR PTE LTD

Vin's

AUTOMOTIVE GROUP

64565062

b786 1111

Rim Lin

7/6/19 1610205

Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722

6453 2121 (4 lines) / 6458 1111 (24 hrs)

6459 9795 / 6459 0433

admin@vinsautogroup.com.sg

www.vinsautogroup.com.sg

Our Ref : OD/062019/3899
Accident date: 18/5/2019
Your Ref : GA170228/1

Tax Invoice :

Date : 3/6/2019

Not Authorized

MOTOR CLAIM DEPARTMENT
AXA INSURANCE (S) PTE LTD
8 Shenton Way
#27-01 AXA Tower
Singapore 068811

ESTIMATE COST OF REPAIRS

Vehicle No.: SKD232X
Model: TOYOTA FORTUNER 2WD AUTO

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

pic taken	1	pc	Front bonnet		\$	360.00	✓
	✓2	pcs	Front bonnet hinge @ \$45.00		\$	90.00	✓
	✓1	pc	Front bonnet rubber		\$	45.00	✗
	1	pc	Front bonnet lower lock		\$	58.00	✓
	1	pc	Front grille		\$	240.00	✓
	1	pc	Front grille chrome		\$	150.00	✓
	1	pc	Front grille emblem		\$	180.00	✓
	2	pcs	Front headlamp @ \$280.00		\$	560.00	✓
	1	pc	Front bumper (special order)		\$	480.00	✓
	1	pc	Front bumper centre grille (special order)		\$	190.00	✓
	✓1	pc	Front bumper LH fog lamp		\$	100.00	✓
	2	pcs	Front bumper fog lamp cover @ \$45.00		\$	90.00	✓
	2	pcs	Front bumper side retainer @ \$45.00		\$	90.00	✓
	1	pc	Front bumper reinforcement (special order)		\$	190.00	✓
2	pcs	Front bumper reinforcement bracket @ \$35.00		\$	70.00	✗	
2	pcs	Front fender @ \$180.00		\$	360.00	✓	
✓2	pcs	Front fender inner sheild @ \$90.00		\$	180.00	✗	
✓20	pcs	Front fender inner sheild clips @ \$2.00		\$	40.00	✗	
		Balance C/F		\$	3,473.00		

* need take photo
work & repair

Vin's

AUTOMOTIVE GROUP

Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
6453 2121 (4 lines) / 6458 1111 (24 hrs)
6459 9795 / 6459 0433
admin@vinsautogroup.com.sg
www.vinsautogroup.com.sg

Our Ref : OD/062019/3899

Accident date: 18/5/2019

Your Ref : GA170228/1

Balance B/F

Tax Invoice :

Date : 3/6/2019

\$ 3,473.00

- 1 pc Front support panel
- 1 pc Front air cond condenser (special order)
- ✓ 1 pc Front air cond condenser receive pipe
- 1 pc Front air cond condenser suction pipe
- 2 pcs Front air cond condenser side guide @ \$45.00
- ✓ 1 pc Front air cond condenser temperature sensor
- ✓ 1 pc Front radiator (special order)
- 1 pc Front radiator top hose
- 1 pc Front radiator lower hose
- ✓ 1 pc Front radiator fan clutch
- ✓ 1 pc Front radiator fan clutch cowling
- ✓ 1 pc Front radiator fan blade
- ✓ 1 pc Water pump belt

Add 10%

- 1 pc Front number plate

To refill air cond gas


To repair front damages

To spray painting

\$	At	340.00	✓
\$	Pu	710.00	✓
\$	At	330.00	✓
\$	Pu	270.00	X
\$	cm	90.00	✓
\$	At	50.00	✓
\$	Pu	820.00	✓
\$	in	30.00	X
\$	in	30.00	X
\$	Ja	160.00	✓
\$	cm	130.00	✓
\$	Dir	110.00	✓
\$	At	60.00	✓
\$		6,603.00	
\$		660.30	
\$		7,263.30	

\$	At	40.00	N	✓
\$		120.00	100%	
\$		780.00	65%	
\$		980.00	90%	
\$		9,183.30		

VIN'S MOTOR PTE LTD





AUTOMOTIVE GROUP

A Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
T 6453 2121 (4 lines) / 6458 1111 (24 hrs)
F 6459 9795 / 6459 0433
E admin@vinsautogroup.com.sg
W www.vinsautogroup.com.sg

Our Ref : OD/062019/3899
Accident date: 18/5/2019
Your Ref : GA170228/1

Tax Invoice : VM20194075

Date : 22/6/2019

MOTOR CLAIM DEPARTMENT
AXA INSURANCE (S) PTE LTD
8 Shenton Way
#27-01 AXA Tower
Singapore 068811

FINAL REPAIR BILL TO

Vehicle No. : SKD232X
Model : TOYOTA FORTUNER 2WD AUTO

To supply spare parts

To repair front damages


To spray painting

Total amount agreed as at limit repair
Add : 7% GST

\$	8,000.00
\$	560.00
\$	<u>8,560.00</u>

VIN'S MOTOR PTE LTD

Please issue Cheque to: Vin's Motor Pte Ltd
Please transfer to: Vin's Motor Pte Ltd
UOB Current Account
A/C No: 451-307-638-4



Claim no: OD/S9M010EC

SATISFACTION CUM DISCHARGE VOUCHER

To: AXA Insurance Pte Ltd

I/We hereby declare that the repairs to my/our motor vehicle registration no. _____

SKD232X have been completed to my/our satisfaction and I/We agree that

payment of the sum of \$ 8560.00 to the repairer for such repairs shall

be in full discharge of my/our claim under Policy No. GA170228/1

in respect of the damage caused to my/our said motor vehicle in the accident

which occurred on 18/05/2019

Date : 14/6/2019

Signature
(Insured)

KJ Allen

NRIC No.

S7588486I