



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

LIM YEW KIAT

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

23/05/2019

TPlantae

Jic le

Accident date: 21/05/2019

Estimated repair cost for vehicle no: SJN5890Y TOYOTA VIOS 1.5 E A '09

CHASSIS: MR053HY9305092075

S/n	Qty	Items	U/price	Amount
1	1	Front Bonnet <i>Repair</i>		\$565.00 <i>X</i>
2	2	Front Bonnet Hinge <i>2nd</i>	\$55.00	\$110.00 <i>+</i>
3	1	Front Bonnet Lock <i>1st</i>		\$105.00 <i>+</i>
4	2	Front Head Lamp <i>cracked</i>	\$455.00	\$910.00 <i>✓</i>
5	1	Front Bumper <i>replaced</i>		\$485.00 <i>✓</i>
6	10	Front Bumper Clip <i>new</i>	\$6.50	\$65.00 <i>30</i>
7	1	Front Bumper Emblem Logo <i>new</i>		\$55.00 <i>✓</i>
8	2	Front Bumper Side Retainer <i>new</i>	\$65.00	\$130.00 <i>✓</i>
9	2	Front Bumper Fog Lamp Cover <i>Not New</i>	\$68.00	\$136.00 <i>X</i>
10	1	Front Bumper Number Plate <i>Bent</i>		\$50.00 <i>✓</i>
11	1	Front Bumper Towing Cover <i>replaced</i>		\$53.00 <i>✓</i>
12	1	Front Bumper Center Support <i>replaced</i>		\$115.00 <i>✓</i>
13	1	Front Bumper Center Lower Garnish <i>replaced</i>		\$88.00 <i>✓</i>
14	2	Front Bumper Bottom Cover <i>Not New</i>	\$155.00	\$310.00 <i>X</i>
15	1	Front Bumper Reinforcement <i>Bent</i>		\$382.00 <i>✓</i>
16	2	Front Bumper Reinforcement Bracket <i>Bent</i>	\$202.00	\$404.00 <i>✓</i>
17	1	Front Bumper Grille <i>cracked</i>		\$255.00 <i>✓</i>
18	1	Front Bumper Grille Chrome <i>new</i>		\$135.00 <i>+</i>
19	8	Front Bumper Grille Clip <i>new</i>	\$6.50	\$52.00 <i>20</i>
20	1	Front Support Panel <i>Bent</i>		\$925.00 <i>X 651</i>
21	2	Front Horn <i>Here</i>	\$110.00	\$220.00 <i>+</i>
22	1	Front Air-Con Condenser <i>Bent</i>		\$1,255.00 <i>✓</i>
23	1	Front Radiator <i>Bent</i>		\$1,819.00 <i>X 1585</i>
24	1	Front Radiator Fan Motor <i>new</i>		\$580.00 <i>+</i>
25	1	Front Radiator Side Cover <i>cracked</i>		\$105.00 <i>✓</i>
26	1	Rear Boot Lid <i>Buckled</i>		\$590.10 <i>✓</i>
27	2	Rear Boot Lid Hinge <i>Bent</i>	\$123.05	\$246.10 <i>✓</i>
28	1	Rear Boot Lid Emblem Logo <i>new</i>		\$42.50 <i>✓</i>

29	1	Rear Boot Lid Vios Logo	<i>3 New</i>		\$43.55	✓
30	1	Rear Boot Lid E Logo			\$28.20	✓
31	1	Rear Boot Lid Inner Lock	<i>damd</i>		\$182.25	✓
32	1	Rear Boot Lid Inner Rubber	<i>lt</i>		\$161.40	✓
33	1	Rear Boot Lid Number Plate	<i>HE m</i>		\$50.00	X
34	2	Rear Boot Lid Number Plate Lamp	<i>HE m</i>	\$83.10	\$166.20	X
35	1	Rear Boot Lid Centre Moulding	<i>HE m</i>		\$172.85	X
36	2	Rear Tail Lamp	<i>cracked</i>	\$321.45	\$642.90	✓
37	4	Rear Tail Lamp Clip	<i>new</i>	\$8.00	\$32.00	✓
38	2	Rear Tail Lamp Panel	<i>LH dented</i>	\$189.90	\$379.80	189.90
39	1	Rear Bumper	<i>Distorted</i>		\$472.00	✓
40	10	Rear Bumper Clip	<i>new</i>	\$6.50	\$65.00	30
41	1	Rear Bumper Reverse Sensor	<i>Damaged</i>		\$350.00	20/10/09
42	2	Rear Bumper Side Retainer Outer	<i>3 New</i>	\$131.40	\$262.80	120
43	2	Rear Bumper Side Retainer Inner		\$121.25	\$242.50	120
44	2	Rear Bumper Side Reflector	<i>cracked</i>	\$182.25	\$364.50	✓
45	2	Rear Bumper Mud Shield	<i>3 New</i>	\$182.20	\$364.40	✓
46	12	Rear Bumper Mud Shield Clip	<i>3 New</i>	\$6.50	\$78.00	+
47	1	Rear End Panel	<i>Distorted</i>		\$781.50	✓
48	1	Rear End Panel Top Garnish	<i>Deland</i>		\$281.45	✓
49	2	Rear Fender	<i>RH Buckled</i>	\$981.75	\$1,963.50	981.75
50	1	Rear R/H Fender Inner Panel	<i>Repair</i>		\$829.60	X
51	1	Rear L/H Fender Air Duct	<i>new</i>		\$138.90	X
52	2	Rear Fender Inner Trim Board	<i>LH torn</i>	\$314.40	\$628.80	225
53	16	Rear Fender Inner Trim Board Clip	<i>new</i>	\$6.50	\$104.00	30
54	1	Rear Spare Tyre Panel	<i>Buckled</i>		\$681.75	✓
55	1	Rear Spare Tyre Panel Top Cover	<i>torn</i>		\$289.95	✓
56	1	Rear Spare Tyre Panel & End Panel Sealant	<i>HE m</i>		\$450.00	X
57	2	Rear Spare Tyre Panel Top Sponge	<i>del</i>	\$382.20	\$764.40	3056
58	1	Rear Exhaust	<i>Best</i>		\$781.45	555
59	1	Rear Exhaust Chrome Pipe	<i>Best</i>		\$166.00	80(SW)
60	2	Rear Exhaust Mounting	<i>HE m</i>	\$64.80	\$129.60	X
61	1	Rear Centre Exhaust	<i>Repair</i>		\$787.20	X
62	1	Rear Windscreen Seal	<i>3 New</i>		\$85.00	✓
63	1	Rear Windscreen Moulding			\$132.10	✓

Subtotal :- \$23,160.65

14241.70

S.N: 280

(10681.27)

SIN 58907.

Labour charges

To remove & refit cushion & trim board	\$280.00 120
To remove & refit reverse sensor	\$100.00 50
To remove & refit rear windscreen	\$120.00 ✓
Gum	\$50.00 ✓
To remove & refit petrol tank	\$280.00 80
To check wiring	\$100.00 60
Tuff kote	\$150.00 120
Towing fee	\$100.00 60
Panel beating	\$3,000.00 2400
Spray painting	\$2,200.00 2000
To remove rear and centre exhaust 80 350	

5160

Subtotal :- \$6,380.00
 Total:- \$29,540.65

total: 142127
 6/5: 12.9K
 14 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

12.9K
 14 days