

REF:

REF:

INC

TAX/05/19/2013

Bureau: NA ~

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OO/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SMG6125T

Policy No. 508272209-03 (04/03/2019-)

Claims No. MT/1045362-002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

X	X	X
N/S	O/S	

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? Yes or No

GIA / PR Sec: _____ Consistent? Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lump Sum: _____ % Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHF 1042X Yr Regn: 23 DEC 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA PRADO c.o. 1,798

Colour: MAROON A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radi: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKN36U005755108

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / SIRIm / STDARIm or

Tyre Size: F: 195/65 R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or NELTON

Front R/Bol. 6 mm

R/Bol. 6 mm

L/Bol. 6 mm

D.O.A. 18/5/19 U.O.I. 22/5/19

Survey held at SMT WOODLAND

Des. of Damages: (Fr) / (Rear) / O/S / N/S / UIC / Roof top or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	SHF 1042X - X
	SMG 6125T - X
30/7/19	FINALIZED LUMP SUM REPAIR \$2,300.00 / 4 REPAIR DAYS
	Used # 10397.40, 82%

Date/Time, File Pass to? ☐ : Prelim ReportDate/Time, File Return to? ☐ : Final Report

2)

Report Format: 7P

Lump Sum / L.S.: (\$ 2300)

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Foot:

Transportation:

Add Fee: ☐ : Site Insp (\$ _____) S + RS \$1☐ : Interview (\$ _____) Photos☐ : Tech. Invo (\$ _____) Other☐ : Weekend (\$ _____)

TOTAL

Shiau Chan (LKKAUTO)

From: MTCL@income.com.sg
Sent: Wednesday, 31 July 2019 4:01 PM
To: Shiau Chan (LKKAUTO)
Subject: RE: REQUEST CLAIM NUMBER

Hi

Claims registered.
Our reference number indicated below for your reference.

Desmond Foo
Manager, Motor Insurance
T +65 6430 7976
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

in with you

From: Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]
Sent: Wednesday, 31 July 2019 11:56 AM
To: MTCL@income.com.sg
Subject: REQUEST CLAIM NUMBER

Dear Sir/Madam,

Please refer to the below:

TP Claims against NTUC Income: Follow-Through Survey

Date : 31/07/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	D:
1	MT/1045362-002	SMRT TAXIS PTE LTD	SHF 1042X	SMG 6125T	

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

eBaoTech

General Claim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident
Vehicle No. (For Motor) Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5087272209-03		HUA HONG PTE. LTD.	200900309M	GFT	drive PREMIUM	SMG6125T	SMG6125T	04/03/2019	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/05/2019 08:52
Date Of Accident	18/05/2019 02:30
Exact Location Of Accident	NORTH CANAL ROAD TOWARDS EU TONG SEN STREET
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHF1042X
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	
Driver	
Name of Driver	ROSMAN B YUSOPE
NRIC No	S1716497Z
Date Of Birth	27/07/1965
Occupation	OUTDOOR
Date Of Driving Pass	23/12/1982
Driving Experience	36 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	468A
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT -T/20190518/2142

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	UNKNOWN
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SMG6125T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIM YUAN HUAJ
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Eu Tong SenG St

Merchant Rd

New Bridge Rd

North Canal Rd

A

B

C

A = SHP1042X
B = SMGT6125T
C = Unknown

$C = \text{Unknown}$

2115719

DECLARATION:

I/We declare the foregoing particulars are true in every respect.



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 01

 21/5/19
Driver's Signature
(If driver is not the policyholder)
Date & Time:

 21/5/2019
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20190521/2177

Police Station Of Origin:
Joo Chiat NPP
267 Onan Road SINGAPORE 424773
Tel No: 1800-3459999

1 of 3

Report No, T/20190521/2177

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 21/05/2019 21:10		Vide Report No.: T/20190518/2142		Station Diary No.: 40	
Informant's Particulars					
Name of Informant: ROSMAN B YUSOPE			Address: APT BLK 468A FERNVALE LINK #03-535 SINGAPORE 791468		
ID Type / ID No.: NRIC NO / S1716497Z			Contact No.: Home/Office: Mobile: 92254200		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 53	Date of Birth: 27/07/1965	Type of Informant: Driver		
Race: Malay			Language:		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident				
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 18/05/2019 02:30	Type of Location: X-Junction
Location: NORTH CANAL ROAD Along North Canal Road and junction of Eu Tong Seng Road near Maybank building				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control:	Traffic Volume:	
Type of Collision:			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHF1042X	Car				Totally Damaged	0
SMG6125T	Car				Slightly Damaged	0

**POLICE FORCE**

T/20190521/2177

2 of 3

Police Station Of Origin:
Joo Chiat NPP
267 Onan Road SINGAPORE 424773
Tel No: 1800-3459999

Report No. T/20190521/2177

CONTINUATION OF REPORT**Brief Details.**

On 18/05/2019 at about 0230hrs, I was driving my taxi along North Canal Road at the junction of Eu Tong Seng Road near Maybank building. As I saw the traffic light green arrow and it was in my favour, I made a right turned when suddenly one black vehicle from the opposite direction beat the red light. I immediately applied my brake to prevent collision, however the black car's right part of the body grazed through my front bumper. The black car continued driving without stopping.

Suddenly, one car (SMG6125T) who was behind my taxi hit onto my rear as he was unable to brake in time. After the incident, myself and the driver behind me got out from our vehicles and exchanged particulars.

No one was injured. I have an in-car camera the recorded the black car the beat the red light and grazed my front bumper.

My taxi front right signal light cracked, front bumper scratch, rear bumper and car boot dented. The car that was behind me suffered damage on his front bonnet and bumper was dented.



SINGAPORE
POLICE FORCE



T/20190521/2177

Police Station Of Origin:
Joo Chiat NPP
267 Onan Road SINGAPORE 424773
Tel No: 1800-3459999

3 of 3

Report No. T/20190521/2177

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

G /

Sgt 2 LIM XI HAO, NICHOLAS

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

21/05/2019 21:10

Officer In Charge Of Case:

TP / HRT /

SJ KALESWARI PALANI

Contact No.: 65476902

Classification Of Case:

Authentication Stamp
NP168



SINGAPORE
POLICE FORCE

SIGNATURE

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	SHF1042X
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Scheme:	Taxi (Company)
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Chassis No.:	JTDKN36U005755108
Propellant:	Petrol-Electric
Engine No.:	2ZR6252371
Motor No.:	3JM6252371
Engine Capacity:	1798 cc
Power Rating:	60.0 kW
Maximum Power Output:	100.0 kW (134 bhp)
Maximum Laden Weight:	1805 kg
Unladen Weight:	1370 kg
Year Of Manufacture:	2014
Original Registration Date:	23 Dec 2014
Lifespan Expiry Date:	22 Dec 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
PQP Paid:	\$51,668.00
COE Expiry Date:	22 Dec 2022
Road Tax Expiry Date:	22 Dec 2019
PARF Eligibility Expiry Date:	22 Dec 2022
Inspection Due Date:	22 Dec 2019
Intended Transfer Date:	05 Aug 2019
CO2 Emission:	92.00 (g/km)
CEV/VES Rebate Utilised Amount:	\$30,000.00
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay-up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

You may print this page for reference.

OK

Print

Case Details

Case Reference Number : TAX/05/19/2093

Company Type : SMRT Taxis Pte Ltd

Insurance Company Name : NTUC Income

Type of Repair : Accident Repair

Estimation ID : EST-6951-ID

Insurance Co-operative Ltd

Accident Date and Time : 17/05/2019 06:30 PM

Vehicle Registration Number : SHF1042X

Assigned By : Taxi Claims Manager Team

Vehicle Age(In Months) : 53

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remark:
One Time Key In	Main			BUMPER REAR	1	458.50	458.60	25.00	343.95	Replace	1	343.9	Replace	✓ 1/21
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0	Check	✓ ?
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check	✓ ?
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check	✓ ?
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	0	0	Check	✓ ?
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Check	✓ ?
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	0	0	Not Give	✓ XJUL
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	Not Give	✓ XJUL
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	1	171.6	Replace	✓ DEF
One Time Key In	Main			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	0	0	Check	✓ ? XJUL
One Time Key In	Main			END PANEL	1	602.10	602.10	25.00	451.58	Replace	0	0	Check	✓ ? XJUL
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	1	37.00	Replace	✓ NEC

Total Spare Part Cost 5,893.36

Surveyor Total 711.55

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 4,714.69

Final Sur Total 569.24

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace Remark
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Give * XSVL
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.0	Replace * /NEC
One Time Key In	Main			TAILGATE ASY	1	1,007.90	1,007.90	25.00	755.92	Replace	1	0	Repair * XR
One Time Key In	Main			TAILGATE OUTSIDE GARNISH	1	504.90	504.90	25.00	378.67	Replace	0	0	Not Give * XSVL
One Time Key In	Main			EMBLEM REAR	1	60.30	60.30	25.00	45.22	Replace	0	0	Not Give * XNN
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace * /NEC
One Time Key In	Main			NAME PLATE (PRIUS)	1	60.80	60.80	25.00	45.60	Replace	0	0	Not Give * XPN
One Time Key In	Main			NAME PLATE (TOYOTA)	1	51.90	51.90	25.00	38.92	Replace	0	0	Not Give * XNN
One Time Key In	Main			STICKER SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Give * XNN
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	0	0	Not Give * XNN
One Time Key In	Main			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	29.40	25.00	22.05	Replace	0	0	Not Give * XNN
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	29.40	25.00	22.05	Replace	0	0	Not Give * XNN
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	29.40	25.00	22.05	Replace	0	0	Not Give * XNN
One Time Key In	Main			SEALANT W/SCREEN	3	37.00	111.00	0.00	111.00	Replace	0	0	Not Give * XNN
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	0	Repair * XR
One Time Key In	Main			LENS & BODY, FR TURN RH	1	511.80	511.80	10.00	460.62	Replace	0	0	Check * ? XSVL
One Time Key In	Main			BRACKET, FR TURN LOWER RH	1	26.00	26.00	25.00	19.50	Replace	0	0	Not Give * XSVL
One Time Key In	Main			BRACKET, FR TURN UPPER RH	1	24.40	24.40	25.00	18.30	Replace	0	0	Not Give * XSVL

Total Spare Part Cost 5,893.36

Surveyor Total 711.55

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 4,714.59

Final Sur Total 569.24

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BRACKET, FR TURN	1	58.20	58.20	25.00	43.65	Replace	0	0	Not Give	X 506
One Time Key In	Main			BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	311.10	25.00	233.33	Replace	0	0	Not Give	X 506
One Time Key In	Main			BUMPER SUPPORT F/RH	1	76.40	76.40	25.00	57.30	Replace	0	0	Not Give	X 506
One Time Key In	Main			HEAD LAMP RH	1	945.20	945.20	10.00	850.68	Replace	0	0	Not Give	X 506
Total Spare Part Cost									5,893.36	Surveyor Total				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)				
Final Spare Part Cost									4,714.69	Final Sur Total				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	845.00	200	
2	Main	TO REPAIR FRONT PORTION	338.00	200	
Total:			1,183.00	400.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY REAR PANEL	180.00	0	CHECK
3	Main	TO RESPRAY TAIL GATE	378.00	200	
4	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0	NN
5	Main	TO REPSRAY FRONT BUMPER	378.00	200	
6	Main	TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	0	NN
Total:			1,674.00	600.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	NN
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	40	
Total:			1,040.00	70.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
3	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	0	NN
4	Main	TO REMOVE / REFIT WINDSCREEN	240.00	0	NN
5	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0	NN
6	Main	TO INSPECT RR LIGHTING MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30	
7	Main	TO WASH AND VACUUM	60.00	0	NN
8	Main	TO REPLACE SUNDRY PARTS	100.00	0	NN
Total:			1,040.00	70.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	4,714.69	569.24
Total Labour Cost	1,183.00	400.00
Total Spray Painting	1,674.00	600.00
Other	1,040.00	70.00
Overall Total	8,611.69	1,639.24
Lump Sum Repair Option	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	8,600.00	1,650.00
Surveyor Approved Amount		1,650.00
No of Repair Days*	7	3
Remarks		LUMP SUM REPAIR 4 DAYS CHECK ITEMS PHOTOS AFTER REPAIR PHOTOS
Surveyor Name		Naz
Signature		

Survey Date 22/05/2019

22/5/19 1500
 LIS
 3 DAYS
 CHECK ITEMS PHOTOS
 AFTER REPAIR PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer


Signature:

Date:



24/5/2019

Section A - Accident Details

Registration Number	SHF1042X
Case Reference Number	TAX/05/19/2093
Registration Date	23/12/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	ROSMAN B YUSOPE
Type of Accident	Others
Accident Date and Time	18/5/2019 2:30 AM
Accident Reported Date and Time	21/5/2019 3:49 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24101576
Special Instruction to ARC, if any	TP
Prepared Date and Time	22/5/2019 11:28 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,433.00	\$500.00
Total Spray Cost	\$1,854.00	\$700.00
Total Spare Part Cost	\$6,792.95	\$1,611.16
Total Other Cost	\$1,040.00	(\$511.16)
TOTAL COST	\$11,119.95	\$2,300.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	7.0	4.0
Prepared / Adjusted By	Kim Ming Chin	Naz (LKK) / NTUC
ARC / Surveyor Sign Off Date	22/05/2019 3:57 PM	22/05/2019 3:43 PM
Signature		
Remarks	LUMP SUM REPAIR 4 DAYS. SURVEYOR CHANGE TO 3 DAYS CHECK ITEMS PHOTOS	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1907-0476	Invoice Number	
Quotation Date	27.07.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$845.00	\$200.00
TO REPAIR FRONT PORTION	\$338.00	\$200.00
TO REPAIR RR END PANEL	\$250.00	\$100.00
Total Labour	\$1,433.00	\$500.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$0.00
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$100.00
Total Spray Painting & Panel Beating	\$1,854.00	\$700.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$40.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$0.00
TO REMOVE / REFIT WINDSCREEN	\$240.00	\$0.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$0.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$30.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Lump Sum Adjustment by Surveyor	\$0.00	(\$581.16)
Total Other Costs	\$1,040.00	(\$511.16)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check
		52016-47030	ARM SUB-ASSY, RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Check
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Check

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park EA, Singapore 757705
FAX Number : 03685592
Estimator Telephone Number : 09602023
Accident Reporting Number : 08662672

Date Generated : 30/07/2019
User ID : PehSuan

52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Check	X	SVC
52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Check	X	SVC
76088-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given	X	SVC
76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Not Given	X	SVC
76891-47020	BUMPER LIP REAR	1.00	\$228.90	25.00	\$171.68	Replace	Replace		DEF
58308-47011	UNDER COVER SUB-ASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Check	X	SVC
58307-47060	END PANEL	0.00	\$602.10	0.00	\$0.00	Replace	Check	X	SVC
	SEALANT SIKAFLEX	1.00	\$37.00	0.00	\$37.00	Replace	Replace		NREL
	SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X	SVC
	PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace		NREL
67005-47241	TAILGATE ASY	1.00	\$1,007.90	100.00	\$0.00	Replace	Repair	X	
76801-47070-B0	TAILGATE OUTSIDE GARNISH	0.00	\$504.90	0.00	\$0.00	Replace	Not Given	X	SVC
75310-47020	EMBLEM REAR	0.00	\$60.30	0.00	\$0.00	Replace	Not Given	X	SVC
75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace		NREL
75442-47030	NAME PLATE (PRIUS)	0.00	\$60.80	0.00	\$0.00	Replace	Not Given	X	
75443-47030	NAME PLATE (TOYOTA)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given	X	
	STICKER SMRT LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Not Given	X	NN
	STICKER DECAL 6555 8888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given	X	
75575-47030	MOULDING BACK WINDOW, LOWER NO.1	0.00	\$29.40	0.00	\$0.00	Replace	Not Given	X	
75574-47020	TAIL GATE DOOR GLASS MOULDING, LH	0.00	\$29.40	0.00	\$0.00	Replace	Not Given	X	NN/611.16
75573-47080	TAIL GATE DOOR GLASS MOULDING, RH	0.00	\$29.40	0.00	\$0.00	Replace	Not Given	X	
	SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X	+ 500.00
52119-47930	BUMPER FRT	1.00	\$482.00	100.00	\$0.00	Replace	Repair	X	+ 770.00
81511-47050	LENS & BODY, FR TURN RH	0.00	\$511.80	0.00	\$0.00	Replace	Check	X	SVC
81519-47050	BRACKET, FR TURN LOWER RH	0.00	\$26.00	0.00	\$0.00	Replace	Not Given	X	SVC
81519-47060	BRACKET, FR TURN UPPER RH	0.00	\$24.40	0.00	\$0.00	Replace	Not Given	X	SVC
81519-47060	BRACKET, FR TURN	0.00	\$58.20	0.00	\$0.00	Replace	Not Given	X	SVC - 20%
53102-47020	BUMPER GRILLE SUB-ASSY, LOWER	0.00	\$311.10	0.00	\$0.00	Replace	Not Given	X	SVC
52115-47040	BUMPER SUPPORT F/RH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given	X	SVC
81130-47500	HEAD LAMP RH	0.00	\$945.20	0.00	\$0.00	Replace	Not Given	X	SVC 2304.93
Total			\$7,273.30		\$711.56				

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52023-12240	BUMPER REINFORCEMENT REAR	1.00	\$205.70	25.00	\$154.28	Replace	Replace
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	1.00	\$139.60	25.00	\$104.70	Replace	Replace
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace
		81511-47050	LENS & BODY, FR TURN RH	1.00	\$511.80	10.00	\$460.62	Replace	Replace
Total					1,037.10		899.60		

FINALIZED LUMP SUM REPAIR \$ 2,300.00 / 4 REPAIR DAYS.

REQUEST FOR SUPPLYMENT PARTS


Contractor:		WEGA ENGINEERING PTE LTD	
Accident Case Number	74X/05/19/2093	Date of Collection	23.5.19
Vehicle No	SHP 1042X	Date of Request	24.5.19
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend (If any)	2 DAYS 1 DAY

S/N	Part Number	Part Description	Quantity	Unit Price
	0943,44,45,46 47,54	Bumper Reinforcement Rear		\$205.70 / BT
	0951,52,53,57 58,59	Arm Sub Assy RR Bumper RH		\$139.60 / BT
	0960	Sensor Reverse		\$180.00 / BR
	0961,62,63,64	Lens & Body Prt Turn RH		\$511.50 / CRX
	0948,49,50	To Repair Bnd panel		\$250.00 \$100
		To Respray Bnd panel		\$400.00 \$100

*** Please submit photographs for damaged parts ***

I, (Name) CHIA H2 NA2 LKK
 (Position) 27/5/19

Do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle

.....


Signature of person making this declaration
 [To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19009120/Nqd3s2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 05-08-2019
189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMG 6125T	Veh. Inspected	SHF 1042X
Policy No.	5087272209-03	Coverage (\$)	0.00
Claim No.	MT/1045362-002	Excess (\$)	0.00
Assign From		Assign Date	22/05/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTDKN36U005755108	Colour	MAROON
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	NEUTON	6 mm
L/H Front Tyre	195/65 R15	NEUTON	6 mm
R/H Rear Tyre	195/65 R15	NEUTON	6 mm
L/H Rear Tyre	195/65 R15	NEUTON	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	18/05/2019	Inspection Date	22/05/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 1042X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER REAR (DISC 25%)	CRACKED	458.60	343.95
1	BUMPER LIP REAR (DISC 25%)	DEFORMED	228.90	171.68
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.93
1	BUMPER REINFORCEMENT REAR (DISC 25%)	BENT	205.70	154.28
1	ARM SUB-ASSY, RR BUMPER RH (DISC 25%)	BENT	139.60	104.70
1	LENS & BODY, FR TURN RH (DISC 10%)	CRACKED	511.80	460.62
1	SEALANT SIKAFLEX (SN)	NECESSARY	37.00	37.00
2	PIXEL STICKER @ \$60.00 (SN)	NECESSARY	120.00	120.00
1	SENSOR REVERSE (SN)	BROKEN	180.00	180.00
1	BUMPER REINFORCEMENT REAR	SERVICEABLE	205.70	-
1	AEM SUB-ASSY, RR BUMPER LH	SERVICEABLE	139.60	-
1	ARM SUB-ASSY, RR BUMPER RH	SERVICEABLE	139.60	-
1	BUMPER SIDE RETAINER RR/LH	SERVICEABLE	94.80	-
1	BUMPER SIDE RETAINER RR/RH	SERVICEABLE	94.80	-
1	BUMPER LIP COVER RR/LH	SERVICEABLE	72.20	-
1	BUMPER LIP COVER RR/RH	SERVICEABLE	118.10	-
1	UNDER COVER SUB-ASSY, RR FLOOR	SERVICEABLE	514.50	-
1	END PANEL	SERVICEABLE	602.10	-
1	SENSOR REVERSE	SERVICEABLE	180.00	-
1	TAILGATE OUTSIDE GARNISH	SERVICEABLE	504.90	-
1	EMBLEM REAR	SERVICEABLE	60.30	-
1	LENS & BODY, FR TURN RH	SERVICEABLE	511.80	-
1	BRACKET, FR TURN LOWER RH	SERVICEABLE	26.00	-
1	BRACKET, FR TURN UPPER RH	SERVICEABLE	24.40	-
1	BRACKET, FR TURN	SERVICEABLE	58.20	-
1	BUMPER GRILLE SUB-ASSY, LOWER	SERVICEABLE	311.10	-
1	BUMPER SUPPORT F/RH	SERVICEABLE	76.40	-
1	HEAD LAMP RH	SERVICEABLE	945.20	-
1	NAME PLATE (PRIUS)	NOT NECESSARY	60.80	-
1	NAME PLATE (TOYOTA)	NOT NECESSARY	51.90	-

Report Ref No. NS/INC19009120/Nqd3s2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	STICKER SMRT LOGO	NOT NECESSARY	7.80	-
1	STICKER DECAL 6555 8888	NOT NECESSARY	21.60	-
1	MOULDING BACK WINDOW, LOWER NO.1	NOT NECESSARY	29.40	-
1	TAIL GATE DOOR GLASS MOULDING, LH	NOT NECESSARY	29.40	-
1	TAIL GATE DOOR GLASS MOULDING, RH	NOT NECESSARY	29.40	-
1	SEALANT W/SCREEN	NOT NECESSARY	37.00	-
1	TAILGATE ASY	TO REPAIR SEE LABOUR	1,007.90	-
1	BUMPER FRT	TO REPAIR SEE LABOUR	482.00	-
			8,370.40	1,611.16
	LABOUR			
	PANEL BEATING & BODYWORK. INCLUSIVE OF THE REPAIR OF TAILGATE ASY AND BUMPER FRT.		1,433.00	500.00
	SPRAY PAINT.		1,854.00	700.00
	TO CHECK WIRING AND SYSTEM FUNCTION.	NOT NECESSARY	80.00	-
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		200.00	40.00
	TO TRANSFER REAR TAILGATE MECHANISM.	NOT NECESSARY	120.00	-
	TO REMOVE / REFIT WINDSCREEN.	NOT NECESSARY	240.00	-
	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	NOT NECESSARY	120.00	-
	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE.		120.00	30.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
			4,327.00	1,270.00
	GRAND TOTAL		12,697.40	2,881.16
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			2,300.00

Report Ref No. NS/INC19009120/Nqd3s2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.