



VC

Case Details

Case Reference Number : TAX/05/19/2073
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB1816B

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-6913-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 16/05/2019 11:15 PM
 Vehicle Age(In Months) : 17

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation												Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	0	Repair	* XR
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 1	2	3.80	7.60	25.00	5.70	Replace	0	0	Not Given	*
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 2	2	3.80	7.60	25.00	5.70	Replace	0	0	Not Given	*
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 3	2	3.80	7.60	25.00	5.70	Replace	0	0	Not Given	*
One Time Key In	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	0	0	Not Given	*
One Time Key In	Main			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	0	0	Not Given	*
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	1	418.72	Replace	* DEF
One Time Key In	Main			FILLER, RR BUMPER , RH	1	119.90	119.90	25.00	89.93	Replace	0	0	Not Given	* X nn
One Time Key In	Main			FILLER, RR BUMPER , LH	1	119.90	119.90	25.00	89.93	Replace	0	0	Not Given	* X nn
One Time Key In	Main			COVER, GUARD RR BUMPER LOWER	1	14.80	14.80	25.00	11.10	Replace	0	0	Not Given	* X nn
Total Spare Part Cost									1,651.96	Surveyor Total		718.72		
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		0		
Final Spare Part Cost									1,651.96	Final Sur Total		718.72		

SMRT Recommendation										Surveyor Approval				
BOI Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	0	0	Check	* X N/A
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace	* / Sharded
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	* / nec
Total Spare Part Cost									1,551.96	Surveyor Total		718.72		
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		0		
Final Spare Part Cost									1,551.96	Final Sur Total		718.72		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	676.00	200	
Total:			676.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY FILLER RR BUMPER LH	180.00	0	
3	Main	TO RESPRAY FILLER RR BUMPER RH	180.00	0	
Total:			738.00	200.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	0	
3	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30	APC
4	Main	TO WASH AND VACUUM	60.00	0	
Total:			560.00	30.00	

5/17/2019

<https://vacswb.smr.com.sg/Estimation.aspx>

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
5	Main	TO REPLACE SUNDRY PARTS	100.00	0	
Total:			560.00	30.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	1,651.96	718.72
Total Labour Cost	676.00	200.00
Total Spray Painting	738.00	200.00
Other	560.00	30.00
Overall Total	3,625.96	1,148.72
Lump Sum Repair Option		
Lump Sum Total	0.00	1,148.72
Surveyor Approved Amount		1,148.72
No of Repair Days*	4	2
Remarks	-	p/p repair, photo before paint.
Surveyor Name		Hwee Jie
Signature		
Survey Date	17/05/2019	Save Clear

REQUEST FOR SUPPLYMENT PARTS

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	TAX/05/19/2073	Date of Collection	18/5/19
Vehicle No	SHB 1816 B	Date of Request	08/5/19
Vehicle Model	TOYOTA PRIUS 4	Number of Days to Extend (If any)	1 X DAYS

S/N	Part Number	Part Description	Quantity	Unit Price
	0722, 23, 24, 25, 29	Rear Bumper Reinforcement		\$318.80 ✓
	30, 31, 32, 33	To Repair Bnd panel		\$250.00 \$100
	5726, 137, 28	To Respray Bnd panel		\$180.00 \$100


BT\$239.10

<<<Please submit photographs for damaged parts>>>

I, (Name) CHIA

(Position) _____

Do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.




 Signature of person making this declaration
 [To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff		
Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

Section A - Accident Details

Registration Number	SHB1816B
Case Reference Number	TAX/05/19/2073
Registration Date	19/12/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	PUBHINDER SINGH S/O POORAN SINGH
Type of Accident	Head to Rear
Accident Date and Time	17/5/2019 7:15 AM
Accident Reported Date and Time	17/5/2019 11:06 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24101543
Special Instruction to ARC, if any	TP / AIG - LKK
Prepared Date and Time	17/5/2019 1:27 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Top View

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$926.00	\$300.00
Total Spray Cost	\$918.00	\$300.00
Total Spare Part Cost	\$1,891.06	\$957.82
Total Other Cost	\$560.00	\$30.00
TOTAL COST	\$4,295.06	\$1,587.82 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Kim Ming Chin	Hwee Jie (LKK) / AIG
ARC / Surveyor Sign Off Date	17/05/2019 1:39 PM	17/05/2019 2:01 PM
Signature		
Remarks	p/p repair, photo before paint.	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1908-0142	Invoice Number	
Quotation Date	13.08.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RR END PANEL	\$250.00	\$100.00
TO REPAIR REAR PORTION	\$676.00	\$200.00
Total Labour	\$926.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR PANEL	\$180.00	\$100.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY FILLER RR BUMPER LH	\$180.00	\$0.00
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$918.00	\$300.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$30.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$560.00	\$30.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159479 13	COVER, RR BUMPER ASSY	1.00	\$423.90	100.00	\$0.00	Replace	Repair
		52462470 30	PAD, RR BUMPER, RH & LH, 1	0.00	\$3.80	0.00	\$0.00	Replace	Not Given
		52462470 20	PAD, RR BUMPER, RH & LH, 2	0.00	\$3.80	0.00	\$0.00	Replace	Not Given
		52462470 10	PAD, RR BUMPER, RH & LH, 3	0.00	\$3.80	0.00	\$0.00	Replace	Not Given
		52575470 40	RETAINER, RR BUMPER, RH	0.00	\$112.70	0.00	\$0.00	Replace	Not Given
		52576470 40	RETAINER, RR BUMPER, LH	0.00	\$111.50	0.00	\$0.00	Replace	Not Given
		52453470 10	GUARD, RR BUMPER, LOWER	1.00	\$558.30	25.00	\$418.73	Replace	Replace
		52565479 00	FILLER, RR BUMPER, RH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given
		52566479 00	FILLER, RR BUMPER, LH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given
		52169470 20	COVER, GUARD RR BUMPER LOWER	0.00	\$14.80	0.00	\$0.00	Replace	Not Given
		52023470 30	REAR BUMPER REINFORCEMENT	0.00	\$318.80	0.00	\$0.00	Replace	Check
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park EA, Singapore 757105
FAX Number : 63855592
Estimate Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 14/04/2019

User ID : PehSuxn

			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
Total					\$2,031.20		\$718.73		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52023470	REAR BUMPER	1.00	\$318.80	25.00	\$239.10	Replace	Replace
		30	REINFORCEMENT						
Total					318.80		239.10		

957.83
+ 300.00
+ 330.00

1587.83