

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No. 08102600E

175 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR SJ203K

No.	Qty	List Items	
1	1	Front bumper	\$ Bu 1,092.35 ✓
2	1	Front bumper RH lower side pad	\$ Od 82.10 ✓
3	1	Front bumper RH fog lamp cover	\$ Sn 84.95 X
4	1	Front bumper RH fog lamp	\$ 330.90 ?
5	1	Front bumper RH side retainer	\$ D11 26.55 ✓
6	1	Front bumper inner foam	\$ Sn 76.45 X
7	1	Front bumper inner reinforcement	\$ R 585.95 X
8	1	RH headlamp	\$ 1,903.35 ?
9	1	Front RH fender	\$ B1 598.05 ✓
10	1	Front RH fender wheel arch garnish	Rd \$/hy 354.75 ✓
11	1	Front RH fender under shield	\$ Sn 152.85 X
12	1 set	Front fender under shield clips	\$ Sn 30.00 X
13	1	Front RH sports rims	Per \$ R 2,714.75 * 100%
			\$ 8,033.00
			Less 20% \$ 1,606.60
			Total : \$ 6,426.40

10%

Labour		
1	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$ 700.00 450
2	To putty and spray Spray Paintings charges.	\$ 600.00 480 480
3	To check wirings and lightings.	\$ 50.00 20
4	To conduct computerise wheel alignment test.	\$ 80.00 60
5	To supply and apply anti rust treatment	\$ 60.00 30
Total :		\$ 1,490.00

Total Parts and Labour : \$ 7,916.40

Not Attached
Resinny B4 paint
4 days