REPAIR ESTIMATE*

VEHICLE NO: SHD 3931C

MAKE

MODEL : HYUNDAI IONIO



DATE 22/5/2019

LKK- Kalvin-

| Qty | Parts Description/ Labour | Type | Unit Price | Amount |
|-----|---|-----------------|--|--------------|
| | Rear Bumper XMY | | | \$ 459.40 |
| | Rear Bumper Centre Moulding Assy | | | \$ 451.25 |
| | Rear Bumper Lower Centre Moulding Assy 🗶 | | | \$ 47.50 |
| | Rear Bumper Side Bracket (LH/RH) | | \$ 33.10 | \$ 66.20 |
| | Rear Bumper Cover Clips ** | | | \$ 22.00 |
| | SUB TOTAL | | | \$ 1,046.35 |
| | LESS 20% | | | \$ 209.27 |
| | DISCOUNTED TOTAL | | | \$ 837.08 |
| | DISCOUNTED TOTAL | | | \$ 637.00 |
| | | | | |
| | Rear No.Plate | | | \$ 25.00 |
| | Rear Bumper Rubber Mat | | | \$ 50.00 |
| | Real Bumper Rubber Mat | | | 50.00 |
| | | | 15000001111 | \$ 75.00 |
| | | | | |
| | Labour Charge | | | 200 |
| | Panel Beating | | | \$ 400.00 |
| | Spray Painting Charge | | 200 | \$ 300.00 |
| | Wiring Charge | | | \$ \$ -30.00 |
| | Remove/Refix Reverse Sensor | | 3 | \$ + 120.00 |
| | TOTAL LABOUR | | notify | \$ 850.00 |
| | ESTIMATE TOTAL | Consultati | herce notify Howing: Howing taining Soray naining | \$ 1,762.08 |
| | (Ca La 1 ang) | | a spray training a spray training resurvey surjest stranger prejudice basis of a sectional Prejudice and | |
| | 1/ 22/5/19 10202 | | Sense from Insurance Combau Sense Sense reserveshed and Sense Sense Reserveshed and | |
| | Cata 1000 ESTIMATE TOTAL 12/5/19 10202. 2/3 P/P After Report plan | eublact to time | 1 approx | |
| | NU Voor nit | cknowledged | n Repairer | |
| | Mus 100 h | Signature: | | 2 2 |
| | This is an initial estimate based on a visual inspection of the | e above v | ehicle. The final repair o | uantum will |

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.