

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5453H**AAD1905-166***Not Notarised*
1/ Rupp &

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date Of Registration:

SHC 5453H

VF1ABL15AUC280938

RENAULT

LATITUDE

17.5.19

CHINA TAIPING

18/12/2014

		PART
1	1	BUMPER COVER REAR
2	1	BUMPER LOWER REAR
3	1	BUMPER BRACKET CTR REAR
4	1	BUMPER BRACKET SIDE RH REAR
5	1	BUMPER RETAINER RH REAR
6	1	BUMPER REFLECTOR RH
7	1	BUMPER BRACKET SIDE LH REAR
8	1	BUMPER RETAINER LH REAR
9	1	BUMPER REFLECTOR LH
10	1	BUMPER BEAM REAR
11	1	BUMPER BEAM BRACKET LH REAR
12	1	BUMPER BEAM BRACKET RH REAR
13	1	BOOT REAR
14	1	BOOT FINISHER
15	1	BOOT WHEATERSTRIP
16	1	BOOT REFLECTOR LAMP LH
17	1	BOOT REFLECTOR LAMP RH
18	1	BOOT BADGE 'RENAULT'
19	1	BOOT BADGE
20	1	BOOT STRUT LH
21	1	BOOT STRUT RH
22	1	BOOT HINGE LH
23	1	BOOT HINGE RH
24	1	BOOT INNER TRIM
25	1	BOOT SWITCH
26	1	BOOT LOCK
27	1	BOOT LOCK CATCH
28	1	LICENCE PLATE LAMP
29	2	BOOT RUBBER PLUG
30	1	FENDER PANEL INNER TRIM REAR RH

		LIST
\$	Buz	1,108.46 ✓
\$	Odyssey	768.84 ✓
\$	Dis	113.47 ✓
\$	Sn	135.97 X
\$	Sn	44.99 X
\$	Sn	43.61 X
\$	Sn	135.97 X
\$	Sn	44.99 X
\$	Sn	43.61 X
\$	Rt	777.52 ✓
\$	Rt	225.95 ✓
\$	Dis	225.95 ✓
\$	Rt	2,872.68 ✓
\$	Carway	470.06 ✓
\$	Dis Inu	323.05 506.52 @ 161.53
\$	cm	493.35 ✓
\$	cm	493.35 ✓
\$	ru	225.36 ✓
\$	ru	225.36 ✓
\$	Sn	276.08 }
\$	Sn	276.08 }
\$	R	367.84 }
\$	R	367.84 }
\$	Sn	586.45 }
\$	Sn	168.13 }
\$	R	202.67 }
\$	R	74.40 }
\$	cm	50.52 ✓
\$	Sn	221.81 X
\$	Sn	671.45 X

Trans-cab Auto Services Pte Ltd**AAD1905-166**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5453H

31	1	FENDER PANEL REAR RH	\$	R	3,299.13	X
32	1	WHEELARCH REAR RH	\$	Sn	543.47	X
33	1	FENDER PANEL REAR LH	\$	R	3,299.13	X
34	1	FENDER PANEL INNER TRIM REAR LH	\$	Sn	671.45	X
35	1	WHEELARCH REAR LH	\$	Sn	543.47	X
36	1	TAILLAMP RH	\$	mg cm	552.55	✓
37	1	TAILLAMP PANEL RH	\$	R	986.70	X
38	1	TAILLAMP LH	\$	mg cm	552.55	✓
39	1	TAILLAMP PANEL LH	\$	R	986.70	X
40	1	OUTER PANEL REAR (End Panel)	\$	Ry	1,471.77	✓
41	1	OUTER PANEL REAR (End Panel)TRIM	\$	cm	404.56	✓
42	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	X
43	1	SPARE WHEEL PANEL TRIM	\$	Sn	612.21	X
44	1	EXHAUST REAR	\$	R	7,489.05	X
45	1	EXHAUST CAP REAR	\$	R	230.49	X

TOTAL	\$	35,868.94
10%	\$	3,586.89
	\$	32,282.05

Special Nett

1	1SET	PARKING AID	\$	Sn	700.00	X
2	1SET	REAR BUMPER CLIP	\$	Rn	66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	Rn	33.00	✓
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	Rn	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	Rn	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	Rn	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	Rn	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	Rn	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	Rn	66.00	✓
10	1	EXHAUST MOUNTING REAR	\$	Sn	17.82	X
11	1SET	BOOT FINISHER CLIP	\$	Rn	24.20	X
12	1	BOOT STICKER "Trans-cab"	\$	Rn	30.00	✓
13	1	BOOT STICKER "6555-3333"	\$	Rn	30.00	✓
14	1	BOOT INNER TRIM CLIP	\$	Rn	45.00	X
15	1SET	FENDER WHEELARCH REAR RH CLIP	\$	Rn	35.00	X
16	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sha	385.00	X
17	1	SPARE TYRE	\$	Sn	330.00	X

Trans-cab Auto Services Pte Ltd**AAD1905-166**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5453H

18	1	FENDER INNER TRIM CLIP RH	\$	nn	28.00	X
19	1	TAILLAMP CLIP RH	\$	nn	5.00	✓
20	2	REAR WINDSCREEN SEALANT	\$	nn	80.00	X
21	1	WINDSCREEN MOULDING	\$	nn	100.00	X
22	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	X
23	1	TAILLAMP CLIP LH	\$	nn	5.00	✓
24	1	FENDER INNER TRIM CLIP LH	\$	nn	28.00	X
25	1SET	FENDER WHEELARCH REAR LH CLIP	\$	nn	35.00	X
TOTAL			\$		2,225.02	

TOTAL PARTS \$ 34,507.07**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	6001
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	6601
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	} 601
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To Rust-Proofing Of The Affected Areas.	\$	170.00	601

Trans-cab Auto Services Pte Ltd**AAD1905-166**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5453H

To repair and realign rear exhaust pipe.	\$	nn 170.00 X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00 X
To supply and re-do rear luggage floor panel insulation padding.	\$	nn 380.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	nn 170.00 X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	nn 380.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00 X
To Check Electrical Lighting Concerned.	\$	170.00 201

TOTAL \$ 15,440.00**Over All Total \$ 49,947.07****(LUMP SUM) Repair Days****20 DAYS**

5 days

~~11448.76~~
11829.46

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: