



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 22/05/2019

User ID : ZhiYangPhua

Section A - Accident Details



Registration Number	SHB5515T
Case Reference Number	TAX/05/19/2053
Registration Date	12/10/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	GOH KWAN ENG
Type of Accident	Head To Side
Accident Date and Time	11/5/2019 4:00 PM
Accident Reported Date and Time	13/5/2019 10:13 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	11/5/2019 4:01 PM
Replacement Vehicle issued?	No
Job Card Number	24101476
Special Instruction to ARC, if any	TOWED BACK FROM TP COMPOUND \$90
Prepared Date and Time	16/5/2019 8:27 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,859.00	\$1,000.00
Total Spray Cost	\$2,970.00	\$1,100.00
Total Spare Part Cost	\$59,919.10	\$27,173.83
Total Other Cost	\$2,926.00	\$1,090.00
TOTAL COST	\$67,674.10	\$30,363.83
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	14.0	7.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee jie
ARC / Surveyor Sign Off Date	17/05/2019 4:13 PM	17/05/2019 3:41 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



Toyota Prius



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 22/05/2019

User ID : ZhiYangPhua

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable							
TO REPAIR FRONT PORTION	\$1,859.00	\$1,000.00							
Total Labour	\$1,859.00	\$1,000.00							
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable							
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00							
TO REPSRAY FRONT HOOD	\$378.00	\$200.00							
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$100.00							
TO RESPRAY FRT MEMBER,RH	\$180.00	\$0.00							
TO RESPRAY FRT MEMBER,LH	\$180.00	\$0.00							
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00							
TO RESPRAY APRON PANEL RH	\$180.00	\$0.00							
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00							
TO RESPRAY APRON PANEL LH	\$180.00	\$0.00							
TO RESPRAY FRONT PILLAR LH	\$180.00	\$0.00							
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00							
Total Spray Painting & Panel Beating	\$2,970.00	\$1,100.00							
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable							
TOWING CHARGE	\$126.00	\$90.00							
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00							
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$50.00							
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00							
TO TOP UP A/C GAS	\$120.00	\$50.00							
TO REMOVE / REFIT SEAT	\$240.00	\$50.00							
TO REMOVE / REFIT WINDSCREEN	\$120.00	\$100.00							
TO ALIGN CHASSIS	\$350.00	\$0.00							
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$450.00	\$450.00							
TO CHECK & RESET SYSTEM FUNCTION	\$350.00	\$120.00							
TO REMOVE & REFIT ROOF LINING	\$120.00	\$80.00							
TO REMOVE AND REFIT WIRE HARDESS	\$250.00	\$0.00							
TO REMOVE AND FEFIX DASHBOARD	\$120.00	\$80.00							
TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	\$120.00	\$0.00							
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00							
TO WASH AND VACUUM	\$60.00	\$0.00							
Total Other Costs	\$2,926.00	\$1,090.00							
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		63310471 60B0	ROOF HEADLINING ASSY	1.00	\$2,059.50	25.00	\$1,544.63 ✓	Replace	Replace
		62210471 40B0	GARNISH ASSY, FRONT PILLAR , RH	0.00	\$200.10 2	0.00	\$0.00	Replace	Check
		62220471 40B0	GARNISH ASSY, FRONT PILLAR , LH	0.00	\$200.10 7	0.00	\$0.00	Replace	Check
		5530047151C0	PANEL ASSY, INSTRUMENT DASH BOARD UPPER	1.00	\$451.60	25.00	\$338.70 ✓	Replace	Replace

400.2



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 22/05/2019

User ID : ZhiYangPhua

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5530247141C1	PANEL SUB-ASSY, INSTRUMENT DASH BOARD	1.00	\$1,542.60	25.00	\$1,156.95	Replace	Replace
		5530347091C0	PANEL SUB-ASSY, INSTRUMENT DASH BOARD LOWER	1.00	\$361.30	25.00	\$270.98	Replace	Replace
		5540747020	COVER SUB-ASSY, INSTRUMENT, LOWER	1.00	\$96.90	25.00	\$72.68	Replace	Replace
		5541047100	PANEL ASSY, INSTRUMENT CLUSTER FINISH	0.00	\$434.10	0.00	\$0.00	Replace	Check
		5560647080	COVER SUB-ASSY, INSTRUMENT PANEL UNDER, NO.1	0.00	\$93.90	0.00	\$0.00	Replace	Check
		6241047100C0	GARNISH ASSY, CENTER PILLAR, RH	0.00	\$162.40	0.00	\$0.00	Replace	Check
		6242047100C0	GARNISH ASSY, CENTER PILLAR, LH	0.00	\$162.40	0.00	\$0.00	Replace	Check
		6241347070C0	GARNISH, CENTER PILLAR, LOWER RH	0.00	\$227.80	0.00	\$0.00	Replace	Check
		6241447070C0	GARNISH, CENTER PILLAR, LOWER LH	0.00	\$227.80	0.00	\$0.00	Replace	Check
		6255247050C0	GARNISH, REAR SEAT SIDE, LH	0.00	\$234.30	0.00	\$0.00	Replace	Check
		6255147020C0	GARNISH, REAR SEAT SIDE, RH	0.00	\$234.30	0.00	\$0.00	Replace	Check
		89173494 95	SENSOR, AIR BAG, FRONT, RH & LH	2.00	\$310.50	10.00	\$558.90	Replace	Replace
		89831280 30	SENSOR, SIDE AIR BAG, RH & LH	2.00	\$567.80	10.00	\$1,022.04	Replace	Replace
		73960471 00	AIR BAG ASSY, INSTRUMENT PANEL PASSENGER	1.00	\$3,240.20	10.00	\$2,916.18	Replace	Replace
		73900470 60C0	AIR BAG ASSY, INSTRUMENT PANEL, LOWER NO.1	0.00	\$1,593.60	0.00	\$0.00	Replace	Check
		62180470 70	AIR BAG ASSY, ROOF SIDE CURTAIN SHIELD, LH	1.00	\$1,463.80	10.00	\$1,317.42	Replace	Replace
		62170470 70	AIR BAG ASSY, ROOF SIDE CURTAIN SHIELD, RH	1.00	\$1,463.80	10.00	\$1,317.42	Replace	Replace
		45130472 41C0	AIR BAG STEERING WHEEL DRIVER, PAD ASSY	1.00	\$2,377.30	10.00	\$2,139.57	Replace	Replace
		73910471 10	AIR BAG ASSY, FRONT SEAT, RH	1.00	\$850.00	10.00	\$765.00	Replace	Replace
		73920471 30	AIR BAG ASSY, FRONT SEAT, LH	1.00	\$850.00	10.00	\$765.00	Replace	Replace
		71551472 70	PAD, FRONT SEAT BACK, RH	0.00	\$268.60	0.00	\$0.00	Replace	Check
		71073477 00C4	COVER SUB-ASSY, FRONT SEAT BACK, RH	0.00	\$1,505.10	0.00	\$0.00	Replace	Check
		71552472 40	PAD, FRONT SEAT BACK, LH	0.00	\$268.60	0.00	\$0.00	Replace	Check
		71074475 70C4	COVER SUB-ASSY, FRONT SEAT BACK, LH	0.00	\$1,505.10	0.00	\$0.00	Replace	Check
		73220472 21C2	SEAT BELT ASSY, FRONT SEAT, LH	1.00	\$838.20	25.00	\$628.65	Replace	Replace
		73210472 81C2	SEAT BELT ASSY, FRONT SEAT, RH	1.00	\$838.20	25.00	\$628.65	Replace	Replace
		73350470 70C3	SEAT BELT ASSY, REAR SEAT, CENTER	0.00	\$520.80	0.00	\$0.00	Replace	Check
		73360470 90C0	SEAT BELT ASSY, REAR SEAT, RH	0.00	\$828.20	0.00	\$0.00	Replace	Check
		73370470 50C0	SEAT BELT ASSY, REAR SEAT, LH	0.00	\$838.20	0.00	\$0.00	Replace	Check
		52119479 62	COVER, FR BUMPER	1.00	\$495.50	25.00	\$371.63	Replace	Replace

9105.2



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 22/05/2019

User ID : ZhiYangPhua

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52128479 06	COVER, FR BUMPER LH	1.00	\$28.10	25.00	\$21.08	Replace	Replace
		52127479 07	COVER, FR BUMPER RH	1.00	\$28.10	25.00	\$21.08	Replace	Replace
		52161160 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace
		53101470 80	GRILLE SUB-ASSY	1.00	\$335.60	25.00	\$251.70	Replace	Replace
		75310470 80	EMBLEM ASSY FRONT	1.00	\$87.10	25.00	\$65.32	Replace	Replace
		53112472 40	GRILLE, RADIATOR	1.00	\$165.00	25.00	\$123.75	Replace	Replace
		52114471 90	BRACKET, FR BUMPER	1.00	\$99.80	25.00	\$74.85	Replace	Replace
			NUMBER PLATE	1.00	\$35.00	0.00	\$35.00	Replace	Replace
			NUMBER PLATE FRAME	1.00	\$25.00	0.00	\$25.00	Replace	Replace
		53395470 40	SEAL, HOOD TO FR END	1.00	\$24.40	25.00	\$18.30	Replace	Replace
		52116470 50	SUPPORT, FR BUMPER LH	1.00	\$82.30	25.00	\$61.72	Replace	Replace
		52115470 50	SUPPORT, FR BUMPER RH	1.00	\$76.90	25.00	\$57.68	Replace	Replace
		52611471 40	ABSORBER, FR BUMPER	1.00	\$70.30	25.00	\$52.72	Replace	Replace
		52021471 10	REINFORCEMENT FRONT UPPER	1.00	\$691.10	25.00	\$518.33	Replace	Replace
		52616470 90	ABSORBER, FR BUMPER LOWER	1.00	\$117.00	25.00	\$87.75	Replace	Replace
		52132470 10	REINFORCEMENT FRONT LOWER	1.00	\$238.50	25.00	\$178.88	Replace	Replace
		52103470 10	EXTENSION SUBASSY, LH	0.00	\$116.30	0.00	\$0.00	Replace	Check
		52102470 20	EXTENSION SUBASSY, RH	0.00	\$116.30	0.00	\$0.00	Replace	Check
		81220470 20	LAMP ASSY, FOG, LH	1.00	\$910.20	10.00	\$819.18	Replace	Replace
		81210470 20	LAMP ASSY, FOG, RH	1.00	\$910.20	10.00	\$819.18	Replace	Replace
		51420470 30	COVER ASSY, ENGINE	0.00	\$180.10	0.00	\$0.00	Replace	Not Given
		53301471 10	HOOD SUB-ASSY	1.00	\$938.40	25.00	\$703.80	Replace	Replace
		53341470 40	INSULATOR, HOOD	0.00	\$393.90	0.00	\$0.00	Replace	Not Given
		90467090 50	INSULATOR, HOOD CLIP	0.00	\$2.30	0.00	\$0.00	Replace	Not Given
		53420471 30	HINGE ASSY, HOOD, LH	1.00	\$57.00	25.00	\$42.75	Replace	Replace
		53410471 30	HINGE ASSY, HOOD, RH	1.00	\$57.00	25.00	\$42.75	Replace	Replace
		53510471 40	LOCK ASSY, HOOD	1.00	\$131.10	25.00	\$98.32	Replace	Replace
		53630470 90	CABLE ASSY, HOOD	0.00	\$53.20	0.00	\$0.00	Replace	Not Given
		75536470 20	MOULDING LH	0.00	\$83.30	0.00	\$0.00	Replace	Not Given
		75535470 20	MOULDING RH	0.00	\$83.30	0.00	\$0.00	Replace	Not Given
		561014E 959	WINDSCREEN FRONT GLASS SUB-ASSY	1.00	\$1,626.40	25.00	\$1,219.80	Replace	Replace
		75533470 70	WINDSCREEN FRONT MOULDING, TOP FRONT	1.00	\$44.00	25.00	\$33.00	Replace	Replace
			SEALANT W/SCREEN	2.00	\$37.00	0.00	\$74.00	Replace	Replace
		55708472 30	WPER GARNISH LOUVER SUB-ASSY	0.00	\$666.90	0.00	\$0.00	Replace	Not Given
		55754470 70	WPER GARNISH SHIELD, COWL WATER, LH	0.00	\$18.90	0.00	\$0.00	Replace	Not Given
		55753470 90	WPER GARNISH SHIELD, COWL WATER, RH	0.00	\$18.90	0.00	\$0.00	Replace	Not Given
		61014470 10	PILLAR, FRONT BODY, LH	0.00	\$339.40	0.00	\$0.00	Replace	Check
		60118470 20	COVER SUB-ASSY, FRONT PILLAR, UPR LH	0.00	\$96.90	0.00	\$0.00	Replace	Check
		88790281 00	THERMISTOR ASSY	0.00	\$68.00	0.00	\$0.00	Replace	Check
		53289470 72	COVER, RADIATOR	0.00	\$227.80	0.00	\$0.00	Replace	Check

964.70



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 22/05/2019

User ID : ZhiYangPhua

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		53205479 00	SUPPORT S/A UPPER	1.00	\$364.90	25.00	\$273.67	Replace	Replace
		53028470 10	SUPPORT SUB-ASSY LOWER	0.00	\$397.40	0.00	\$0.00	Replace	Check
		53203479 01	SUPPORT S/A LH	0.00	\$237.00	0.00	\$0.00	Replace	Check
		53202479 01	SUPPORT S/A RH	0.00	\$237.00	0.00	\$0.00	Replace	Check
		53217470 30	BRACE, HOOD LOCK SUPPORT	0.00	\$76.20	0.00	\$0.00	Replace	Check
		53214470 50	SUPPORT, RADIATOR UPPER LH	0.00	\$76.70	0.00	\$0.00	Replace	Check
		53213470 50	SUPPORT, RADIATOR UPPER RH	0.00	\$76.70	0.00	\$0.00	Replace	Check
		81185476 91	UNIT, HEADLAMP, LH	1.00	\$2,558.90	10.00	\$2,303.01	Replace	Replace
		81145476 91	UNIT, HEADLAMP, RH	1.00	\$2,558.90	10.00	\$2,303.01	Replace	Replace
		81056476 90	COMPUTER SUBASSY, HEADLAMP, LH NO.1	0.00	\$486.40	0.00	\$0.00	Replace	Check
		8101647690	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	0.00	\$486.40	0.00	\$0.00	Replace	Check
		86510470 50	HORN ASSY, HIGH	0.00	\$112.80	0.00	\$0.00	Replace	Check
		86520470 30	HORN ASSY, LOW	0.00	\$112.80	0.00	\$0.00	Replace	Check
		88460103 20	AIR CON CONDENSER ASSY	0.00	\$1,317.70	0.00	\$0.00	Replace	Check
		88710471 60	TUBE & ACCESSORY	0.00	\$574.40	0.00	\$0.00	Replace	Check
		88703470 80	HOSE SUB-ASSY, DISCHARGE	0.00	\$337.10	0.00	\$0.00	Replace	Check
			COOLANT	0.00	\$12.30	0.00	\$0.00	Replace	Check
		16592370 20	GUIDE, RADIATOR AIR	0.00	\$93.90	0.00	\$0.00	Replace	Check
		16594370 10	GUIDE, RADIATOR AIR, UPPER	0.00	\$44.70	0.00	\$0.00	Replace	Check
		16595370 50	GUIDE, RADIATOR AIR, LH	0.00	\$58.80	0.00	\$0.00	Replace	Check
		16593370 40	GUIDE, RADIATOR AIR, RH	0.00	\$54.80	0.00	\$0.00	Replace	Check
		16400373 10	RADIATOR ASSY	0.00	\$1,841.10	0.00	\$0.00	Replace	Check
		90480400 21	GROMMET (FOR RADIATOR LOWER SUPPORT)	0.00	\$12.70	0.00	\$0.00	Replace	Check
		16523370 10	CUSHION, (FOR RADIATOR UPPER SUPPORT)	0.00	\$9.80	0.00	\$0.00	Replace	Check
		16361370 60	FAN RADIATOR, LH	0.00	\$181.80	0.00	\$0.00	Replace	Check
		16361370 70	FAN RADIATOR, RH	0.00	\$233.00	0.00	\$0.00	Replace	Check
		16711371 60	FAN SHROUD RADIATOR	0.00	\$219.30	0.00	\$0.00	Replace	Check
		16363370 60	MOTOR, COOLING FAN, LH	0.00	\$543.50	0.00	\$0.00	Replace	Check
		16363361 60	MOTOR, COOLING FAN, RH	0.00	\$443.40	0.00	\$0.00	Replace	Check
		16571372 10	HOSE, RADIATOR, NO.1	0.00	\$42.60	0.00	\$0.00	Replace	Check
		16572372 10	HOSE, RADIATOR, NO.2	0.00	\$40.20	0.00	\$0.00	Replace	Check
		164A237 012	TANK, RESERVE SEALED W/O CAP	0.00	\$127.00	0.00	\$0.00	Replace	Check
		16261371 50	HOSE, WATER BYPASS, NO.1	0.00	\$37.40	0.00	\$0.00	Replace	Check
		16264371 20	HOSE, WATER BYPASS, NO.2	0.00	\$37.40	0.00	\$0.00	Replace	Check
		16267370 90	HOSE, WATER BYPASS, NO.3	0.00	\$20.10	0.00	\$0.00	Replace	Check
		16281371 00	HOSE, WATER BYPASS, NO.4	0.00	\$13.20	0.00	\$0.00	Replace	Check
		16296370 10	HOSE, WATER BYPASS, NO.8	0.00	\$37.90	0.00	\$0.00	Replace	Check

8077.7



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 22/05/2019

User ID : ZhiYangPhua

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		16268371 00	PIPE, WATER BYPASS, NO.1	0.00	\$11.00	0.00	\$0.00	Replace	Check
		16268371 20	PIPE, WATER BYPASS, NO.2	0.00	\$11.00	0.00	\$0.00	Replace	Check
		16279370 20	PIPE, WATER BYPASS, NO.3	0.00	\$56.40	0.00	\$0.00	Replace	Check
		16577370 90	PIPE, RADIATOR	0.00	\$32.90	0.00	\$0.00	Replace	Check
		16573370 20	HOSE, RADIATOR, NO.3	0.00	\$29.60	0.00	\$0.00	Replace	Check
		16282370 90	HOSE, WATER BYPASS, NO.5	0.00	\$13.20	0.00	\$0.00	Replace	Check
		16278370 20	PIPE, WATER BYPASS, NO.5	0.00	\$51.80	0.00	\$0.00	Replace	Check
		16283370 21	HOSE, WATER BYPASS, NO.6	0.00	\$13.20	0.00	\$0.00	Replace	Check
		G904047 040	INVERTER WATER PUMP ASSY	0.00	\$432.00	0.00	\$0.00	Replace	Check
		G922E47 010	HOSE, HV WATER PUMP INLET	0.00	\$37.90	0.00	\$0.00	Replace	Check
		G922F47 010	HOSE, HV WATER PUMP OUTLET	0.00	\$29.60	0.00	\$0.00	Replace	Check
		G91H047 011	TANK ASSY, INVERTER RESERVE	0.00	\$371.30	0.00	\$0.00	Replace	Check
		G922A47 010	HOSE, INVERTER COOLING INLET	0.00	\$43.10	0.00	\$0.00	Replace	Check
		G922C47 010	HOSE, INVERTER COOLING OUTLET	0.00	\$29.60	0.00	\$0.00	Replace	Check
		G922H47 010	HOSE, INVERTER RADIATOR INLET	0.00	\$40.70	0.00	\$0.00	Replace	Check
		G125A47 010	COOLER, MOTOR COOLING	0.00	\$249.10	0.00	\$0.00	Replace	Check
		821H247 010	WIRE, AIR CONDITIONER	0.00	\$445.70	0.00	\$0.00	Replace	Check
		8211147J 21	WIRE, ENGINE ROOM MAIN	0.00	\$6,138.00	0.00	\$0.00	Replace	Check
		28800371 30	BATTERY	0.00	\$1,584.90	0.00	\$0.00	Replace	Check
		74404470 30	CLAMP SUB-ASSY, BATTERY	0.00	\$41.40	0.00	\$0.00	Replace	Check
		74482470 10	CLAMP, BATTERY, NO.2	0.00	\$43.30	0.00	\$0.00	Replace	Check
		82621470 20	COVER, FUSIBLE LINK	0.00	\$28.30	0.00	\$0.00	Replace	Check
		8262047090	BLOCK ASSY, FUSIBLE LINK	0.00	\$99.80	0.00	\$0.00	Replace	Check
		8267147040	BLOCK, JUNCTION	0.00	\$15.80	0.00	\$0.00	Replace	Check
		2885037070	SENSOR ASSY, BATTERY STATE	0.00	\$256.80	0.00	\$0.00	Replace	Check
		2885937030	HOLDER, BATTERY CURRENT SENSOR	0.00	\$11.70	0.00	\$0.00	Replace	Check
		17751371 10	INLET, AIR CLEANER, NO.1	0.00	\$130.50	0.00	\$0.00	Replace	Check
		17752371 21	INLET, AIR CLEANER, NO.2	0.00	\$93.90	0.00	\$0.00	Replace	Check
		17753370 10	INLET, AIR CLEANER, NO.3	0.00	\$35.30	0.00	\$0.00	Replace	Check
		17893371 30	RESONATOR, INTAKE AIR	0.00	\$14.90	0.00	\$0.00	Replace	Check
		17771370 20	BRACKET, AIR CLEANER	0.00	\$26.90	0.00	\$0.00	Replace	Check
		17700373 30	AIR CLEANER ASSY	0.00	\$956.20	0.00	\$0.00	Replace	Check
		90904060 08	TUBE, UNION (FOR AIR CLEANER HOSE)	0.00	\$19.40	0.00	\$0.00	Replace	Check
		5710147070	MEMBER SUB-ASSY, FR RH	0.00	\$2,012.70	0.00	\$0.00	Replace	Check
		5710247090	MEMBER SUB-ASSY, FR LH	0.00	\$1,959.50	0.00	\$0.00	Replace	Check
		8531947170	WIPER WASHER INLET	0.00	\$55.40	0.00	\$0.00	Replace	Check

1542280



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 22/05/2019

User ID : ZhiYangPhua

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		8531547160	WIPER WASHER JAR	0.00	\$183.60	0.00	\$0.00	Replace	Check
		53801470 80	FENDER SUB-ASSY, FR, RH	1.00	\$933.10	100.00	\$0.00	Replace	Repair
		75374471 40	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$52.90	25.00	\$39.67	Replace	Replace
		53807470 20	SEAL SUB-ASSY, RH	1.00	\$50.20	25.00	\$37.65	Replace	Replace
		53875470 70	LINER, FR FENDER, RH	0.00	\$198.40	0.00	\$0.00	Replace	Check
		5370147111	APRON SUB-ASSY, FRONT FENDER, RH	0.00	\$944.20	0.00	\$0.00	Replace	Check
		53802471 00	FENDER SUB-ASSY, FR, LH	1.00	\$933.10	25.00	\$699.83	Replace	Replace
		75374471 40	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$52.90	25.00	\$39.67	Replace	Replace
		53828470 70	PROTECTOR, FR FENDER LH	0.00	\$90.40	0.00	\$0.00	Replace	Check
		53808470 20	SEAL SUB-ASSY, LH	0.00	\$50.20	0.00	\$0.00	Replace	Check
		53876471 10	LINER, FR FENDER, LH	1.00	\$194.30	25.00	\$145.73	Replace	Replace
		53852470 41	PAD, FR WHEEL LH	0.00	\$57.70	0.00	\$0.00	Replace	Check
		53702471 01	APRON SUB-ASSY, FRONT FENDER, LH	0.00	\$944.20	0.00	\$0.00	Replace	Check
		67002471 62	PANEL SUB-ASSY, FRONT DOOR LH	1.00	\$1,249.60	100.00	\$0.00	Replace	Repair
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace
		8861047040	CHECK ASSY, FRONT DOOR	0.00	\$153.50	0.00	\$0.00	Replace	Not Given
		6872012151	HINGE ASSY, FRONT DOOR, UPPER LH	0.00	\$82.10	0.00	\$0.00	Replace	Not Given
		6874012120	HINGE ASSY, FRONT DOOR, LOWER LH	0.00	\$92.10	0.00	\$0.00	Replace	Not Given
Total					\$72,456.40		\$27,173.83		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

2468.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: